

US Army Corps of Engineers
New York District

FINAL

FINAL STATUS SURVEY REPORT

FORT MONMOUTH
EATONTOWN, NEW JERSEY

15 August 2012

SIGNATURES

The undersigned certify that they have reviewed and provided comments on the enclosed report that was prepared for the radiological investigation of Fort Monmouth, New Jersey.

Prepared by:

WATTERS.DAVID.J.1399921224

Digitally signed by WATTERS.DAVID.J.1399921224
DN: c=US, o=U.S. Government, ou=DoD, ou=PKI, ou=USA, cn=WATTERS.DAVID.J.1399921224
Date: 2012.08.15 15:47:42 -04'00'

DAVID J. WATTERS, CHP
Health Physicist
U.S. Army Corps of Engineers (Baltimore District)

15 August 2012
Date

Reviewed by:

MOORE.JAMES.T.1254211105

Digitally signed by MOORE.JAMES.T.1254211105
DN: c=US, o=U.S. Government, ou=DoD, ou=PKI, ou=USA, cn=MOORE.JAMES.T.1254211105
Date: 2012.08.15 15:59:45 -04'00'

JAMES T. MOORE, PMP
Project Manager
U.S. Army Corps of Engineers (Baltimore District)

15 August 2012
Date

Reviewed by:

MILLER.NEIL.T.1299145090

Digitally signed by MILLER.NEIL.T.1299145090
DN: c=US, o=U.S. Government, ou=DoD, ou=PKI, ou=USA, cn=MILLER.NEIL.T.1299145090
Date: 2012.08.15 15:50:38 -04'00'

NEIL T. MILLER, OHST, CSHS
Health Physicist
U.S. Army Corps of Engineers (Buffalo District)

15 August 2012
Date

EXECUTIVE SUMMARY

The U.S. Army Corps of Engineers (USACE) has developed this radiological Final Status Survey Report (FSSR) to support radiological closure of properties on Fort Monmouth in Eatontown and Tinton Falls, New Jersey. This FSSR reports the results of radiological surveys implemented in accordance with the USACE Radiological Scoping Survey Plan (RSSP), issued as final in June 2012 (USACE, 2012a). Radiological surveys were performed in June 2012 to secure unrestricted radiological release and facilitate transfer of real property as part of Base Realignment and Closure (BRAC).

The USACE RSSP and this final status survey (FSS) were designed based on information from the Final Phase I Historical Site Assessment (HSA) (CABRERA, 2007a), the Final Phase II Environmental Condition of Property Investigation (CABRERA, 2007b), and the HSA supplement developed by USACE in 2012 (USACE, 2012b). The FSS was designed using the approach outlined in the Multi-Agency Radiation Survey and Site Investigation Manual (MARSSIM) (U.S. Nuclear Regulatory Commission [NRC], 2000) and incorporates Department of the Army, Army Materiel Command (AMC) guidance (AMC, 2004), as applicable. The "scoping surveys" described in the USACE RSSP were designed in accordance with MARSSIM FSS requirements in order to generate sufficient information to release areas confirmed to be free of residual contamination for unrestricted use.

Approximately 25 buildings, building complexes, and/or open areas were identified in the HSA as areas where radioactive materials (RAM) were used or stored. Based on the information collected, the HSA classified four of the buildings as MARSSIM impacted. Information obtained subsequent to the HSA, and documented in the HSA Supplement (USACE, 2012b), resulted in classification of an additional building as MARSSIM impacted (total of five): Buildings 275, 283, 292, 2540 and 2541.

Radiological FSSs were performed in Buildings 275, 283, 292, 2540 and 2541. The surveys were designed in accordance with MARSSIM final status survey design criteria using conservative assumptions. Derived concentration guideline levels (DCGLs) applied to the surveys are the conservative NRC generic screening criteria. The sum of the ratios (SOR) rule was applied to all survey results to address the potential presence of multiple radionuclide contaminants. All SOR results in all buildings, including biased locations, are less than the limit of SOR = one. In addition, evaluations of building systems (drain and ventilation) for radioactive contaminants did not identify any radiological impacts to building systems. Based on historical research and the FSS field observations and supporting laboratory analytical data, all buildings surveyed are considered suitable for unrestricted release in accordance with Subpart E to 10 CFR 20, Radiological Criteria for License Termination.

TABLE OF CONTENTS

SECTION PAGE

EXECUTIVE SUMMARY II

1.0 PROJECT DESCRIPTION 1

1.1 BACKGROUND 1
1.2 SUMMARY OF HISTORICAL SITE ASSESSMENT 2
1.2.1 Site History 3
1.2.2 Potential Radiological Contaminants 4
1.3 SUMMARY OF IMPACTED AREAS 5
1.3.1 Building 275 5
1.3.2 Building 283 5
1.3.3 Building 292 6
1.3.4 Building 2540 6
1.3.5 Building 2541 7

2.0 RESIDUAL RADIOACTIVITY SCREENING LEVELS – SURVEY DCGLS 8

3.0 SURVEY DESIGN AND METHODOLOGY 9

3.1 SCOPE 9
3.2 CONCEPTUAL SITE MODEL 9
3.3 MARSSIM COMPLIANCE TESTING 10
3.3.1 Low Energy Beta RCOPCs – Wet Smear Analysis 10
3.3.2 Measureable Beta RCOPCs – Direct Measurement 10
3.3.3 Alpha RCOPCs – Direct Measurement 11
3.3.4 Sum of the Ratios (SOR) 11
3.4 IMPACTED BUILDING MARSSIM CLASSIFICATIONS AND AREA-SPECIFIC RCOPCS 12
3.4.1 Building 275 12
3.4.2 Building 283 13
3.4.3 Building 292 13
3.4.4 Building 2540 14
3.4.5 Building 2541 15
3.5 SURVEY DESIGN 15
3.5.1 MARSSIM-required Number of Survey Points 18
3.5.2 Reference Area and Reference Materials 20
3.5.3 Determination of Survey Point Locations 21
3.5.4 Selection of Area Size for Survey Units 21
3.5.5 Surface Scan Requirements 22
3.5.6 Interpretation of Results 23
3.5.7 Decision Rules 24
3.5.8 Performing the Sign Test 24

4.0 SAMPLING APPARATUS AND FIELD INSTRUMENTATION 25

4.1 DIRECT AND SCAN RADIATION MEASUREMENTS 26
4.1.1 Alpha and Beta Static Minimum Detectable Concentrations 28
4.1.2 Alpha and Beta Scan Minimum Detectable Concentrations 28
4.1.3 Gamma Exposure Rate Measurements 30
4.2 SMEAR COLLECTION AND MDCS 32
4.3 VOLUMETRIC SAMPLE COLLECTION AND ANALYSIS 33

5.0 DATA QUALITY ASSESSMENT 34

5.1 DATA COMPLETENESS 34
5.2 STATISTICAL ANALYSIS 34
5.3 INSTRUMENT QA/QC 34
5.4 OFF-SITE LABORATORY SAMPLE ANALYSIS 35
5.4.1 Method Blank 36
5.4.2 Laboratory Control Sample / Laboratory Control Sample Duplicate 36
5.4.3 Detection Limits 37
5.4.4 Method Performance and Summary Assessment 37
5.5 DUPLICATE MEASUREMENTS AND FIELD DUPLICATE SMEARS 38
5.5.1 Static Gross Alpha/Beta Duplicates 38
5.5.2 Off-site Gross Alpha/Beta Analyses 38
5.5.3 Off-site Low Energy Beta Analyses 38

6.0 INTERPRETATION OF FINAL STATUS SURVEY RESULTS 40

6.1 REFERENCE MATERIAL BACKGROUND 40
6.2 CONFIRMATION OF ASSUMED 10% REMOVABLE FRACTION 41
6.3 FSS RESULTS BY BUILDING 42
6.3.1 Building 275 - Museum 43
6.3.2 Building 283 – Squier Hall 45
6.3.3 Building 292 - Museum Storage 47
6.3.4 Building 2540 – CECOM Laboratory 48
6.3.5 Building 2541 – CECOM Butler Building 56

7.0 CONCLUSION 58

8.0 REFERENCES 59

LIST OF TABLES

Table 1: Final Status Survey RCOPCs 5

Table 2: NRC Screening Criteria – FSS DCGLs 8

Table 3: Instrument Count Times, MDCs, and Fraction of DCGL Achieved 16

Table 4: Overview of Major Activities and Tasks 17

Table 5: MARSSIM Suggested Area Limits For Survey Units 22

Table 6: Area Factors and Required Class 1 Scan Sensitivity 23

Table 7: Decision Rules 24

Table 8: Selected Instrumentation 26

Table 9: FSS Detector Efficiencies 26

Table 10: Direct Alpha Beta Measurement Nominal Sensitivities 31

Table 11: Gas Proportional Detector Material Backgrounds 41

Table 12: Summary of Survey Unit SOR Results 42

Table 13: Summary of Survey Unit Alpha/Beta Results 43

LIST OF FIGURES

(Figures are attached at the end of the document text)

Figure 1: Site Location Map

Figure 2: Fort Monmouth Overview Map

Figure 3: Current View of Fort Monmouth, Main Post

Figure 4: Current View of Fort Monmouth, Charles Wood Area

Figure 5: Building 2540 Floor Plan and Survey Units

LIST OF APPENDICES

Appendix A: Sample/Measurement Location Maps

Appendix B: Posting Plots of SOR Results

Appendix C: Survey Unit Data and SOR Results

Appendix D: Background Reference Area Data

Appendix E: Instrument and Check Source Calibration Certificates

Appendix F: Instrument Quality Control Data

Appendix G: Field Notebook

Appendix H: Scan Data

Appendix I: Duplicate Measurement Results

Appendix J: Laboratory Data Packages

ACRONYMS

^{241}Am	Americium-241
^{252}Cf	Californium-252
^{14}C	Carbon-14
^{137}Cs	Cesium-137
^{36}Cl	Chlorine-36
^{57}Co	Cobalt-57
^{60}Co	Cobalt-60
^{154}Eu	Europium-154
^{63}Ni	Nickel-63
^{238}Pu	Plutonium-238
^{147}Pm	Promethium-147
^{226}Ra	Radium-226
^{90}Sr	Strontium-90
^{99}Tc	Technetium-99
^{230}Th	Thorium-230
^{232}Th	Thorium-232
^{3}H	Tritium
^{90}Y	Yttrium-90
AMC	Army Materiel Command
ARA	Army Radiation Authorizations
BRAC	Base Realignment and Closure
CABRERA	Cabrera Services, Inc.
CECOM	U.S. Army Communications-Electronics Command
CFR	U.S. Code of Federal Regulations
cm^2	Square Centimeter
COC	Chain of Custody
cpm	Counts per Minute
CQC	Contractor Quality Control
CSM	Conceptual Site Model
DCF	Dose Conversion Factor
DCGLor DCGL$_W$	Derived Concentration Guideline Level
DoD	Department of Defense
dpm/100 cm^2	Disintegrations per Minute per 100 Square Centimeters
DQCR	Daily Quality Control Report
ECP	Environmental Condition of Property
ELAP	Environmental Laboratory Accreditation Program
FSS	Final Status Survey
FSSR	Final Status Survey Report
ft	Foot
ft^2	Square feet
HEPA	High Efficiency Particulate Air
HP	Health Physicist
HSA	Historical Site Assessment
IDW	Investigation-derived waste
LBGR	Lower Bound of Gray Region
LCS	Laboratory Control Sample

LCSD	Laboratory Control Sample Duplicate
LSC	Liquid Scintillation Counter
m	meters
m^2	Square Meters
µR/hr	Micro-Roentgen per Hour
MARSSIM	Multi-Agency Radiation Survey and Site Investigation Manual
MDC or MDC_{SCAN}	Minimum Detectable Concentration
MDA	Minimum detectable activity
MeV	Mega Electron Volts
min	minute
mrem/yr	Millirem Per Year
NAD	Normalized Absolute Difference
NIST	National Institute of Standards and Technology
NRC	U.S. Nuclear Regulatory Commission
PCBs	Polychlorinated Biphenyls
PM	Project Manager
PPE	Personal Protective Equipment
QA	Quality Assurance
QC	Quality Control
R&D	Research and Development
RAM	Radioactive materials
RCOPC	Radionuclide Contaminant of Potential Concern
RSC	Radiation Safety Committee
RSSP	Radiological Scoping Survey Plan
sec	Second
SOP	Standard Operating Procedure
SOR	Sum of the Ratios
SU	Survey Unit
U.S.	United States
USACE	U. S. Army Corps of Engineers

1.0 PROJECT DESCRIPTION

The U.S. Army Corps of Engineers (USACE) has developed this radiological Final Status Survey Report (FSSR) to support radiological closure of properties on Fort Monmouth in Eatontown and Tinton Falls, New Jersey. This FSSR reports the results of radiological surveys implemented in accordance with the USACE Radiological Scoping Survey Plan (RSSP), issued as final in June 2012 (USACE, 2012a). Radiological surveys were performed in June 2012 to secure unrestricted radiological release and facilitate transfer of real property as part of Base Realignment and Closure (BRAC). Figure 1 identifies the location of Fort Monmouth (figures are located at the end of this FSSR, after the References Section).

The USACE RSSP and this final status survey (FSS) were designed based on information from the Final Phase I Historical Site Assessment (HSA) (CABRERA, 2007a), the Final Phase II Environmental Condition of Property Investigation (CABRERA, 2007b), and the HSA supplement developed by USACE in 2012 (USACE, 2012b). The FSS was designed using the approach outlined in the Multi-Agency Radiation Survey and Site Investigation Manual (MARSSIM) (U.S. Nuclear Regulatory Commission [NRC], 2000) and incorporates Department of the Army, Army Materiel Command (AMC) guidance (AMC, 2004), as applicable. The "scoping surveys" described in the USACE RSSP were designed in accordance with MARSSIM FSS requirements in order to generate sufficient information to release areas confirmed to be free of residual contamination for unrestricted use.

The Army intends to release all facilities and areas at Fort Monmouth for unrestricted use. As part of the BRAC process, the type and location of potential hazards must be identified, and mitigated if necessary, prior to release. This FSSR demonstrates that all areas are suitable for unrestricted radiological release and that mitigation of radiological hazards is unnecessary.

This FSSR summarizes HSA findings, repeats substantive requirements of the RSSP, and presents the results of the radiological surveys performed with minimal information incorporated by reference. This minimizes the need to lookup information in supporting reference documents, facilitating primary review of a single document.

1.1 Background

Fort Monmouth was identified as one of the military installations slated for closure as part of BRAC 2005 (Public Law 101-510 as amended). BRAC is the process by which the nation reshapes its military installations to become more efficient and effective in supporting its forces. As part of this process, an Environmental Condition of Property (ECP) assessment was completed for Fort Monmouth. The ECP assists the Army in evaluation of the type and locations of potential radiological hazards at the facility and the surrounding environment. This FSSR presents the results of radiological surveys performed to specifically address areas identified in

the HSA (as supplemented) that performed former operations involving radioactive materials (RAM) falling under NRC licenses, or under Department of the Army Radiation Authorizations (ARAs). The applicable NRC licenses and ARAs are summarized in the HSA.

The overall project intent is to plan, perform, and document radiological decommissioning efforts to allow release of facilities for "unrestricted release". This phase and previous phases include: 1) the identification of known sources/areas of radioactive contamination; 2) identification of areas that need further action; 3) assessment of the likelihood of contaminant migration; 4) identification of areas as impacted or non-impacted in accordance with MARSSIM; 5) identification of data gaps in impacted areas; 6) determination of the radiological status of the impacted areas through performance of final status surveys; and 7) demonstration that all areas are suitable for unrestricted radiological release.

1.2 Summary of Historical Site Assessment

A final HSA was prepared in support of the Environmental Condition of Property assessment based on document review, personal observation, and interviews with personnel at Fort Monmouth (CABRERA, 2007a). In addition, a supplement to the HSA was developed by USACE to summarize additional information (USACE, 2012b).

The HSA reviewed available information regarding Fort Monmouth, including operating history, survey results, and potential pathways for radioactive and hazardous material release. Information sources reviewed included:

- Fort Monmouth operating history, including RAM licenses, permits, and use authorizations and protocols;
- Minutes of the Fort Monmouth Radiation Safety Committee (RSC) for reference to any spills, releases of radioactive material to the environment surrounding the Site during facility operations, and onsite disposals of radioactive or hazardous materials;
- Surveys for RAM present at Fort Monmouth;
- Physical tours of the Fort Monmouth facilities expected to be impacted due to both current (then current) and former RAM usage;
- Off-installation document repositories including the NRC Public Document Room, U.S. Army Public Health Command, and U.S. Army Field Support Command.

As part for the HSA process, Interviews were conducted and documented with 35 personnel from varying groups, including:

- Facility Management
- Security
- Department of Public Works

- U.S. Army Communications-Electronics Command (CECOM) Radiation Analysis and Compliance Division and Laboratory/Research and Development (R&D) Operations
- Museum Operations
- Postal Operations
- Industrial Hygiene and Safety
- Supply Management

Approximately 25 buildings, building complexes, and/or open areas were identified in the HSA as areas where RAM were used or stored. Based on the information collected, the HSA classified four of the buildings as MARSSIM impacted. Information obtained subsequent to the HSA, and documented in the HSA Supplement, resulted in classification of an additional building as MARSSIM impacted (total of five buildings). The impacted buildings are discussed in Section 1.3 and shown in Figures 2 and 3.

1.2.1 Site History

Fort Monmouth is located 12 miles west of the Atlantic Ocean and 45 miles south of New York City, just north of Eatontown in Monmouth County, New Jersey (Figure 1). Military operations began at this installation in 1917. Documents gathered from various sources were reviewed and evaluated to extract information on the possession and use of RAM. These documents included licenses, permits, authorizations, inventory records, surveys, historical drawings, and floor plans. In addition, the HSA included a visual inspection of all buildings and areas where RAM was used or stored, and interviews with individuals knowledgeable of RAM handling, storage, and disposal. The use of RAM at Fort Monmouth was historically conducted in accordance with a number of NRC licenses and ARAs.

The presence of RAM at Fort Monmouth has been predominantly limited to certain areas and functions of the installation. Historically, laboratory R&D in the areas of radio and electronics use of vacuum tubes and radium dials, and military support equipment such as night vision goggles that contain radioactive commodities have been the most common uses of RAM at Fort Monmouth. Some of the past activities involving RAM were performed as part of the Signal Corps Laboratories, first housed in the Squier Building (Building 283) and then in the Myers Center. The majority of work with RAM was performed by CECOM under license with the NRC in Building 2540. Other work was performed in the Evans Area of the base, which was closed in the late 1990s due to BRAC 1993 activities, and the work then transferred to the CECOM office and laboratory in the Charles Wood Area.

At the time the HSA was finalized (in 2007), a research laboratory in Building 2540 in the Charles Wood Area was the only site to regularly use and store RAM as part of R&D activities. A designated storage area was set aside for drums containing material waiting for disposal, including tritium exit signs removed from Fort Monmouth buildings, smoke alarms containing

RAM, and other instruments with associated check sources. These items were periodically removed to Wright Patterson Air Force Base for disposal/recycling. At this time, all work involving RAM at Building 2540 has ceased and all RAM have been removed from the facility.

The administrative arm of the CECOM Safety Office was housed in the adjacent building, 2539, prior to relocating to Aberdeen Proving Ground in Maryland. The Safety Office maintains files pertaining to the use of any RAM on the installation as well as active and inactive NRC licenses and ARAs for Fort Monmouth. Documents indicate that radioactive material was used in chemical and explosives detectors operated by personnel working in security entrance areas, postal facilities, and shipping areas, and emergency responder personnel throughout the installation. Electron capture detectors containing ^{63}Ni were used in the Environmental Laboratory to analyze samples for pesticides and Polychlorinated Biphenyls (PCBs). All of this equipment involves the use of sealed sources rather than research-type dispersible materials. Leak test were performed regularly on sealed sources and no source ever failed a leak test.

1.2.2 Potential Radiological Contaminants

Radiological contaminants of potential concern (RCOPCs) were developed from research of Fort Monmouth's NRC RAM licenses and amendments and interviews with key personnel. Based on this research, the RCOPC list is shown in Table 1.

It should be noted that this list represents the primary radionuclides that were used at Fort Monmouth, but may not be all-inclusive since there were NRC licenses applicable to Fort Monmouth that permitted possession of any radionuclide with atomic numbers 1 through 95. The goal of developing a RCOPC list is to determine the instrumentation needs for the FSSs in order to ensure that all residual contamination will be detected and properly characterized. The list of RCOPCs dictated the requirement that instrumentation must be able to detect alpha, low energy to high energy beta, and gamma radiation.

The majority of the RCOPCs at Fort Monmouth are associated with the historic use and storage of radioactive commodities by the Garrison and current and former tenants. In addition, radioactive calibration sources and R&D commodities historically used by CECOM presented additional potential sources of radioactive material at Fort Monmouth.

Table 1 lists RCOPCs and their primary charged particle emissions. It should be noted that other radionuclides were used at Fort Monmouth as part of CECOM operations. However, based on information documented in the HSA (as supplemented), these radionuclides are not considered RCOPCs for this survey. Such radionuclides were calibration or test standards in a sealed or electroplated physical form and were subjected to required routine leak tests. Documentation indicates that no source ever failed a leak tests at Fort Monmouth and that all sources performed as designed, containing their radioactive material and preventing dispersal. In addition, ^{232}Th, as

an oxide in glass lenses, was demilitarized by CECOM (USACE, 2012b). However, ^{232}Th is not considered a RCOPC because it is non-dispersive and does not leach from thoriated lenses.

Table 1: Final Status Survey RCOPCs

ROC	Half-life	Principal Emission	Max Energy (MeV)	Average Energy (MeV)
^{3}H	12.3 y	Beta	0.02	0.01
^{63}Ni	100 y	Beta	0.07	0.02
^{57}Co	270.9 d	Electron	0.13	0.02
^{14}C	5700 y	Beta	0.16	0.05
^{147}Pm	2.62 y	Beta	0.22	0.06
^{99}Tc	2.13E5 y	Beta	0.29	0.08
^{60}Co	5.27 y	Beta	0.32	0.10
^{137}Cs	30.2 y	Beta	0.51	0.19
^{154}Eu	8.6 y	Beta	1.85	0.22
^{36}Cl	3.01E5 y	Beta	0.71	0.25
^{90}Sr/^{90}Y	29.12 y	Beta	2.28	0.56
^{226}Ra	1600 y	Alpha	4.78	NA
^{230}Th	7.54E4 y	Alpha	4.69	NA
^{241}Am	432.2 y	Alpha	5.49	NA

1.3 Summary of Impacted Areas

1.3.1 Building 275

Building 275 was a communications-electronics museum. Thoriated lenses (night vision lens), a Kodak camera, a radium-containing component on a radio, and vacuum tube were among several museum display items that gave off readings above background level during the HSA reconnaissance. These items and numerous other radioactive items have since been removed.

1.3.2 Building 283

Building 283 last housed administrative offices and previously housed research laboratories and signal school training classrooms. Evidence of radio communication work was found on shelves in the basement work area (radio manual, wire used in radio circuitry).

1.3.3 Building 292

Building 292 served as storage space for the museum. At the time of the HSA reconnaissance, this storage space contained a Chinese radio, a vacuum tube, suspected radioactive commodities, and radium-contaminated components in a posted radioactive storage locker (all with radiological readings above background levels). This storage space once contained 65 items containing RAM. All radioactive and other items have since been removed.

1.3.4 Building 2540

Building 2540 housed the CECOM Laboratory and Radiological testing facility. Inventory lists cite use of multiple radiological materials and many were in use at the time of the HSA. Radiation Safety Surveys were conducted regularly in Building 2540, specifically mentioning the calibration range (Room 108), radiological lab, prep lab (Room 102), calibration lab, radwaste storage, excess waste storage (Room 109), exposure room, irradiator room, and panoramic range (Room 106A). The portion of the building referred to as "Building 2540" was primarily used for sample analysis and instrument calibration. The northern portion, referred to as "Building 2540A", was primarily used for R&D.

Some historic surveys indicated radiation levels elevated beyond background in certain locations. The surveys note that a Mobile Laboratory, which was considered part of this building, had a closeout survey completed in August 2001. Minutes from RSC meetings discuss the disposal of low-level radioactive waste (drums containing tritium exit signs and smoke detectors) by shipping to Wright Patterson Air Force Base as well as an inventory of sources, smoke detectors, instruments, etc. Radiological Work Permits were issued for the use of x-ray machines, calibrator use of ^{137}Cs, ^{238}Pu, ^{99}Tc, and ^{60}Co, R&D use of ^{137}Cs, a radium-beryllium source, ^{252}Cf, and ^{60}Co, and demilitarization activities from excess storage of ^{232}Th (thoriated lenses), ^{226}Ra, and ^{3}H.

Radioactive materials were regulated under NRC licenses. R&D activities were performed in the northern portion of the building, Building 2540A; testing was performed in a low-level environmental lab (e.g., use of high-purity germanium detector, scintillator, etc.); a radioactive material storage area was established; the building contains a former irradiator room (Room 7) that used a 2000-curie ^{60}Co source (decayed) and produced a dose rate of 500 roentgens/hour; ^{252}Cf was used for calibration and instrument testing, along with various sealed sources. One of the laboratories had a fume hood, which was regularly surveyed. Some work involving liquid forms of ^{241}Am and ^{230}Th was performed in the fume hood in the nuclear counting laboratory and in Dr. Kronenberg's former office.

At the time of the HSA, the storage room adjacent to the building (Room 109) contained unused sealed sources/devices, including RADIAC meters (for training) and ten 55-gallon drums

containing items such as smoke detectors and tritium compasses. These items have been removed and post-removal radiological safety surveys were performed prior to this FSS.

1.3.5 Building 2541

Building 2541 is a "Butler Building" located in close proximity to Building 2540. It was last used to store RADIAC equipment. Newly identified information, documented in the HSA Supplement, indicates that demilitarization of excess ^{232}Th (night vision lenses), ^{226}Ra, and tritium occurred in this building (USACE, 2012b). The initial HSA did not include Building 2541 as an impacted building because the demilitarization activities were thought to have occurred in Building 2540.

2.0 RESIDUAL RADIOACTIVITY SCREENING LEVELS – SURVEY DCGLS

The radionuclides potentially present at the site are numerous and varied with respect to radiation and unrestricted release criteria. NUREG-1757, Vol. 2, (NRC, 2003) provides the NRC's discussion regarding demonstration of compliance with the dose criteria in 10 CFR Part 20, Subpart E, using a screening approach to dose analysis. The look-up screening levels are found in Table H.1 of NUREG-1757, Vol. 2. When screening values were not available in the look-up tables, values were selected from NUREG/CR-5512, Vol. 3, (NRC, 1999a) Table 5.19, *Concentration (dpm/100 cm^2) equivalent to 25 mrem/y for the specified value of P_{crit}*. Values were selected at P_{crit} equal to 0.90 which is the same as those from DandD, Version 2.1 and those published in the lookup table. The screening levels and the "removable" radioactivity goal for each RCOPC are presented in Table 2. These screening levels are the derived concentration guideline levels (DCGLs) that are used for the design of this survey and for unrestricted release compliance testing of survey data.

Consistent with NRC modeling assumptions used to develop the screening levels, the survey is designed assuming that approximately 10% of total surface radioactivity is removable. This assumption was verified as part of the FSS and is discussed later in this FSSR.

Table 2: NRC Screening Criteria – FSS DCGLs

ROC	Half-life	Principal Emission	Screening Criteria (dpm/100 cm^2)	
			Total	Removable [(1)]
^{3}H	12.3 y	Beta	1.20E+08	1.20E+07
^{63}Ni	100 y	Beta	1.80E+06	1.80E+05
^{57}Co	270.9 d	Electron	2.11E+05	2.11E+04
^{14}C	5700 y	Beta	3.70E+06	3.70E+05
^{147}Pm	2.62 y	Beta	3.43E+05	3.43E+04
^{99}Tc	2.13E5 y	Beta	1.30E+06	1.30E+05
^{60}Co	5.27 y	Beta	7.10E+03	7.10E+02
^{137}Cs	30.2 y	Beta	2.80E+04	2.80E+03
^{154}Eu	8.6 y	Beta	1.15E+04	1.15E+03
^{36}Cl	3.01E5 y	Beta	5.00E+05	5.00E+04
^{90}Sr/^{90}Y	29.12 y	Beta	8.70E+03	8.70E+02
^{226}Ra	1600 y	Alpha	315	31.5
^{230}Th	7.54E4 y	Alpha	36.9	3.69
^{241}Am	432.6 y	Alpha	27.0	2.7

Note: [(1)] Removable fraction inferred from total assuming 10% is removable.

3.0 SURVEY DESIGN AND METHODOLOGY

3.1 Scope

FSSs were designed in accordance with MARSSIM (NRC, 2000) and AMC (2004) guidance. This survey specifically addresses the FSS of five buildings:

- Building 275, the Museum
- Building 292, the Museum storage facility
- Building 283, the Squier Building
- Building 2540, the CECOM Laboratory, and
- Building 2541, the CECOM Laboratory Butler building.

The surveying and sampling protocols and rationale are presented in sections to follow.

The overall objective of the FSS is to demonstrate that areas with little or no residual radioactivity are suitable for release for unrestricted use. This objective was achieved through completion of the following tasks.

- Direct alpha and beta radioactivity scan surveys
- Integrated direct surface alpha and beta radioactivity measurements
- Smear sample collection and analysis
- Biased smear sampling of suspect floor drains, sink traps, and hoods and ventilation systems

3.2 Conceptual Site Model

The radiological Conceptual Site Model (CSM), originally developed as part of the HSA, uses available information to provide potential contaminant pathways to support the determination of methods to assess the nature and extent of contamination, the determination of areas and media to be sampled, and the development of strategies for data collection. The Fort Monmouth CSM is presented in complete format in the project HSA (CABRERA, 2007a) and is summarized below.

Surface contamination of building materials (work surfaces, shelves, floors, walls, ceilings, hoods, ventilation systems, etc.) is considered a primary transport mechanism. A secondary mechanism shows contaminants leaching from soil or from leaky drain/sewer systems to soil and groundwater. Contaminant pathway scenarios are summarized as follows:

Scenario 1 - Leaks and/or spills: this possibility could result from sealed sources or storage containers that have been compromised, laboratory spill incidents, or the transfer of contamination from unsealed radiological sources/commodities.

Scenario 2 - Storage/disposal activities: materials that have been stored on the museum shelves or in the museum storage building (Buildings 275 and 292), any materials stored onsite awaiting offsite disposal, or any materials disposed of down laboratory sinks (either in Building 2540 – CECOM laboratory or in Building 283 old research facilities) could then contaminate areas apart from where they were in active use.

3.3 MARSSIM Compliance Testing

As stated previously, the RCOPCs are numerous with a variety of differing charged particle emissions. This FSS implements three primary quantification methods to determine whether or not a location or area meets the DCGLs listed in Table 2: 1) wet smear collection and off-site analysis, 2) direct beta measurements with handheld detectors, and 3) direct alpha measurements with handheld detectors.

3.3.1 Low Energy Beta RCOPCs – Wet Smear Analysis

Tritium, ^{57}Co, and ^{63}Ni emit low energy beta particles and cannot be reliably quantified using handheld instrumentation. As a result, these radionuclides were quantified through collection and analysis of wet smear samples. Wet smear samples were collected over an area of approximately 100 square centimeters (cm^2). These wet smears were analyzed off-site by liquid scintillation counting. The analysis was designed to measure all betas with energies less than 0.16 mega electron volts (MeV).

For all survey areas, the most restrictive low energy beta DCGL is associated with ^{57}Co. To be conservative, low energy beta smear sample results are compared to the removable ^{57}Co DCGL for compliance testing. This analysis is based on the assumption that 10% of the total radioactivity is removable.

It should be noted that this method will detect ^{14}C if it is present on a smear. This FSS uses direct measurements to quantify ^{14}C (see Section 3.3.2). As a result, it is possible that any ^{14}C present may be "double counted", being measured by both techniques. While conservative, this method is considered appropriate due to the low energy emission of ^{14}C and its effects on direct measurement efficiency.

3.3.2 Measureable Beta RCOPCs – Direct Measurement

RCOPCs with beta endpoint energies greater than 0.15 MeV can be reliably measured using handheld detectors. These RCOPCs were quantified using a gas proportional detector.

For all survey areas, the most restrictive DCGL for measureable betas is associated with ^{60}Co. To be conservative, gross beta results are compared to the total ^{60}Co DCGL for compliance testing.

3.3.3 Alpha RCOPCs – Direct Measurement

The alpha emitting RCOPCs can be reliably measured using handheld detectors. These RCOPCs were quantified using a gas proportional detector.

For survey areas where ^{230}Th and ^{241}Am are RCOPCs, the most restrictive DCGL for alpha is associated with ^{241}Am. To be conservative, gross alpha results are compared to the total ^{241}Am DCGL for compliance testing.

For survey areas where ^{230}Th and ^{241}Am are not RCOPCs, the DCGL for alpha is associated with ^{226}Ra. Gross alpha results are compared to the total ^{226}Ra DCGL for compliance testing.

3.3.4 Sum of the Ratios (SOR)

The low energy beta, measureable beta, and alpha results must be evaluated collectively for compliance testing. This is accomplished through use of the unity rule, also called the "sum of ratios" (SOR). At each measurement location, radiological conditions are evaluated using the sum of ratios which must not exceed "1" (i.e., "unity"). The concentrations are limited as follows (MARSSIM equation 4-3):

$$\frac{C_1}{DCGL_1}+\frac{C_2}{DCGL_2}+\frac{C_3}{DCGL_3}+...\le 1$$

Where: C = concentration, and

DCGL = guideline value for each individual radionuclide (1, 2, ..., n)

The low energy beta smear and direct alpha and beta measurement results are compared to the most restrictive DCGLs for the survey unit. These comparisons or ratios are summed and the SOR determined from the following equations. It should be noted that negative ratios are set to zero during summing to ensure SOR results are not inappropriately biased low. Through application of the SOR approach, the DCGL for the survey becomes SOR equal to one.

<u>Areas Where ^{230}Th and ^{241}Am are RCOPCs</u>

$$\text{SOR} = \frac{\text{low energy beta result}}{\text{removable DCGL}_{\text{Co-57}}} + \frac{\text{measureable beta result}}{\text{total DCGL}_{\text{Co-60}}} + \frac{\text{alpha result}}{\text{total DCGL}_{\text{Am-241}}}$$

Areas Where ^{230}Th and ^{241}Am are not RCOPCs

$$\text{SOR} = \frac{\text{low energy beta result}}{\text{removable DCGL}_{\text{Co-57}}} + \frac{\text{measureable beta result}}{\text{total DCGL}_{\text{Co-60}}} + \frac{\text{alpha result}}{\text{total DCGL}_{\text{Ra-226}}}$$

It should be noted that any stated "low energy beta activity" is conservatively assumed to be entirely due to low energy betas. However, a portion of the gross residual count rate may be attributable to other radionuclides of concern. For the sake of evaluating potential contamination, this conservative assumption was deemed appropriate.

3.4 Impacted Building MARSSIM Classifications and Area-Specific RCOPCs

Impacted areas are classified based on contamination potential as per guidance in MARSSIM Sections 2.2, 4.4, 5.5.2, and 5.5.3. Namely,

- Class 1: Areas that have a potential for radioactive contamination (based on site operating history) or known contamination. The area may have been contaminated above the release criteria, and it is possible to find radioactivity above the release criteria;

- Class 2: The area had radioactive material use, but it is unlikely to have radioactivity above the release criteria;

- Class 3: The area had some use of radioactive material, but it is very unlikely to have radioactivity above a small fraction of the release criteria.

The survey unit classifications are based on MARSSIM guidance on classifying areas per the potential level of residual radioactive material contamination relative to the established release criteria (i.e., DCGLs).

In the following building descriptions, the restrictive RCOPC (i.e., lowest) is identified with its respective DCGL for each quantification method: 1) low energy beta emitters, which include ^{3}H, ^{57}Co, and ^{63}Ni; 2) readily detectable beta emitters which include ^{14}C and other beta emitters with maximum beta energies greater than 0.15 MeV; and 3) alpha emitters.

3.4.1 Building 275

Building 275 was surveyed as a MARSSIM Class 3 area. Building 275 is the former Communications-Electronics Museum, which contained various historical displays including demilitarized artifacts. During the site observation conducted for the HSA, several displays with radioactive material were identified: the AN/PRC-10 Radio Miniaturization Display, the Vacuum Tube Development Display, the Night Vision Equipment Display, and the Combat

Photography Display. Since the physical form of RAM associated with these artifacts are of robust construction, spread of contamination was unlikely to occur, but contaminant pathway Scenario 2 from the CSM was considered applicable in Building 275.

To be conservative, all radionuclides listed in Table 1 are considered RCOPCs in Building 275, with the exception of ^{230}Th and ^{241}Am (radionuclides associated only with Building 2540 operations). Specific DCGLs for surveys in Building 275 are as follows:

- Low energy beta emitter: ^{57}Co with DCGL of 21,000 disintegrations per minute per 100 square centimeters (dpm/100 cm^2) (removable)
- Directly measured beta emitter: ^{60}Co with DCGL of 7,100 dpm/100 cm^2
- Directly measured alpha emitter: ^{226}Ra with DCGL of 315 dpm/100 cm^2

Building 275 includes a single Class 3 survey unit. The building layout and measurement/ sample locations are shown in Appendix A, Figure A-1.

3.4.2 Building 283

Building 283 was surveyed as a MARSSIM Class 3 area. Building 283 was utilized as a laboratory with wet labs. Limited evidence was found of radio communication work that was performed in the basement of the building. Laboratory drains lines were covered over, but original janitorial sinks remain. Contaminant pathway Scenarios 1 and 2 from the CSM were considered applicable in Building 283.

To be conservative, all radionuclides listed in Table 1 are considered RCOPCs in Building 283, with the exception of ^{230}Th and ^{241}Am (radionuclides associated only with Building 2540 operations). Specific DCGLs for surveys in Building 283 are as follows:

- Low energy beta emitter: ^{57}Co with DCGL of 21,000 dpm/100 cm^2 (removable)
- Directly measured beta emitter: ^{60}Co with DCGL of 7,100 dpm/100 cm^2
- Directly measured alpha emitter: ^{226}Ra with DCGL of 315 dpm/100 cm^2

Building 283 includes two Class 3 survey units. The building layout and measurement/sample locations are identified on Figures A-2 through A-4 in Appendix A.

3.4.3 Building 292

Building 292 was surveyed as a MARSSIM Class 3 area. Building 292 was used for storage of museum artifacts containing RAM inside three locked and posted cabinets in one area of the building. A foreign radio with radioluminescent backlight components and an electron tube were found in the main storage area of the building during the HSA reconnaissance. The main storage area, located in the northwest portion of the building, had 6-8 moveable storage shelves

containing hundreds to thousands of artifacts. Additional shelf storage was present in a back (north) area of the building. Contaminant pathway Scenario 2 from the CSM was considered applicable in Building 292.

To be conservative, all radionuclides listed in Table 1 are considered RCOPCs in Building 292, with the exception of ^{230}Th and ^{241}Am (radionuclides associated only with Building 2540 operations). Specific DCGLs for surveys in Building 292 are as follows:

- Low energy beta emitter: ^{57}Co with DCGL of 21,000 dpm/100 cm^2 (removable)
- Directly measured beta emitter: ^{60}Co with DCGL of 7,100 dpm/100 cm^2
- Directly measured alpha emitter: ^{226}Ra with DCGL of 315 dpm/100 cm^2

Building 292 includes a single Class 3 survey unit. The building layout and measurement/ sample locations are identified on Figure A-5 in Appendix A.

3.4.4 Building 2540

Building 2540 was surveyed as a MARSSIM Class 1 area, with the exception of the administrative areas of the building, which were surveyed as a single Class 3 area. Building 2540 housed the CECOM Laboratory and radiological testing facility. The building housed a gamma irradiator, RADIAC calibrators, a storage room for low-level radioactive material with multiple radioactive sources from the demilitarization of commodities, a nuclear counting laboratory, and several health physics laboratories. Radioactive sources consisted of alpha, beta, gamma, and low fluence neutron emitters. Sample testing work was performed with liquid forms of low-activity ^{230}Th and ^{241}Am in the nuclear counting laboratory and in Dr. Kronenberg's office. Contaminant pathway Scenarios 1 and 2 from the CSM were considered applicable in Building 2540. The building layout is shown if Figure 5 at the end of this FSSR. Measurement/sample locations are identified on Figures A-6 through A-13 in Appendix A.

To be conservative, all radionuclides listed in Table 1 are considered RCOPCs in Building 2540. However, ^{230}Th and ^{241}Am are only RCOPCs in the nuclear counting laboratory (SU's 8 and 9) and in Survey Units 6 and 7 where Dr. Kronenberg's office was located, not in other portions of the building. Specific DCGLs for surveys in Building 2540 are as follows:

<u>Nuclear Counting Laboratory and Dr. Kronenberg's Office Environs (SUs 6 through 9):</u>

- Low energy beta emitter: ^{57}Co with DCGL of 21,000 dpm/100 cm^2 (removable)
- Directly measured beta emitter: ^{60}Co with DCGL of 7,100 dpm/100 cm^2
- Directly measured alpha emitter: ^{241}Am with DCGL of 27 dpm/100 cm^2

All Areas in Building 2450 Except Nuclear Counting Laboratory and Dr. Kronenberg's Office Environs:

- Low energy beta emitter: ^{57}Co with DCGL of 21,000 dpm/100 cm^2 (removable)
- Directly measured beta emitter: ^{60}Co with DCGL of 7,100 dpm/100 cm^2
- Directly measured alpha emitter: ^{226}Ra with DCGL of 315 dpm/100 cm^2

Building 2540 includes 14 Class 1 survey units and one Class 3 survey unit. The building layout is shown in Figure 5. Measurement/sample locations are identified on maps in Appendix A.

3.4.5 Building 2541

Building 2541 was surveyed as a MARSSIM Class 1 area. Building 2541 was, in part, used for demilitarization of excess ^{232}Th (night vision lenses), ^{226}Ra, and ^{3}H.

To be conservative, all radionuclides listed in Table 1 are considered RCOPCs in Building 2541, with the exception of ^{230}Th and ^{241}Am (radionuclides associated only with Building 2540 operations). Specific DCGLs for surveys in Building 2541 are as follows:

- Low energy beta emitter: ^{57}Co with DCGL of 21,000 dpm/100 cm^2 (removable)
- Directly measured beta emitter: ^{60}Co with DCGL of 7,100 dpm/100 cm^2
- Directly measured alpha emitter: ^{226}Ra with DCGL of 315 dpm/100 cm^2

Building 2541 includes 2 Class 1 survey units. Measurement/sample locations are identified on Figure A-14 Appendix A.

3.5 Survey Design

The FSSs were performed to demonstrate that residual radioactivity in each survey unit satisfied the predetermined criteria for release for unrestricted use. The FSSs provide data to demonstrate that all radiological parameters do not exceed the established DCGLs and that collectively, they meet the annual dose criteria. For the FSS, the survey units represent the fundamental elements for compliance demonstration using the statistical tests.

The design of this survey incorporates the methods and locations for the performance of direct radioactivity scan surveys and integrated direct radioactivity measurements in order to assess the nature and extent of RCOPs. Due to very low energy beta emissions, ^{3}H, ^{57}Co, and ^{63}Ni are problematic because they cannot reliably be scanned for or quantified using handheld instrumentation. These radionuclides were measured through smear sample collection and laboratory analysis. To account for scanning weaknesses of these radionuclides, the sample density per survey unit is set considerably higher than that required by MARSSIM.

In accordance with MARSSIM, the null hypothesis (H_o) tested for this plan is that residual contamination exceeds the release criteria. The alternative hypothesis (H_a) is that residual contamination meets the release criteria. The statistical tests attempt to reject the null hypothesis.

Characteristics of selected instrumentation are provided in detail in Section 4. However, the integrated count times, minimum detectable concentrations (MDCs), and fraction of DCGL achieved with the stated count times are provided in Table 3 here for reference.

The survey plan consists of systematic processes and procedures that have been deemed acceptable by industry practices and the NRC. MARSSIM methodology and its graded approach were afforded particular attention in the survey design. Activities (organized units of work needed to complete a function) have been defined and tasks (specific work assignments within a specific activity) were assigned. Table 4 provides a listing of specific survey activities and tasks.

Table 3: Instrument Count Times, MDCs, and Fraction of DCGL Achieved

Type	RCOPC	Isotopic DCGL ($dpm/100cm^2$)	Count Time (min)	Nominal MDC ($dpm/100cm^2$)	DCGL Fraction
Low energy Beta	^{57}Co	2.11E+04 (removable)	Not measured directly (smears performed)		
Beta	^{60}Co	7,100	1	624	9%
Alpha	^{226}Ra	315	1	27.8	9%
	^{241}Am	27	5	11.4	42%

Table 4: Overview of Major Activities and Tasks

Activities	Tasks
Evaluate contamination potential	1. Review radiological data from HSA.
	2. Identify radionuclides of concern and determine DCGLs.
	3. Identify boundaries of survey units and MARSSIM Classes.
Establish reference system	1. Determine frequency and locations of measurements to meet criteria.
	2. Prepare facility survey maps and work packages.
Determine background levels	1. Measure indoor gamma levels in similar non-impacted building.
	2. Measure alpha and beta levels on various materials.
Perform measurements	1. Perform surface scans.
	2. Perform static measurements and smears for low energy betas.
	3. Perform exposure rate measurements.
	4. Collect gross alpha/beta smears at locations with SOR > 0.2 to confirm dose modeling assumptions.
	5. Collect volumetric samples as necessary identify RCOPCs in building systems.
Analyze samples	1. Analyze smears and volumetric samples.
Interpret data	1. Convert data to standard units and calculate SOR.
	2. Calculate average, sigma, maximum, and minimum levels.
	3. Compare data with Sign test criteria.
Prepare report (This FSSR)	1. Construct data tables.
	2. Develop graphics.
	3. Prepare text.
	4. Submit report.

3.5.1 MARSSIM-required Number of Survey Points

Determining the number of samples required per survey unit is a MARSSIM graded approach. The following technique was used to determine the number of samples required. As no scoping measurements had been collected, all calculations presented in this section were verified before survey completion of individual survey units.

Reviews were made during the initial scanning/static measurement phase to confirm survey unit classifications were appropriate. Reviews include for example, if 20% of any DCGL is detected in a Class 3 survey unit, the classification of the survey unit was evaluated. (The 20% value is an acceptable industry practice published by ORISE (ORISE, undated).) This process assures that ultimately all surveys have conservatism built into the design. No survey unit classifications were modified during these reviews as part of this FSS. Based on the FSS results in Building 2540 survey units, it appears the Class 1 survey unit classification was very conservative (Class 2 would have been appropriate). However, the decision to Classify Building 2540 areas as Class 1 during survey planning was appropriate based on the limited characterization data that existed before the FSS.

Section 5.5.2.2 of MARSSIM describes the process for determining the number of survey measurements necessary to ensure a data set is sufficient for statistical analysis. The method for determining the number of data points (N) for the survey unit is based on the expected contaminant variability and the predetermined acceptable Type I and Type II error rates. The project data quality objectives established the Type I and Type II error rates (α and β respectively) at 0.05.

The "relative shift" (Δ/σ) is the ratio involving the concentration to be measured (Δ) relative to the expected variability in that concentration sigma (σ), and can be thought of as an expression of the resolution of the measurements. The sigma (σ) is selected from the larger of that found in the survey unit or the reference area. The shift (Δ) is the width of the statistical gray region or difference in the release criterion and the lower bound of the gray region (LBGR). The gray region is the area where the impact of making an incorrect error decision (Type I or Type II error) is small. The Lower Bound of the Gray Region (LBGR) represents average concentrations that one expects to find.

The relative shift is calculated as follows:

$$\Delta/\sigma = \frac{DCGL_w - LBGR}{\sigma}$$

Where: $DCGL_w$ = Derived Concentration Guideline Level

LBGR = concentration at the Lower Bound of the Gray Region (LBGR). The LBGR is the concentration at which the survey unit has an acceptable probability of passing the statistical tests.

σ = an estimate of the standard deviation of the concentration of residual radioactivity in the survey unit (which includes real spatial variability in the concentration as well as the precision of the measurement system).

DCGLs for RCOPCs are listed in Table 2. Because multiple radionuclides may be present in each survey unit, compliance testing is based on SORs. By definition, an SOR of 1.0 is equivalent to the release criteria and can represent the $DCGL_w$ in the above equation.

The standard deviation (sigma) associated with the surface concentration of any residual radioactivity in the survey units was estimated to be low during development of the RSSP since significant contamination was not expected to be encountered. In addition, the standard deviation was not expected to be adversely affected by measurement precision, as selected instrumentation and laboratory measurement methods have adequate precision at excepted concentrations. The standard deviation (sigma) was estimated at approximately 15% of an SOR of 1.0, or 0.15. Setting the LBGR equal to one-half of the DCGL, the relative shift was calculated as follows:

$$\Delta/\sigma = \frac{DCGL_w - LBGR}{\sigma}$$

Or, substituting values

$$\Delta/\sigma = \frac{1.0 - 0.5}{0.15} = 3.3$$

Using the parameters discussed above, the relative shift was calculated to be 3.3, or, conservatively, rounded to 3. The number of suggested measurement locations per SU is 14 per MARSSIM (NRC, 2000, Table 5.5) given a relative shift of 3 and an error rate for both Type I and Type II errors of five percent (i.e., $\alpha = \beta = 0.05$). However, for prudent conservatism the number of systematic measurement/sample locations for each survey unit was increased to

approximately 30. This is consistent with AMC guidance (AMC, 2004) for Class 3 areas. In addition, the increased density helps in identification and quantification of low energy beta RCOPCs that cannot be reliably scanned for with handheld instruments.

The relative shift was calculated for each survey unit based on the actual FSS results and is presented in Section 6 of this report along with FSS survey results. For each survey unit, the actual relative shift was in excess of 3.3 indicating that sufficient sampling density was achieved.

3.5.2 Reference Area and Reference Materials

A reference area building was established for quantifying radioactivity in "background," non-impacted conditions. A reference area is a geographical area from which representative measurements of background conditions are selected for comparison with measurements collected in specific survey units. The background reference area has similar physical, chemical, radiological, and biological characteristics to the impacted area being surveyed, but is not contaminated by site activities. The distribution of measurements in the reference area is similar to the distribution of measurements in the survey units where residual radioactivity is not present. The reference area was selected as Building 1205, West Point Cadet Training building, based on field observations and professional judgment.

Fourteen background measurements were performed and recorded for each survey instrument to establish "background radioactivity" for different types of surface material being surveyed. (e.g., concrete, floor tile, concrete block wall, etc.). Section 6.1 provides the results of reference area measurements. The average gross count rate in the reference materials is subtracted from the gross count rate in the survey units to determine activity concentration.

The following sets of measurements were performed within the reference area to establish the necessary comparison criteria for decision rule implementation:

- Integrated direct surface alpha radioactivity measurements
- Integrated direct surface beta radioactivity measurements
- General area exposure rate measurements

As permitted by NUREG-1757, Vol. 2, A.3.3, measured backgrounds for different materials are subtracted from individual measurement points and the Sign test applied to the background corrected data set. Chapter 2 of NUREG-1505 (NRC, 1999b) is quoted: "When a specific background can be established for individual samples, the results of the survey unit measurements can be compared directly to the DCGL, since each is a measurement of the residual radioactivity alone." During this FSS, the Sign test was not performed for any survey units because all SOR values were less than one for all measurement locations.

3.5.3 Determination of Survey Point Locations

Before the surveys were conducted within a survey unit, a fixed reproducible starting point was selected in the southwestern corner of the survey unit at ground level. The survey unit points are based on an X-Y reference-coordinate system that is provided with the work maps. Tape measures and building layout maps were used in the measurement of the survey units for the survey. Visual aids such as grease marker writing and removable tape can were used to mark survey point locations within the survey units.

Lower walls up to 2 meters above the floor were surveyed as part of a survey unit.

For Class 1 survey units, the location of starting grid node within each survey unit was determined using a random number generator to generate an X and Y coordinate in feet from a reference point (0, 0). Locations of the remaining survey points are gridded from that location.

All locations of Class 3 and reference area survey points were a random selection via a random number generator to generate an X and Y coordinate in feet from a reference point (0, 0). A working map with coordinates for all required locations was developed prior to the start of a survey unit.

The (0, 0) point was set as the southwest corner of the entrance to the survey unit or survey area at ground level. The referenced points are clearly identified on each survey unit map. Survey unit maps have been developed as part of this USACE FSSR (see Appendix A).

3.5.4 Selection of Area Size for Survey Units

Suggested survey unit sizes from MARSSIM are listed in Table 5. Survey units used in this FSS conform to the MARSSIM suggestions. These areas are suggested in MARSSIM because they give a reasonable sampling density and they are consistent with most commonly used dose modeling codes. To facilitate survey design and ensure that the number of survey data points is relatively uniformly distributed among areas of similar contamination potential, the buildings were divided into survey units that share a common history or other characteristics, or are naturally distinguishable from other portions of the building. However, the size and shape of a particular survey unit was adjusted to conform to the existing features of the floor area as necessary. MARSSIM suggests that a survey unit have a minimum floor area of 10 m^2 (108 ft^2) so smaller rooms were sometimes combined with similar nearby areas.

Table 5: MARSSIM Suggested Area Limits For Survey Units

Class	Structures (Floor Area)
1	Up to 100 m^2 (1,076 ft^2)
2	100 to 1000 m^2 (1,076 to 10,763 ft^2)
3	No limit

3.5.5 Surface Scan Requirements

Scanning was used to identify areas of elevated radioactivity within the survey. These locations are marked and receive additional investigations to determine the concentration, area, and extent of contamination, if confirmed to be present.

The required area covered by scan measurement is based on the survey unit classification as derived from MARSSIM Table 5.9. For the Class 1 Survey Units in Buildings 2540 and 2541, a 100% scan of the reasonably accessible portions of floors and lower walls was performed. For Class 3 Survey Units scanning was performed on areas based on the potential for contamination and the judgment of the radiation survey staff; there was no set percentage. Scanning for ^{3}H, ^{57}Co, and ^{63}Ni is not technically feasible with available technology and very low yields for the low energy beta emitters such as ^{14}C.

Sensitivity for scanning techniques used in Class 2 and 3 areas is not tied to the area between measurement locations, as they are in a Class 1 area. The scanning techniques selected represent the best reasonable effort based on the survey objectives. A comparison of DCGLs and MDCs is presented in Section 4.1.

3.5.5.1 Class 1 Scan Requirements

For Class 1 areas, MARSSIM specifies scan sensitivity requirements. The required scan sensitivity is defined in MARSSIM equation 5.3, as follows:

$$\text{Scan MDC}_{\text{required}} = \text{DCGL}_{\text{w}} * \text{Area Factor}$$

The estimated scan sensitivity for ^{230}Th and ^{241}Am exceeds their DCGLs. Thus, it was necessary to derive area factors for these radionuclides to confirm scan sensitivity is adequate for the Class 1 survey units in Building 2540.

The area factor is based on the size of the survey unit and the spacing of systematic samples.

Area factors for ^{230}Th and ^{241}Am were derived using the DandD Version 2.1 dose modeling program developed by NRC. For each radionuclide, the program was executed assuming surface contamination was distributed over an infinite area. The program was then executed using the contamination was distributed over a 3.33 m^2 area, which was established based on the MARSSIM maximum recommended size for Class 1 survey units of 100 m^2 and the established sampling density of 30 measurements per survey unit. The output of DandD provided dose conversion factors (DCFs). The area factors were calculated as the ratio of the infinite area DCF to the 3.33 m^2 area DCF. Required scan sensitivities were calculated using these area factors and are shown in Table 6. DandD output reports are included in Appendix A of the RSSP.

Table 6: Area Factors and Required Class 1 Scan Sensitivity

Nuclide	Dose Conversion Factor (mrem/yr per dpm/100 cm^2)		Area Factor	DCGL (dpm/100 cm^2)	Required Scan MDC (dpm/100 cm^2)
	Infinite Area	3.33 m^2	3.33 m^2		
^{230}Th	0.681	0.227	3.0	36.9	111
^{241}Am	0.931	0.31	3.0	27.0	81.1

The estimated scan sensitivities for ^{230}Th and ^{241}Am presented in Section 4.1.2 meet the MARSSIM requirement based on this analysis. This was confirmed based on actual instrument efficiencies and observed backgrounds.

3.5.6 Interpretation of Results

Data of a specific quality and quantity are needed to test the null hypothesis. This sampling plan is designed to provide these data.

3.5.6.1 Basic Statistics and Range

Following a determination of SOR, basic statistical quantities should be calculated first from the data set, these include:

- Maximum
- Minimum
- Mean
- Standard deviation
- Number of samples

3.5.6.2 Data Reduction and Review

The data reduction and review process ensures that all procedures pertaining to sample preparation and handling, proper identification of analysis output (charts, graphs, etc), correctness and completeness of all data, adherence to documented procedures, documentation of

abnormalities and the proper format has been used to report all data. The processing of data, by manual computation, input of data for computer processing, and direct computer output, was performed and is documented in this FSSR.

3.5.7 Decision Rules

The following decision rules are adapted from MARSSIM Table 8.2 "Summary of Statistical Tests" for radionuclides in background. These decision rules are applied to SORs calculated based on:

- Wet smear samples collected and analyzed off site for low energy gross beta
- Direct surface alpha radioactivity measurements performed within buildings/indoor areas
- Direct surface beta radioactivity measurements performed within buildings/indoor areas.

Table 7: Decision Rules

Survey Results	Conclusion
All measurements less than DCGL	Survey unit meets release criterion for Class 1, 2, and 3
Average greater than DCGL	Survey unit does not meet release criterion. Evaluate to determine if surveys units are appropriately classified and attempt to bound elevated area
Any measurement greater than DCGL and the average less than DCGL	For Class 1 survey units – Conduct Sign test and elevated measurement comparison. For Class 2 and 3 – evaluate to determine if survey units are appropriately classified.

3.5.8 Performing the Sign Test

The Sign test would have been applied if any measurement in a survey unit is greater than DCGL and the average of all measurements is less than DCGL. However, all measurements with background subtracted in all survey units are less than the DCGL of SOR = 1. Thus, based on the decision rules in Table 7, it was unnecessary to perform the Sign test; all survey units meet the release criteria.

4.0 SAMPLING APPARATUS AND FIELD INSTRUMENTATION

This section describes the survey instruments and methodologies used during implementation of the FSSs. Specific measurement/ sampling frequencies and approaches are discussed in Section 3. The FSS field investigation was a MARSSIM graded approach requiring a combination of field screening methods and offsite smear evaluations.

Instrumentation or measurement techniques were selected based on detection sensitivity to provide technically defensible results that meet the objectives of the survey. When radionuclide contaminants could not be detected at desired levels by direct measurement, the portion of the survey dealing with measurements at discrete locations is designed to rely primarily on smear or sampling and laboratory analysis. Survey instrumentation used during the FSS is shown below in Table 8. The selected instrumentation suite was capable of quantifying alpha, beta and gamma radiation.

- For building surfaces, scanning, direct measurements, exposure rate measurements, and surface smears were performed to measure surface radioactivity concentrations of site RCOPCs. These measurements are based on gamma, alpha or beta emissions, depending upon the RCOPC of interest.

- Wet smears collected for low energy betas were analyzed for low energy beta radioactivity by liquid scintillation at an offsite laboratory. These smears were collected to determine total activity concentration of ^{3}H, ^{57}Co, and ^{63}Ni for compliance testing (using the assumption that the observed smear activity represents 10% of the total activity).

- Dry smears were analyzed off-site for alpha and beta radioactivity. These smears are used to verify the NRC screening dose modeling assumption that 10% of the total radioactivity is removable.

- Both wet and dry smears were collected in building systems to determine if there were any radiological impacts to ventilation systems in Building 2540 and sinks and drains in Buildings 2540 and 283.

Ludlum gas proportional detectors, Model 43-37 and 43-37-1, were used with Ludlum Model 2360 data loggers utilizing P-10 counting gas (10% methane, 90% argon). The 43-37 and 43-37-1 probes were calibrated with ^{99}Tc to determine beta efficiency and ^{230}Th to determine alpha efficiency. Certificates of calibration are included as Appendix E to this FSSR. Table 9 provides the observed efficiencies for the three probes used during the FSS.

Table 8: Selected Instrumentation

Measurement Type	Detector Type	Detector Area	Instrument Model	Detector Model
Alpha/Beta Scan	P-10 gas proportional	821 cm^2 active	Ludlum 2360	Ludlum 43-37-1
Alpha/Beta Scan & Directs	P-10 gas proportional	582 cm^2 active	Ludlum 2360	Ludlum 43-37
Gamma Exposure Rate	Sodium iodide scintillator	Not applicable	Ludlum 19	Internal

Table 9: FSS Detector Efficiencies

Instrument / Probe	Serial Number	Isotope	ε_i	$\varepsilon_{Surface}$	ε_{total}
2360 / 43-37	275724 / 092501	Th-230	0.38	0.25	0.096
		Tc-99	0.36	0.25	0.091
2360 / 43-37	275713 / 093966	Th-230	0.39	0.25	0.098
		Tc-99	0.37	0.25	0.091
2360 / 43-37-1	138251 / 136631	Th-230	0.43	0.25	0.11
		Tc-99	0.34	0.25	0.084

4.1 Direct and Scan Radiation Measurements

Building surfaces were measured for alpha and beta radioactivity using direct scan survey and direct measurement techniques. Gamma exposure rates were measured at one meter above the floor surface and recorded over all floor area measurement locations. Exposure rate measurements were also performed at each wall measurement location with the detector held in close proximately to the wall surface.

Alpha and beta radioactivity direct scan surveys were performed on floors and lower walls using a Ludlum Model 43-37-1 gas flow proportional detector floor monitor (active area of 821 cm^2).

In Building 275 some scan surveys were performed with a Ludlum Model 43-37 due to size limitations (active area of 584 cm^2). All direct static measurements were performed with the 43-37 detectors. Both the 43-37-1 and 43-37 detectors were coupled to Ludlum 2360 Alpha-Beta Data Loggers. The 43-37-1 and the 43-37 probes were calibrated to measure both alpha and beta surface activity simultaneously (i.e., dual channel analysis). Alpha and beta measurement results were recorded separately. The Ludlum 2360 data logger allows for recording of both alpha and beta channels simultaneously at a set interval, allowing for a high density of data points. During scan surveys, the instantaneous rolling average alpha and beta count rates were recorded at one or two second intervals (Appendix H provides a large table with all scan data, in excess of 30,000 total data points).

The 43-37-1 and 43-37 detectors are not sensitive to relatively low-energy alpha/beta radioactivity due to the presence of their Mylar® entrance windows. ^{3}H, ^{57}Co, and ^{63}Ni are considered low energy (hard-to-detect) beta emitters and are RCOPCs in all survey units. In order to quantify these radionuclides, wet smear sample collection and off-site analyses was performed in lieu of direct measurements. This off-site analysis was performed via liquid scintillation counting. The upper window of the analysis was set at approximately 0.16 MeV, reducing the undesired detection of higher energy beta emitters, which were directly measured. Low energy beta smear results are considered representative of 10% of the total radioactivity concentration of the low energy beta RCOPCs for compliance testing purposes.

The concept of material specific background radioactivity measurements was previously introduced. Fourteen gross alpha and beta background measurements were performed and recorded for each detector for different types of surface materials that were suspected to contribute significantly to instrument response. Reference areas were not established for some material types that were not expected to significantly impact instrument response, such as metal and drywall. For these materials a survey unit specific instrument background was established by positioning the detector face away from any surface in the survey unit and performing an integrated count.

The primary purpose of the background measurements is to correct the instrument for ambient gamma dose and material specific beta/alpha emissions that can result in additional beta or alpha counts. Instrument net count rate was determined as the difference between the measurement count rate and the instrument-specific, material-specific, average background count rate measured or the survey unit specific ambient background (for materials with no significant natural background impact on instrument response).

Analysis count times for integrated alpha/beta measurements were dependent upon the alpha DCGL applicable to the survey unit. As illustrated in Table 3, the count time was either one minute or five minutes.

4.1.1 Alpha and Beta Static Minimum Detectable Concentrations

NUREG-1507 provides a rigorous derivation of the expression for instrument sensitivity, typically stated as the MDC. The MDC equations and example values for both static measurements and swipe analysis are presented in this section. The following is an *a priori* analysis and actual MDCs will be determined with background and calibration data for instruments to be used. Per the MARSSIM "Roadmap" For direct measurements and sample analyses, minimum detectable concentrations less than 10% of the DCGL are preferable while MDCs up to 50% of the DCGL are acceptable.

The most restrictive DCGL is for ^{241}Am at 27 dpm/100 cm^2 and to obtain an alpha MDC of 50% of the DCGL, the length of the count was five minutes. When ^{241}Am was not potentially present, ^{226}Ra and ^{60}Co drive the count duration requirements and the count time was decreased to one minute. The following equation for the MDC from NUREG-1507, (Equation 3-10), as modified for efficiency and detector area, applies:

$$StaticMDC = \frac{3 + 4.65 * \sqrt{C_b}}{(\varepsilon_s) * (\varepsilon_i) * T * \left(\frac{a}{100}\right)}$$

where: C_b = Background count in analysis time

ε_i = Intrinsic instrument efficiency

ε_s = Surface efficiency

T = Time of background analysis interval

a = active probe area in cm^2

Determining the MDC in counts per minute (cpm) requires knowledge of the survey instrument efficiency, the material source efficiency and the background rates. The count time for the actual MDCs was verified immediately prior to the survey and remained as either one or five minutes.

4.1.2 Alpha and Beta Scan Minimum Detectable Concentrations

Scanning is the process by which the operator uses portable radiation detection instruments to detect the presence of radionuclides on a specific surface (i.e., wall, floor, equipment). The term scanning survey is used to describe the process of moving portable radiation detectors across a suspect surface with the intent of locating radionuclide contamination. Scanning surveys are

performed to locate radiation anomalies indicating residual gross activity that may require further investigation or action.

4.1.2.1 Beta Scan MDC

For beta scanning, the time interval over an area is typically one to two seconds. The following equation is developed from above and NUREG-1507.

$$ScanMDC = \frac{1.38 * \sqrt{b_i} * \frac{60}{i}}{\sqrt{0.5} * (\varepsilon_s) * (\varepsilon_i) * \left(\frac{a}{100}\right)}$$

where: 1.38 = a desired performance proportions level of 0.95 for true positive results and a level 0.6 false positives;

b_i = Background counts during the observation interval;

i = Observation interval in seconds; and

$\sqrt{0.5}$ = MARSSIM determined level of performance for the surveyor.

There is no scanning capability for low energy (hard-to-detect) beta emissions. Results for detectable betas for all RCOPCs are tabulated in Table 10.

4.1.2.2 Alpha Scan MDC

Scanning MDCs for alpha emitters with low background detectors must be derived differently than scanning for beta emitters. MARSSIM has formulas and probability concepts for scanning alpha contamination when the background is less than 3 cpm. Abelquist (Abelquist, 2001) has developed scan MDCs on structure surfaces for alpha radiation by use of Poisson summation statistics. Appendix J in MARSSIM provides a complete derivation of the formula used to determine the probability of observing a single count:

$$P(n \geq 1) = 1 - e^{-\left(\frac{G \varepsilon t}{60}\right)}$$

Where: $P(n \geq 1)$ = the probability of observing a single count;

G = the elevated area activity (dpm);

ε = the detector efficiency; and

t = the residence time of the detector over the activity (sec).

The scan process must be in two stages: continuous monitoring and stationary sampling (pausing). During the continuous monitoring, the surveyor listens to the number of clicks. Because the instrument background is low (<3 cpm), a single count gives the surveyor cause to stop and investigate further by pausing for an additional number of seconds. The scan MDC for alpha contamination must be based on the continuous monitoring stage which is illustrated as follows.

Per Abelquist's example pages 193-197: setting the P(n $\geq$ 1) at the 90% level and solving for G which is now defined as the alpha scan MDC.

$$scanMDC_{alpha} = \frac{[-\ln(1 - P(n \geq 1))]60}{\varepsilon_i \varepsilon_s t}$$

where: ε_i = Intrinsic instrument efficiency

ε_s = Surface efficiency

t = residence time (sec), calculated from scan rate

Approximate MDCs for RCOPCs are presented in Table 10. The time interval for scanning was one second, equivalent to a scan speed of one detector width per second in areas where ^{230}Th and ^{241}Am were not RCOPCs. In areas were ^{230}Th and ^{241}Am were RCOPCs, the scan speed was one-half detector width per second.

4.1.3 Gamma Exposure Rate Measurements

General area gamma dose rate measurements were qualitatively performed during the survey activities to ensure worker health and safety and to document exposure rates in survey units. Measurements were performed using Ludlum Model 19 exposure rate detectors. The measurements were performed one meter above each measurement/sample location on a SU floor surface. Exposure rate measurements were also performed at wall measurement locations with the instrument held in close proximity to the wall surface.

Table 10: Direct Alpha Beta Measurement Nominal Sensitivities

ROC	Half-life	Principal Emission	Max Energy (MeV)	Average Energy (MeV)	Particles per decay	DCGL (dpm/100 cm^2)	Es	Ei	Background Scan (cpm)	Background Static (cpm)	Scan Speed (inch/sec)	Static Count Time (min)	Net Count Rate at DCGL (cpm)	Scan MDC (dpm/100 cm^2)	Static MDC (dpm/100 cm^2)
^{3}H	12.3 y	Beta	0.02	0.01	1.0	1.20E+08	Radionuclide not measured Directly								
^{63}Ni	100 y	Beta	0.07	0.02	1.0	1.80E+06									
^{57}Co	270.9 d	Electron	0.13	0.02	1.0	2.11E+05									
^{14}C	5700 y	Beta	0.16	0.05	1.0	3.70E+06	0.25	0.06	1700	1200	6	1	3.24E+05	5.06E+03	1.87E+03
^{147}Pm	2.62 y	Beta	0.22	0.06	1.0	3.43E+05	0.25	0.10	1700	1200	6	1	5.01E+04	3.04E+03	1.12E+03
^{99}Tc	2.13E5 y	Beta	0.29	0.08	1.0	1.30E+06	0.25	0.16	1700	1200	6	1	3.04E+05	1.90E+03	7.02E+02
^{60}Co	5.27 y	Beta	0.32	0.10	1.0	7.10E+03	0.25	0.18	1700	1200	6	1	1.87E+03	1.69E+03	6.24E+02
^{137}Cs	30.2 y	Beta	0.51	0.19	1.0	2.80E+04	0.50	0.31	1700	1200	6	1	2.53E+04	4.90E+02	1.81E+02
^{154}Eu	8.6 y	Beta	1.85	0.22	1.0	1.15E+04	0.50	0.34	1700	1200	6	1	1.14E+04	4.47E+02	1.65E+02
^{36}Cl	3.01E5 y	Beta	0.71	0.25	0.98	5.00E+05	0.50	0.36	1700	1200	6	1	5.15E+05	4.30E+02	1.59E+02
$^{90}Sr/^{90}Y$	29.12 y	Beta	2.28	0.56	2.0	8.70E+03	0.50	0.51	1700	1200	6	1	2.59E+04	1.49E+02	5.51E+01
^{226}Ra	1600 y	Alpha	4.78	NA	1.0	315	0.25	0.47	17	12	6	1	2.16E+02	1.43E+02	2.78E+01
^{230}Th	7.54E4 y	Alpha	4.69	NA	1.0	36.9	0.25	0.47	17	12	3	5	2.53E+01	7.16E+01	1.14E+01
^{241}Am	432.6 y	Alpha	5.49	NA	1.0	27	0.25	0.47	17	12	3	5	1.85E+01	7.16E+01	1.14E+01

4.2 Smear Collection and MDCs

The following is quoted from MARSSIM, "…measurements of smears are very difficult to interpret quantitatively. Therefore the results of smear samples should not be used for determining compliance. Rather they should be used as a diagnostic tool to determine if further investigation is necessary." This advice was followed except for instances when a direct measurement could not be made reliably, (i.e., ^{3}H, ^{57}Co, and ^{63}Ni quantification), which was quantified based on wet smear evaluations.

The off-site laboratory, Pace Analytical Services, Inc. of Greensburg Pennsylvania, is a Department of Defense (DoD) Environmental Laboratory Accreditation Program (ELAP) certified.

The analysis procedure for low energy beta wet smear analysis is summarized as follows:

- Smears were wet in the field with deionized water, collected over an approximate 100 cm^2 area, and placed into a 20-mL glass vial containing 5-10 mL of deionized water. Wet smears were analyzed for low energy beta activity using off-site liquid scintillation counting. A Packard Tri-Carb 3100 liquid scintillation counter (LSC) (or similar equipment) was used for the analysis.

- Each sample was combined with scintillation counting cocktail in the 20-mL glass vial and counted. The system was calibrated to measure beta particles with energies up to 0.16 MeV (the upper level discriminator was set at approximately 0.16 MeV). The system did not discriminate specific radionuclides and all gross counts are assumed to result from the most restrictive RCOPC, ^{57}Co.

- The gross beta efficiency was determined using a commercially available ^{63}Ni standard traceable to the National Institute of Standards and Technology (NIST). The Tri-Carb 3100 is maintained under a routine service program and quench curves as appropriate established annually. Daily control charts (performance checks) are maintained of counts of background and unquenched ^{3}H and ^{14}C NIST traceable beta standards.

- Results are transferred from the LSC data printout or file in units of cpm or counts, background is subtracted and the net count-rate is converted to activity using the determined efficiency based on instrument response to a ^{63}Ni source. The activity is reported is gross alpha and gross beta activity per sample.

NUREG-1757 requires that residual radioactivity on surfaces must be mostly fixed (not loose), with the fraction of loose (removable) residual radioactivity no greater than 10% of the total surface activity.

As an attempt to confirm the removable fraction for other higher energy beta and alpha emitters, dry smears were collected at direct measurement locations with results indicating greater than 20% of a DCGL. Smear samples were analyzed for alpha and beta radioactivity by the Pace Analytical Laboratory. The gross alpha and gross beta MDCs were less than 1 dpm/100 cm^2.

4.3 Volumetric Sample Collection and Analysis

Volumetric building system samples were not collected. Instead wet and/or dry smear samples were collected to determine whether or not building systems were impacted by RAM. Results are discussed in Section 6.

5.0 DATA QUALITY ASSESSMENT

A quality assessment of the data collected during the Final Status Surveys was performed. The assessment included the following aspects of the data set:

- The completeness of the data set with respect to the requirements outlined in the RSSP.
- Basic (i.e. minimum, maximum, mean) Statistical Analysis of the data set
- Quality Assurance (QA)/Quality Control (QC) records for instrumentation

5.1 Data Completeness

All data that was specified in the RSSP was collected and analyzed successfully.

5.2 Statistical Analysis

Basic statistical analysis was performed on the data collected during implementation of the RSSP requirements. The analysis included quantities such as the minimum, maximum, and mean of static alpha/beta measurements, as well as minimum, maximum, and mean of low energy beta analysis results. The values for this analysis are presented in the summary tables in Appendix C to this report. Statistics for SOR values in all survey units are provided in Table 12. Statistics for static alpha and beta measurements area provided in Table 13.

5.3 Instrument QA/QC

Ludlum Model 19 exposure rate meters were used to assess ambient gamma exposure rate. Large areas gas proportional detectors were used to quantify alpha and beta surface radioactivity for MARSSIM compliance testing. These instruments were operated in accordance with standard operating procedures and the manufacturer user's manuals. Quality control measures were implemented on days the instruments were used, at a minimum, to ensure their proper operation.

Initial Gas Proportional Detector Efficiency Calibration and Operating Test

Prior to use, thirty one minute counts were performed on each of the Model 43-37 and 43-37-1 gas proportional detectors using ^{230}Th (alpha) and ^{99}Tc (beta) NIST-traceable sources. The reduced chi-square statistic was calculated for the thirty alpha counts and thirty beta counts and compared to 0.05 and 0.95 acceptance criteria for each instrument. After establishing that each of the instruments passed the chi-square test, the intrinsic efficiency of each detector for alpha and beta was determined. These efficiencies were compared to efficiencies established during instrument calibration to ensure they were approximately the same as the calibration facility determined. Each of the comparisons was favorable, and the efficiencies established were used

for reduction of FSS data. Appendix F provides the initial setup information for each detector used.

General Instrument Conditions

During daily QA/QC checks instruments were inspected for physical damage, battery voltage levels, current calibration, and erroneous readings, in accordance with standard operating procedures (SOPs). The gas flow rate for gas proportional detectors was evaluated routinely throughout the day to ensure adequate P-10 counting gas concentrations were present in the active volume of the detectors; Mylar windows on the gas flow proportional detectors were also evaluated for rips or tears throughout the day for the same purpose.

Instrument Response Checks

Model 19 exposure rate meters were response checked daily by comparing response to a designated ^{137}Cs NIST traceable source. The acceptance criteria for these instrument response checks were ± 20% of the mean response generated using thirty initial source checks. Results were plotted on control charts. Ambient background was also recorded at the time of the daily checks. Control charts and results of daily QC measurements are provided in Appendix F.

Model 43-37 and 43-37-1 gas proportional detectors were checked daily by comparing response to designated ^{230}Th (alpha) and ^{99}Tc (beta) NIST-traceable sources and to ambient background. The acceptance criteria for these instrument response checks were ± 20% of the mean response generated using thirty initial source checks. Results were plotted on control charts. The graphs also include two and three sigma indicators based on the initial thirty counts for information purposes. Control charts and results of daily QC measurements are provided in Appendix F.

There were no QA/QC issues identified with the radiological instrumentation used during implementation of the FSS at Fort Monmouth.

5.4 Off-Site Laboratory Sample Analysis

Gross alpha/beta gas proportional and low energy beta liquid scintillation analysis of the of smear samples was performed by the off-site laboratory, Pace Analytical.

The laboratory performed internal validation of all sample results and assigned qualifiers. The laboratory validation addressed sample chain of custody, instrument performance, ability to meet required detection limits, the results of the QC samples, and other factors that might affect data quality. The results of the validation were summarized in a case narrative provided for each shipment of samples received by the laboratory. As a part of its analytical data review, USACE reviewed the results of the quality control samples. The following sections provide a summary of those reviews. All off-site laboratory data reports and case narratives are included in Appendix J.

5.4.1 Method Blank

Method blanks consisted of unused smears, known to be free of the contaminants of interest. The method blanks were analyzed along with samples of an associated analytical batch and receives the same reagents, in the same quantities, and was carried through the same sample preparation (e.g., digestion/extraction) and analysis steps as all other samples. The method blank provides assurances that an analyte of interest was not inadvertently added to the samples through a reagent or analytical operation and that the detector is not contaminated or compromised. A method blank analysis was performed at a rate of one per batch of 20 or fewer samples.

5.4.1.1 Gross Alpha/Beta

Pace analyzed 25 method blanks for the gross alpha/beta smear analyses. Two of the alpha results were slightly above the minimum detectable activity (MDA) for the analysis. All other blanks were less than MDA for alpha and all were less than MDA for beta. As a result, some sample results in batches RADC12468 and RADC12470 were qualified with a "B" flag. This is considered acceptable for the FSS, as it indicates that the results may be slightly overly conservative for these batches (resulting in possible false positives). No results were rejected as a result of method blank analyses.

5.4.1.2 Low Energy Beta

Pace analyzed 42 method blanks for the low energy beta smear analyses. All results were less than the MDA for the analysis. No results were rejected or qualified as a result of method blank analyses.

5.4.2 Laboratory Control Sample / Laboratory Control Sample Duplicate

Laboratory control samples (LCSs) and laboratory control sample duplicates (LCSDs) were prepared and analyzed by Pace. A LCS is a sample that is prepared by adding a known aliquot of the analyte of interest, or a surrogate analyte to a volume of laboratory certified reagent grade water (for low energy beta), or counting a NIST traceable source(s) for gross alpha/beta. The LCS was analyzed with the associated sample batch using the same analytical procedures and instruments. The LCS results were used as a measure of the accuracy of the analytical methods. Pace analyzed one LCS and one LCSD with each batch of 20 or fewer samples.

5.4.2.1 Gross Alpha/Beta

Pace performed 25 LCS and 25 LCSD analyses for the gross alpha/beta analyses. In each batch at least one LCS and/or LCSD failed the laboratory acceptance criteria, exceeding the upper control limit. This indicates that the gross alpha/beta results may be biased slightly high and may explain why two method blanks exceeded the MDA. As a result of these LCS/LCDS

evaluations, some samples were reported with a narrative notation that the results may be biased high. No sample results were rejected based on the results of their evaluations.

While there is potential bias, the results are considered acceptable for the FSS because if a bias does exist it would result in conservative interpretation of survey results.

5.4.2.2 Low Energy Beta

Pace performed 42 LCS and 42 LCSD analyses for the low energy beta analyses. All LCS and LCSD results were within laboratory acceptance criteria. No sample results were rejected or qualified based on the results of their evaluations.

5.4.3 Detection Limits

MDC requirements were established during the development of project data quality objectives and represent the sensitivity required for the analytical procedures. The MDC is a statistical parameter that represents the uncertainty associated with the measured concentration of an analyte near background concentrations. When practical, MDCs were set well below project-specific action criteria such as regulatory limits or clean-up goals. The MDCs were set sufficiently low to provide assurances that the concentrations of analytes that were "undetectable" will not exceed action limits. For this FSS, the MDCs were set at well below any project DCGL.

The laboratory met the MDA requirements of less than 1 dpm alpha and 5 dpm beta for all gross alpha/beta analyses (all alpha and beta MDAs were less than 1 dpm). No data were qualified because of a failure to meet the requested MDAs.

The laboratory met the MDA goal of less than 10 dpm for the vast majority of the low energy beta analyses. Two percent of the analyses (19 of 823) have MDAs slightly in excess of 10 dpm, with the maximum MDA being 33 dpm. This was considered acceptable because the maximum observed MDA is only 0.2% of the applicable DCGL. No data were qualified because of a failure to meet the requested MDAs.

5.4.4 Method Performance and Summary Assessment

Overall, the performance of the laboratory analyses was adequate. The samples were analyzed for all of the analytes as required by the contracts with the laboratories as part of the FSS. The data were subjected to data review and verification by Pace personnel and appropriate qualifiers applied to the data. In addition, USACE independently reviewed the data for the QC samples: LCS, LCSD, and method blanks. The results of the QC samples were generally acceptable, although an apparent high bias was identified in the gross alpha/beta data. None of the data was

rejected during the data validation and review process. All data reported by the laboratory is of appropriate quality for FSS decision making.

5.5 Duplicate Measurements and Field Duplicate Smears

Duplicate static alpha/beta measurements were performed and duplicate smears were collected and analyzed to provide an evaluation of the precision of the measurement processes. Duplicate results were compared to initial results by calculating the normalized absolute difference (NAD).

$$\text{NAD} = \frac{|\text{initial result - duplicate result}|}{\sqrt{\sigma^2_{\text{initial}} + \sigma^2_{\text{duplicate}}}}$$

NAD values were compared to an acceptance criteria of less than or equal to 2.58. The following subsections present the results of duplicate analyses.

5.5.1 Static Gross Alpha/Beta Duplicates

During performance of the FSS, 83 duplicate static alpha/beta measurements were performed. The NAD equation was applied to gross alpha counts and gross beta counts for each analysis. The variance of each result (σ^2) was assumed to be the gross counts, based on the applicability of Poisson statistics. All alpha results were within the NAD acceptance criteria of 2.58 or less. Two beta results were slightly in excess of the criteria with NAD values of 3.3 and 3.4. Considering that the vast majority of the results were within the acceptance criteria, the gross alpha/beta static measurement results are deemed to exhibit acceptable levels of precision. Appendix I provides a table with the results of each duplicate evaluation.

5.5.2 Off-site Gross Alpha/Beta Analyses

During performance of the FSS, 23 duplicate gross alpha/beta smear samples were collected and submitted to Pace for analysis. The NAD equation was applied to each analysis. The variance of each result (σ^2) was assumed to be the half the laboratory-reported uncertainty squared. The value of one half was used because the lab reported data at the 95% confidence level. Evaluations were not performed on negative results. All alpha and beta results are within the NAD acceptance criteria of 2.58 or less. Thus, the gross alpha/beta smear analysis results are deemed to exhibit acceptable levels of precision. Appendix I provides a table with the results of each duplicate evaluation.

5.5.3 Off-site Low Energy Beta Analyses

During performance of the FSS, 50 duplicate low energy beta smears were collected using identical smears and glass vials and submitted to Pace for analysis. The NAD equation was applied to each analysis. The variance of each result (σ^2) was assumed to be the half the laboratory-reported uncertainty squared. The value of one half was used because the lab reported data

at the 95% confidence level. Evaluations were not performed on negative results; approximately half of the duplicate analyses cannot be compared because one or more results are negative.

All low energy beta results are within the NAD acceptance criteria of 2.58 or less. Thus, the low energy beta smear analysis results are deemed to exhibit acceptable levels of precision. Appendix I provides a table with the results of each duplicate evaluation.

6.0 INTERPRETATION OF FINAL STATUS SURVEY RESULTS

Final status surveys and sampling of potentially impacted building structures at Fort Monmouth has been completed in accordance with the requirements specified in the RSSP. Field Changes from the RSSP requirements are noted in this section, as applicable.

In accordance with MARSSIM, measurement results for direct alpha, direct beta and low energy beta removable were divided by their respective DCGLs. The resulting ratios were then added together using a sum of ratios (SOR) calculation.

6.1 Reference Material Background

Site specific background values were determined for four different materials for each detector: laminate tile, poured concrete, concrete block, and ceramic tile. Background reference areas for each material were established in Building 1205, the West Point Cadet Training building, which had no known or suspected historic use of RAM. The building is of similar age and construction of the impacted site buildings.

Each background reference material was surveyed using 14 random static alpha and beta measurements for each material. Count times were one minute. Reference area measurements were applied to multiple survey units as long as the material being surveyed was similar to that in the reference area. When materials in survey units differed from the four material-specific background materials (e.g., wood, metal, drywall), the ambient background in the survey unit was determined by performance of an integrated count with the detector facing upward (away from any surface) to determine net count rate.

A summary of the results of reference area/material background data is provided in Table 11. Individual results of background measurements are included as Appendix D to this RSSP.

Table 11: Gas Proportional Detector Material Backgrounds

Probe / SN	Material	Alpha (cpm)				Beta (cpm)			
		min	max	stdev	Average	min	max	stdev	Average
Ludlum 43-37 (SN 092501)	Ceramic Tile	12	23	3.0	17.7	1193	1341	41	1275
Ludlum 43-37 (SN 093966)	Ceramic Tile	5	18	4.6	11.6	963	1073	28	1026
Ludlum 43-37-1 (SN 136361)	Ceramic Tile	20	40	6.0	29.5	1470	1669	52	1587
Ludlum 43-37 (SN 092501)	Concrete Block	4	17	3.9	8.93	388	720	140	555
Ludlum 43-37 (SN 093966)	Concrete Block	0	7	1.8	2.50	287	679	152	459
Ludlum 43-37-1 (SN 136361)	Concrete Block	2	15	3.4	10.9	455	931	194	705
Ludlum 43-37 (SN 092501)	Laminate Tile	2	14	3.1	8.64	366	497	36	404
Ludlum 43-37 (SN 093966)	Laminate Tile	1	6	1.4	2.64	234	350	31	270
Ludlum 43-37-1 (SN 136361)	Laminate Tile	2	12	2.6	7.64	358	538	43	430
Ludlum 43-37 (SN 092501)	Poured Concrete	3	14	3.2	8.64	426	534	28	467
Ludlum 43-37 (SN 093966)	Poured Concrete	1	9	2.7	4.21	305	390	24	344
Ludlum 43-37-1 (SN 136361)	Poured Concrete	4	14	2.9	9.21	453	622	51	543

6.2 Confirmation of Assumed 10% Removable Fraction

Gross alpha/beta smears were collected and analyzed at locations with SOR values greater than 0.20 and at many other locations to confirm the assumption that 10% (or less) of the total radioactivity is removable. This assumption is inherent in the NRC screening criteria. This comparison could not be performed because none of the measurements confirmed the presence of contamination. In addition, the vast majority of the gross alpha and beta results are less than the minimum detectable activity of one dpm or less. The highest alpha and beta smear results are 2.6 and 2.6 dpm/100 cm^2, respectively. Individual smear results are provided in the Appendix J laboratory reports.

While the data collected could not be used to mathematically prove the 10% removable assumption is accurate, the very low results indicate that removable radioactive contaminants are not present in significant quantities. On this basis, the NRC screening criteria are considered appropriate DCGLs for this survey.

Table 12: Summary of Survey Unit SOR Results

Building Number	Survey Unit ID	Number of Measurements		SOR Statistics (non-biased)				Relative Shift
		Systematic/ Random	Biased	Average	Standard Deviation	Min.	Max.	
275 (Museum)	1	30	0	0.04	0.032	0.000	0.11	30
283 (Squier)	1	40	0	0.06	0.040	0.00	0.16	24
283 (Squier)	2	17	10	0.14	0.051	0.05	0.24	17
292 (Museum Storage)	1	30	0	0.09	0.035	0.03	0.14	26
2540 (CECOM)	1	32	1	0.24	0.047	0.18	0.33	16
2540 (CECOM)	2	21	1	0.36	0.062	0.26	0.46	10
2540 (CECOM)	3	47	1	0.33	0.042	0.24	0.41	16
2540 (CECOM)	4	30	1	0.12	0.015	0.09	0.17	60
2540 (CECOM)	5	36	1	0.02	0.048	0.00	0.18	20
2540 (CECOM)	6	32	2	0.27	0.12	0.08	0.54	6.2
2540 (CECOM)	7	49	2	0.02	0.042	0.00	0.20	23
2540 (CECOM)	8	30	3	0.04	0.043	0.000	0.16	22
2540 (CECOM)	9	80	2	0.23	0.14	0.000	0.64	5.5
2540 (CECOM)	10	24	1	0.10	0.020	0.06	0.13	45
2540 (CECOM)	11	42	1	0.01	0.012	0.00	0.04	82
2540 (CECOM)	12	32	2	0.06	0.023	0.00	0.11	40
2540 (CECOM)	13	40	1	0.03	0.024	0.00	0.07	41
2540 (CECOM)	14	27	1	0.13	0.15	0.00	0.47	5.7
2540 (CECOM)	15	30	1	0.07	0.046	0.01	0.19	20
2541 (CECOM Demil)	1	30	1	0.17	0.053	0.10	0.33	16
2541 (CECOM Demil)	2	30	1	0.03	0.026	0.00	0.08	38

6.3 FSS Results by Building

This section presents the results of FSSs performed in each of the buildings and survey units. Results are presented by building. Table 12 provides a summary of the survey unit SOR results for all survey units. Table 13 provides a summary of static alpha and static beta results for each survey unit. Low energy beta results are not summarized in Table 13 because over 99% of the results are less than MDA and the maximum result is 8.7 dpm/100 cm^2, an extremely small fraction of the DCGL of 21,000 dpm/100 cm^2. Appendix C provides the individual results for each measurement location in each survey unit.

All locations in all survey units have SOR values less than one, indicating all survey units and buildings are suitable for release for unrestricted use. All relative shifts (delta over sigma values), which were calculated based on actual SOR average and standard deviation, are greater

than the survey design specification in the RSSP of 3 indicating that a sufficient number of measurement locations were established in each survey unit.

Biased measurement locations were established based on scanning information, requirements for the RSSP, and professional judgment. Some biased measurements were performed to evaluate building drainage and ventilation systems. All biased measurements produced SOR values less than one.

Table 13: Summary of Survey Unit Alpha/Beta Results

Building Number	SU ID	Direct Alpha Statistics (non-biased) dpm/100 cm^2				Direct Beta Statistics (non-biased) dpm/100 cm^2			
		Avg.	Std. Dev.	Min.	Max.	Average	Std. Dev.	Min.	Max.
275 (Museum)	1	5	4	-2	12	141	202	-169	598
283 (Squier)	1	13	10	-8	43	82	294	-508	737
283 (Squier)	2	32	10	16	50	223	280	-250	709
292 (Museum Storage)	1	8	7	-2	21	414	181	-55	714
2540 (CECOM)	1	25	7	13	39	1155	250	726	1649
2540 (CECOM)	2	52	12	31	69	1420	208	1119	1749
2540 (CECOM)	3	59	13	35	83	1047	183	709	1552
2540 (CECOM)	4	1	5	-6	17	817	78	667	1059
2540 (CECOM)	5	-2	5	-10	8	-98	391	-574	1166
2540 (CECOM)	6	5	3	0	11	616	353	-99	1025
2540 (CECOM)	7	-1	2	-6	5	-156	173	-388	604
2540 (CECOM)	8	-1	2	-7	3	174	163	-182	673
2540 (CECOM)	9	6	4	0	17	74	109	-107	436
2540 (CECOM)	10	5	4	-2	12	571	95	406	805
2540 (CECOM)	11	2	5	-11	11	-38	103	-269	271
2540 (CECOM)	12	1	5	-10	15	380	148	13	563
2540 (CECOM)	13	3	6	-9	18	68	184	-203	500
2540 (CECOM)	14	28	36	-3	113	282	310	-177	795
2540 (CECOM)	15	-4	13	-32	19	425	283	103	1128
2541 (CECOM Demil)	1	24	14	7	64	668	81	554	908
2541 (CECOM Demil)	2	10	8	-2	27	-201	37	-265	-120

6.3.1 Building 275 - Museum

Building 275 is the Communications-Electronics Museum, which contains various historical displays that formerly displayed demilitarized artifacts. The building was surveyed as a MARSSIM Class 3 area. The highest potential for contamination in this building was in the

display cases where radioactive artifacts were displayed. Figure A-1 in Appendix A identifies the building layout.

Deviations from RSSP

The RSSP indicated that display case shelves would be scanned at a rate of 5% of the surface area for residual contamination. Instead 100% of the bottom surfaces of all display cases were scanned. This was deemed appropriate, as the most likely locations for contamination would be in the display cases.

No other deviations from the RSSP occurred.

Alpha Beta Scan

Alpha/beta scans were performed over 100% of the bottom surfaces of all display cases. The scans did not indicate the presence of contamination and there were no sustained elevated measurements that would indicate a small elevated area. Instantaneous rolling average alpha and beta count rates were recorded at two second intervals and are included in Appendix H to this FSSR.

MARSSIM Random Measurement Location Results

Building 275 consisted of a single Class 3 Survey unit with 30 randomly established measurement locations. Figure A-1 identifies the survey unit layout and the sample locations. All SOR values were less than one, ranging from 0.0 to 0.11 and averaging 0.04. Figure B-1 (in Appendix B) is a posting plot of SOR data. Exposure rate measurements performed at each location ranged from 6 to 14 µR/hr, averaging 9.4 µR/hr.

There were no discernible indications that residual radioactivity was present.

Biased Measurements

In accordance with the RSSP biased gross alpha/beta and low energy beta smear samples were collected in the following display cases: AN/PRC-10 Radio Miniaturization Display, Vacuum Tube Development Display, Night Vision Equipment Display, and the Combat Photography Display. Analysis results for these samples were all less than the gross alpha and beta MDAs (MDAs less than 1 dpm/100 cm^2). The maximum alpha and beta smear results were 0.52 and 0.11 dpm/100cm^2, respectively. All low energy beta results were less than the MDA of approximately 10 dpm/100 cm^2.

6.3.2 Building 283 – Squier Hall

Building 283 was historically utilized as a laboratory with wet labs. Evidence was found of radio communication work performed in the basement of the building. Approximately 20 years ago the building was completely remodeled and converted into office space. As a result, laboratory drain lines were covered over by carpet, but original janitorial sinks remain in the building. During performance of the survey, three floor drains covered by carpet were identified. The building was surveyed as a MARSSIM Class 3 area. Based on information documented in the HSA, the most likely location for potential contamination was the radio room in the basement. Figure A-2 identifies the building layout.

Deviations from RSSP

The RSSP included performance of an alpha/beta scan over approximately 5% of the total floor area of former wet lab rooms. The location of wet lab rooms could not be limited to certain areas as no prints are available that identify their location. With the exception of bathrooms, janitor closets, the auditorium, and utility areas, all portions of the building have renovated and carpeted. Based on these facts, scanning of potential wet labs was not performed. Instead, a second survey unit was established (Survey Unit 2). This survey unit included all locations in the initial survey unit (Survey Unit 1) that were carpeted. Survey Unit 1 measurements were performed on top of carpet when it was present. Survey Unit 2 measurements where performed beneath the carpet by cutting and removing the carpet.

The RSSP indicated that the radio room would be scanned at a rate of approximately 5% of its floor area. Instead 100% of the reasonably accessible floor area was scanned (approximately 70% of the total floor area due to the presence of fixed shelving and stored metal conduit). This was deemed appropriate, as the most likely location for contamination in Squier Hall was in the radio room.

The RSSP included the collection of one sludge sample from drains within each of the janitor's closet sinks. It also included collection of sludge samples from covered floor drains (if identified). There was insufficient material in the janitor closet sink traps and the floor drains identified to support collection of a volumetric sample. Instead, smear samples were collected.

Biased smear samples were collected from two basement sumps. This was performed prior to identification of the covered floor drains as a possible substitute for sampling floor drains. Collection of smears in the sumps was not included in the RSSP.

No other deviations from the RSSP occurred.

Alpha Beta Scan

Alpha/beta scans were performed over 100% of the reasonably accessible floor area in the radio room. Due to the presence of fixed shelving and stored metal conduit along the wall, this resulted in scan coverage of approximately 70% of the total floor (the middle portion of the room). In addition, scans were performed over floor areas in the general vicinity of janitor sinks. The scans did not indicate the presence of contamination and there were no sustained elevated measurements that would indicate a small elevated area. Instantaneous rolling average alpha and beta count rates were recorded at one second intervals and are included in Appendix H to this FSSR.

MARSSIM Random Measurement Location Results

Building 283 consisted of two Class 3 Survey units. Survey Unit 1 was defined in the RSSP and has 30 randomly established measurement locations (see Figure A-2). Survey Unit 2 was added during performance of the survey work to address the potential for contamination under renovated areas with carpet. In Survey Unit 2 locations, measurements were performed beneath the carpet with the carpet removed. Survey Unit 2 includes all 17 Survey Unit 1 locations that were carpeted (see Figure A-3).

Figure A-2 identifies the Survey Unit 1 layout and sample locations. All SOR values were less than one, ranging from 0.0 to 0.16 and averaging 0.06. Figure B-2 is a posting plot of SOR data. Exposure rate measurements performed at each location ranged from 4 to 15 µR/hr, averaging 8.2 µR/hr.

Figure A-3 identifies the Survey Unit 2 layout and sample locations. All SOR values were less than one, ranging from 0.05 to 0.24 and averaging 0.14. Figure B-3 is a posting plot of SOR data. Exposure rate measurements performed at each location ranged from 4 to 14 µR/hr, averaging 9.0 µR/hr.

There were no discernible indications that residual radioactivity was present in either survey unit.

Biased Measurements

Figure A-4 identifies the six biased measurement locations performed in the basement radio room. All SOR values were less than one, ranging from 0.06 to 0.11 and averaging 0.09. Figure B-4 is a posting plot of SOR data. Exposure rate measurements performed at each location ranged from 10 to 16 µR/hr, averaging 12.7 µR/hr. There were no discernible indications that residual radioactivity was present in the radio room.

Biased gross alpha/beta and low energy beta smear samples were collected in the four janitor sinks, the four sink traps, and in two basement sumps. The maximum gross alpha and beta

results for these smears were from the smear collected in the basement sump and are 2.6 and 1.1 dpm/100cm^2, respectively. All low energy beta results were less than the MDC of approximately 10 dpm/100 cm^2. Based on the very low results of these smear analyses it is concluded that these building systems were not impacted by RAM.

Biased gross alpha/beta and low energy beta smear samples were collected in two floor drains, from Room 102 and 214A. The maximum alpha and beta results for these smears are 0.319 (less than MDC) and 1.8 dpm/100cm^2, respectively. All low energy beta results were less than the MDC of approximately 10 dpm/100 cm^2. Based on the very low results of these smear analyses it is concluded that these building systems were not impacted by RAM.

6.3.3 Building 292 - Museum Storage

Building 292 was the Museum storage facility, where museum artifacts containing RAM were stored. The building was surveyed as a MARSSIM Class 3 area. Artifacts containing RAM were stored in one area of the building inside three locked cabinets, with a radioactive material posting. A foreign radio with radioluminescent backlight components and an electron tube were also found in the main storage area during HSA reconnaissance. The main storage area had 6-8 moveable storage shelves containing hundreds to thousands of artifacts, which were removed at the time of the FSS. Additional shelf storage was present in a back area of the building. However, the majority of the shelf storage was removed at the time of the survey. The highest potential for contamination in this building was in the area where the storage cabinets were located. Figure A-5 identifies the building layout. The storage cabinets were located in the vicinity of sample point 10 on Figure A-5.

Deviations from RSSP

No deviations from the RSSP occurred during FSS activities in Building 292.

Alpha Beta Scan

Alpha/beta scans were performed in floor areas surrounding the storage cabinets, the former location of the movable storage cabinets and the back area shelf storage locations. Scans were also performed over the shelves in the storage cabinets. Figure A-5 identifies the areas that were scanned. The scans did not indicate the presence of contamination and there were no sustained elevated measurements that would indicate a small elevated area. Instantaneous rolling average alpha and beta count rates were recorded at one second intervals and are included in Appendix H to this FSSR.

MARSSIM Random Measurement Location Results

Building 292 consisted of a single Class 3 Survey unit with 30 randomly established measurement locations. Figure A-5 identifies the survey unit layout and the sample locations. All SOR values were less than one, ranging from 0.03 to 0.14 and averaging 0.09. Figure B-5 is a posting plot of SOR data. Exposure rate measurements performed at each location ranged from 3 to 7 µR/hr, averaging 4.7 µR/hr.

There were no discernible indications that residual radioactivity was present. Differences in SOR values were primarily driven by beta count variability. This slight variability was likely due to changes in beta background as a result of geometry and building materials.

Biased Measurements

In accordance with the RSSP biased gross alpha/beta and low energy beta smear samples were collected in the three storage cabinets. The maximum alpha and beta results for these smears are 0.65 and 2.4 dpm/100cm^2, respectively. All other smear results were less than the MDC (MDCs less than 1 dpm/100 cm^2). All low energy beta results were less than the MDC of approximately 10 dpm/100 cm^2.

6.3.4 Building 2540 – CECOM Laboratory

Building 2540 housed the CECOM Laboratory and radiological testing facility. The building housed a gamma irradiator and several RADIAC calibrators, and contained a low-level storage room with multiple radioactive sources from the demilitarization of commodities, a nuclear counting laboratory, and several health physics laboratories. Radioactive sources consisted of alpha, beta, gamma, and neutron emitters. All areas in Building 2540 were surveyed as MARSSIM Class 1, with the exception of the administrative area, which was surveyed as a Class 3 area. Figure 5 of this FSSR identifies the building layout and survey unit layout. Figures A-6 through A-14 identify the measurement locations in each survey unit.

Deviations from RSSP

The RSSP did not include measurement locations on interior walls of the Class 1 survey units. Instead, it only included wall measurement locations on the outer walls of each survey unit. A substantial quantity of additional points was established during the FSS to ensure all Class 1 survey unit walls were surveyed with the same measurement density. This was accomplished by continuing the measurement location grid along interior walls.

Measurement location coordinates presented in the original RSSP (developed by a contractor in 2007) were carried forward in the revised USACE RSSP used to perform this FSS. In some survey units the coordinates did not match the actual building/room dimensions. In such cases,

new sample locations were determined in the field using a triangular grid and a random start point. All sample locations maps in this FSSR identify the actual sample locations where FSS data was collected.

The RSSP did not include survey of the administrative area in Building 2540. During performance of the FSS it was decided that this area should be surveyed. As a result, Survey Unit 15 was established as a Class 3 survey unit. This area was surveyed last, after all data was collected in other survey units. The Class 3 designation was considered appropriate based on the results of measurements in the Class 1 areas; considering that all results in the Class 1 areas had SOR values less than one indicating that a Class 2 designation may have been appropriate for those areas.

6.3.4.1 Survey Units 1, 2, and 3

Survey Units 1, 2, and 3 are located in the "mural room" in the northwest corner of the building. This area (a single larger room) was used for R&D activities. Figure A-6 identifies measurement locations in the survey units. Survey Unit 1 is the floor of the western portion of the room, Survey unit 2 is the floor of the eastern portion, and Survey Unit 3 is the lower walls (up to 2 meters) of the room.

Alpha Beta Scan

Alpha/beta scans were performed over 100% of floor areas and over 100% of lower walls, up to 2 meters. It was noted that in general, count rates (and exposure rates) in this room were slightly higher than most other areas of the building. However, there were no sustained elevated measurements that would indicate a small elevated area of radioactivity. Instantaneous rolling average alpha and beta count rates were recorded at one second intervals and are included in Appendix H to this FSSR.

MARSSIM Random Measurement Location Results

Appendix C provides results for each measurement location in each survey unit. The following paragraphs summarize the results.

Survey Unit 1 is the western portion of the room floor. All SOR values are less than one, ranging from 0.15 to 0.33 and averaging 0.24. Figure B-6 is a posting plot of SOR data. Exposure rate measurements performed at each location ranged from 10 to 16 µR/hr, averaging 14 µR/hr.

Survey Unit 2 is the eastern portion of the room floor. All SOR values are less than one, ranging from 0.26 to 0.46 and averaging 0.36. Figure B-6 is a posting plot of SOR data. Exposure rate measurements performed at each location ranged from 12 to 19 µR/hr, averaging 15 µR/hr.

While no small areas of elevated radioactivity were identified in this survey unit, it was noted that radioactivity levels were generally slightly higher than the western portion of the room.

Survey Unit 3 is the lower walls of the room. All SOR values are less than one, ranging from 0.24 to 0.41 and averaging 0.33. Figure B-6 is a posting plot of SOR data. Exposure rate measurements performed at each location ranged from 10 to 20 µR/hr, averaging 14 µR/hr.

While measurement results in these survey units were slightly greater than other portions of the building, SOR values are considerably less than the limit of one indicating the survey units are suitable for release for unrestricted use.

Biased Measurements

Alpha/beta scan surveys did not identify any areas of elevated radioactivity. However, the scan surveyor flagged the area in each survey unit exhibiting the highest count rate for performance of a biased static measurement. The SOR results of these biased measurements are 0.30, 0.31, and 0.27, in Survey Units 1, 2, and 3, respectively.

6.3.4.2 Survey Units 4 and 5

Survey Units 4 and 5 are located south of the "mural room". This area, a single room, was used as a support area for R&D activities. Figure A-7 identifies measurement locations in the survey units. Survey Unit 4 is the floor and Survey Unit 5 is the lower walls of the room.

Alpha Beta Scan

Alpha/beta scans were performed over 100% of floor areas and over 100% of lower walls, up to 2 meters. There were no sustained elevated measurements that would indicate a small elevated area of radioactivity. Instantaneous rolling average alpha and beta count rates were recorded at one second intervals and are included in Appendix H to this FSSR.

MARSSIM Random Measurement Location Results

Appendix C provides results for each measurement location in each survey unit. The following paragraphs summarize the results.

Survey Unit 4 is the floor of the room. All SOR values are less than one, ranging from 0.09 to 0.17 and averaging 0.12. Figure B-7 is a posting plot of SOR data. Exposure rate measurements performed at each location ranged from 8 to 14 µR/hr, averaging 9.9 µR/hr.

Survey Unit 5 is the lower walls of the room. All SOR values are less than one, ranging from 0.0 to 0.18 and averaging 0.02. Figure B-7 is a posting plot of SOR data. Exposure rate measurements performed at each location ranged from 7 to 15 µR/hr, averaging 10 µR/hr.

SOR values in these survey units are considerably less than the limit of one indicating the survey units are suitable for release for unrestricted use.

Biased Measurements

Alpha/beta scan surveys did not identify any areas of elevated radioactivity. However, the scan surveyor flagged the area in each survey unit exhibiting the highest count rate for performance of a biased static measurement. The SOR results of these biased measurements are 0.11 and 0.0, in Survey Units 4 and 5, respectively.

6.3.4.3 Survey Units 6 and 7

Survey Units 6 and 7 include the machine shop, a small storage room supporting the machine shop, and Dr. Kronenberg's Office. Dr. Kronenberg stored samples spiked with liquid forms of ^{230}Th and ^{241}Am in his office. As a result, ^{230}Th and ^{241}Am were considered RCOPCs in these survey units. The alpha DCGL for the survey units is 27 dpm/100 cm^2 (compared to 315 dpm/100 cm^2 in most other survey units) resulting in slower scan speeds and longer static count times. Figure A-8 identifies measurement locations in the survey units. Survey Unit 6 is the floors of the rooms and Survey Unit 7 is the lower walls of the rooms.

Alpha Beta Scan

Alpha/beta scans were performed over 100% of floor areas and over 100% of lower walls, up to 2 meters. Scan speed was reduced to one half detector width per second to meet the requirements for the lower alpha DCGL. There were no sustained elevated measurements that would indicate a small elevated area of radioactivity. Instantaneous rolling average alpha and beta count rates were recorded at one second intervals and are included in Appendix H to this FSSR.

MARSSIM Random Measurement Location Results

Appendix C provides results for each measurement location in each survey unit. Count times for static measurements were five minutes to meet the MDC requirement for the lower alpha DCGL. The following paragraphs summarize the results.

Survey Unit 6 is the floor of the rooms. All SOR values are less than one, ranging from 0.08 to 0.54 and averaging 0.27. Figure B-8 is a posting plot of SOR data. Exposure rate measurements performed at each location ranged from 6 to 10 µR/hr, averaging 7.5 µR/hr.

Survey Unit 7 is the lower walls of the room. All SOR values are less than one, ranging from 0.0 to 0.20 and averaging 0.02. Figure B-8 is a posting plot of SOR data. Exposure rate measurements performed at each location ranged from 5 to 11 µR/hr, averaging 7.6 µR/hr.

SOR values in these survey units are less than the limit of one indicating the survey units are suitable for release for unrestricted use.

Biased Measurements

Alpha/beta scan surveys did not identify any areas of elevated radioactivity. However, the scan surveyor flagged the areas in the office and the machine shop exhibiting the highest count rate for performance of biased static measurements. The SOR results of these biased measurements in Survey Unit 6 are 0.18 and 0.21. The SOR results of these biased measurements in Survey Unit 7 are 0.03 and 0.02.

A gross alpha/beta smear was also collected in the sink trap in the machine shop. Its alpha and beta results are 0.99 and 0.72 dpm/100 cm^2, both slightly greater than MDC. Based on these very low results it is concluded that the drain system was not impacted by RAM.

6.3.4.4 Survey Units 8 and 9

Survey Units 8 and 9 include the counting laboratory and health physics offices. Samples were prepared in the counting laboratory fume hood by spiking them with liquid forms of ^{230}Th and ^{241}Am. As a result, ^{230}Th and ^{241}Am were considered RCOPCs in these survey units. The alpha DCGL for the survey units is 27 dpm/100 cm^2 (compared to 315 dpm/100 cm^2 in most other survey units) resulting in slower scan speeds and longer static count times. Figure A-9 identifies measurement locations in the survey units. Survey Unit 8 is the floors of the rooms and Survey Unit 9 is the lower walls of the rooms.

Alpha Beta Scan

Alpha/beta scans were performed over 100% of floor areas and over 100% of lower walls, up to 2 meters. Scan speed was reduced to one half detector width per second to meet the requirements for the lower alpha DCGL. Scans were also performed on and in fixed laboratory benches and countertops and in the fume hood. There were no sustained elevated measurements that would indicate a small elevated area of radioactivity. Instantaneous rolling average alpha and beta count rates were recorded at one second intervals and are included in Appendix H to this FSSR.

MARSSIM Random Measurement Location Results

Appendix C provides results for each measurement location in each survey unit. Count times for static measurements were five minutes to meet the MDC requirement for the lower alpha DCGL. The following paragraphs summarize the results.

Survey Unit 8 is the floor of the rooms. All SOR values are less than one, ranging from 0.0 to 0.16 and averaging 0.04. Figure B-9 is a posting plot of SOR data. Exposure rate measurements performed at each location ranged from 3 to 5 µR/hr, averaging 3.9 µR/hr.

Survey Unit 9 is the lower walls of the room. All SOR values are less than one, ranging from 0.0 to 0.64 and averaging 0.23. Figure B-9 is a posting plot of SOR data. Exposure rate measurements performed at each location ranged from 3 to 5 µR/hr, averaging 4.0 µR/hr.

SOR values in these survey units are less than the limit of one indicating the survey units are suitable for release for unrestricted use.

Biased Measurements

Alpha/beta scan surveys did not identify any areas of elevated radioactivity. However, the scan surveyor flagged areas for performance of biased static measurements. The SOR results of these biased measurements in Survey Unit 8 are 0.04, 0.22, and 0.03. The SOR results of these biased measurements in Survey Unit 9 are 0.44 and 0.30.

In accordance with the RSSP, biased measurements were performed and smears were collected in the fume hood and the exhaust outlet for the fume hood. Survey Unit 9 location 33 was inside on the wall of the fume hood as well, with an SOR result of 0.0. A measurement was performed in the exhaust vent pipe with an SOR result of 0.0. Gross alpha/beta smear results in the fume hood base and the exhaust vent are less than the MDCs for alpha and beta (MDCs less than 1 dpm/100 cm^2). Low energy beta smear results are less than the MDC of approximately 10 dpm/100 cm^2. Based on these results, it is concluded that the exhaust outlet and ductwork was not impacted by RAM.

A gross alpha/beta smear was also collected in the sink trap in the counting laboratory. Its results are less than the MDCs for alpha and beta (MDCs less than 1 dpm/100 cm^2).

6.3.4.5 Survey Units 10 and 11

Survey Units 10 and 11 include the storage room/utility room. Figure A-10 identifies measurement locations in the survey units. Survey Unit 10 is the floors of the room and Survey Unit 11 is the lower walls of the room.

Alpha Beta Scan

Alpha/beta scans were performed over 100% of floor areas and over 100% of lower walls, up to 2 meters. There were no sustained elevated measurements that would indicate a small elevated area of radioactivity. Instantaneous rolling average alpha and beta count rates were recorded at one second intervals and are included in Appendix H to this FSSR.

MARSSIM Random Measurement Location Results

Appendix C provides results for each measurement location in each survey unit. The following paragraphs summarize the results.

Survey Unit 10 is the floor of the room. All SOR values are less than one, ranging from 0.06 to 0.13 and averaging 0.10. Figure B-10 is a posting plot of SOR data. Exposure rate measurements performed at each location ranged from 3 to 6 µR/hr, averaging 4.8 µR/hr.

Survey Unit 11 is the lower walls of the room. All SOR values are less than one, ranging from 0.0 to 0.04 and averaging 0.01. Figure B-10 is a posting plot of SOR data. Exposure rate measurements performed at each location ranged from 3 to 6 µR/hr, averaging 4.5 µR/hr.

SOR values in these survey units are less than the limit of one indicating the survey units are suitable for release for unrestricted use.

Biased Measurements

Alpha/beta scan surveys did not identify any areas of elevated radioactivity. However, the scan surveyor flagged areas for performance of biased static measurements. The SOR results of these biased measurements in Survey Unit 10 and 11 are 0.10 and 0.02, respectively.

6.3.4.6 Survey Units 12 and 13

Survey Units 12 and 13 are the calibration range room. Figure A-11 identifies measurement locations in the survey units. Survey Unit 12 is the floors of the room and Survey Unit 13 is the lower walls of the room.

Alpha Beta Scan

Alpha/beta scans were performed over 100% of floor areas and over 100% of lower walls, up to 2 meters. There were no sustained elevated measurements that would indicate a small elevated area of radioactivity. Instantaneous rolling average alpha and beta count rates were recorded at one second intervals and are included in Appendix H to this FSSR.

MARSSIM Random Measurement Location Results

Appendix C provides results for each measurement location in each survey unit. The following paragraphs summarize the results.

Survey Unit 12 is the floor of the room. All SOR values are less than one, ranging from 0.0 to 0.11 and averaging 0.06. Figure B-11 is a posting plot of SOR data. Exposure rate measurements performed at each location ranged from 3 to 5 µR/hr, averaging 4.3 µR/hr.

Survey Unit 13 is the lower walls of the room. All SOR values are less than one, ranging from 0.0 to 0.07 and averaging 0.02. Figure B-11 is a posting plot of SOR data. Exposure rate measurements performed at each location ranged from 3 to 6 µR/hr, averaging 4.3 µR/hr.

SOR values in these survey units are less than the limit of one indicating the survey units are suitable for release for unrestricted use.

Biased Measurements

Alpha/beta scan surveys did not identify any areas of elevated radioactivity. However, the scan surveyor flagged areas for performance of biased static measurements. The SOR results of these biased measurements in Survey Unit 12 are 0.04 and 0.07. The SOR result in Survey Unit 13 is 0.0.

6.3.4.7 Survey Unit 14

Survey Unit 14 is the former radioactive waste storage room (Room 109) and the outdoor pad leading to the storage room. Due to the small area of the survey unit, walls and floors are included in the single survey unit. Figure A-12 identifies measurement locations in the survey unit.

Alpha Beta Scan

Alpha/beta scans were performed over 100% of floor areas and over 100% of lower walls, up to 2 meters. There were no sustained elevated measurements that would indicate a small elevated area of radioactivity. It was noted that the outdoor pad uniformly exhibited higher alpha and beta count rates than most portions of the building. Considering the uniformity of the results, the higher radioactivity is attributed to natural background in the concrete. Instantaneous rolling average alpha and beta count rates were recorded at one second intervals and are included in Appendix H to this FSSR.

MARSSIM Random Measurement Location Results

Appendix C provides results for each measurement location.

All SOR values in Survey unit 14 are less than one, ranging from 0.0 to 0.47 and averaging 0.13. Figure B-12 is a posting plot of SOR data. As can be seen in the figure, the pad at the southern portion of the survey unit exhibited higher SOR values attributable to natural radioactivity. Exposure rate measurements performed at each location ranged from 3 to 6 µR/hr, averaging 4.2 µR/hr.

SOR values in this survey unit are less than the limit of one indicating the survey unit is suitable for release for unrestricted use.

Biased Measurements

Alpha/beta scan surveys did not identify any areas of elevated radioactivity. However, the scan surveyor flagged one floor area for performance of a biased static measurement. The SOR result of this biased measurement is 0.09.

6.3.4.8 Survey Unit 15

Survey Unit 15 is a Class 3 survey unit including a portion of the hallways in the building, the administrative office area, and the bathroom. Figure A-13 identifies measurement locations in the survey unit.

Alpha Beta Scan

Alpha/beta scans were performed over 100% of floor areas in the hallways and approximately 30% of the floor areas in the office areas. There were no sustained elevated measurements that would indicate a small elevated area of radioactivity. Instantaneous rolling average alpha and beta count rates were recorded at one second intervals and are included in Appendix H to this FSSR.

MARSSIM Random Measurement Location Results

Appendix C provides results for each measurement location.

All SOR values in Survey unit 15 are less than one, ranging from 0.01 to 0.19 and averaging 0.07. Figure B-13 is a posting plot of SOR data. Exposure rate measurements performed at each location ranged from 4 to 15 µR/hr, averaging 11 µR/hr.

SOR values in this survey unit are less than the limit of one indicating the survey unit is suitable for release for unrestricted use.

Biased Measurements

Alpha/beta scan surveys did not identify any areas of elevated radioactivity. However, the scan surveyor flagged one floor area for performance of a biased static measurement. The SOR result of this biased measurement is 0.03.

6.3.5 Building 2541 – CECOM Butler Building

Building 2541 was surveyed as a MARSSIM Class 1 area. Building 2541 was historically used, in part, for demilitarization of excess ^{232}Th (night vision lenses), ^{226}Ra, and ^{3}H. Two survey units were established in Building 2541 in accordance the RSSP. Survey Unit 1 is the floors and

Survey Unit 2 is the lower walls. Figure A-14 identifies the building layout and measurement locations.

Deviations from RSSP

No deviations from the RSSP occurred during FSS activities in Building 2541.

Alpha Beta Scan

Alpha/beta scans were performed over 100% of floor areas and the lower walls. There were no sustained elevated measurements that would indicate a small elevated area of radioactivity. Instantaneous rolling average alpha and beta count rates were recorded at one second intervals and are included in Appendix H to this FSSR.

MARSSIM Measurement Location Results

Appendix C provides results for each measurement location in each survey unit. The following paragraphs summarize the results.

Survey Unit 1 is the floor of the building. All SOR values are less than one, ranging from 0.10 to 0.33 and averaging 0.17. Figure B-14 is a posting plot of SOR data. Exposure rate measurements performed at each location ranged from 3 to 5 µR/hr, averaging 3.9 µR/hr.

Survey Unit 2 is the lower walls of the building. All SOR values are less than one, ranging from 0.0 to 0.08 and averaging 0.03. Figure B-14 is a posting plot of SOR data. Exposure rate measurements performed at each location ranged from 3 to 5 µR/hr, averaging 3.8 µR/hr.

SOR values in these survey units are less than the limit of one indicating the survey units are suitable for release for unrestricted use.

Biased Measurements

Alpha/beta scan surveys did not identify any areas of elevated radioactivity. However, the scan surveyor flagged one floor area and one wall area for performance of biased static measurements. The SOR result of these biased measurements is 0.13 and 0.04 in Survey Units 1 and 2, respectively.

7.0 CONCLUSION

Radiological FSSs were performed in Buildings 275, 283, 292, 2540 and 2541 at Fort Monmouth, New Jersey. The surveys were designed in accordance with MARSSIM final status survey design criteria using conservative assumptions. DCGLs applied to the surveys are the conservative NRC generic screening criteria. The sum of the ratios rule was applied to all survey results to address the potential presence of multiple radionuclide contaminants. All SOR results in all buildings, including biased locations, are less than the limit of one. In addition, evaluations of building systems (drain and ventilation) for radioactive contaminants did not identify any radiological impacts to building systems. Based on historical research and the FSS field observations and supporting laboratory analytical data, all buildings surveyed are considered suitable for unrestricted release in accordance with Subpart E to 10 CFR 20, Radiological Criteria for License Termination.

8.0 REFERENCES

(Abelquist, 2001) *Decommissioning Health Physics*, EW Abelquist, IOP Publishing Ltd, 2001.

(AMC, 2004) Army Materiel Command, *Guidance on Radiological Decommissioning Survey for Areas where U.S. Nuclear Regulatory Commission Licensed Commodities Were Used*, AMCPE-SG-G (11-9h), April 2004.

(CABRERA, 2007a) *Historical Site Assessment and Addendum to Environmental Condition of Property Report, Fort Monmouth, Eatontown, New Jersey*, January 2007.

(CABRERA, 2007b) *Recommendations for Phase II Environmental Condition of Property Investigation, Fort Monmouth, Eatontown, New Jersey*, 2007.

(CABRERA, 2007c) *Site Safety Plan for Radiological Scoping Surveys, Fort Monmouth, Eatontown, New Jersey*, April 2007.

(NRC, 1992) *Residual Radioactive Contamination From Decommissioning: Technical Basis for Translating Contamination Levels to Annual Total Effective Dose Equivalent,* NUREG/CR-5512 V1, October 1992.

(NRC, 1999a) *Residual Radioactive Contamination From Decommissioning: Parameter Analysis,* NUREG/CR-5512 V3, October 1999.

(NRC, 1999b) *A Non-Parametric Statistical Methodology for the Design and Analysis of Final Status Decommissioning Surveys*, NUREG-1505, U.S. NRC, 1999.

(NRC, 2000) NUREG-1575, *Multi-Agency Radiation Survey and Site Investigation Manual* (MARSSIM), U.S. Nuclear Regulatory Commission, dated August, 2000.

(NRC, 2003) *Consolidated NMSS Decommissioning Guidance,* NUREG-1757 Volumes 1 and 2, U.S. NRC, 2003.


(ORISE, undated) PTP's MARSSIM Cheat Sheet, Professional Training Programs, Oak Ridge Associated Universities (ORAU), Student Handout; undated.

(Shaw, 2007) *Site Specific Health and Safety Plan For Fort Monmouth Phase II ECP*, Shaw 2007.

(USACE, 2012a) *Radiological Scoping Survey Plan, Fort Monmouth, Eatontown, New Jersey, Final,* U.S. Army Corps of Engineers, June 2012.

(USACE, 2012b) *Supplement to - Historical Site Assessment, Fort Monmouth, Eatontown, New Jersey*, U.S. Army Corps of Engineers, May 2012.

FIGURES



N

W E

S

FORT MONMOUTH

MONMOUTH COUNTY
NEW JERSEY

Date: April, 2007

Project #: 05-3132.01

File Name: Figure 1

Prepared By: B.Pangelova

Figure 1

CABRERA SERVICES
RADIOLOGICAL · ENVIRONMENTAL · REMEDIATION



N
W E
S

Legend

- Impacted Buildings / Areas
- Non- Impacted Buildings / Areas of Interest
- Site Buildings
- Athletic Field Area
- Surface Water Body area
- Wetland Area

0 1,900 3,800 Feet

FORT MONMOUTH OVERVIEW MAP

Fort MONMOUTH, NEW JERSEY

Date: April, 2007


Project #: 05-3132.01

File Name: Figure 2

Prepared By: B.Pangelova

Figure 2

CABRERA SERVICES
RADIOLOGICAL · ENVIRONMENTAL · REMEDIATION



N
W
E
S

Legend

- Impacted Buildings / Areas
- Non- Impacted Buildings / Areas of Interest
- Site Buildings
- Athletic Field Area
- Surface Water Body area
- Wetland Area

0 550 1,100 Feet

FORT MONMOUTH, MAIN POST

Fort Monmouth, Main Post
NEW JERSEY

Date: April, 2007
Project #: 05-3132.04
File Name: Figure 3
Prepared By: B.Pangelova

Figure 3

CABRERA SERVICES
RADIOLOGICAL · ENVIRONMENTAL · REMEDIATION



N
W E
S

Legend

- Impacted Buildings / Areas
- Non- Impacted Buildings / Areas of Interest
- Site Buildings
- Athletic Field Area
- Surface Water Body area
- Wetland Area

0 520 1,040 Feet

FORT MONMOUTH, CHARLES WOOD AREA

Fort Monmouth, Charles Wood Area
NEW JERSEY

Date: April, 2007
Project #: 05-3132.04
File Name: Figure 4
Prepared By: B.Pangelova

Figure 4

CABRERA SERVICES
RADIOLOGICAL · ENVIRONMENTAL · REMEDIATION



Legend

- SU1 (Radiation Facillity)
- SU2 (Radiation Facillity)
- SU4 (Work Area)
- SU6 (Machine Shop)
- SU8
- SU10
- SU12
- SU14
- SU15 (Class 3)

BUILDING 2540
FLOOR PLAN and
CLASS 1 SURVEY UNITS

FORT MONMOUTH
NEW JERSEY

Date: September, 2006
Project #: 05-3132.04
File Name: Figure 8
Prepared By: B.Pangelova

Figure 5


CABRERA SERVICES
RADIOLOGICAL · ENVIRONMENTAL · REMEDIATION

MODIFIED: Original Contractor Figure Modified by USACE on 26 July 2012

APPENDIX A

Sample/Measurement Location Maps

Building 275 - Museum Locations



USACE
New York District

Location Name


Fort Monmouth
New Jersey


FIGURE A-1

Building 275 SU01
Locations

10 August 2012 | FINAL

Building 283 - Squier Hall - Survey Unit 01 Locations





USACE
New York District

1st Floor Location - Location Name

2nd Floor Location - Location Name


Fort Monmouth
New Jersey


FIGURE A-2

Building 283 SU01
Locations

10 August 2012	FINAL

Building 283 - Squier Hall - Survey Unit 02 Locations





USACE
New York District

1st Floor Location - Location Name

2nd Floor Location - Location Name


Fort Monmouth
New Jersey

FIGURE A-3

Building 283 SU02
Locations

10 August 2012 | FINAL

Building 283 - Squier Hall - Basement Locations



USACE
New York District

Table Top - Location Name

Floor Location - Location Name


Fort Monmouth
New Jersey

FIGURE A-4

Building 283 Basement Locations

10 August 2012 | FINAL

Building 292 - Museum Storage Building - Sample Locations



USACE
New York District

\# Floor Sample Location

Floor Scanning Locations


Fort Monmouth
New Jersey

FIGURE A-5

Building 292 SU01
Locations

10 August 2012 | FINAL

Building 2540 - Survey Unit 01, 02 and 03 Locations



USACE
New York District

(#) Wall Location - Location Name


Floor Location - Location Name

Fort Monmouth
New Jersey

FIGURE A-6
Building 2540 SU01, 02 and 03 Locations

10 August 2012 | FINAL

Building 2540 - Survey Unit 04 and 05 Locations



USACE
New York District

Wall Location - Location Name

Floor Location - Location Name


Fort Monmouth
New Jersey

FIGURE A-7

Building 2540 SU04 and 05 Locations

10 August 2012 | FINAL

Building 2540 - Survey Unit 06 and 07 SOR Data



USACE
New York District

(#) Wall Location - Location Name

Floor Location - Location Name

Fort Monmouth
New Jersey


FIGURE A-8

Building 2540 SU06 and 07 Locations


10 August 2012 | FINAL

Building 2540 - Survey Unit 08 and 09 Locations

SU08



SU09



USACE
New York District

\# Top Map - SU08 Floor Location Names

\# Bottom Map - SU09 Wall Location Name


Fort Monmouth
New Jersey

FIGURE A-9

Building 2540 SU08 and 09 Locations

10 August 2012 | FINAL

Building 2540 - Survey Unit 10 and 11 Locations



USACE
New York District

(#) Wall Location - Location Name

Floor Location - Location Name


Fort Monmouth
New Jersey

FIGURE A-10

Building 2540 SU10 and 11 Locations

10 August 2012 | FINAL

Building 2540 - Survey Unit 12 and 13 Locations



USACE
New York District

Wall Location - Location Name

Floor Location - Location Name


Fort Monmouth
New Jersey

FIGURE A-11

Building 2540 SU12 and 13 Locations

10 August 2012 | FINAL

Building 2540 - Survey Unit 14 Locations



USACE
New York District

Wall Location - Location Name

Floor Location - Location Name


Fort Monmouth
New Jersey

FIGURE A-12

Building 2540 SU14
Locations

10 August 2012 | FINAL

Building 2540 - Survey Unit 15 Locations



USACE
New York District

Floor Location - Location Name


Fort Monmouth
New Jersey

FIGURE A-13

Building 2540 SU15
Locations

10 August 2012 | FINAL

Building 2541 - Survey Unit 01 and 02 Locations



USACE
New York District

(#) Wall Location - Location Name

Floor Location - Location Name

Fort Monmouth
New Jersey

FIGURE A-14


Building 2541 SU01 and 02 Locations

10 August 2012 | FINAL

APPENDIX B

Posting Plots of SOR Results

Building 275 - Museum SOR Data



SOR Value

1.0
0.9
0.8
0.7
0.6
0.5
0.4
0.3
0.2
0.1
0.0

USACE
New York District

Note:

Color SOR contours based on kriging of floor data

(#) Wall Location - Sum of the Ratios Value

Floor Location - Sum of the Ratios Value


Fort Monmouth
New Jersey


FIGURE B-1

Building 275 SU01
SOR Data

10 August 2012 | FINAL

Building 283 - Squier Hall - Survey Unit 01 SOR Results





USACE
New York District

1st Floor Location - Sum of the Ratios Value

2nd Floor Location - Sum of the Ratios Value


Fort Monmouth
New Jersey


FIGURE B-2

Building 283 SU01
SOR Data

10 August 2012 | FINAL

Building 283 - Squier Hall - Survey Unit 02 SOR Results





USACE
New York District

1st Floor Location - Sum of the Ratios Value

2nd Floor Location - Sum of the Ratios Value


Fort Monmouth
New Jersey

FIGURE B-3

Building 283 SU02
SOR Data

10 August 2012 | FINAL

Building 283 - Squier Hall - Basement SOR Data



USACE
New York District

(#) Table Top - Sum of the Ratios Value

Floor Location - Sum of the Ratios Value


Fort Monmouth
New Jersey

FIGURE B-4

Building 283 Basement
SOR Data

10 August 2012 | FINAL

Building 292 - Museum Storage Building - SOR Data



USACE
New York District

Sum of the Ratios Value


Fort Monmouth
New Jersey

FIGURE B-5

Building 292 SU01
SOR Data

10 August 2012 | FINAL

Building 2540 - Survey Unit 01, 02 and 03 SOR Data



USACE
New York District

Note:

Color SOR contours based on kriging of floor data

(#) Wall Location - Sum of the Ratios Value


Floor Location - Sum of the Ratios Value

Fort Monmouth
New Jersey

FIGURE B-6
Building 2540 SU01, 02 and 03
SOR Data

10 August 2012 | FINAL

Building 2540 - Survey Unit 04 and 05 SOR Data



USACE
New York District

Note:

Color SOR contours based on kriging of floor data

(#) Wall Location - Sum of the Ratios Value

Floor Location - Sum of the Ratios Value


Fort Monmouth
New Jersey

FIGURE B-7

Building 2540 SU04 and 05 SOR Data

10 August 2012 | FINAL

Building 2540 - Survey Unit 06 and 07 SOR Data



USACE
New York District

Note:

Color SOR contours based on kriging of floor data

(#) Wall Location - Sum of the Ratios Value

Floor Location - Sum of the Ratios Value

Fort Monmouth
New Jersey


FIGURE B-8

Building 2540 SU06 and 07 SOR Data

10 August 2012 | FINAL

Building 2540 - Survey Unit 08 and 09 SOR Data

SU08



SU09



USACE
New York District

Note:

Color SOR contours based on kriging of floor data

Top Map - SU08 Floor SOR Values

Bottom Map - SU09 Wall SOR Values


Fort Monmouth
New Jersey

FIGURE B-9

Building 2540 SU08 and 09 SOR Data

10 August 2012 | FINAL

Building 2540 - Survey Unit 10 and 11 SOR Data



SOR Value

1.00
0.90
0.80
0.70
0.60
0.50
0.40
0.30
0.20
0.10
0.00

USACE
New York District

Note:

Color SOR contours based on kriging of floor data

(#) Wall Location - Sum of the Ratios Value

Floor Location - Sum of the Ratios Value


Fort Monmouth
New Jersey

FIGURE B-10

Building 2540 SU10 and 11 SOR Data

10 August 2012 | FINAL

Building 2540 - Survey Unit 12 and 13 SOR Data



USACE
New York District

Note:

Color SOR contours based on kriging of floor data

(#) Wall Location - Sum of the Ratios Value

Floor Location - Sum of the Ratios Value


Fort Monmouth
New Jersey

FIGURE B-11

Building 2540 SU12 and 13 SOR Data

10 August 2012 | FINAL

Building 2540 - Survey Unit 14 SOR Data



SOR Value

1.0
0.9
0.8
0.7
0.6
0.5
0.4
0.3
0.2
0.1
0.0

USACE
New York District

Note:

Color SOR contours based on kriging of floor data

(#) Wall Location - Sum of the Ratios Value

Floor Location - Sum of the Ratios Value


Fort Monmouth
New Jersey


FIGURE B-12

Building 2540 SU14
SOR Data

10 August 2012 | FINAL

Building 2540 - Survey Unit 15 SOR Data





USACE
New York District

\# Floor Location - SOR Data


Fort Monmouth
New Jersey

FIGURE B-13

Building 2540 SU15
Locations

10 August 2012 | FINAL

Building 2541 - Survey Unit 01 and 02 SOR Data



USACE
New York District

Note:

Color SOR contours based on kriging of floor data

(#) Wall Location - Sum of the Ratios Value

Floor Location - Sum of the Ratios Value

Fort Monmouth
New Jersey

FIGURE B-14

Building 2541 SU01 and 02 SOR Data

10 August 2012 | FINAL

APPENDIX C

Survey Unit Data and SOR Results

Building 275, Survey Unit 01

α Limit (dpm/100cm^2) 315 β Limit (dpm/100cm2) 7100 Low Energy β Limit (dpm/100cm2) 21000

Location ID	SU Coordinates			Surface Type	Count Time (min)	Exposure Rate(uR/hr)	Measurement Result (cpm)		Background (cpm)		Net Radioactivity (dpm/100 cm2)		Low Energy Beta (dpm/100 cm2)	SOR
	x	y	z				Alpha	Beta	Alpha	Beta	Alpha	Beta		
1	35.2848	44.319	0	Carpet	1	7	3	387	*1*	*477*	3.49	-169.35	1.15	0.011
2	16.245	11.9796	0	Carpet	1	14	0	511	*1*	*477*	-1.75	63.98	-0.251	0.009
3	51.3145	35.5062	1.8207	Wood Pannel	1	12	6	763	*1*	*477*	8.74	538.16	0.0386	0.104
4	37.9906	63.4911	0	Carpet	1	8	0	399	*1*	*477*	-1.75	-146.77	-1.89	0.000
5	41.7122	76.5814	0	Carpet	1	6	5	417	*1*	*477*	6.99	-112.90	-1.35	0.022
6	42.2844	108.9449	0	Laminate Tile	1	8	5	488	2.6	270	4.12	410.88	0.867	0.071
7	48.6127	11.0747	0	Carpet	1	10	6	487	*1*	*477*	8.74	18.82	1.68	0.030
8	17.263	90.6403	0	Carpet	1	8	4	421	*1*	*477*	5.24	-105.37	0.579	0.017
9	6.5321	98.0095	3.5371	Drywall	1	11	6	589	*1*	*477*	8.74	210.75	3.62	0.057
10	-0.498	2.6797	5.4338	Drywall	1	12	6	724	*1*	*477*	8.74	464.77	3.34	0.093
11	35.4755	-0.0434	5.1296	Drywall	1	11	6	795	*1*	*477*	8.74	598.37	1.41	0.112
12	-0.448	83.2243	4.7945	Wood Pannel	1	8	4	602	*1*	*477*	5.24	235.21	2.27	0.050
13	2.2819	84.1178	0	Carpet	1	8	4	486	*1*	*477*	5.24	16.94	0.85	0.019
14	20.8092	5.4757	0	Carpet	1	9	1	541	*1*	*477*	0.00	120.43	1.14	0.017
15	18.8128	70.7329	0	Carpet	1	6	4	488	*1*	*477*	5.24	20.70	4.46	0.020
16	37.1345	40.6418	0	Carpet	1	8	1	536	*1*	*477*	0.00	111.02	5.88	0.016
17	38.9531	25.6085	0	Carpet	1	12	1	508	*1*	*477*	0.00	58.33	1.97	0.008
18	50.2479	69.4282	0	Carpet	1	12	6	502	*1*	*477*	8.74	47.04	5.02	0.034
19	34.6738	63.7019	0	Carpet	1	7	4	462	*1*	*477*	5.24	-28.23	-4.25	0.017
20	46.8336	0.6503	0	Carpet	1	12	8	521	*1*	*477*	12.23	82.79	3.34	0.050
21	13.4203	54.6505	0	Carpet	1	7	2	513	*1*	*477*	1.75	67.74	4.47	0.015
22	39.4621	6.0507	0	Carpet	1	10	4	587	*1*	*477*	5.24	206.98	0.581	0.046
23	7.7776	34.8609	0	Carpet	1	8	3	538	*1*	*477*	3.49	114.78	1.98	0.027
24	8.4259	24.2226	0	Carpet	1	10	1	584	*1*	*477*	0.00	201.34	1.72	0.028
25	51.3313	28.8789	0.9171	Wood Pannel	1	10	2	542	*1*	*477*	1.75	122.31	-2.45	0.023
26	24.1504	113.5012	0	Carpet	1	10	6	576	*1*	*477*	8.74	186.29	5	0.054
27	20.6943	100.3047	0	Carpet	1	9	0	517	*1*	*477*	-1.75	75.27	-2.45	0.011
28	21.491	95.4036	0	Carpet	1	8	5	495	*1*	*477*	6.99	33.87	1.41	0.027
29	21.8533	15.5561	0	Carpet	1	10	3	597	*1*	*477*	3.49	225.80	2.78	0.043
30	-0.4597	64.3799	4.8568	Wood Pannel	1	10	7	779	*1*	*477*	10.48	568.27	-3.56	0.113
										Min (non-biased)	-1.75	-169	-4.25	0.00
										Max (non-biased)	12.23	598	5.88	0.11
										Average (non-biased)	4.74	141	1.31	0.04
										Standard Deviation (non-biased)	3.95	202	2.57	0.03

Building 283, Survey Unit 01

α Limit (dpm/100cm^2) 315 β Limit (dpm/100cm2) 7100 Low Energy β Limit (dpm/100cm2) 21000

Location ID	SU Coordinates			Surface Type	Count Time (min)	Exposure Rate(uR/hr)	Measurement Result (cpm)		Background (cpm)		Net Radioactivity (dpm/100 cm2)		Low Energy Beta (dpm/100 cm2)	SOR
	x	y	z				Alpha	Beta	Alpha	Beta	Alpha	Beta		
1	114.9	2.4	0	Carpet	1	12	4	584	*1.0*	*517.0*	5.2	126	4.12	0.035
2	155.1	34.8	0	Carpet	1	12	2	637	*1.0*	*517.0*	1.7	226	3.56	0.038
3	22.5	144.9	0	Carpet	1	9	3	528	*1.0*	*517.0*	3.5	21	0.252	0.014
4	133.8	274.7	0	Laminate Tile	1	4	13	516	8.6	404.4	7.8	210	1.09	0.054
5	8.5	31.9	0	Carpet	1	11	1	579	*1.0*	*517.0*	0.0	117	2.2	0.017
6	137.6	165.6	0	Carpet	1	5	10	432	*2.0*	*639.0*	14.3	-390	-0.85	0.045
7	37.1	63.7	0	Ceramic Tile	1	14	8	756	11.6	1026.0	-6.2	-508	-0.309	0.000
8	145.1	40.0	0	Carpet	1	12	2	597	*1.0*	*517.0*	1.7	151	2.18	0.027
9	174.3	234.7	0	Laminate Tile	1	4	15	513	8.6	404.4	11.3	204	-0.579	0.065
10	164.2	36.6	0	Carpet	1	10	7	576	*1.0*	*517.0*	10.5	111	-2.24	0.049
11	0.0	251.4	3.0793	Drywall	1	10	9	777	*1.0*	*517.0*	14.0	489	-1.14	0.113
12	115.2	175.0	0	Carpet	1	4	26	444	*2.0*	*639.0*	42.8	-367	1.35	0.136
13	0.0	10.5	1.4661	Drywall	1	10	4	643	*1.0*	*517.0*	5.2	237	1.11	0.050
14	218.0	69.9	4.8896	Drywall	1	15	9	850	*1.0*	*517.0*	14.0	627	2.47	0.133
15	55.0	15.3	0	Carpet	1	8	1	540	*1.0*	*517.0*	0.0	43	2.45	0.006
16	174.9	144.1	0.1268	Drywall	1	4	16	659	*2.0*	*639.0*	25.0	38	3.01	0.085
17	180.9	214.9	0	Carpet	1	4	8	574	*2.0*	*639.0*	10.7	-122	4.66	0.034
18	70.5	197.4	0	Carpet	1	5	16	463	*2.0*	*639.0*	25.0	-331	0.791	0.079
19	4.7	59.8	0	Carpet	1	10	3	562	*1.0*	*517.0*	3.5	85	4.71	0.023
20	157.3	291.2	0.764	Concrete Block	1	5	16	655	8.9	555.2	12.6	188	2.18	0.067
21	162.1	239.2	0	Laminate Tile	1	4	17	493	8.6	404.4	14.9	167	-1.7	0.071
22	258.0	35.0	0	Laminate Tile	1	10	5	557	2.6	269.6	4.1	541	3.01	0.089
23	25.9	259.3	0	Carpet	1	9	5	523	*1.0*	*517.0*	7.0	11	2.73	0.024
24	263.5	0.3	2.2342	Wood Wall	1	14	3	634	*1.0*	*517.0*	3.5	220	1.08	0.042
25	162.2	173.4	0	Carpet	1	4	15	476	*2.0*	*639.0*	23.2	-307	4.66	0.074
26	193.2	35.0	0	Carpet	1	10	15	598	*2.0*	*639.0*	23.2	-77	7.42	0.074
27	49.8	54.3	0	Laminate Tile	1	5	19	796	8.6	404.4	18.5	737	4.38	0.163
28	157.8	3.2	0	Carpet	1	9	11	584	*2.0*	*639.0*	16.1	-103	2.2	0.051
29	37.7	228.6	0	Laminate Tile	1	6	20	538	8.6	404.4	20.3	251	-2.56	0.100
30	7.1	23.7	0	Carpet	1	8	11	565	*2.0*	*639.0*	16.1	-139	5.8	0.051
Radio Room - Floor 1 (5')	4.0	5.0	0	Poured Concrete	1	6	11	559	4.2	344.4	11.9	404	1.35	0.095
Radio Room - Floor 2 (10')	4.0	10.0	0	Poured Concrete	1	6	11	510	4.2	344.4	11.9	312	1.64	0.082
Radio Room - Floor 3 (15')	4.0	15.0	0	Poured Concrete	1	6	14	562	4.2	344.4	17.1	409	2.04	0.112
Radio Room - Floor 4 (20')	4.0	20.0	0	Poured Concrete	1	6	10	551	4.2	344.4	10.1	389	3.55	0.087
Radio Room - Table Top 1	7.0	5.0	-	Wood	1	6	14	360	*3.0*	*429.0*	19.2	-130	1.89	0.061
Radio Room - Table Top 2	7.0	10.0	-	Wood	1	6	16	366	*3.0*	*429.0*	22.7	-119	3.27	0.072
Bathroom 1 - Main Stairs	-	-	-	Ceramic Tile	1	13	13	999	17.7	1275.3	-8.4	-520	1.94	0.000
Bathroom 2 - 2nd Floor WW	-	-	-	Granite Tile	1	15	19	769	*3.0*	*429.0*	28.5	640	2.72	0.181
Bathroom 3 - 1st Floor WW	-	-	-	Granite Tile	1	15	15	726	*3.0*	*429.0*	21.4	559	-2.58	0.147
Bathroom 4 - RM 129	-	-	-	Poured Concrete	1	5	20	394	8.6	467.0	20.3	-137	2.83	0.064
										Min (non-biased)	-6.2	-508	-2.56	0.000
										Max (non-biased)	42.8	737	7.42	0.163
										Average (non-biased)	42.8	82	1.93	0.060
										Standard Deviation (non-biased)	42.8	294	2.43	0.040

Building 283, Survey Unit 02

α Limit (dpm/100cm^2) 315 β Limit (dpm/100cm2) 7100 Low Energy β Limit (dpm/100cm2) 21000

Location ID	SU Coordinates			Surface Type	Count Time (min)	Exposure Rate(uR/hr)	Measurement Result (cpm)		Background (cpm)		Net Radioactivity (dpm/100 cm2)		Low Energy Beta (dpm/100 cm2)	SOR
	x	y	z				Alpha	Beta	Alpha	Beta	Alpha	Beta		
1	114.9	2.4	0	Mastic	1	10	11	853	*2*	*639*	16.1	402.7	2.2	0.108
2	155.1	34.8	0	Mastic	1	14	20	859	*2*	*639*	32.1	414.0	-2.52	0.160
3	22.5	144.9	0	Mastic	1	9	23	800	*2*	*639*	37.5	303.0	-0.83	0.162
4	-	-	-	-	-	-	-	-	-	-	-	-	-	-
5	8.5	31.9	0	Mastic	1	11	29	870	*2*	*639*	48.2	434.7	-0.562	0.214
6	137.6	165.6	0	Mastic	1	4	18	571	*2*	*639*	28.5	-128.0	1.66	0.091
7	-	-	-	-	-	-	-	-	-	-	-	-	-	-
8	145.1	40.0	0	Mastic	1	10	19	819	*2*	*639*	30.3	338.7	-3.32	0.144
9	-	-	-	-	-	-	-	-	-	-	-	-	-	-
10	164.2	36.6	0	Mastic	1	12	17	852	*2*	*639*	26.8	400.8	4.76	0.142
11	-	-	-	-	-	-	-	-	-	-	-	-	-	-
12	115.2	175.0	0	Mastic	1	4	25	506	*2*	*639*	41.0	-250.3	3.88	0.130
13	-	-	-	-	-	-	-	-	-	-	-	-	-	-
14	-	-	-	-	-	-	-	-	-	-	-	-	-	-
15	55.0	15.3	0	Mastic	1	12	29	965	*2*	*639*	48.2	613.4	-2.76	0.239
16	-	-	-	-	-	-	-	-	-	-	-	-	-	-
17	180.9	214.9	0	Mastic	1	6	21	641	*2*	*639*	33.9	3.8	2.76	0.108
18	70.5	197.4	0	Mastic	1	6	30	584	*2*	*639*	49.9	-103.5	0	0.159
19	4.7	59.8	0	Mastic	1	10	17	894	*1*	*517*	28.5	709.4	-2.77	0.191
20	-	-	-	-	-	-	-	-	-	-	-	-	-	-
21	-	-	-	-	-	-	-	-	-	-	-	-	-	-
22	-	-	-	-	-	-	-	-	-	-	-	-	-	-
23	25.9	259.3	0	Mastic	1	10	22	806	*2*	*639*	34.9	314.2	-7.61	0.155
24	-	-	-	-	-	-	-	-	-	-	-	-	-	-
25	162.2	173.4	0	Mastic	1	5	16	615	*2*	*639*	25.0	-45.2	1.93	0.079
26	193.2	35.0	0	Mastic	1	11	17	836	*2*	*639*	26.8	370.7	5.51	0.137
27	-	-	-	-	-	-	-	-	-	-	-	-	-	-
28	157.8	3.2	0	Mastic	1	10	13	643	*2*	*639*	19.6	7.5	-0.27	0.063
29	-	-	-	-	-	-	-	-	-	-	-	-	-	-
30	7.1	23.7	0	Mastic	1	9	11	642	*2*	*639*	16.1	5.6	-1.66	0.052
Bias 1	-	-	-	-	-	-	-	-	-	-	-	-	-	-
Bias 2	-	-	-	-	-	-	-	-	-	-	-	-	-	-
										Min (non-biased)	16.1	-250	-7.61	0.052
										Max (non-biased)	49.9	709	5.51	0.239
										Average (non-biased)	32.0	223	0.02	0.137
										Standard Deviation (non-biased)	10.5	280	3.37	0.051

Building 292, Survey Unit 01

α Limit (dpm/100cm^2) 315 β Limit (dpm/100cm2) 7100 Low Energy β Limit (dpm/100cm2) 21000

Location ID	SU Coordinates			Surface Type	Count Time (min)	Exposure Rate(uR/hr)	Measurement Result (cpm)		Background (cpm)		Net Radioactivity (dpm/100 cm2)		Low Energy Beta (dpm/100 cm2)	SOR
	x	y	z				Alpha	Beta	Alpha	Beta	Alpha	Beta		
1	190.1	113.4	2.9	Concrete Block	1	5	9	430	2.5	459.4	11.36	-55	1.68	0.036
2	116.0	46.3	0.0	Poured Concrete	1	4	13	607	4.2	344.4	15.35	494	0.849	0.118
3	134.8	90.1	0.0	Poured Concrete	1	5	6	624	4.2	344.4	3.12	526	-1.65	0.084
4	75.9	77.2	0.0	Poured Concrete	1	5	5	603	4.2	344.4	1.37	487	-1.63	0.073
5	64.3	80.9	0.0	Carpet	1	5	6	479	*2.0*	*379.0*	6.99	188	2.24	0.049
6	173.6	89.6	0.0	Poured Concrete	1	5	13	648	4.2	344.4	15.35	571	2.79	0.129
7	161.2	53.9	0.0	Poured Concrete	1	5	5	515	4.2	344.4	1.37	321	4.29	0.050
8	223.5	31.5	0.0	Carpet	1	6	8	679	*2.0*	*379.0*	10.48	565	4.23	0.113
9	79.7	38.3	0.0	Poured Concrete	1	3	7	446	4.2	344.4	4.87	191	3.57	0.043
10	44.8	72.4	0.0	Carpet	1	4	8	445	*2.0*	*379.0*	10.48	124	1.89	0.051
11	84.8	19.3	0.0	Laminate Tile	1	5	9	629	2.6	269.6	11.11	676	3.01	0.131
12	133.6	31.5	0.0	Poured Concrete	1	4	5	520	4.2	344.4	1.37	330	-1.41	0.051
13	96.2	1.1	0.0	Laminate Tile	1	5	5	621	2.6	269.6	4.12	661	2.72	0.106
14	20.8	106.0	0.0	Laminate Tile	1	6	13	522	2.6	269.6	18.10	475	0.797	0.124
15	138.3	81.9	0.0	Poured Concrete	1	4	3	724	4.2	344.4	-2.12	714	5.5	0.101
16	157.9	72.3	1.6	Poured Concrete	1	4	8	473	4.2	344.4	6.61	242	-1.15	0.055
17	18.9	95.7	0.0	Drywall	1	7	8	516	*2.0*	*379.0*	10.48	258	0.522	0.070
18	57.5	101.4	0.0	Carpet	1	5	2	488	*2.0*	*379.0*	0.00	205	1.9	0.029
19	140.2	14.4	0.0	Laminate Tile	1	4	11	637	2.6	269.6	14.60	691	-1.14	0.144
20	74.1	22.9	0.0	Laminate Tile	1	4	2	513	2.6	269.6	-1.12	458	-1.41	0.064
21	194.9	93.6	0.0	Poured Concrete	1	6	15	638	4.2	344.4	18.85	552	2.53	0.138
22	52.1	25.0	0.0	Carpet	1	5	9	638	*2.0*	*379.0*	12.23	487	2.46	0.108
23	115.4	56.5	0.0	Poured Concrete	1	5	15	551	4.2	344.4	18.85	389	1.63	0.115
24	138.1	92.5	0.0	Poured Concrete	1	4	8	606	4.2	344.4	6.61	492	-0.583	0.090
25	151.6	56.1	0.0	Poured Concrete	1	5	8	535	4.2	344.4	6.61	359	2.75	0.072
26	134.6	75.6	0.0	Poured Concrete	1	4	16	595	4.2	344.4	20.59	471	4.2	0.132
27	187.6	33.6	0.0	Laminate Tile	1	4	4	445	2.6	269.6	2.37	330	-1.98	0.054
28	98.2	40.6	0.0	Poured Concrete	1	4	3	520	4.2	344.4	-2.12	330	0.818	0.047
29	84.5	102.7	0.0	Carpet	1	4	6	643	*2.0*	*379.0*	6.99	497	5.21	0.092
30	80.4	4.9	0.0	Laminate Tile	1	6	8	478	2.6	269.6	9.36	392	4.39	0.085
										Min (non-biased)	-2.12	-55	-1.98	0.029
										Max (non-biased)	20.59	714	5.50	0.144
										Average (non-biased)	8.14	414	1.63	0.085
										Standard Deviation (non-biased)	6.64	181	2.23	0.035

Building 2540, Survey Unit 01

α Limit (dpm/100cm^2) 315 β Limit (dpm/100cm2) 7100 Low Energy β Limit (dpm/100cm2) 21000

Location ID	SU Coordinates			Surface Type	Count Time (min)	Exposure Rate(uR/hr)	Measurement Result (cpm)		Background (cpm)		Net Radioactivity (dpm/100 cm2)		Low Energy Beta (dpm/100 cm2)	SOR
	x	y	z				Alpha	Beta	Alpha	Beta	Alpha	Beta		
1	0.1481	2.1204	0	Laminate Tile	1	14	17	1031	2.64	270	25.09	1433	5.61	0.282
2	5.6047	2.1204	0	Laminate Tile	1	16	21	1024	2.64	270	32.07	1419	-0.02	0.302
3	11.0614	2.1204	0	Laminate Tile	1	15	17	945	2.64	270	25.09	1271	-0.87	0.259
4	16.518	2.1204	0	Laminate Tile	1	15	13	907	2.64	270	18.10	1199	3.90	0.227
5	21.9747	2.1204	0	Laminate Tile	1	14	20	1146	2.64	270	30.33	1649	0.26	0.329
6	2.8764	6.846	0	Laminate Tile	1	16	13	982	2.64	270	18.10	1340	1.35	0.246
7	8.333	6.846	0	Laminate Tile	1	15	25	955	2.64	270	39.06	1290	3.57	0.306
8	13.7897	6.846	0	Laminate Tile	1	13	16	976	2.64	270	23.34	1329	1.91	0.261
9	19.2463	6.846	0	Laminate Tile	1	15	17	1023	2.64	270	25.09	1418	-4.17	0.279
10	0.1481	11.5716	0	Laminate Tile	1	15	17	975	2.64	270	25.09	1327	0.79	0.267
11	5.6047	11.5716	0	Laminate Tile	1	11	12	959	2.64	270	16.35	1297	1.35	0.235
12	11.0614	11.5716	0	Laminate Tile	1	14	24	1001	2.64	270	37.32	1376	0.81	0.312
13	16.518	11.5716	0	Laminate Tile	1	13	21	946	2.64	270	32.07	1273	1.92	0.281
14	21.9747	11.5716	0	Laminate Tile	1	15	17	1016	2.64	270	25.09	1404	1.40	0.278
15	2.8764	16.2972	0	Laminate Tile	1	16	22	946	2.64	270	33.82	1273	-4.23	0.287
16	8.333	16.2972	0	Laminate Tile	1	15	19	912	2.64	270	28.58	1209	-0.02	0.261
17	13.7897	16.2972	0	Laminate Tile	1	12	21	988	2.64	270	32.07	1352	1.92	0.292
18	19.2463	16.2972	0	Laminate Tile	1	15	17	1080	8.64	404	14.91	1271	-1.71	0.226
19	0.1481	21.0228	0	Laminate Tile	1	13	24	900	8.64	404	27.39	933	0.53	0.218
20	5.6047	21.0228	0	Laminate Tile	1	14	17	947	8.64	404	14.91	1021	0.80	0.191
21	11.0614	21.0228	0	Laminate Tile	1	14	23	956	8.64	404	25.61	1038	2.73	0.228
22	16.518	21.0228	0	Laminate Tile	1	14	27	893	8.64	404	32.74	919	-0.02	0.233
23	21.9747	21.0228	0	Laminate Tile	1	14	21	1087	8.64	404	22.04	1285	-0.60	0.251
24	2.8764	25.7484	0	Laminate Tile	1	13	24	904	8.64	404	27.39	940	6.77	0.220
25	8.333	25.7484	0	Laminate Tile	1	14	27	820	8.64	404	32.74	782	1.35	0.214
26	13.7897	25.7484	0	Laminate Tile	1	12	26	790	8.64	404	30.96	726	-0.31	0.200
27	19.2463	25.7484	0	Laminate Tile	1	10	17	983	8.64	404	14.91	1089	-0.02	0.201
28	0.1481	30.474	0	Laminate Tile	1	13	18	810	8.64	404	16.69	763	1.35	0.161
29	5.6047	30.474	0	Laminate Tile	1	12	21	828	8.64	404	22.04	797	1.08	0.182
30	11.0614	30.474	0	Laminate Tile	1	10	19	800	8.64	404	18.47	744	2.22	0.164
31	16.518	30.474	0	Laminate Tile	1	11	16	820	8.64	404	13.12	782	-0.86	0.152
32	21.9747	30.474	0	Laminate Tile	1	12	16	935	8.64	404	13.12	999	-2.51	0.182
Bias-1	0.1481	23.0228	0	Laminate Tile	1	12	35	979	8.64	404	47.01	1081	0.54	0.302
										Min (non-biased)	13.12	726	-4.23	0.152
										Max (non-biased)	39.06	1649	6.77	0.329
										Average (non-biased)	24.80	1155	0.82	0.241
										Standard Deviation (non-biased)	7.35	250	2.32	0.047

Building 2540, Survey Unit 02

α Limit (dpm/100cm^2) 315 β Limit (dpm/100cm2) 7100 Low Energy β Limit (dpm/100cm2) 21000

Location ID	SU Coordinates			Surface Type	Count Time (min)	Exposure Rate(uR/hr)	Measurement Result (cpm)		Background (cpm)		Net Radioactivity (dpm/100 cm2)		Low Energy Beta (dpm/100 cm2)	SOR
	x	y	z				Alpha	Beta	Alpha	Beta	Alpha	Beta		
1	27.4	2.1	0	Laminate Tile	1	16	41	1199	2.64	270	67.0	1749	0.80	0.459
2	32.9	2.1	0	Laminate Tile	1	19	37	1179	2.64	270	60.0	1711	-0.02	0.432
3	38.3	2.1	0	Laminate Tile	1	15	39	1139	2.64	270	63.5	1636	2.22	0.432
4	24.7	6.8	0	Laminate Tile	1	16	40	1091	2.64	270	65.3	1546	6.12	0.425
5	30.2	6.8	0	Laminate Tile	1	15	22	1126	2.64	270	33.8	1611	-0.52	0.334
6	35.6	6.8	0	Laminate Tile	1	14	38	1081	2.64	270	61.8	1527	3.82	0.411
7	27.4	11.6	0	Laminate Tile	1	15	34	1070	2.64	270	54.8	1506	-6.71	0.386
8	32.9	11.6	0	Laminate Tile	1	16	32	1072	2.64	270	51.3	1510	-1.67	0.375
9	38.3	11.6	0	Laminate Tile	1	15	38	1094	2.64	270	61.8	1551	-0.26	0.415
10	24.7	16.3	0	Laminate Tile	1	12	33	1067	2.64	270	53.0	1500	4.18	0.380
11	30.2	16.3	0	Laminate Tile	1	14	42	1105	2.64	270	68.8	1572	-1.35	0.440
12	35.6	16.3	0	Laminate Tile	1	13	35	1120	2.64	270	56.5	1600	-1.63	0.405
13	27.4	21.0	0	Laminate Tile	1	14	35	1078	8.64	404	47.0	1268	2.80	0.328
14	32.9	21.0	0	Laminate Tile	1	14	26	1021	8.64	404	31.0	1160	-1.09	0.262
15	38.3	21.0	0	Laminate Tile	1	15	26	1059	8.64	404	31.0	1232	-0.81	0.272
16	24.7	25.7	0	Laminate Tile	1	14	37	1089	8.64	404	50.6	1288	2.79	0.342
17	30.2	25.7	0	Laminate Tile	1	16	29	1015	8.64	404	36.3	1149	-2.76	0.277
18	35.6	25.7	0	Laminate Tile	1	15	33	1029	8.64	404	43.4	1175	-2.72	0.303
19	27.4	30.5	0	Laminate Tile	1	15	33	999	8.64	404	43.4	1119	1.41	0.296
20	32.9	30.5	0	Laminate Tile	1	15	30	1081	8.64	404	38.1	1273	1.14	0.300
21	38.3	30.5	0	Laminate Tile	1	15	45	1008	8.64	404	64.8	1136	0.85	0.366
Bias 1	35.9	11.1	0	Laminate Tile	1	18	34	1026	8.64	404	45.2	1170	2.48	0.308
										Min (non-biased)	31.0	1119	-6.71	0.262
										Max (non-biased)	68.8	1749	6.12	0.459
										Average (non-biased)	51.6	1420	0.31	0.364
										Standard Deviation (non-biased)	12.4	208.3	2.85	0.062

Building 2540, Survey Unit 03

α Limit (dpm/100cm^2) 315 β Limit (dpm/100cm2) 7100 Low Energy β Limit (dpm/100cm2) 21000

Location ID	SU Coordinates			Surface Type	Count Time (min)	Exposure Rate(uR/hr)	Measurement Result (cpm)		Background (cpm)		Net Radioactivity (dpm/100 cm2)		Low Energy Beta (dpm/100 cm2)	SOR
	x	y	z				Alpha	Beta	Alpha	Beta	Alpha	Beta		
1	6.5	0.0	0.1	Poured Concrete	1	16	32	1031	4.21	344	48.5	1292	-0.81	0.336
2	13.1	0.0	0.1	Poured Concrete	1	14	34	1093	4.21	344	52.0	1409	1.41	0.364
3	19.7	0.0	0.1	Poured Concrete	1	20	35	1169	4.21	344	53.8	1552	-0.90	0.389
4	26.3	0.0	0.1	Poured Concrete	1	18	37	1127	4.21	344	57.3	1473	0.58	0.389
5	32.9	0.0	0.1	Poured Concrete	1	16	40	1005	4.21	344	62.5	1243	3.34	0.374
6	39.5	0.0	0.1	Poured Concrete	1	15	39	1011	4.21	344	60.8	1254	3.71	0.370
7	45.5	0.5	0.1	Poured Concrete	1	20	31	1004	4.21	344	46.8	1241	-3.12	0.323
8	45.5	7.1	0.1	Poured Concrete	1	14	24	985	4.21	344	34.6	1205	1.97	0.280
9	45.5	13.7	0.1	Poured Concrete	1	15	33	981	4.21	344	50.3	1198	-1.63	0.328
10	45.5	20.3	0.1	Poured Concrete	1	15	31	913	4.21	344	46.8	1070	1.14	0.299
11	45.5	26.9	0.1	Poured Concrete	1	15	27	818	4.21	344	39.8	891	-1.64	0.252
12	45.2	33.1	0.1	Poured Concrete	1	15	26	783	4.21	344	38.1	825	3.34	0.237
13	38.6	33.1	0.1	Poured Concrete	1	15	33	810	4.21	344	50.3	876	0.58	0.283
14	32.0	33.1	0.1	Poured Concrete	1	15	29	999	4.21	344	43.3	1232	-6.77	0.311
15	25.4	33.1	0.1	Poured Concrete	1	12	29	959	4.21	344	43.3	1156	-0.25	0.300
16	18.9	33.1	0.1	Poured Concrete	1	14	29	926	4.21	344	43.3	1094	-0.52	0.292
17	12.3	33.1	0.1	Poured Concrete	1	12	29	871	4.21	344	43.3	991	1.14	0.277
18	5.7	33.1	0.1	Poured Concrete	1	12	29	852	4.21	344	43.3	955	-0.84	0.272
19	0.0	32.2	0.1	Poured Concrete	1	11	36	862	4.21	344	55.5	974	1.14	0.314
20	0.0	25.6	0.1	Poured Concrete	1	15	39	910	4.21	344	60.8	1064	2.78	0.343
21	0.0	19.0	0.1	Poured Concrete	1	13	38	937	4.21	344	59.0	1115	0.58	0.344
22	0.0	12.5	0.1	Poured Concrete	1	14	48	950	4.21	344	76.5	1139	-0.79	0.403
23	0.0	5.9	0.1	Poured Concrete	1	16	38	992	4.21	344	59.0	1219	1.17	0.359
24	3.3	0.0	5.8	Poured Concrete	1	15	39	1017	8.64	467	54.1	1035	-1.90	0.318
25	9.8	0.0	5.8	Poured Concrete	1	12	38	931	8.64	467	52.4	873	-1.35	0.289
26	16.4	0.0	5.8	Poured Concrete	1	12	50	968	8.64	467	73.8	943	5.87	0.367
27	23.0	0.0	5.8	Poured Concrete	1	13	50	932	8.64	467	73.8	875	2.28	0.358
28	29.6	0.0	5.8	Poured Concrete	1	15	42	1037	8.64	467	59.5	1073	-0.53	0.340
29	36.2	0.0	5.8	Poured Concrete	1	15	54	1029	8.64	467	80.9	1058	1.15	0.406
30	42.7	0.0	5.8	Poured Concrete	1	17	51	1001	8.64	467	75.6	1005	1.49	0.381
31	45.5	3.8	5.8	Poured Concrete	1	16	50	1002	8.64	467	73.8	1007	-0.52	0.376
32	45.5	10.4	5.8	Poured Concrete	1	15	52	970	8.64	467	77.3	946	3.20	0.379
33	45.5	17.0	5.8	Poured Concrete	1	16	37	993	8.64	467	50.6	990	-1.68	0.300
34	45.5	23.6	5.8	Poured Concrete	1	15	46	1030	8.64	467	66.6	1059	1.43	0.361
35	45.5	30.1	5.8	Poured Concrete	1	15	40	1026	8.64	467	55.9	1052	-3.71	0.326
36	41.9	33.1	5.8	Poured Concrete	1	15	38	1033	8.64	467	52.4	1065	0.04	0.316
37	35.3	33.1	5.8	Poured Concrete	1	14	50	907	8.64	467	73.8	828	6.76	0.351
38	28.7	33.1	5.8	Poured Concrete	1	14	47	1025	8.64	467	68.4	1050	0.86	0.365
39	22.1	33.1	5.8	Poured Concrete	1	13	47	936	8.64	467	68.4	883	0.60	0.342
40	15.6	33.1	5.8	Poured Concrete	1	10	34	844	8.64	467	45.2	709	0.31	0.244
41	9.0	33.1	5.8	Poured Concrete	1	10	51	867	8.64	467	75.6	753	-0.53	0.346
42	2.4	33.1	5.8	Poured Concrete	1	12	47	855	8.64	467	68.4	730	4.19	0.320
43	0.0	28.9	5.8	Poured Concrete	1	15	46	991	8.64	467	66.6	986	-0.53	0.350

Building 2540, Survey Unit 03

α Limit (dpm/100cm^2) 315 β Limit (dpm/100cm2) 7100 Low Energy β Limit (dpm/100cm2) 21000

Location ID	SU Coordinates			Surface Type	Count Time (min)	Exposure Rate(uR/hr)	Measurement Result (cpm)		Background (cpm)		Net Radioactivity (dpm/100 cm2)		Low Energy Beta (dpm/100 cm2)	SOR
	x	y	z				Alpha	Beta	Alpha	Beta	Alpha	Beta		
44	0.0	22.3	5.8	Poured Concrete	1	14	43	932	8.64	467	61.3	875	-1.65	0.318
45	0.0	15.7	5.8	Poured Concrete	1	12	55	968	8.64	467	82.7	943	-1.94	0.395
46	0.0	9.2	5.8	Poured Concrete	1	16	43	1052	8.64	467	61.3	1101	1.47	0.350
47	0.0	2.6	5.8	Poured Concrete	1	14	49	942	8.64	467	72.0	894	8.68	0.355
Bias 1				Poured Concrete	1	14	35	917	8.64	467	47.0	847	-1.96	0.269
										Min (non-biased)	34.6	709	-6.77	0.237
										Max (non-biased)	82.7	1552	8.68	0.406
										Average (non-biased)	58.7	1047	0.63	0.334
										Standard Deviation (non-biased)	12.6	183	2.67	0.042

Building 2540, Survey Unit 04

α Limit (dpm/100cm^2) 315 β Limit (dpm/100cm2) 7100 Low Energy β Limit (dpm/100cm2) 21000

Location ID	SU Coordinates			Surface Type	Count Time (min)	Exposure Rate(uR/hr)	Measurement Result (cpm)		Background (cpm)		Net Radioactivity (dpm/100 cm2)		Low Energy Beta (dpm/100 cm2)	SOR
	x	y	z				Alpha	Beta	Alpha	Beta	Alpha	Beta		
1	1.6	3.4	0	Laminate Tile	1	14	6	967	8.64	404	-4.71	1059	2.65	0.149
2	6.9	3.4	0.0	Laminate Tile	1	14	10	947	8.64	404	2.42	1021	2.51	0.152
3	12.2	3.4	0.0	Laminate Tile	1	10	7	855	8.64	404	-2.93	848	0.44	0.119
4	17.5	3.4	0.0	Laminate Tile	1	9	5	761	8.64	404	-6.50	671	0.44	0.095
5	22.8	3.4	0.0	Laminate Tile	1	10	6	818	8.64	404	-4.71	778	3.20	0.110
6	28.1	3.4	0.0	Laminate Tile	1	8	14	759	8.64	404	9.56	667	2.64	0.124
7	9.5	8.0	0.0	Laminate Tile	1	11	11	822	8.64	404	4.20	786	4.30	0.124
8	14.8	8.0	0.0	Laminate Tile	1	8	8	853	8.64	404	-1.15	844	4.84	0.119
9	20.1	8.0	0.0	Laminate Tile	1	10	7	831	8.64	404	-2.93	803	6.76	0.113
10	25.4	8.0	0.0	Laminate Tile	1	10	6	819	8.64	404	-4.71	780	7.33	0.110
11	12.2	12.6	0.0	Laminate Tile	1	10	10	853	8.64	404	2.42	844	1.27	0.127
12	17.5	12.6	0.0	Laminate Tile	1	9	11	797	8.64	404	4.20	739	5.13	0.118
13	22.8	12.6	0.0	Laminate Tile	1	10	11	855	8.64	404	4.20	848	2.09	0.133
14	28.1	12.6	0.0	Laminate Tile	1	9	10	851	8.64	404	2.42	840	2.64	0.126
15	9.5	17.2	0.0	Laminate Tile	1	12	12	833	8.64	404	5.99	807	2.91	0.133
16	14.8	17.2	0.0	Laminate Tile	1	10	10	816	8.64	404	2.42	775	3.74	0.117
17	20.1	17.2	0.0	Laminate Tile	1	10	9	843	8.64	404	0.64	825	3.74	0.118
18	25.4	17.2	0.0	Laminate Tile	1	8	6	820	8.64	404	-4.71	782	3.20	0.110
19	12.2	21.8	0.0	Laminate Tile	1	10	12	829	8.64	404	5.99	799	2.91	0.132
20	17.5	21.8	0.0	Laminate Tile	1	10	10	860	8.64	404	2.42	857	0.98	0.128
21	22.8	21.8	0.0	Laminate Tile	1	9	7	827	8.64	404	-2.93	795	1.60	0.112
22	28.1	21.8	0.0	Laminate Tile	1	8	12	816	8.64	404	5.99	775	1.32	0.128
23	9.5	26.4	0.0	Laminate Tile	1	12	10	818	8.64	404	2.42	778	-0.33	0.117
24	14.8	26.4	0.0	Laminate Tile	1	9	9	852	8.64	404	0.64	842	-1.16	0.121
25	20.1	26.4	0.0	Laminate Tile	1	10	8	871	8.64	404	-1.15	878	4.07	0.124
26	25.4	26.4	0.0	Laminate Tile	1	9	7	812	8.64	404	-2.93	767	-3.35	0.108
27	12.2	31.0	0.0	Laminate Tile	1	10	14	824	8.64	404	9.56	790	3.53	0.142
28	17.5	31.0	0.0	Laminate Tile	1	10	8	857	8.64	404	-1.15	852	-1.99	0.120
29	22.8	31.0	0.0	Laminate Tile	1	9	8	853	8.64	404	-1.15	844	-5.29	0.119
30	28.1	31.0	0.0	Laminate Tile	1	8	18	836	8.64	404	16.69	812	7.09	0.168
Bias 1	13.2	28.0	0.0	Laminate Tile	1	10	8	825	8.64	404	-1.15	792	1.10	0.112
										Min (non-biased)	-6.50	667	-5.29	0.095
										Max (non-biased)	16.69	1059	7.33	0.168
										Average (non-biased)	1.35	817	2.31	0.124
										Standard Deviation (non-biased)	5.17	78.0	2.85	0.015

Building 2540, Survey Unit 05

α Limit (dpm/100cm^2) 315 β Limit (dpm/100cm2) 7100 Low Energy β Limit (dpm/100cm2) 21000

Location ID	SU Coordinates			Surface Type	Count Time (min)	Exposure Rate(uR/hr)	Measurement Result (cpm)		Background (cpm)		Net Radioactivity (dpm/100 cm2)		Low Energy Beta (dpm/100 cm2)	SOR
	x	y	z				Alpha	Beta	Alpha	Beta	Alpha	Beta		
1	6.3	0.0	0.2	Poured Concrete	1	15	7	921	4.21	344	4.87	1085	-2.54	0.168
2	13.0	0.0	0.2	Drywall	1	14	7	728	*6.00*	*749*	1.75	-40	-0.06	0.006
3	19.6	0.0	0.2	Metal	1	10	10	528	*6.00*	*749*	6.99	-416	0.50	0.022
4	26.3	0.0	0.2	Drywall	1	9	6	616	*6.00*	*749*	0.00	-250	-0.89	0.000
5	30.0	2.9	0.2	Drywall	1	10	4	607	*6.00*	*749*	-3.49	-267	-0.06	0.000
6	30.0	9.6	0.2	Drywall	1	9	4	552	*6.00*	*749*	-3.49	-371	-1.99	0.000
7	30.0	16.2	0.2	Drywall	1	10	6	692	*6.00*	*749*	0.00	-107	-0.06	0.000
8	30.0	22.9	0.2	Metal	1	8	0	569	*6.00*	*749*	-10.48	-339	2.15	0.000
9	30.0	29.5	0.2	Drywall	1	9	2	658	*6.00*	*749*	-6.99	-171	1.31	0.000
10	25.2	35.6	0.2	Metal	1	8	7	774	*6.00*	*749*	1.75	47	-1.72	0.012
11	18.5	35.6	0.2	Drywall	1	13	4	688	*6.00*	*749*	-3.49	-115	3.59	0.000
12	11.9	35.6	0.2	Drywall	1	12	2	686	*6.00*	*749*	-6.99	-119	6.28	0.000
13	8.3	28.3	0.2	Drywall	1	12	2	599	*6.00*	*749*	-6.99	-282	0.50	0.000
14	8.3	21.6	0.2	Drywall	1	10	3	708	*6.00*	*749*	-5.24	-77	-1.45	0.000
15	8.3	15.0	0.2	Drywall	1	11	2	695	*6.00*	*749*	-6.99	-102	2.46	0.000
16	8.3	8.3	0.2	Drywall	1	14	3	689	*6.00*	*749*	-5.24	-113	-4.48	0.000
17	8.2	2.5	0.2	Metal	1	12	6	630	*6.00*	*749*	0.00	-224	-2.26	0.000
18	0.0	3.3	0.2	Poured Concrete	1	13	7	964	4.21	344	4.87	1166	1.04	0.180
19	3.0	0.0	5.9	Poured Concrete	1	15	9	891	4.21	344	8.36	1028	-0.62	0.171
20	9.7	0.0	5.9	Drywall	1	11	3	685	*6.00*	*749*	-5.24	-120	-2.54	0.000
21	16.3	0.0	5.9	Drywall	1	10	7	670	*6.00*	*749*	1.75	-149	2.97	0.006
22	22.9	0.0	5.9	Drywall	1	7	5	444	*6.00*	*749*	-1.75	-574	-0.62	0.000
23	29.6	0.0	5.9	Drywall	1	10	3	658	*6.00*	*749*	-5.24	-171	0.21	0.000
24	30.0	6.2	5.9	Drywall	1	8	4	569	*6.00*	*749*	-3.49	-339	-5.03	0.000
25	30.0	12.9	5.9	Drywall	1	7	4	504	*6.00*	*749*	-3.49	-461	-0.89	0.000
26	30.0	19.5	5.9	Drywall	1	8	2	479	*6.00*	*749*	-6.99	-508	-4.63	0.000
27	30.0	26.2	5.9	Drywall	1	8	5	569	*6.00*	*749*	-1.75	-339	1.32	0.000
28	28.5	35.6	5.9	Drywall	1	10	3	673	*6.00*	*749*	-5.24	-143	-1.99	0.000
29	21.8	35.6	5.9	Drywall	1	8	3	694	*6.00*	*749*	-5.24	-103	0.50	0.000
30	15.2	35.6	5.9	Drywall	1	11	4	682	*6.00*	*749*	-3.49	-126	2.14	0.000
31	8.5	31.3	5.9	Drywall	1	11	3	686	*6.00*	*749*	-5.24	-119	-0.90	0.000
32	8.3	24.9	5.9	Drywall	1	11	1	670	*6.00*	*749*	-8.74	-149	-0.33	0.000
33	8.3	18.3	5.9	Drywall	1	10	7	651	*6.00*	*749*	1.75	-184	-1.72	0.006
34	8.3	11.7	5.9	Drywall	1	12	5	610	*6.00*	*749*	-1.75	-262	-0.75	0.000
35	8.5	2.5	5.9	Metal	1	10	9	668	*6.00*	*749*	5.24	-152	-9.19	0.017
36	8.5	34.2	5.9	Drywall	1	10	2	761	*6.00*	*749*	-6.99	23	-0.89	0.003
Bias 1	30.0	5.7	3.7	Drywall	1	7	2	620	*6.00*	*749*	-6.99	-243	1.93	0.000
											Min (non-biased)	-10.48	-574	-9.19	0.000
											Max (non-biased)	8.36	1166	6.28	0.180
											Average (non-biased)	-2.41	-98	-0.57	0.016
											Standard Deviation (non-biased)	4.63	391	2.72	0.048

Building 2540, Survey Unit 06

α Limit (dpm/100cm^2) 27 β Limit (dpm/100cm2) 7100 Low Energy β Limit (dpm/100cm2) 21000

Location ID	SU Coordinates			Surface Type	Count Time (min)	Exposure Rate(uR/hr)	Measurement Result (cpm)		Background (cpm)		Net Radioactivity (dpm/100 cm2)		Low Energy Beta (dpm/100 cm2)	SOR
	x	y	z				Alpha	Beta	Alpha	Beta	Alpha	Beta		
1	0.5	1.1	0.0	Carpet	5	10	9	670.4	*5.0*	*683*	6.99	-23	1.85	0.259
2	5.7	1.1	0.0	Carpet	5	7	8.2	727.2	*5.0*	*683*	5.59	84	6.36	0.219
3	11.0	1.1	0.0	Carpet	5	7	10.4	689.6	*5.0*	*683*	9.44	13	3.53	0.351
4	16.3	1.1	0.0	Laminate Tile	5	6	9.2	771	8.6	404	0.99	690	4.05	0.134
5	21.5	1.1	0.0	Laminate Tile	5	8	9.8	760.6	8.6	404	2.06	670	4.55	0.171
6	3.1	5.7	0.0	Carpet	5	10	11.6	735.2	*8.6*	*735*	5.35	0	4.31	0.198
7	8.4	5.7	0.0	Carpet	5	10	14.2	687	*8.6*	*735*	9.99	-90	0.58	0.370
8	13.6	5.7	0.0	Carpet	5	9	9.8	682.4	*8.6*	*735*	2.14	-99	3.00	0.079
9	18.9	5.7	0.0	Laminate Tile	5	8	11.6	737.8	8.6	404	5.27	627	3.12	0.284
10	0.5	10.2	0.0	Laminate Tile	5	7	9.6	949	8.6	404	1.71	1025	5.90	0.208
11	5.7	10.2	0.0	Laminate Tile	5	7	9.8	765.6	8.6	404	2.06	680	4.82	0.172
12	11.0	10.2	0.0	Laminate Tile	5	6	9.8	707.8	8.6	404	2.06	571	6.41	0.157
13	16.3	10.2	0.0	Laminate Tile	5	7	12.4	702.6	8.6	404	6.70	561	5.60	0.328
14	21.5	10.2	0.0	Laminate Tile	5	7	9	721.4	8.6	404	0.64	597	3.72	0.108
15	3.1	14.8	0.0	Laminate Tile	5	8	8.8	785.8	8.6	404	0.28	718	1.41	0.112
16	8.4	14.8	0.0	Laminate Tile	5	7	12	747.6	8.6	404	5.99	646	7.00	0.313
17	13.6	14.8	0.0	Laminate Tile	5	6	11	704.4	8.6	404	4.20	565	6.63	0.236
18	18.9	14.8	0.0	Laminate Tile	5	6	9.4	722.4	8.6	404	1.35	598	6.63	0.135
19	0.5	19.4	0.0	Laminate Tile	5	7	5	742.6	2.6	270	4.12	890	1.60	0.278
20	5.7	19.4	0.0	Laminate Tile	5	7	4.2	747	2.6	270	2.72	898	6.46	0.228
21	11.0	19.4	0.0	Laminate Tile	5	9	5.6	744	2.6	270	5.17	893	2.57	0.317
22	16.3	19.4	0.0	Laminate Tile	5	6	4.6	698.2	2.6	270	3.42	806	3.15	0.240
23	21.5	19.4	0.0	Laminate Tile	5	6	7.8	733.6	2.6	270	9.01	873	4.89	0.457
24	3.1	23.9	0.0	Laminate Tile	5	8	6.4	800.4	2.6	270	6.56	999	6.23	0.384
25	8.4	23.9	0.0	Laminate Tile	5	8	9	763.2	2.6	270	11.11	929	3.36	0.542
26	13.6	23.9	0.0	Laminate Tile	5	9	7	738.6	2.6	270	7.61	882	3.57	0.406
27	18.9	23.9	0.0	Laminate Tile	5	7	5.2	712.4	2.6	270	4.47	833	-0.14	0.283
28	0.5	28.5	0.0	Laminate Tile	5	8	6.6	797.4	2.6	270	6.91	993	3.72	0.396
29	5.7	28.5	0.0	Laminate Tile	5	8	7.6	787.8	2.6	270	8.66	975	3.23	0.458
30	11.0	28.5	0.0	Laminate Tile	5	9	12.6	767.8	8.6	404	7.06	684	3.92	0.358
31	16.3	28.5	0.0	Laminate Tile	5	7	4.6	701.2	2.6	270	3.42	812	3.72	0.241
32	21.5	28.5	0.0	Laminate Tile	5	6	7.6	731.4	2.6	270	8.66	869	4.01	0.443
Bias 1				Laminate Tile	5	8	9.8	777	8.6	404	2.06	701	-0.83	0.175
Bias 2				Laminate Tile	5	7	4.4	633.8	2.6	270	3.07	685	3.32	0.210
										Min (non-biased)	0.28	-99	-0.14	0.079
										Max (non-biased)	11.11	1025	7.00	0.542
										Average (non-biased)	4.99	616	4.07	0.273
										Standard Deviation (non-biased)	3.01	353.1	1.90	0.117

Building 2540, Survey Unit 07

α Limit (dpm/100cm^2) 27 β Limit 7100 Low Energy β Limit (dpm/100cm2) 21000

Location ID	SU Coordinates			Surface Type	Count Time (min)	Exposure Rate(uR/hr)	Measurement Result (cpm)		Background (cpm)		Net Radioactivity (dpm/100 cm2)		Low Energy Beta (dpm/100 cm2)	SOR
	x	y	z				Alpha	Beta	Alpha	Beta	Alpha	Beta		
1	6.5	0.0	0.1	Drywall	5	10	5.2	703	*5.0*	683	0.35	37	4.97	0.018
2	13.3	0.0	0.1	Drywall	5	11	5.8	708	*5.0*	683	1.40	46	5.26	0.059
3	20.0	0.0	0.1	Drywall	5	8	10.2	850	8.6	735	2.85	216	5.94	0.136
4	21.7	5.0	0.1	Drywall	5	7	6.8	585.6	8.6	735	-3.21	-281	4.36	0.000
5	21.7	11.8	0.1	Drywall	5	6	8.4	587.4	8.6	735	-0.36	-278	3.14	0.000
6	21.7	18.5	0.1	Drywall	5	7	8	573.4	8.6	735	-1.07	-304	4.49	0.000
7	21.7	25.2	0.1	Drywall	5	9	7.6	574.6	8.6	735	-1.78	-302	3.91	0.000
8	21.1	31.3	0.1	Drywall	5	7	8	606.8	8.6	735	-1.07	-241	6.22	0.000
9	14.3	31.3	0.1	Drywall	5	7	5.2	634.8	8.6	735	-6.06	-189	5.48	0.000
10	7.6	31.3	0.1	Drywall	5	8	7.6	681.6	8.6	735	-1.78	-100	3.73	0.000
11	0.8	31.3	0.1	Drywall	5	9	8	705.2	8.6	735	-1.07	-56	4.88	0.000
12	0.0	25.4	0.1	Drywall	5	9	8	657.6	8.6	735	-1.07	-146	3.72	0.000
13	0.0	18.7	0.1	Drywall	5	9	4	607.8	*5.0*	683	-1.75	-142	2.07	0.000
14	0.0	11.9	0.1	Drywall	5	6	3	718	*5.0*	683	-3.49	65	4.88	0.009
15	0.0	5.2	0.1	Drywall	5	8	5.8	656.4	*5.0*	683	1.40	-51	2.96	0.052
16	3.2	0.0	5.9	Drywall	5	7	4.6	488.4	*5.0*	683	-0.70	-367	3.47	0.000
17	9.9	0.0	5.9	Drywall	5	8	5.2	692.2	*5.0*	683	0.35	17	6.35	0.016
18	16.6	0.0	5.9	Concrete Block	5	11	8.2	876.4	8.9	555	-1.30	604	4.88	0.085
19	21.7	1.7	5.9	Drywall	5	9	8.4	609.4	8.6	735	-0.36	-236	3.16	0.000
20	21.7	8.4	5.9	Drywall	5	6	7.2	554.4	8.6	735	-2.50	-340	6.20	0.000
21	21.7	15.1	5.9	Drywall	5	6	8.6	536.4	8.6	735	0.00	-374	6.43	0.000
22	21.7	21.9	5.9	Drywall	5	7	6.6	562	8.6	735	-3.57	-326	1.22	0.000
23	21.7	28.6	5.9	Drywall	5	5	10.4	529	8.6	735	3.21	-388	5.52	0.119
24	17.7	31.3	5.9	Drywall	5	7	7.6	565.6	8.6	735	-1.78	-319	4.11	0.000
25	10.9	31.3	5.9	Drywall	5	6	9.8	615	8.6	735	2.14	-226	5.46	0.080
26	4.2	31.3	5.9	Drywall	5	6	8.2	668.8	8.6	735	-0.71	-125	3.72	0.000
27	0.0	28.8	5.9	Drywall	5	7	11.6	650.4	8.6	735	5.35	-159	4.68	0.198
28	0.0	22.0	5.9	Metal	5	8	3.6	554.4	*5.0*	683	-2.45	-243	5.46	0.000
29	0.0	15.3	5.9	Drywall	5	7	3.4	586.2	*5.0*	683	-2.80	-183	6.24	0.000
30	0.0	8.6	5.9	Metal	5	6	3.8	547.8	*5.0*	683	-2.10	-255	4.12	0.000
31	0.0	1.8	5.9	Drywall	5	6	2.6	635	*5.0*	683	-4.19	-91	4.10	0.000
32	6.5	10.0	0.1	Drywall	5	9	3.4	651.4	*5.0*	683	-2.80	-60	-10.90	0.000
33	13.3	10.0	0.1	Drywall	5	9	3	632.2	*5.0*	683	-3.49	-96	-7.75	0.000
34	20.0	10.0	0.1	Metal	5	8	9.8	561.4	8.6	735	2.14	-327	-9.47	0.079
35	3.2	10.0	5.9	Drywall	5	6	2.8	640.2	*5.0*	683	-3.84	-81	-7.18	0.000
36	9.9	10.0	5.9	Drywall	5	7	3.6	603.8	*5.0*	683	-2.45	-150	-9.38	0.000
37	16.7	10.0	5.9	Drywall	5	7	7.8	589	8.6	735	-1.43	-275	-10.50	0.000
38	15.6	5.2	0.1	Drywall	5	8	5.6	683.8	*5.0*	683	1.05	1	-7.18	0.039
39	16.1	5.2	0.1	Drywall	5	10	7.4	690.4	8.6	735	-2.14	-84	-9.96	0.000
40	15.6	1.8	5.9	Drywall	5	9	3.8	636.2	*5.0*	683	-2.10	-89	-7.97	0.000
41	16.2	1.8	5.9	Drywall	5	8	6.4	696	8.6	735	-3.92	-73	-10.70	0.000
42	15.6	8.6	5.9	Drywall	5	7	3.8	613.2	*5.0*	683	-2.10	-132	-8.13	0.000
43	16.2	8.6	5.9	Drywall	5	6	8.8	610.8	8.6	735	0.36	-234	-10.20	0.013

Building 2540, Survey Unit 07

α Limit (dpm/100cm^2) 27 β Limit 7100 Low Energy β Limit (dpm/100cm2) 21000

Location ID	SU Coordinates			Surface Type	Count Time (min)	Exposure Rate(uR/hr)	Measurement Result (cpm)		Background (cpm)		Net Radioactivity (dpm/100 cm2)		Low Energy Beta (dpm/100 cm2)	SOR
	x	y	z				Alpha	Beta	Alpha	Beta	Alpha	Beta		
44	6.5	10.5	0.1	Drywall	5	6	2.2	584.6	*5.0*	683	-4.89	-186	-1.57	0.000
45	13.3	10.5	0.1	Drywall	5	7	3	523.8	*5.0*	683	-3.49	-300	-8.18	0.000
46	20.1	10.5	0.1	Metal	5	9	7.6	593.8	8.6	735	-1.78	-266	-7.69	0.000
47	3.2	10.5	5.9	Drywall	5	7	2.6	655.6	*5.0*	683	-4.19	-52	-3.20	0.000
48	9.9	10.5	5.9	Drywall	5	5	2.6	605.2	*5.0*	683	-4.19	-147	-8.26	0.000
49	16.7	10.5	5.9	Drywall	5	7	7.6	548.4	8.6	735	-1.78	-351	-3.46	0.000
Bias 1				Drywall	5	10	5.4	557.8	5.0	683	0.70	-236	-1.93	0.026
Bias 2				Concrete Block	5	8	6.6	616.8	8.9	555	-4.15	115	-	0.016
										Min (non-biased)	-6.06	-388	-10.90	0.000
										Max (non-biased)	5.35	604	6.43	0.198
										Average (non-biased)	-1.41	-156	-0.01	0.019
										Standard Deviation (non-biased)	2.27	173	6.34	0.042

Building 2540, Survey Unit 08

α Limit (dpm/100cm^2) 27 β Limit (dpm/100cm2) 7100 Low Energy β Limit (dpm/100cm2) 21000

Location ID	SU Coordinates			Surface Type	Count Time (min)	Exposure Rate(uR/hr)	Measurement Result (cpm)		Background (cpm)		Net Radioactivity (dpm/100 cm2)		Low Energy Beta (dpm/100 cm2)	SOR
	x	y	z				Alpha	Beta	Alpha	Beta	Alpha	Beta		
1	3.1	3.4	0.0	Laminate Tile	5	4	5.6	482	8.64	404	-5.43	146	4.12	0.021
2	9.3	3.4	0.0	Laminate Tile	5	4	10	474	8.64	404	2.42	131	0.77	0.108
3	15.4	3.4	0.0	Laminate Tile	5	4	7.2	460.4	8.64	404	-2.57	105	-1.99	0.015
4	21.6	3.4	0.0	Laminate Tile	5	4	7	454.2	8.64	404	-2.93	94	2.43	0.013
5	27.8	3.4	0.0	Laminate Tile	5	3	6.8	464	8.64	404	-3.29	112	1.05	0.016
6	34.0	3.4	0.0	Laminate Tile	5	4	6	430.6	8.64	404	-4.71	49	-1.72	0.007
7	40.1	3.4	0.0	Laminate Tile	5	4	7.4	435	8.64	404	-2.22	58	1.32	0.008
8	0.0	8.7	0.0	Laminate Tile	5	4	8	466.8	8.64	404	-1.15	117	-2.26	0.017
9	6.2	8.7	0.0	Laminate Tile	5	4	8.8	472.6	8.64	404	0.28	128	-0.89	0.028
10	12.4	8.7	0.0	Laminate Tile	5	3	5.8	465.4	8.64	404	-5.07	115	6.29	0.016
11	18.5	8.7	0.0	Laminate Tile	5	3	8	450.6	8.64	404	-1.15	87	1.87	0.012
12	24.7	8.7	0.0	Laminate Tile	5	3	7.4	458.2	8.64	404	-2.22	101	7.09	0.015
13	30.9	8.7	0.0	Laminate Tile	5	4	8.6	356.2	8.64	404	-0.08	-91	4.07	0.000
14	37.0	8.7	0.0	Laminate Tile	5	3	6.6	349.2	8.64	404	-3.64	-104	-2.54	0.000
15	43.2	8.7	0.0	Laminate Tile	5	4	4.6	307.4	8.64	404	-7.21	-182	0.50	0.000
16	3.1	14.1	0.0	Laminate Tile	5	5	6.8	465	8.64	404	-3.29	114	-2.82	0.016
17	9.3	14.1	0.0	Laminate Tile	5	4	2.6	627.2	2.64	270	-0.07	673	3.24	0.095
18	15.4	14.1	0.0	Laminate Tile	5	5	1.8	384.4	2.64	270	-1.47	216	0.21	0.030
19	21.6	14.1	0.0	Laminate Tile	5	4	2.2	399.6	2.64	270	-0.77	245	1.32	0.035
20	27.8	14.1	0.0	Laminate Tile	5	3	2.8	360.6	2.64	270	0.27	171	2.15	0.034
21	34.0	14.1	0.0	Laminate Tile	5	4	2	441.4	2.64	270	-1.12	323	-1.72	0.046
22	40.1	14.1	0.0	Laminate Tile	5	4	4	442.8	2.64	270	2.37	326	4.36	0.134
23	0.0	19.4	0.0	Laminate Tile	5	4	1	409.8	2.64	270	-2.87	264	2.14	0.037
24	6.2	19.4	0.0	Laminate Tile	5	5	2.8	400.8	2.64	270	0.27	247	3.24	0.045
25	12.4	19.4	0.0	Laminate Tile	5	3	1.8	414.4	2.64	270	-1.47	272	2.99	0.039
26	18.5	19.4	0.0	Laminate Tile	5	4	2.6	402.2	2.64	270	-0.07	249	0.50	0.035
27	24.7	19.4	0.0	Laminate Tile	5	4	2.6	393	2.64	270	-0.07	232	-2.25	0.033
28	30.9	19.4	0.0	Laminate Tile	5	4	3.6	470	2.64	270	1.67	377	-2.56	0.115
29	37.0	19.4	0.0	Laminate Tile	5	4	4.4	453	2.64	270	3.07	345	-0.89	0.162
30	43.2	19.4	0.0	Laminate Tile	5	4	3.6	432	2.64	270	1.67	306	-0.90	0.105
Bias 1	1.5	11.2	0.0	Laminate Tile	5	5	2.2	400.4	2.64	270	-0.77	246	3.86	0.035
Bias 2	11.8	7.5	0.0	Laminate Tile	5	5	2.6	410.4	2.64	270	4.87	265	6.65	0.218
Bias 3	15.4	11.1	0.0	Laminate Tile	5	4	2	395.8	2.64	270	-1.12	237	0.86	0.033
										Min (non-biased)	-7.21	-182	-2.82	0.000
										Max (non-biased)	3.07	673	7.09	0.162
										Average (non-biased)	-1.36	174	0.97	0.041
										Standard Deviation (non-biased)	2.47	163	2.70	0.043

Building 2540, Survey Unit 09

α Limit (dpm/100cm^2) 27 β Limit (dpm/100cm2) 7100 Low Energy β Limit (dpm/100cm2) 21000

Location ID	SU Coordinates			Surface Type	Count Time (min)	Exposure Rate(uR/hr)	Measurement Result (cpm)		Background (cpm)		Net Radioactivity (dpm/100 cm2)		Low Energy Beta (dpm/100 cm2)	SOR
	x	y	z				Alpha	Beta	Alpha	Beta	Alpha	Beta		
1	2.9	0.0	0.2	Metal	5	4	4	546	*2.0*	*396*	-0.4	283	-0.64	0.040
2	9.4	0.0	0.2	Drywall	5	5	5.8	461	*2.0*	*396*	4.4	123	-2.85	0.179
3	15.9	0.0	0.2	Drywall	5	5	3.4	479.8	*2.0*	*396*	0.9	158	3.37	0.055
4	22.4	0.0	0.2	Metal	5	4	3.4	399.4	*2.0*	*396*	2.4	7	1.17	0.092
5	28.9	5.1	0.2	Drywall	5	5	5.8	418.2	*2.0*	*396*	6.6	42	-0.37	0.252
6	35.4	0.0	0.2	Drywall	5	4	6	457.4	*2.0*	*396*	7.0	116	3.81	0.275
7	41.9	0.0	0.2	Drywall	5	5	6.8	475	*2.0*	*396*	8.4	149	-2.07	0.332
8	43.5	9.0	0.2	Metal	5	4	8.2	365.2	*2.0*	*396*	10.8	-58	1.25	0.401
9	43.5	11.4	0.2	Concrete Block	5	4	10.4	584.4	2.5	459	13.8	235	-0.21	0.544
10	43.5	17.9	0.2	Concrete Block	5	4	8.4	520	2.5	459	10.3	114	-1.31	0.398
11	41.8	22.8	0.2	Concrete Block	5	4	3.6	552.8	2.5	459	1.9	176	-1.84	0.096
12	35.3	22.8	0.2	Concrete Block	5	4	5	526.8	2.5	459	4.4	127	-0.61	0.180
13	28.7	22.8	0.2	Concrete Block	5	4	6.4	629	2.5	459	6.8	319	-2.28	0.297
14	22.2	22.8	0.2	Concrete Block	5	5	3	522.8	2.5	459	0.9	119	0.68	0.049
15	15.7	22.8	0.2	Concrete Block	5	4	4.6	494.2	2.5	459	3.7	65	0.99	0.145
16	9.2	22.8	0.2	Concrete Block	5	4	5.8	494.6	2.5	459	5.8	66	-0.55	0.223
17	2.7	22.8	0.2	Concrete Block	5	4	6	503.2	2.5	459	6.1	82	-3.63	0.238
18	0.0	19.0	0.2	Concrete Block	5	3	7.2	513	2.5	459	8.2	101	1.79	0.318
19	0.0	12.5	0.2	Concrete Block	5	3	7.6	691.2	2.5	459	8.9	436	0.63	0.391
20	0.0	6.0	0.2	Concrete Block	5	4	4.8	602.2	2.5	459	4.0	269	1.55	0.187
21	6.1	0.0	5.9	Metal	5	4	3.4	416	*2.0*	*396*	2.4	38	0.55	0.096
22	12.6	0.0	5.9	Drywall	5	3	4.4	434.8	*2.0*	*396*	4.2	73	0.54	0.166
23	19.1	0.0	5.9	Drywall	5	4	4.2	449.6	*2.0*	*396*	3.8	101	-3.08	0.157
24	25.6	5.1	5.9	Drywall	5	3	4.8	443.6	*2.0*	*396*	4.9	90	-1.97	0.194
25	32.1	0.0	5.9	Metal	5	4	5	431.6	*2.0*	*396*	5.2	67	-1.98	0.204
26	38.6	0.0	5.9	Metal	5	4	5.2	360.2	*2.0*	*396*	5.6	-67	-0.63	0.207
27	43.5	1.7	5.9	Concrete Block	5	4	6	626	2.5	459	6.1	313	-2.25	0.271
28	43.5	8.2	5.9	Concrete Block	5	4	5.6	471	2.5	459	5.4	22	-1.06	0.204
29	43.5	14.7	5.9	Concrete Block	5	4	8	514	2.5	459	9.6	103	-1.54	0.370
30	43.5	21.2	5.9	Concrete Block	5	4	6.4	517.2	2.5	459	6.8	109	-2.43	0.268
31	38.5	22.8	5.9	Concrete Block	5	5	5.2	484	2.5	459	4.7	46	-3.35	0.181
32	32.0	22.8	5.9	Concrete Block	5	4	6	494.2	2.5	459	6.1	65	-0.51	0.236
33	25.5	22.8	5.9	Metal	5	4	1.8	339	*2.0*	*396*	-0.3	-107	0.81	0.000
34	19.0	22.8	5.9	Concrete Block	5	4	6.6	538.4	2.5	459	7.2	149	-0.52	0.286
35	12.5	22.8	5.9	Concrete Block	5	4	2.8	668.8	2.5	459	0.5	394	0.14	0.075
36	6.0	22.8	5.9	Glass	5	3	5.4	402	*2.0*	*396*	5.9	12	0.69	0.222
37	0.0	22.2	5.9	Concrete Block	5	4	11.4	636	2.5	459	15.6	332	0.00	0.623
38	0.0	15.7	5.9	Concrete Block	5	5	9.8	526.6	2.5	459	12.8	126	-1.66	0.490
39	0.0	9.2	5.9	Concrete Block	5	4	5.2	544.4	2.5	459	4.7	160	-0.68	0.197
40	0.0	2.7	5.9	Concrete Block	5	3	8.4	573	2.5	459	10.3	214	-2.82	0.412
41	11.9	22.2	5.9	Drywall	5	4	6.6	462.4	*2.0*	*396*	8.0	125	0.59	0.315
42	11.9	15.7	5.9	Drywall	5	3	7.8	459	*2.0*	*396*	10.1	119	-1.36	0.392
43	11.9	9.2	5.9	Drywall	5	3	6.8	441	*2.0*	*396*	8.4	85	-2.21	0.323

Building 2540, Survey Unit 09

α Limit (dpm/100cm^2) 27 β Limit (dpm/100cm2) 7100 Low Energy β Limit (dpm/100cm2) 21000

Location ID	SU Coordinates			Surface Type	Count Time (min)	Exposure Rate(uR/hr)	Measurement Result (cpm)		Background (cpm)		Net Radioactivity (dpm/100 cm2)		Low Energy Beta (dpm/100 cm2)	SOR
	x	y	z				Alpha	Beta	Alpha	Beta	Alpha	Beta		
44	11.9	2.7	5.9	Metal	5	4	4.4	377.4	*2.0*	*396*	4.2	-35	4.25	0.156
45	12.4	22.2	5.9	Drywall	5	4	3.2	443.4	*2.0*	*396*	2.1	90	1.14	0.090
46	12.4	15.7	5.9	Drywall	5	4	5.2	446.6	*2.0*	*396*	5.6	96	0.31	0.221
47	12.4	9.2	5.9	Drywall	5	4	2.6	468.2	*2.0*	*396*	1.0	136	-22.50	0.058
48	12.4	2.7	5.9	Metal	5	4	3.4	397.2	*2.0*	*396*	2.4	3	3.10	0.091
49	28.0	22.2	5.9	Metal	5	4	6.8	426.2	*6.0*	*449*	1.4	-44	-0.56	0.053
50	28.0	15.7	5.9	Drywall	5	3	12.2	447.2	*6.0*	*449*	11.1	-4	4.17	0.410
51	28.0	9.2	5.9	Drywall	5	3	12.6	457.2	*6.0*	*449*	11.8	15	-0.79	0.438
52	28.0	2.7	5.9	Drywall	5	3	9.4	458.8	*6.0*	*449*	6.1	18	1.97	0.227
53	28.5	1.7	5.9	Drywall	5	4	11.8	447.2	*6.0*	*449*	10.3	-4	-4.19	0.383
54	28.5	3.2	5.9	Drywall	5	4	7.8	457.4	*6.0*	*449*	3.2	15	-1.08	0.121
55	28.5	14.7	5.9	Drywall	5	4	11	442.4	*6.0*	*449*	8.9	-13	1.41	0.330
56	28.5	21.2	5.9	Drywall	5	4	8.2	456.4	*6.0*	*449*	3.9	13	1.15	0.147
57	33.6	1.7	5.9	Drywall	5	5	12.2	457.2	*6.0*	*449*	11.1	15	-0.52	0.412
58	38.6	5.6	5.9	Drywall	5	4	8.6	444.8	*6.0*	*449*	4.6	-9	-1.17	0.172
59	34.1	1.7	5.9	Drywall	5	3	6.8	455.8	*2.0*	*396*	8.4	113	-4.17	0.327
60	38.6	5.1	5.9	Drywall	5	4	8.8	450.4	*6.0*	*449*	5.0	2	-0.36	0.185
61	11.9	19.0	0.3	Drywall	5	5	7.8	482.6	*6.0*	*449*	3.2	62	1.98	0.128
62	11.9	12.5	0.3	Drywall	5	4	10.6	502.4	*6.0*	*449*	8.2	100	-2.90	0.318
63	11.9	6.0	0.3	Metal	5	5	11	439.8	*6.0*	*449*	8.9	-18	0.54	0.330
64	12.4	19.0	0.3	Drywall	5	4	8.2	473	*6.0*	*449*	3.9	44	0.80	0.152
65	12.4	12.5	0.3	Drywall	5	4	8.4	524.2	*6.0*	*449*	4.3	141	-2.84	0.178
66	12.4	6.0	0.3	Metal	5	3	8.6	446.2	*6.0*	*449*	4.6	-6	6.35	0.172
67	28.0	19.0	0.3	Metal	5	4	6.8	426.2	*6.0*	*449*	1.4	-44	-2.24	0.053
68	28.0	12.5	0.3	Metal	5	3	6.6	424.8	*6.0*	*449*	1.1	-46	-3.51	0.040
69	28.0	6.0	0.3	Metal	5	3	9.2	457	*6.0*	*449*	5.7	14	-0.87	0.213
70	28.5	17.9	0.3	Drywall	5	4	15.6	474.6	*6.0*	*449*	17.1	47	0.56	0.641
71	28.5	11.4	0.3	Drywall	5	5	7.6	435	*6.0*	*449*	2.9	-27	1.38	0.106
72	28.5	4.9	0.3	Drywall	5	5	8.8	450	*6.0*	*449*	5.0	1	1.40	0.185
73	33.6	4.9	0.3	Drywall	5	4	6.8	428	*6.0*	*449*	1.4	-40	1.11	0.053
74	35.4	5.6	0.3	Drywall	5	3	7	437	*6.0*	*449*	1.8	-23	2.73	0.066
75	41.9	5.6	0.3	Drywall	5	5	5.8	452.6	*6.0*	*449*	-0.4	6	-3.61	0.001
76	34.1	4.9	0.3	Metal	5	4	9.2	404.6	*6.0*	*449*	5.7	-84	2.48	0.212
77	35.4	5.1	0.3	Metal	5	4	12.8	425.6	*6.0*	*449*	12.1	-45	0.81	0.449
78	41.9	5.1	0.3	Metal	5	3	11.6	419.6	*6.0*	*449*	10.0	-56	-4.08	0.370
79	28.9	5.6	0.3	Drywall	5	4	7.2	431.6	*6.0*	*449*	2.1	-33	0.27	0.079
80	32.1	5.6	5.9	Drywall	5	4	8.6	444.4	*6.0*	*449*	4.6	-9	-0.64	0.172
Bias 1	28.0	12.2	4.1	Drywall	5	5	8.6	443	*2.0*	*396*	11.5	89	5.33	0.440
Bias 2				Metal	5	5	10.4	478.2	*6.0*	*449*	7.8	54	3.33	0.298
										Min (non-biased)	-0.4	-107	-22.50	0.000
										Max (non-biased)	17.1	436	6.35	0.641
										Average (non-biased)	5.9	74	-0.55	0.229
										Standard Deviation (non-biased)	3.8	109	3.26	0.141

Building 2540, Survey Unit 10

α Limit (dpm/100cm^2) 315 β Limit (dpm/100cm2) 7100 Low Energy β Limit (dpm/100cm2) 21000

Location ID	SU Coordinates			Surface Type	Count Time (min)	Exposure Rate(uR/hr)	Measurement Result (cpm)		Background (cpm)		Net Radioactivity (dpm/100 cm2)		Low Energy Beta (dpm/100 cm2)	SOR
	x	y	z				Alpha	Beta	Alpha	Beta	Alpha	Beta		
1	4.5	0.4	0.0	Poured Concrete	1	4	9	621	4.21	344	8.36	520	-7.16	0.100
2	9.8	0.4	0.0	Poured Concrete	2	5	7	563	4.21	344	4.87	411	-8.12	0.073
3	15.1	0.4	0.0	Poured Concrete	3	4	4	567	4.21	344	-0.37	419	2.07	0.059
4	1.9	5.0	0.0	Poured Concrete	4	5	10	648	4.21	344	10.11	571	1.29	0.113
5	7.2	5.0	0.0	Poured Concrete	5	4	10	601	4.21	344	10.11	483	1.68	0.100
6	12.5	5.0	0.0	Poured Concrete	6	4	11	676	4.21	344	11.86	624	4.57	0.126
7	4.5	9.6	0.0	Poured Concrete	7	5	3	668	4.21	344	-2.12	609	3.80	0.086
8	9.8	9.6	0.0	Poured Concrete	8	5	7	656	4.21	344	4.87	586	5.34	0.098
9	15.1	9.6	0.0	Poured Concrete	9	6	8	772	4.21	344	6.61	805	0.33	0.134
10	1.9	14.1	0.0	Poured Concrete	10	3	6	736	4.21	344	3.12	737	1.68	0.114
11	7.2	14.1	0.0	Poured Concrete	11	4	6	645	4.21	344	3.12	566	-0.06	0.090
12	12.5	14.1	0.0	Poured Concrete	12	4	3	630	4.21	344	-2.12	537	2.26	0.076
13	4.5	18.7	0.0	Poured Concrete	13	5	7	623	4.21	344	4.87	524	6.51	0.090
14	9.8	18.7	0.0	Poured Concrete	14	5	8	634	4.21	344	6.61	545	1.48	0.098
15	15.1	18.7	0.0	Poured Concrete	15	5	4	616	4.21	344	-0.37	511	-1.41	0.072
16	1.9	23.3	0.0	Poured Concrete	16	5	8	632	4.21	344	6.61	541	6.55	0.098
17	7.2	23.3	0.0	Poured Concrete	17	4	5	638	4.21	344	1.37	552	2.45	0.082
18	12.5	23.3	0.0	Poured Concrete	18	6	10	654	4.21	344	10.11	583	0.91	0.114
19	4.5	27.8	0.0	Poured Concrete	19	5	3	667	4.21	344	-2.12	607	2.65	0.086
20	9.8	27.8	0.0	Poured Concrete	20	5	5	639	4.21	344	1.37	554	2.65	0.083
21	15.1	27.8	0.0	Poured Concrete	21	5	8	560	4.21	344	6.61	406	2.25	0.078
22	1.9	32.4	0.0	Poured Concrete	22	6	11	674	4.21	344	11.86	620	2.26	0.125
23	7.2	32.4	0.0	Poured Concrete	23	5	9	689	4.21	344	8.36	648	0.33	0.118
24	12.5	32.4	0.0	Poured Concrete	24	6	9	729	4.21	344	8.36	724	0.14	0.128
Bias 1	6.0	14.1	0.0	Poured Concrete	26	5	6	657	4.21	344	3.12	588	-0.56	0.093
										Min (non-biased)	-2.12	406	-8.12	0.059
										Max (non-biased)	11.86	805	6.55	0.134
										Average (non-biased)	5.01	571	1.36	0.097
										Standard Deviation (non-biased)	4.39	95	3.37	0.020

Building 2540, Survey Unit 11

α Limit (dpm/100cm^2) 315 β Limit (dpm/100cm2) 7100 Low Energy β Limit (dpm/100cm2) 21000

Location ID	SU Coordinates			Surface Type	Count Time (min)	Exposure Rate(uR/hr)	Measurement Result (cpm)		Background (cpm)		Net Radioactivity (dpm/100 cm2)		Low Energy Beta (dpm/100 cm2)	SOR
	x	y	z				Alpha	Beta	Alpha	Beta	Alpha	Beta		
1	6.5	0.0	0.2	Metal	1	5	8	402	*4.0*	*545*	7.1	-269	3.04	0.023
2	13.1	0.0	0.2	Concrete Block	1	6	5	484	8.9	555	-7.0	-134	3.22	0.000
3	16.6	3.1	0.2	Concrete Block	1	4	11	598	8.9	555	3.7	81	0.14	0.023
4	16.6	9.7	0.2	Concrete Block	1	4	11	538	8.9	555	3.7	-32	1.88	0.012
5	16.6	16.3	0.2	Concrete Block	1	5	8	573	8.9	555	-1.7	33	1.68	0.005
6	16.6	22.9	0.2	Concrete Block	1	4	8	699	8.9	555	-1.7	271	0.52	0.038
7	16.6	29.5	0.2	Concrete Block	1	5	10	581	8.9	555	1.9	49	3.23	0.013
8	7.8	18.6	0.2	Concrete Block	1	4	9	573	8.9	555	0.1	33	4.95	0.005
9	14.3	18.6	0.2	Concrete Block	1	4	11	506	8.9	555	3.7	-93	2.64	0.012
10	11.0	33.8	0.2	Concrete Block	1	3	15	552	8.9	555	10.8	-6	2.45	0.034
11	4.5	33.8	0.2	Concrete Block	1	5	14	514	8.9	555	9.0	-78	3.83	0.029
12	7.8	22.5	0.2	Concrete Block	1	4	6	530	8.9	555	-5.2	-47	1.68	0.000
13	1.2	22.5	0.2	Concrete Block	1	4	13	495	8.9	555	7.3	-113	2.83	0.023
14	0.0	28.4	0.2	Concrete Block	1	5	7	509	8.9	555	-3.4	-87	1.10	0.000
15	0.0	21.8	0.2	Concrete Block	1	5	3	546	8.9	555	-10.6	-17	0.71	0.000
16	0.0	15.2	0.2	Concrete Block	1	4	11	530	8.9	555	3.7	-47	-1.02	0.012
17	0.0	8.6	0.2	Concrete Block	1	4	5	546	8.9	555	-7.0	-17	-0.25	0.000
18	0.0	2.1	0.2	Concrete Block	1	5	5	520	8.9	555	-7.0	-66	3.93	0.000
19	3.2	0.0	5.9	Metal	1	4	9	418	*4.0*	*545*	8.9	-239	-0.59	0.028
20	9.8	0.0	5.9	Concrete Block	1	5	6	502	8.9	555	-5.2	-100	2.16	0.000
21	16.4	0.0	5.9	Concrete Block	1	4	9	503	8.9	555	0.1	-98	-0.10	0.000
22	16.6	6.4	5.9	Concrete Block	1	5	12	630	8.9	555	5.5	141	-0.25	0.037
23	16.6	13.0	5.9	Concrete Block	1	5	9	663	8.9	555	0.1	203	2.00	0.029
24	16.6	19.6	5.9	Concrete Block	1	5	13	555	8.9	555	7.3	0	2.00	0.023
25	16.6	26.2	5.9	Concrete Block	1	4	11	497	8.9	555	3.7	-110	5.59	0.012
26	16.6	32.8	5.9	Concrete Block	1	5	11	613	8.9	555	3.7	109	-0.25	0.027
27	11.0	18.1	5.9	Concrete Block	1	4	10	517	8.9	555	1.9	-72	2.99	0.006
28	14.3	33.8	5.9	Concrete Block	1	5	11	538	8.9	555	3.7	-32	0.56	0.012
29	7.8	33.8	5.9	Concrete Block	1	6	8	483	8.9	555	-1.7	-136	1.20	0.000
30	1.2	33.8	5.9	Concrete Block	1	5	12	519	8.9	555	5.5	-68	3.33	0.018
31	4.5	22.5	5.9	Concrete Block	1	4	13	553	8.9	555	7.3	-4	-0.89	0.023
32	0.0	31.7	5.9	Concrete Block	1	5	7	480	8.9	555	-3.4	-142	1.20	0.000
33	0.0	25.1	5.9	Concrete Block	1	5	13	574	8.9	555	7.3	35	0.87	0.028
34	0.0	18.5	5.9	Concrete Block	1	4	10	565	8.9	555	1.9	18	1.83	0.009
35	0.0	11.9	5.9	Concrete Block	1	4	13	569	8.9	555	7.3	26	-0.25	0.027
36	0.0	5.4	5.9	Concrete Block	1	4	11	517	8.9	555	3.7	-72	3.45	0.012
37	14.3	17.3	5.9	Concrete Block	1	4	12	501	8.9	555	5.5	-102	-1.06	0.017
38	11.0	17.3	0.2	Concrete Block	1	4	12	503	8.9	555	5.5	-98	3.12	0.018
39	7.8	17.3	5.9	Concrete Block	1	5	12	472	8.9	555	5.5	-157	2.00	0.017
40	1.2	23.8	5.9	Concrete Block	1	5	9	529	8.9	555	0.1	-49	4.08	0.001
41	4.5	23.8	0.2	Concrete Block	1	5	8	510	8.9	555	-1.7	-85	0.23	0.000
42	7.8	23.8	5.9	Concrete Block	1	4	9	549	8.9	555	0.1	-12	4.07	0.001
Bias 1	0.0	0.3	2.8	Concrete Block	1	5	13	494	8.9	555	7.3	-115	5.81	0.023
										Min (non-biased)	-10.6	-269	-1.06	0.000
										Max (non-biased)	10.8	271	5.59	0.038
										Average (non-biased)	1.9	-38	1.76	0.014
										Standard Deviation (non-biased)	5.1	103	1.72	0.012

Building 2540, Survey Unit 12

α Limit (dpm/100cm^2) 315 β Limit (dpm/100cm2) 7100 Low Energy β Limit (dpm/100cm2) 21000

Location ID	SU Coordinates			Surface Type	Count Time (min)	Exposure Rate(uR/hr)	Measurement Result (cpm)		Background (cpm)		Net Radioactivity (dpm/100 cm2)		Low Energy Beta (dpm/100 cm2)	SOR
	x	y	z				Alpha	Beta	Alpha	Beta	Alpha	Beta		
1	1.2	2.1	0.0	Poured Concrete	1	5	4	539	4.21	344	-0.37	366	-5.84	0.052
2	8.1	2.1	0.0	Poured Concrete	1	5	3	533	4.21	344	-2.12	355	-8.72	0.050
3	14.9	2.1	0.0	Poured Concrete	1	4	5	617	4.21	344	1.37	513	-9.78	0.077
4	21.7	2.1	0.0	Poured Concrete	1	4	5	624	4.21	344	1.37	526	-10.50	0.078
5	4.6	8.0	0.0	Poured Concrete	1	4	5	596	4.21	344	1.37	473	-6.73	0.071
6	11.5	8.0	0.0	Laminate Tile	1	3	4	569	2.64	270	2.37	563	-8.70	0.087
7	18.3	8.0	0.0	Poured Concrete	1	4	6	596	4.21	344	3.12	473	-6.63	0.077
8	25.1	8.0	0.0	Poured Concrete	1	5	6	638	4.21	344	3.12	552	-8.54	0.088
9	1.2	13.9	0.0	Poured Concrete	1	4	3	600	4.21	344	-2.12	481	-8.69	0.068
10	8.1	13.9	0.0	Poured Concrete	1	4	6	588	4.21	344	3.12	458	-9.66	0.074
11	14.9	13.9	0.0	Poured Concrete	1	4	5	600	4.21	344	1.37	481	-10.40	0.072
12	21.7	13.9	0.0	Poured Concrete	1	4	5	564	4.21	344	1.37	413	-7.98	0.063
13	4.6	19.8	0.0	Poured Concrete	1	4	4	614	4.21	344	-0.37	507	-7.30	0.071
14	11.5	19.8	0.0	Poured Concrete	1	5	4	589	4.21	344	-0.37	460	-8.90	0.065
15	18.3	19.8	0.0	Poured Concrete	1	4	7	565	4.21	344	4.87	415	-9.73	0.074
16	25.1	19.8	0.0	Poured Concrete	1	5	7	624	4.21	344	4.87	526	-7.52	0.090
17	1.2	25.7	0.0	Poured Concrete	1	4	5	589	4.21	344	1.37	460	3.68	0.069
18	8.1	25.7	0.0	Poured Concrete	1	5	2	567	4.21	344	-3.87	419	2.33	0.059
19	14.9	25.7	0.0	Poured Concrete	1	4	5	592	4.21	344	1.37	466	-10.90	0.070
20	21.7	25.7	0.0	Poured Concrete	1	5	13	587	4.21	344	15.35	456	-6.53	0.113
21	4.6	31.6	0.0	Poured Concrete	1	5	6	483	8.64	467	-4.71	30	-7.21	0.004
22	11.5	31.6	0.0	Poured Concrete	1	4	6	571	4.21	344	3.12	426	-7.40	0.070
23	18.3	31.6	0.0	Poured Concrete	1	4	8	633	8.64	467	-1.15	312	-8.31	0.044
24	25.1	31.6	0.0	Poured Concrete	1	5	13	620	8.64	467	7.77	288	-6.64	0.065
25	1.2	37.5	0.0	Laminate Tile	1	4	10	491	8.64	404	2.42	163	-9.43	0.031
26	8.1	37.5	0.0	Laminate Tile	1	4	9	470	8.64	404	0.64	124	-5.79	0.019
27	14.9	37.5	0.0	Poured Concrete	1	3	3	649	8.64	467	-10.07	342	-6.57	0.048
28	21.7	37.5	0.0	Poured Concrete	1	3	7	653	8.64	467	-2.93	350	-7.75	0.049
29	4.6	43.4	0.0	Laminate Tile	1	4	6	471	8.64	404	-4.71	125	-7.81	0.018
30	11.5	43.4	0.0	Poured Concrete	1	5	6	608	8.64	467	-4.71	265	-10.90	0.037
31	18.3	43.4	0.0	Poured Concrete	1	5	13	474	8.64	467	7.77	13	-11.10	0.027
32	25.1	43.4	0.0	Poured Concrete	1	5	5	651	8.64	467	-6.50	346	-7.33	0.049
Bias 1	23.0	5.1	0.0	Poured Concrete	1	4	10	600	8.64	467	2.42	250	-1.39	0.043
Bias 2				Poured Concrete	1	4	15	603	8.64	467	11.34	256	3.03	0.072
										Min (non-biased)	-10.07	13	-11.10	0.004
										Max (non-biased)	15.35	563	3.68	0.113
										Average (non-biased)	0.75	380	-7.60	0.060
										Standard Deviation (non-biased)	4.73	148	3.17	0.023

Building 2540, Survey Unit 13

α Limit (dpm/100cm^2) 315 β Limit (dpm/100cm2) 7100 Low Energy β Limit (dpm/100cm2) 21000

Location ID	SU Coordinates			Surface Type	Count Time (min)	Exposure Rate(uR/hr)	Measurement Result (cpm)		Background (cpm)		Net Radioactivity (dpm/100 cm2)		Low Energy Beta (dpm/100 cm2)	SOR
	x	y	z				Alpha	Beta	Alpha	Beta	Alpha	Beta		
1	1.5	0.0	4.3	Poured Concrete	1	5	4	541	4.21	344	-0.37	370	-10.00	0.052
2	6.3	0.0	4.3	Poured Concrete	1	4	7	569	4.21	344	4.87	423	-8.34	0.075
3	11.1	0.0	4.3	Poured Concrete	1	4	5	545	4.21	344	1.37	377	-11.50	0.058
4	15.8	0.0	4.3	Poured Concrete	1	4	7	545	4.21	344	4.87	377	-12.20	0.069
5	20.6	0.0	4.3	Poured Concrete	1	6	4	541	4.21	344	-0.37	370	-10.00	0.052
6	25.3	0.0	4.3	Poured Concrete	1	5	4	546	4.21	344	-0.37	379	-10.10	0.053
7	26.9	3.2	4.3	Concrete Block	1	4	5	570	2.50	459	4.37	208	-8.28	0.043
8	26.9	8.0	4.3	Concrete Block	1	5	3	725	2.50	459	0.87	500	-11.00	0.073
9	26.9	12.7	4.3	Concrete Block	1	5	3	547	2.50	459	0.87	165	-8.17	0.026
10	26.9	17.5	4.3	Concrete Block	1	4	11	538	2.50	459	14.85	148	-8.85	0.068
11	26.9	22.2	4.3	Concrete Block	1	4	6	575	2.50	459	6.12	217	-10.20	0.050
12	26.9	27.0	4.3	Concrete Block	1	4	8	570	8.93	555	-1.66	28	-7.90	0.004
13	26.9	31.8	4.3	Concrete Block	1	5	14	535	8.93	555	9.05	-38	-4.94	0.029
14	26.9	36.5	4.3	Concrete Block	1	5	10	533	8.93	555	1.91	-42	-8.69	0.006
15	26.9	41.3	4.3	Concrete Block	1	5	10	542	8.93	555	1.91	-25	-6.87	0.006
16	24.6	43.7	4.3	Concrete Block	1	4	16	589	8.93	555	12.61	64	-9.21	0.049
17	19.8	43.7	4.3	Metal	1	3	14	437	*5.00*	*529*	16.05	-173	-7.47	0.051
18	15.1	43.7	4.3	Concrete Block	1	5	11	523	8.93	555	3.69	-61	-5.82	0.012
19	10.3	43.7	4.3	Concrete Block	1	5	10	585	8.93	555	1.91	56	-9.43	0.014
20	0.0	39.8	4.3	Drywall	1	4	13	463	*5.00*	*529*	14.27	-124	-8.62	0.045
21	0.0	36.5	4.3	Concrete Block	1	5	8	561	8.93	555	-1.66	11	-8.81	0.002
22	0.8	34.0	4.3	Concrete Block	1	4	14	555	8.93	555	9.05	0	-7.63	0.029
23	4.1	34.0	4.3	Concrete Block	1	4	9	582	8.93	555	0.13	50	-8.99	0.008
24	6.9	34.0	4.3	Concrete Block	1	5	5	501	8.93	555	-7.01	-102	-9.16	0.000
25	0.0	27.0	4.3	Concrete Block	1	4	5	547	8.93	555	-7.01	-15	-11.30	0.000
26	0.0	20.7	4.3	Concrete Block	1	5	10	629	8.93	555	1.91	139	-10.40	0.026
27	0.0	16.0	4.3	Concrete Block	1	4	8	537	8.93	555	-1.66	-34	-6.11	0.000
28	0.0	11.2	4.3	Concrete Block	1	3	13	542	8.93	555	7.26	-25	-6.96	0.023
29	0.0	6.4	4.3	Concrete Block	1	5	9	533	8.93	555	0.13	-42	-8.18	0.000
30	0.0	1.7	4.3	Concrete Block	1	4	6	580	8.93	555	-5.22	47	-9.03	0.007
31	9.0	43.7	4.3	Concrete Block	1	5	11	506	8.93	555	3.69	-93	-7.09	0.012
32	9.0	39.8	4.3	Concrete Block	1	3	8	526	8.93	555	-1.66	-55	-10.70	0.000
33	9.0	35.0	4.3	Concrete Block	1	5	4	612	8.93	555	-8.79	107	-9.72	0.015
34	5.5	33.5	4.3	Concrete Block	1	4	9	577	8.93	555	0.13	41	-9.80	0.006
35	2.5	33.5	4.3	Concrete Block	1	5	13	522	8.93	555	7.26	-62	-9.19	0.023
36	0.8	43.7	4.3	Drywall	1	3	7	477	*5.00*	*529*	3.57	-98	-7.72	0.011
37	3.2	43.7	4.3	Drywall	1	3	15	470	*5.00*	*529*	17.84	-111	-5.34	0.057
38	5.6	43.7	4.3	Metal	1	3	9	421	*5.00*	*529*	7.13	-203	-7.65	0.023
39	8.5	43.0	4.3	Concrete Block	1	4	12	469	8.93	555	5.48	-162	-8.28	0.017
40	8.5	36.5	4.3	Concrete Block	1	4	8	614	8.93	555	-1.66	111	-7.79	0.016
Bias 1	13.8	43.7	3.8	Concrete Block	1	4	10	540	8.93	555	1.91	-29	2.78	0.006
										Min (non-biased)	-8.79	-203	-12.20	0.000
										Max (non-biased)	17.84	500	-4.94	0.075
										Average (non-biased)	3.14	68	-8.69	0.028
										Standard Deviation (non-biased)	6.19	184	1.66	0.024

Building 2540, Survey Unit 14

α Limit (dpm/100cm^2) 315 β Limit (dpm/100cm2) 7100 Low Energy β Limit (dpm/100cm2) 21000

Location ID	SU Coordinates			Surface Type	Count Time (min)	Exposure Rate(uR/hr)	Measurement Result (cpm)		Background (cpm)		Net Radioactivity (dpm/100 cm2)		Low Energy Beta (dpm/100 cm2)	SOR
	x	y	z				Alpha	Beta	Alpha	Beta	Alpha	Beta		
1	9.4	4.6	0.0	Poured Concrete	1	4	51	668	4.21	344	81.75	609	2.97	0.345
2	15.2	4.6	0.0	Poured Concrete	1	5	55	767	4.21	344	88.74	795	1.37	0.394
3	21.0	4.6	0.0	Poured Concrete	1	5	69	757	4.21	344	113.20	776	5.05	0.469
4	26.9	4.6	0.0	Poured Concrete	1	4	56	711	4.21	344	90.48	690	2.33	0.385
5	6.5	9.6	0.0	Poured Concrete	1	3	45	693	4.21	344	71.26	656	5.74	0.319
6	12.3	9.6	0.0	Poured Concrete	1	4	44	739	4.21	344	69.52	742	2.79	0.325
7	18.1	9.6	0.0	Poured Concrete	1	5	38	723	4.21	344	59.03	712	-0.10	0.288
8	24.0	9.6	0.0	Poured Concrete	1	4	51	745	4.21	344	81.75	754	4.72	0.366
9	3.6	14.6	0.0	Poured Concrete	1	4	12	528	8.64	467	5.99	115	5.68	0.035
10	9.4	14.6	0.0	Poured Concrete	1	4	7	555	8.64	467	-2.93	166	4.91	0.024
11	15.2	14.6	0.0	Poured Concrete	1	4	9	581	8.64	467	0.64	215	4.72	0.032
12	0.7	19.6	0.0	Poured Concrete	1	4	13	609	8.64	467	7.77	267	3.76	0.062
13	6.5	19.6	0.0	Poured Concrete	1	4	11	510	8.64	467	4.20	81	4.72	0.025
14	12.3	19.6	0.0	Poured Concrete	1	4	14	580	8.64	467	9.56	213	4.41	0.060
15	3.6	24.6	0.0	Poured Concrete	1	5	18	591	8.64	467	16.69	233	5.38	0.086
16	9.4	24.6	0.0	Poured Concrete	1	3	12	571	8.64	467	5.99	196	0.87	0.047
17	15.2	24.6	0.0	Poured Concrete	1	3	10	574	8.64	467	2.42	201	4.41	0.036
18	0.0	17.7	5.3	Concrete Block	1	6	14	535	8.93	555	9.05	-38	0.56	0.029
19	0.0	22.8	2.4	Concrete Block	1	5	8	488	8.93	555	-1.66	-126	5.60	0.000
20	0.5	27.6	1.1	Concrete Block	1	5	9	534	8.93	555	0.13	-40	3.48	0.001
21	6.4	27.6	1.1	Concrete Block	1	3	7	492	8.93	555	-3.44	-119	2.16	0.000
22	12.2	27.6	1.1	Concrete Block	1	5	5	444	2.50	459	4.37	-29	1.05	0.014
23	16.8	22.8	4.2	Concrete Block	1	5	9	502	2.50	459	11.36	80	1.84	0.047
24	16.8	17.7	1.3	Concrete Block	1	4	10	541	2.50	459	13.10	153	2.49	0.063
25	15.2	14.0	1.4	Concrete Block	1	4	7	686	2.50	459	7.86	426	0.39	0.085
26	9.3	14.0	1.4	Metal	1	3	7	365	1.00	459	10.48	-177	1.04	0.033
27	3.5	14.0	1.4	Concrete Block	1	4	4	509	1.00	459	5.24	94	4.45	0.030
Bias 1	15.0	12.0	0.0	Concrete Block	1	4	11	598	1.00	459	17.47	262	-2.22	0.092
										Min (non-biased)	-3.44	-177	-2.22	0.000
										Max (non-biased)	113.20	795	5.74	0.469
										Average (non-biased)	27.86	282	3.02	0.132
										Standard Deviation (non-biased)	36.19	310	2.09	0.152

Building 2540, Survey Unit 15

α Limit (dpm/100cm^2) 315 β Limit (dpm/100cm2) 7100 Low Energy β Limit (dpm/100cm2) 21000

Location ID	SU Coordinates			Surface Type	Count Time (min)	Exposure Rate(uR/hr)	Measurement Result (cpm)		Background (cpm)		Net Radioactivity (dpm/100 cm2)		Low Energy Beta (dpm/100 cm2)	SOR
	x	y	z				Alpha	Beta	Alpha	Beta	Alpha	Beta		
1	27	18	0	Carpet		15	8	922	*26.0*	*861*	-32.11	115	3.54	0.016
2	57	2	0	Laminate Tile		7	5	465	2.6	270	4.12	368	3.99	0.065
3	6	21	0	Carpet		12	16	1018	*26.0*	*861*	-17.84	295	6.24	0.042
4	39	25	0	Carpet		13	12	1014	*13.0*	*800*	-1.75	403	2.37	0.057
5	20	25	0	Carpet		12	11	1038	*13.0*	*800*	-3.49	448	3.39	0.063
6	4	19	0	Carpet		12	17	1007	*26.0*	*861*	-16.05	275	2.40	0.039
7	75	6	0	Laminate Tile		5	15	527	8.6	404	11.34	231	1.92	0.069
8	30	26	0	Carpet		10	9	1076	*13.0*	*800*	-6.99	519	-1.77	0.073
9	15	23	0	Carpet		14	22	1051	*26.0*	*861*	-7.13	358	4.18	0.051
10	74	2	0	Laminate Tile		4	5	434	2.6	270	4.12	309	3.02	0.057
11	18	17	0	Carpet		14	16	968	*13.0*	*800*	5.24	316	2.62	0.061
12	36	28	0	Carpet		12	15	1178	*13.0*	*800*	3.49	711	3.31	0.111
13	2	27	0	Carpet		13	14	1112	*26.0*	*861*	-21.40	472	4.68	0.067
14	45	10	0	Carpet		10	14	939	*26.0*	*861*	-21.40	147	3.91	0.021
15	80	2	0	Laminate Tile		4	8	492	8.6	404	-1.15	165	1.32	0.023
16	60	3	0	Laminate Tile		7	18	488	8.6	404	16.69	157	3.01	0.075
17	37	4	0	Laminate Tile		10	6	809	2.6	270	5.87	1015	2.50	0.162
18	19	25	0	Carpet		12	14	1068	*13.0*	*800*	1.75	504	5.44	0.077
19	18	25	0	Carpet		13	24	1083	*13.0*	*800*	19.22	533	5.47	0.136
20	44	2	0	Laminate Tile		13	8	869	2.6	270	9.36	1128	5.85	0.189
21	34	6	0	Laminate Tile		10	12	888	8.6	404	5.99	910	2.62	0.147
22	8	29	0	Carpet		14	20	1171	*26.0*	*861*	-10.70	583	6.61	0.082
23	37	14	0	Carpet		12	14	991	26.0	861	-21.40	245	1.74	0.035
24	50	17	0	Laminate Tile		9	7	969	8.6	404	-2.93	1062	4.16	0.150
25	44	9	0	Carpet		12	15	980	*26.0*	*861*	-19.62	224	2.24	0.032
26	38	13	0	Carpet		11	13	855	*13.0*	*800*	0.00	103	3.91	0.015
27	23	10	0	Carpet		13	13	1019	26.0	861	-23.19	297	1.86	0.042
28	37	15	0	Carpet		11	23	1009	26.0	861	-5.35	278	6.14	0.040
29	40	20	0	Carpet		13	10	901	*13.0*	*800*	-5.24	190	1.60	0.027
30	2	29	0	Carpet		10	24	1062	*26.0*	*861*	-3.57	378	3.14	0.053
Bias 1	69	0.5	0	Laminate Tile		7	9	496	8.6	404	0.64	172	-0.83	0.026
										Min (non-biased)	-32.11	103	-1.77	0.015
										Max (non-biased)	19.22	1128	6.61	0.189
										Average (non-biased)	-4.47	425	3.38	0.069
										Standard Deviation (non-biased)	12.63	283	1.78	0.046

Building 2541, Survey Unit 01

α Limit (dpm/100cm^2) 315 β Limit (dpm/100cm2) 7100 Low Energy β Limit (dpm/100cm2) 21000

Location ID	SU Coordinates			Surface Type	Count Time (min)	Exposure Rate(uR/hr)	Measurement Result (cpm)		Background (cpm)		Net Radioactivity (dpm/100 cm2)		Low Energy Beta (dpm/100 cm2)	SOR
	x	y	z				Alpha	Beta	Alpha	Beta	Alpha	Beta		
1	3.1	4.2	0.0	Poured Concrete	1	4	8	653	4.21	344	6.61	581	2.51	0.103
2	9.5	4.2	0.0	Poured Concrete	1	5	13	696	4.21	344	15.4	662	3.34	0.142
3	15.8	4.2	0.0	Poured Concrete	1	5	14	682	4.21	344	17.1	635	1.97	0.144
4	22.2	4.2	0.0	Poured Concrete	1	4	20	694	4.21	344	27.6	658	1.41	0.180
5	28.5	4.2	0.0	Poured Concrete	1	5	15	640	4.21	344	18.8	556	0.31	0.138
6	34.9	4.2	0.0	Poured Concrete	1	4	34	730	4.21	344	52.0	726	-0.25	0.267
7	0.4	9.7	0.0	Poured Concrete	1	4	33	767	4.21	344	50.3	795	2.79	0.272
8	6.7	9.7	0.0	Poured Concrete	1	5	20	683	4.21	344	27.6	637	-0.79	0.177
9	13.1	9.7	0.0	Poured Concrete	1	4	17	639	4.21	344	22.3	554	3.70	0.149
10	19.4	9.7	0.0	Poured Concrete	1	4	15	668	4.21	344	18.8	609	-1.49	0.146
11	25.8	9.7	0.0	Poured Concrete	1	4	10	706	4.21	344	10.1	680	-0.84	0.128
12	32.1	9.7	0.0	Poured Concrete	1	4	15	784	4.21	344	18.8	827	0.61	0.176
13	3.1	15.2	0.0	Poured Concrete	1	4	14	650	4.21	344	17.1	575	-3.79	0.135
14	9.5	15.2	0.0	Poured Concrete	1	3	17	663	4.21	344	22.3	599	-0.33	0.155
15	15.8	15.2	0.0	Poured Concrete	1	3	18	697	4.21	344	24.1	663	-2.37	0.170
16	22.2	15.2	0.0	Poured Concrete	1	3	11	647	4.21	344	11.9	569	-1.31	0.118
17	28.5	15.2	0.0	Poured Concrete	1	4	14	679	4.21	344	17.1	630	-0.69	0.143
18	34.9	15.2	0.0	Poured Concrete	1	5	36	752	4.21	344	55.5	767	-3.40	0.284
19	0.4	20.7	0.0	Poured Concrete	1	4	41	827	4.21	344	64.3	908	-0.71	0.332
20	6.7	20.7	0.0	Poured Concrete	1	5	16	731	4.21	344	20.6	727	-0.64	0.168
21	13.1	20.7	0.0	Poured Concrete	1	4	16	675	4.21	344	20.6	622	-2.89	0.153
22	19.4	20.7	0.0	Poured Concrete	1	3	8	687	4.21	344	6.6	645	1.23	0.112
23	25.8	20.7	0.0	Poured Concrete	1	3	15	728	4.21	344	18.8	722	0.18	0.161
24	32.1	20.7	0.0	Poured Concrete	1	4	16	728	4.21	344	20.6	722	-0.14	0.167
25	3.1	26.2	0.0	Poured Concrete	1	4	24	673	4.21	344	34.6	618	-3.45	0.197
26	9.5	26.2	0.0	Poured Concrete	1	3	17	684	4.21	344	22.3	639	-0.70	0.161
27	15.8	26.2	0.0	Poured Concrete	1	4	10	712	4.21	344	10.1	692	1.95	0.130
28	22.2	26.2	0.0	Poured Concrete	1	3	20	697	4.21	344	27.6	663	0.50	0.181
29	28.5	26.2	0.0	Poured Concrete	1	3	14	695	4.21	344	17.1	660	-0.33	0.147
30	34.9	26.2	0.0	Poured Concrete	1	3	14	716	4.21	344	17.1	699	-1.44	0.153
Bias 1				Poured Concrete	1	4	10	725	4.21	344	10.1	716	4.13	0.133
										Min (non-biased)	6.6	554	-3.79	0.103
										Max (non-biased)	64.3	908	3.70	0.332
										Average (non-biased)	23.8	668	-0.17	0.170
										Standard Deviation (non-biased)	14.2	81.5	1.96	0.053

Building 2541, Survey Unit 02

α Limit (dpm/100cm^2) 315 β Limit (dpm/100cm2) 7100 Low Energy β Limit (dpm/100cm2) 21000

Location ID	SU Coordinates			Surface Type	Count Time (min)	Exposure Rate(uR/hr)	Measurement Result (cpm)		Background (cpm)		Net Radioactivity (dpm/100 cm2)		Low Energy Beta (dpm/100 cm2)	SOR
	x	y	z				Alpha	Beta	Alpha	Beta	Alpha	Beta		
1	0	4.2	3.8	Metal	1	5	10	459	*6*	*525*	7.13	-124	-5.12	0.023
2	0	8.5	3.8	Metal	1	3	21	433	*6*	*525*	26.76	-173	1.04	0.085
3	0	12.8	3.8	Metal	1	3	13	415	*6*	*525*	12.49	-207	4.91	0.040
4	0	17.1	3.8	Metal	1	3	8	410	*6*	*525*	3.57	-216	-1.19	0.011
5	0	21.4	3.8	Metal	1	3	10	449	*6*	*525*	7.13	-143	-0.89	0.023
6	0	25.7	3.8	Metal	1	4	5	398	*6*	*525*	-1.78	-239	1.61	0.000
7	0	30	3.8	Metal	1	5	5	406	*6*	*525*	-1.78	-224	-1.16	0.000
8	4.3	30	3.8	Metal	1	4	10	430	*6*	*525*	7.13	-179	0.77	0.023
9	8.6	30	3.8	Metal	1	4	13	422	*6*	*525*	12.49	-194	-2.26	0.040
10	12.9	30	3.8	Metal	1	4	14	434	*6*	*525*	14.27	-171	-1.16	0.045
11	17.2	30	3.8	Metal	1	5	6	400	*6*	*525*	0.00	-235	4.92	0.000
12	21.5	30	3.8	Metal	1	3	8	403	*6*	*525*	3.57	-230	-2.82	0.011
13	25.8	30	3.8	Metal	1	4	8	404	*6*	*525*	3.57	-228	-2.55	0.011
14	30.1	30	3.8	Metal	1	4	16	413	*6*	*525*	17.84	-211	-1.43	0.057
15	34.4	30	3.8	Metal	1	3	20	429	*6*	*525*	24.97	-181	2.70	0.079
16	35	26.3	3.8	Metal	1	4	16	419	*6*	*525*	17.84	-199	2.14	0.057
17	35	22	3.8	Metal	1	3	10	398	*6*	*525*	7.13	-239	5.53	0.023
18	35	17.7	3.8	Metal	1	4	20	461	*6*	*525*	24.97	-120	-3.01	0.079
19	35	13.4	3.8	Metal	1	3	9	421	*6*	*525*	5.35	-196	2.52	0.017
20	35	9.1	3.8	Metal	1	4	16	401	*6*	*525*	17.84	-233	3.35	0.057
21	35	4.8	3.8	Metal	1	4	14	402	*6*	*525*	14.27	-231	-0.25	0.045
22	35	0.5	3.8	Metal	1	4	14	427	*6*	*525*	14.27	-184	3.90	0.045
23	31.2	0	3.8	Metal	1	4	7	408	*6*	*525*	1.78	-220	1.41	0.006
24	26.9	0	3.8	Metal	1	3	8	420	*6*	*525*	3.57	-198	-0.79	0.011
25	22.6	0	3.8	Metal	1	3	12	434	*6*	*525*	10.70	-171	1.15	0.034
26	18.3	0	3.8	Metal	1	4	15	404	*6*	*525*	16.05	-228	3.34	0.051
27	14	0	3.8	Metal	1	4	6	454	*6*	*525*	0.00	-134	-3.28	0.000
28	9.7	0	3.8	Metal	1	4	7	405	*6*	*525*	1.78	-226	2.27	0.006
29	5.4	0	3.8	Metal	1	4	10	384	*6*	*525*	7.13	-265	2.51	0.023
30	1.1	0	3.8	Metal	1	4	18	404	*6*	*525*	21.40	-228	1.97	0.068
Bias 1				Metal	1	4	13	390	*6*	*525*	12.49	-254	-2.49	0.040
										Min (non-biased)	-1.78	-265	-5.12	0.000
										Max (non-biased)	26.76	-120	5.53	0.085
										Average (non-biased)	10.05	-201	0.67	0.032
										Standard Deviation (non-biased)	8.28	36.7	2.74	0.026

APPENDIX D

Background Reference Area Data

Building 1205 Reference Background Area
Location East West Hallway
X 4.8'
Y 289'

	X Distance (Feet)	Y Distance (Feet)
Location 1	0	151
Location 2	1	185
Location 3	4	65
Location 4	4	179
Location 5	0	174
Location 6	0	11
Location 7	4	94
Location 8	4	112
Location 9	4	166
Location 10	1	45
Location 11	4	32
Location 12	4	64
Location 13	1	17
Location 14	3	266

Location	Date	Time	Count Length (Min.)	Probe ID	α (cpm)	Beta (cpm)	Average Alpha	Average Beta	Material	Comment
1	6/11/2012	10:50:00 AM	1	Ludlum 43-37-1 (SN 136361)	5	420			Laminate Tile	
2	6/11/2012	11:00:00 AM	1	Ludlum 43-37-1 (SN 136361)	2	447			Laminate Tile	
3	6/11/2012	10:42:00 AM	1	Ludlum 43-37-1 (SN 136361)	12	405			Laminate Tile	
4	6/11/2012	10:57:00 AM	1	Ludlum 43-37-1 (SN 136361)	8	381			Laminate Tile	
5	6/11/2012	10:55:00 AM	1	Ludlum 43-37-1 (SN 136361)	8	437			Laminate Tile	
6	6/11/2012	11:05:00 AM	1	Ludlum 43-37-1 (SN 136361)	10	461			Laminate Tile	
7	6/11/2012	10:44:00 AM	1	Ludlum 43-37-1 (SN 136361)	8	538			Laminate Tile	
8	6/11/2012	10:47:00 AM	1	Ludlum 43-37-1 (SN 136361)	10	431	7.64	430.14	Laminate Tile	
9	6/11/2012	10:52:00 AM	1	Ludlum 43-37-1 (SN 136361)	9	418			Laminate Tile	
10	6/11/2012	10:38:00 AM	1	Ludlum 43-37-1 (SN 136361)	9	442			Laminate Tile	
11	6/11/2012	10:35:00 AM	1	Ludlum 43-37-1 (SN 136361)	8	406			Laminate Tile	
12	6/11/2012	10:40:00 AM	1	Ludlum 43-37-1 (SN 136361)	5	358			Laminate Tile	
13	6/11/2012	10:32:00 AM	1	Ludlum 43-37-1 (SN 136361)	5	412			Laminate Tile	
14	6/11/2012	11:02:00 AM	1	Ludlum 43-37-1 (SN 136361)	8	466			Laminate Tile	
1	6/11/2012	10:50:00 AM	1	Ludlum 43-37 (SN 092501)	7	391			Laminate Tile	
2	6/11/2012	11:00:00 AM	1	Ludlum 43-37 (SN 092501)	2	366			Laminate Tile	
3	6/11/2012	10:42:00 AM	1	Ludlum 43-37 (SN 092501)	6	402			Laminate Tile	
4	6/11/2012	10:57:00 AM	1	Ludlum 43-37 (SN 092501)	9	385			Laminate Tile	
5	6/11/2012	10:55:00 AM	1	Ludlum 43-37 (SN 092501)	7	386			Laminate Tile	
6	6/11/2012	11:05:00 AM	1	Ludlum 43-37 (SN 092501)	9	455			Laminate Tile	
7	6/11/2012	10:44:00 AM	1	Ludlum 43-37 (SN 092501)	12	497			Laminate Tile	
8	6/11/2012	10:47:00 AM	1	Ludlum 43-37 (SN 092501)	8	411	8.64	404.36	Laminate Tile	
9	6/11/2012	10:52:00 AM	1	Ludlum 43-37 (SN 092501)	7	366			Laminate Tile	
10	6/11/2012	10:38:00 AM	1	Ludlum 43-37 (SN 092501)	14	399			Laminate Tile	
11	6/11/2012	10:35:00 AM	1	Ludlum 43-37 (SN 092501)	10	438			Laminate Tile	
12	6/11/2012	10:40:00 AM	1	Ludlum 43-37 (SN 092501)	9	379			Laminate Tile	
13	6/11/2012	10:32:00 AM	1	Ludlum 43-37 (SN 092501)	8	395			Laminate Tile	
14	6/11/2012	11:02:00 AM	1	Ludlum 43-37 (SN 092501)	13	391			Laminate Tile	

1	6/11/2012	10:31:35 AM	1	Ludlum 43-37 (SN 093966)	2	242	2.64	269.64	Laminate Tile	
2	6/11/2012	10:39:14 AM	1	Ludlum 43-37 (SN 093966)	2	285			Laminate Tile	
3	6/11/2012	10:25:02 AM	1	Ludlum 43-37 (SN 093966)	1	238			Laminate Tile	
4	6/11/2012	10:37:16 AM	1	Ludlum 43-37 (SN 093966)	2	245			Laminate Tile	
5	6/11/2012	10:35:27 AM	1	Ludlum 43-37 (SN 093966)	1	258			Laminate Tile	
6	6/11/2012	10:12:18 AM	1	Ludlum 43-37 (SN 093966)	3	297			Laminate Tile	
7	6/11/2012	10:27:01 AM	1	Ludlum 43-37 (SN 093966)	4	350			Laminate Tile	
8	6/11/2012	10:28:58 AM	1	Ludlum 43-37 (SN 093966)	3	252			Laminate Tile	
9	6/11/2012	10:33:34 AM	1	Ludlum 43-37 (SN 093966)	2	234			Laminate Tile	
10	6/11/2012	10:21:27 AM	1	Ludlum 43-37 (SN 093966)	3	254			Laminate Tile	
11	6/11/2012	10:19:35 AM	1	Ludlum 43-37 (SN 093966)	6	281			Laminate Tile	
12	6/11/2012	10:23:24 AM	1	Ludlum 43-37 (SN 093966)	1	296			Laminate Tile	
13	6/11/2012	10:17:24 AM	1	Ludlum 43-37 (SN 093966)	4	274			Laminate Tile	
14	6/11/2012	10:41:20 AM	1	Ludlum 43-37 (SN 093966)	3	269			Laminate Tile	
1	6/11/2012	11:34:00 AM	1	Ludlum Model 19 (SN 245026)	4		4.21		Laminate Tile	
2	6/11/2012	11:42:00 AM	1	Ludlum Model 19 (SN 245026)	4				Laminate Tile	
3	6/11/2012	11:27:00 AM	1	Ludlum Model 19 (SN 245026)	4				Laminate Tile	
4	6/11/2012	11:40:00 AM	1	Ludlum Model 19 (SN 245026)	4				Laminate Tile	
5	6/11/2012	11:38:00 AM	1	Ludlum Model 19 (SN 245026)	4				Laminate Tile	
6	6/11/2012	11:11:00 AM	1	Ludlum Model 19 (SN 245026)	4				Laminate Tile	
7	6/11/2012	11:30:00 AM	1	Ludlum Model 19 (SN 245026)	7				Laminate Tile	
8	6/11/2012	11:32:00 AM	1	Ludlum Model 19 (SN 245026)	4				Laminate Tile	
9	6/11/2012	11:36:00 AM	1	Ludlum Model 19 (SN 245026)	3				Laminate Tile	
10	6/11/2012	11:24:00 AM	1	Ludlum Model 19 (SN 245026)	3				Laminate Tile	
11	6/11/2012	11:15:00 AM	1	Ludlum Model 19 (SN 245026)	5				Laminate Tile	
12	6/11/2012	11:26:00 AM	1	Ludlum Model 19 (SN 245026)	5				Laminate Tile	
13	6/11/2012	11:13:00 AM	1	Ludlum Model 19 (SN 245026)	4				Laminate Tile	
14	6/11/2012	11:44:00 AM	1	Ludlum Model 19 (SN 245026)	4				Laminate Tile	
1	6/11/2012	11:34:00 AM	1	Ludlum Model 19 (SN 253050)	5		4.43		Laminate Tile	
2	6/11/2012	11:42:00 AM	1	Ludlum Model 19 (SN 253050)	4				Laminate Tile	
3	6/11/2012	11:27:00 AM	1	Ludlum Model 19 (SN 253050)	4				Laminate Tile	
4	6/11/2012	11:40:00 AM	1	Ludlum Model 19 (SN 253050)	4				Laminate Tile	
5	6/11/2012	11:38:00 AM	1	Ludlum Model 19 (SN 253050)	3				Laminate Tile	
6	6/11/2012	11:11:00 AM	1	Ludlum Model 19 (SN 253050)	4				Laminate Tile	
7	6/11/2012	11:30:00 AM	1	Ludlum Model 19 (SN 253050)	8				Laminate Tile	
8	6/11/2012	11:32:00 AM	1	Ludlum Model 19 (SN 253050)	5				Laminate Tile	
9	6/11/2012	11:36:00 AM	1	Ludlum Model 19 (SN 253050)	3				Laminate Tile	
10	6/11/2012	11:24:00 AM	1	Ludlum Model 19 (SN 253050)	4				Laminate Tile	
11	6/11/2012	11:15:00 AM	1	Ludlum Model 19 (SN 253050)	4				Laminate Tile	
12	6/11/2012	11:26:00 AM	1	Ludlum Model 19 (SN 253050)	5				Laminate Tile	
13	6/11/2012	11:13:00 AM	1	Ludlum Model 19 (SN 253050)	5				Laminate Tile	
14	6/11/2012	11:44:00 AM	1	Ludlum Model 19 (SN 253050)	4				Laminate Tile	

Building 1205	Reference Background Area
Location	Cafeteria - Windows to Second Column
X	48.6
Y	21.1

	X Distance (Feet)	Y Distance (Feet)
Location 1	7	5
Location 2	28	20
Location 3	4	4
Location 4	32	16
Location 5	2	12
Location 6	31	13
Location 7	4	7
Location 8	4	3
Location 9	40	0
Location 10	6	7
Location 11	4	5
Location 12	25	3
Location 13	13	9
Location 14	44	12

Location	Date	Time	Count Length (Min.)	Probe ID	α (cpm)	Beta (cpm)	Average Alpha	Average Beta	Material	Comment
1	6/11/2012	10:50:00 AM	1	Ludlum 43-37-1 (SN 136361)	28	1563			Ceramic Tlie	
2	6/11/2012	11:00:00 AM	1	Ludlum 43-37-1 (SN 136361)	40	1669			Ceramic Tlie	
3	6/11/2012	10:42:00 AM	1	Ludlum 43-37-1 (SN 136361)	30	1579			Ceramic Tlie	
4	6/11/2012	10:57:00 AM	1	Ludlum 43-37-1 (SN 136361)	25	1525			Ceramic Tlie	
5	6/11/2012	10:55:00 AM	1	Ludlum 43-37-1 (SN 136361)	24	1643			Ceramic Tlie	
6	6/11/2012	11:05:00 AM	1	Ludlum 43-37-1 (SN 136361)	20	1470			Ceramic Tlie	
7	6/11/2012	10:44:00 AM	1	Ludlum 43-37-1 (SN 136361)	39	1641	29.50	1586.50	Ceramic Tlie	
8	6/11/2012	10:47:00 AM	1	Ludlum 43-37-1 (SN 136361)	31	1582			Ceramic Tlie	
9	6/11/2012	10:52:00 AM	1	Ludlum 43-37-1 (SN 136361)	34	1543			Ceramic Tlie	
10	6/11/2012	10:38:00 AM	1	Ludlum 43-37-1 (SN 136361)	26	1593			Ceramic Tlie	
11	6/11/2012	10:35:00 AM	1	Ludlum 43-37-1 (SN 136361)	22	1630			Ceramic Tlie	
12	6/11/2012	10:40:00 AM	1	Ludlum 43-37-1 (SN 136361)	30	1600			Ceramic Tlie	
13	6/11/2012	10:32:00 AM	1	Ludlum 43-37-1 (SN 136361)	29	1571			Ceramic Tlie	
14	6/11/2012	11:02:00 AM	1	Ludlum 43-37-1 (SN 136361)	35	1602			Ceramic Tlie	
1	6/11/2012	10:50:00 AM	1	Ludlum 43-37 (SN 092501)	21	1261			Ceramic Tlie	
2	6/11/2012	11:00:00 AM	1	Ludlum 43-37 (SN 092501)	20	1244			Ceramic Tlie	
3	6/11/2012	10:42:00 AM	1	Ludlum 43-37 (SN 092501)	18	1270			Ceramic Tlie	
4	6/11/2012	10:57:00 AM	1	Ludlum 43-37 (SN 092501)	19	1253			Ceramic Tlie	
5	6/11/2012	10:55:00 AM	1	Ludlum 43-37 (SN 092501)	20	1230			Ceramic Tlie	
6	6/11/2012	11:05:00 AM	1	Ludlum 43-37 (SN 092501)	19	1314			Ceramic Tlie	
7	6/11/2012	10:44:00 AM	1	Ludlum 43-37 (SN 092501)	16	1282	17.71	1275.29	Ceramic Tlie	
8	6/11/2012	10:47:00 AM	1	Ludlum 43-37 (SN 092501)	12	1255			Ceramic Tlie	
9	6/11/2012	10:52:00 AM	1	Ludlum 43-37 (SN 092501)	18	1341			Ceramic Tlie	
10	6/11/2012	10:38:00 AM	1	Ludlum 43-37 (SN 092501)	15	1288			Ceramic Tlie	
11	6/11/2012	10:35:00 AM	1	Ludlum 43-37 (SN 092501)	18	1328			Ceramic Tlie	
12	6/11/2012	10:40:00 AM	1	Ludlum 43-37 (SN 092501)	23	1277			Ceramic Tlie	
13	6/11/2012	10:32:00 AM	1	Ludlum 43-37 (SN 092501)	15	1318			Ceramic Tlie	
14	6/11/2012	11:02:00 AM	1	Ludlum 43-37 (SN 092501)	14	1193			Ceramic Tlie	

1	6/11/2012	10:58:23 AM	1	Ludlum 43-37 (SN 093966)	6	1047	11.57	1026.00	Ceramic Tlie
2	6/11/2012	11:02:23 AM	1	Ludlum 43-37 (SN 093966)	9	1015			Ceramic Tlie
3	6/11/2012	11:05:13 AM	1	Ludlum 43-37 (SN 093966)	12	1009			Ceramic Tlie
4	6/11/2012	10:54:27 AM	1	Ludlum 43-37 (SN 093966)	18	1014			Ceramic Tlie
5	6/11/2012	11:08:37 AM	1	Ludlum 43-37 (SN 093966)	5	998			Ceramic Tlie
6	6/11/2012	10:52:55 AM	1	Ludlum 43-37 (SN 093966)	15	963			Ceramic Tlie
7	6/11/2012	11:01:48 AM	1	Ludlum 43-37 (SN 093966)	11	1073			Ceramic Tlie
8	6/11/2012	11:06:46 AM	1	Ludlum 43-37 (SN 093966)	13	1021			Ceramic Tlie
9	6/11/2012	10:49:13 AM	1	Ludlum 43-37 (SN 093966)	13	1049			Ceramic Tlie
10	6/11/2012	11:00:07 AM	1	Ludlum 43-37 (SN 093966)	7	1053			Ceramic Tlie
11	6/11/2012	11:03:31 AM	1	Ludlum 43-37 (SN 093966)	18	1048			Ceramic Tlie
12	6/11/2012	10:51:09 AM	1	Ludlum 43-37 (SN 093966)	14	1024			Ceramic Tlie
13	6/11/2012	10:56:31 AM	1	Ludlum 43-37 (SN 093966)	16	1015			Ceramic Tlie
14	6/11/2012	10:47:05 AM	1	Ludlum 43-37 (SN 093966)	5	1035			Ceramic Tlie
1	6/11/2012	12:01:00 PM	1	Ludlum Model 19 (SN 245026)	8		8.50		Ceramic Tlie
2	6/11/2012	12:05:00 PM	1	Ludlum Model 19 (SN 245026)	8				Ceramic Tlie
3	6/11/2012	11:55:00 AM	1	Ludlum Model 19 (SN 245026)	8				Ceramic Tlie
4	6/11/2012	12:06:00 PM	1	Ludlum Model 19 (SN 245026)	8				Ceramic Tlie
5	6/11/2012	11:59:00 AM	1	Ludlum Model 19 (SN 245026)	9				Ceramic Tlie
6	6/11/2012	12:07:00 PM	1	Ludlum Model 19 (SN 245026)	9				Ceramic Tlie
7	6/11/2012	11:58:00 AM	1	Ludlum Model 19 (SN 245026)	10				Ceramic Tlie
8	6/11/2012	11:53:00 AM	1	Ludlum Model 19 (SN 245026)	7				Ceramic Tlie
9	6/11/2012	11:47:00 AM	1	Ludlum Model 19 (SN 245026)	8				Ceramic Tlie
10	6/11/2012	11:49:00 AM	1	Ludlum Model 19 (SN 245026)	8				Ceramic Tlie
11	6/11/2012	11:57:00 AM	1	Ludlum Model 19 (SN 245026)	10				Ceramic Tlie
12	6/11/2012	11:51:00 AM	1	Ludlum Model 19 (SN 245026)	8				Ceramic Tlie
13	6/11/2012	12:03:00 PM	1	Ludlum Model 19 (SN 245026)	10				Ceramic Tlie
14	6/11/2012	12:09:00 PM	1	Ludlum Model 19 (SN 245026)	8				Ceramic Tlie
1	6/11/2012	12:01:00 PM	1	Ludlum Model 19 (SN 253050)	8		9.00		Ceramic Tlie
2	6/11/2012	12:05:00 PM	1	Ludlum Model 19 (SN 253050)	8				Ceramic Tlie
3	6/11/2012	11:55:00 AM	1	Ludlum Model 19 (SN 253050)	9				Ceramic Tlie
4	6/11/2012	12:06:00 PM	1	Ludlum Model 19 (SN 253050)	9				Ceramic Tlie
5	6/11/2012	11:59:00 AM	1	Ludlum Model 19 (SN 253050)	8				Ceramic Tlie
6	6/11/2012	12:07:00 PM	1	Ludlum Model 19 (SN 253050)	10				Ceramic Tlie
7	6/11/2012	11:58:00 AM	1	Ludlum Model 19 (SN 253050)	11				Ceramic Tlie
8	6/11/2012	11:53:00 AM	1	Ludlum Model 19 (SN 253050)	10				Ceramic Tlie
9	6/11/2012	11:47:00 AM	1	Ludlum Model 19 (SN 253050)	7				Ceramic Tlie
10	6/11/2012	11:49:00 AM	1	Ludlum Model 19 (SN 253050)	8				Ceramic Tlie
11	6/11/2012	11:57:00 AM	1	Ludlum Model 19 (SN 253050)	10				Ceramic Tlie
12	6/11/2012	11:51:00 AM	1	Ludlum Model 19 (SN 253050)	10				Ceramic Tlie
13	6/11/2012	12:03:00 PM	1	Ludlum Model 19 (SN 253050)	10				Ceramic Tlie
14	6/11/2012	12:09:00 PM	1	Ludlum Model 19 (SN 253050)	8				Ceramic Tlie

Building 1205	Reference Background Area
Location	Basement Room B-5 (Large Rectangle)
X	56.6
Y	21.6

	X Distance (Feet)	Y Distance (Feet)
Location 1	47	1
Location 2	55	3
Location 3	14	9
Location 4	8	7
Location 5	18	17
Location 6	19	12
Location 7	1	9
Location 8	52	13
Location 9	25	6
Location 10	47	7
Location 11	52	16
Location 12	14	20
Location 13	49	5
Location 14	2	20

Location	Date	Time	Count Length (Min.)	Probe ID	α (cpm)	Beta (cpm)	Average Alpha	Average Beta	Material	Comment
1	6/11/2012	12:37:00 PM	1	Ludlum 43-37-1 (SN 136361)	4	527			Poured Concrete	Painted
2	6/11/2012	12:48:00 PM	1	Ludlum 43-37-1 (SN 136361)	8	622			Poured Concrete	Painted
3	6/11/2012	12:30:00 PM	1	Ludlum 43-37-1 (SN 136361)	9	507			Poured Concrete	Painted
4	6/11/2012	12:28:00 PM	1	Ludlum 43-37-1 (SN 136361)	11	540			Poured Concrete	Painted
5	6/11/2012	12:34:00 PM	1	Ludlum 43-37-1 (SN 136361)	11	463			Poured Concrete	Painted
6	6/11/2012	12:33:00 PM	1	Ludlum 43-37-1 (SN 136361)	12	562			Poured Concrete	Painted
7	6/11/2012	12:24:00 PM	1	Ludlum 43-37-1 (SN 136361)	8	588	9.21	542.64	Poured Concrete	Painted
8	6/11/2012	12:44:00 PM	1	Ludlum 43-37-1 (SN 136361)	6	611			Poured Concrete	Painted
9	6/11/2012	12:35:00 PM	1	Ludlum 43-37-1 (SN 136361)	7	593			Poured Concrete	Painted
10	6/11/2012	12:39:00 PM	1	Ludlum 43-37-1 (SN 136361)	11	561			Poured Concrete	Painted
11	6/11/2012	12:46:00 PM	1	Ludlum 43-37-1 (SN 136361)	7	532			Poured Concrete	Painted
12	6/11/2012	12:32:00 PM	1	Ludlum 43-37-1 (SN 136361)	13	453			Poured Concrete	Painted
13	6/11/2012	12:42:00 PM	1	Ludlum 43-37-1 (SN 136361)	8	512			Poured Concrete	Painted
14	6/11/2012	12:26:00 PM	1	Ludlum 43-37-1 (SN 136361)	14	526			Poured Concrete	Painted
1	6/11/2012	12:37:00 PM	1	Ludlum 43-37 (SN 092501)	4	468			Poured Concrete	Painted
2	6/11/2012	12:48:00 PM	1	Ludlum 43-37 (SN 092501)	9	510			Poured Concrete	Painted
3	6/11/2012	12:30:00 PM	1	Ludlum 43-37 (SN 092501)	8	448			Poured Concrete	Painted
4	6/11/2012	12:28:00 PM	1	Ludlum 43-37 (SN 092501)	6	472			Poured Concrete	Painted
5	6/11/2012	12:34:00 PM	1	Ludlum 43-37 (SN 092501)	14	461			Poured Concrete	Painted
6	6/11/2012	12:33:00 PM	1	Ludlum 43-37 (SN 092501)	11	466			Poured Concrete	Painted
7	6/11/2012	12:24:00 PM	1	Ludlum 43-37 (SN 092501)	11	534	8.64	467.00	Poured Concrete	Painted
8	6/11/2012	12:44:00 PM	1	Ludlum 43-37 (SN 092501)	8	469			Poured Concrete	Painted
9	6/11/2012	12:35:00 PM	1	Ludlum 43-37 (SN 092501)	7	485			Poured Concrete	Painted
10	6/11/2012	12:39:00 PM	1	Ludlum 43-37 (SN 092501)	12	448			Poured Concrete	Painted
11	6/11/2012	12:46:00 PM	1	Ludlum 43-37 (SN 092501)	3	459			Poured Concrete	Painted
12	6/11/2012	12:32:00 PM	1	Ludlum 43-37 (SN 092501)	12	426			Poured Concrete	Painted
13	6/11/2012	12:42:00 PM	1	Ludlum 43-37 (SN 092501)	9	440			Poured Concrete	Painted
14	6/11/2012	12:26:00 PM	1	Ludlum 43-37 (SN 092501)	7	452			Poured Concrete	Painted

1	6/11/2012	12:11:00 PM	1	Ludlum 43-93 (SN 311206)	75	76.43	Poured Concrete	Painted
2	6/11/2012	12:30:00 PM	1	Ludlum 43-93 (SN 311206)	79		Poured Concrete	Painted
3	6/11/2012	12:24:00 PM	1	Ludlum 43-93 (SN 311206)	73		Poured Concrete	Painted
4	6/11/2012	12:23:00 PM	1	Ludlum 43-93 (SN 311206)	76		Poured Concrete	Painted
5	6/11/2012	12:19:00 PM	1	Ludlum 43-93 (SN 311206)	81		Poured Concrete	Painted
6	6/11/2012	12:20:00 PM	1	Ludlum 43-93 (SN 311206)	88		Poured Concrete	Painted
7	6/11/2012	12:22:00 PM	1	Ludlum 43-93 (SN 311206)	90		Poured Concrete	Painted
8	6/11/2012	12:15:00 PM	1	Ludlum 43-93 (SN 311206)	74		Poured Concrete	Painted
9	6/11/2012	12:29:00 PM	1	Ludlum 43-93 (SN 311206)	68		Poured Concrete	Painted
10	6/11/2012	12:17:00 PM	1	Ludlum 43-93 (SN 311206)	67		Poured Concrete	Painted
11	6/11/2012	12:18:00 PM	1	Ludlum 43-93 (SN 311206)	77		Poured Concrete	Painted
12	6/11/2012	12:27:00 PM	1	Ludlum 43-93 (SN 311206)	69		Poured Concrete	Painted
13	6/11/2012	12:13:00 PM	1	Ludlum 43-93 (SN 311206)	81		Poured Concrete	Painted
14	6/11/2012	12:26:00 PM	1	Ludlum 43-93 (SN 311206)	72		Poured Concrete	Painted
1	6/11/2012	12:11:00 PM	1	Ludlum Model 19 (SN 245026)	4	4.64	Poured Concrete	Painted
2	6/11/2012	12:30:00 PM	1	Ludlum Model 19 (SN 245026)	4		Poured Concrete	Painted
3	6/11/2012	12:24:00 PM	1	Ludlum Model 19 (SN 245026)	4		Poured Concrete	Painted
4	6/11/2012	12:23:00 PM	1	Ludlum Model 19 (SN 245026)	6		Poured Concrete	Painted
5	6/11/2012	12:19:00 PM	1	Ludlum Model 19 (SN 245026)	5		Poured Concrete	Painted
6	6/11/2012	12:20:00 PM	1	Ludlum Model 19 (SN 245026)	4		Poured Concrete	Painted
7	6/11/2012	12:22:00 PM	1	Ludlum Model 19 (SN 245026)	5		Poured Concrete	Painted
8	6/11/2012	12:15:00 PM	1	Ludlum Model 19 (SN 245026)	4		Poured Concrete	Painted
9	6/11/2012	12:29:00 PM	1	Ludlum Model 19 (SN 245026)	4		Poured Concrete	Painted
10	6/11/2012	12:17:00 PM	1	Ludlum Model 19 (SN 245026)	5		Poured Concrete	Painted
11	6/11/2012	12:18:00 PM	1	Ludlum Model 19 (SN 245026)	5		Poured Concrete	Painted
12	6/11/2012	12:27:00 PM	1	Ludlum Model 19 (SN 245026)	5		Poured Concrete	Painted
13	6/11/2012	12:13:00 PM	1	Ludlum Model 19 (SN 245026)	4		Poured Concrete	Painted
14	6/11/2012	12:26:00 PM	1	Ludlum Model 19 (SN 245026)	6		Poured Concrete	Painted
1	6/11/2012	12:11:00 PM	1	Ludlum Model 19 (SN 253050)	4	4.43	Poured Concrete	Painted
2	6/11/2012	12:30:00 PM	1	Ludlum Model 19 (SN 253050)	4		Poured Concrete	Painted
3	6/11/2012	12:24:00 PM	1	Ludlum Model 19 (SN 253050)	4		Poured Concrete	Painted
4	6/11/2012	12:23:00 PM	1	Ludlum Model 19 (SN 253050)	5		Poured Concrete	Painted
5	6/11/2012	12:19:00 PM	1	Ludlum Model 19 (SN 253050)	5		Poured Concrete	Painted
6	6/11/2012	12:20:00 PM	1	Ludlum Model 19 (SN 253050)	4		Poured Concrete	Painted
7	6/11/2012	12:22:00 PM	1	Ludlum Model 19 (SN 253050)	6		Poured Concrete	Painted
8	6/11/2012	12:15:00 PM	1	Ludlum Model 19 (SN 253050)	4		Poured Concrete	Painted
9	6/11/2012	12:29:00 PM	1	Ludlum Model 19 (SN 253050)	4		Poured Concrete	Painted
10	6/11/2012	12:17:00 PM	1	Ludlum Model 19 (SN 253050)	4		Poured Concrete	Painted
11	6/11/2012	12:18:00 PM	1	Ludlum Model 19 (SN 253050)	4		Poured Concrete	Painted
12	6/11/2012	12:27:00 PM	1	Ludlum Model 19 (SN 253050)	5		Poured Concrete	Painted
13	6/11/2012	12:13:00 PM	1	Ludlum Model 19 (SN 253050)	4		Poured Concrete	Painted
14	6/11/2012	12:26:00 PM	1	Ludlum Model 19 (SN 253050)	5		Poured Concrete	Painted

Building 1205	Reference Background Area
Location	Basement Room B-5 (Block Concrete Wall)
X	56.5
Y	6

	X Distance (Feet)	Y Distance (Feet)
Location 1	7	4
Location 2	23	1
Location 3	17	0
Location 4	33	5
Location 5	12	3
Location 6	12	5
	3	4
Location 8	27	4
Location 9	26	2
Location 10	14	4
Location 11	49	4
Location 12	14	3
Location 13	46	1
Location 14	30	3

Location	Date	Time	Count Length (Min.)	Probe ID	α (cpm)	Beta (cpm)	Average Alpha	Average Beta	Material	Comment
1	6/11/2012	1:19:30 AM	1	Ludlum 43-37-1 (SN 136361)	13	522			Block Concrete	Painted
2	6/11/2012	1:08:57 AM	1	Ludlum 43-37-1 (SN 136361)	10	893			Block Concrete	Painted
3	6/11/2012	1:10:47 AM	1	Ludlum 43-37-1 (SN 136361)	12	547			Block Concrete	Painted
4	6/11/2012	1:04:11 AM	1	Ludlum 43-37-1 (SN 136361)	10	846			Block Concrete	Painted
5	6/11/2012	1:17:47 AM	1	Ludlum 43-37-1 (SN 136361)	7	583			Block Concrete	Painted
6	6/11/2012	1:16:13 AM	1	Ludlum 43-37-1 (SN 136361)	12	533			Block Concrete	Painted
7	6/11/2012	1:22:21 AM	1	Ludlum 43-37-1 (SN 136361)	13	455	10.93	704.86	Block Concrete	Painted
8	6/11/2012	1:05:44 AM	1	Ludlum 43-37-1 (SN 136361)	15	912			Block Concrete	Painted
9	6/11/2012	1:07:18 AM	1	Ludlum 43-37-1 (SN 136361)	15	875			Block Concrete	Painted
10	6/11/2012	1:12:39 AM	1	Ludlum 43-37-1 (SN 136361)	10	509			Block Concrete	Painted
11	6/11/2012	12:57:23 PM	1	Ludlum 43-37-1 (SN 136361)	12	868			Block Concrete	Painted
12	6/11/2012	1:14:18 AM	1	Ludlum 43-37-1 (SN 136361)	2	496			Block Concrete	Painted
13	6/11/2012	12:59:19 PM	1	Ludlum 43-37-1 (SN 136361)	13	931			Block Concrete	Painted
14	6/11/2012	1:02:24 AM	1	Ludlum 43-37-1 (SN 136361)	9	898			Block Concrete	Painted
1	6/11/2012	11:24:04 AM	1	Ludlum 43-37 (SN 092501)	11	388			Block Concrete	Painted
2	6/11/2012	11:13:27 AM	1	Ludlum 43-37 (SN 092501)	8	692			Block Concrete	Painted
3	6/11/2012	11:15:36 AM	1	Ludlum 43-37 (SN 092501)	6	433			Block Concrete	Painted
4	6/11/2012	11:08:26 AM	1	Ludlum 43-37 (SN 092501)	4	649			Block Concrete	Painted
5	6/11/2012	11:22:22 AM	1	Ludlum 43-37 (SN 092501)	9	410			Block Concrete	Painted
6	6/11/2012	11:20:49 AM	1	Ludlum 43-37 (SN 092501)	4	421			Block Concrete	Painted
7	6/11/2012	11:26:51 AM	1	Ludlum 43-37 (SN 092501)	5	414	8.93	555.21	Block Concrete	Painted
8	6/11/2012	11:10:15 AM	1	Ludlum 43-37 (SN 092501)	7	720			Block Concrete	Painted
9	6/11/2012	11:11:54 AM	1	Ludlum 43-37 (SN 092501)	9	716			Block Concrete	Painted
10	6/11/2012	11:17:23 AM	1	Ludlum 43-37 (SN 092501)	17	445			Block Concrete	Painted
11	6/11/2012	11:02:00 AM	1	Ludlum 43-37 (SN 092501)	15	706			Block Concrete	Painted
12	6/11/2012	11:19:04 AM	1	Ludlum 43-37 (SN 092501)	7	442			Block Concrete	Painted
13	6/11/2012	11:03:57 AM	1	Ludlum 43-37 (SN 092501)	11	652			Block Concrete	Painted
14	6/11/2012	11:05:53 AM	1	Ludlum 43-37 (SN 092501)	12	685			Block Concrete	Painted

1	6/11/2012	9:12:41 AM	1	Ludlum 43-37 (SN 093966)	0	287	2.50	459.43	Block Concrete	Painted
2	6/11/2012	9:28:41 AM	1	Ludlum 43-37 (SN 093966)	3	614			Block Concrete	Painted
3	6/11/2012	9:16:47 AM	1	Ludlum 43-37 (SN 093966)	2	318			Block Concrete	Painted
4	6/11/2012	9:19:12 AM	1	Ludlum 43-37 (SN 093966)	4	532			Block Concrete	Painted
5	6/11/2012	9:08:39 AM	1	Ludlum 43-37 (SN 093966)	3	328			Block Concrete	Painted
6	6/11/2012	9:25:07 AM	1	Ludlum 43-37 (SN 093966)	3	313			Block Concrete	Painted
7	6/11/2012	9:26:56 AM	1	Ludlum 43-37 (SN 093966)	1	306			Block Concrete	Painted
8	6/11/2012	9:30:18 AM	1	Ludlum 43-37 (SN 093966)	3	592			Block Concrete	Painted
9	6/11/2012	9:14:59 AM	1	Ludlum 43-37 (SN 093966)	4	527			Block Concrete	Painted
10	6/11/2012	9:21:07 AM	1	Ludlum 43-37 (SN 093966)	2	331			Block Concrete	Painted
11	6/11/2012	9:03:16 AM	1	Ludlum 43-37 (SN 093966)	1	679			Block Concrete	Painted
12	6/11/2012	9:23:20 AM	1	Ludlum 43-37 (SN 093966)	0	348			Block Concrete	Painted
13	6/11/2012	9:05:12 AM	1	Ludlum 43-37 (SN 093966)	7	668			Block Concrete	Painted
14	6/11/2012	9:10:19 AM	1	Ludlum 43-37 (SN 093966)	2	589			Block Concrete	Painted
1	6/11/2012	12:51:00 PM	1	Ludlum Model 19 (SN 245026)	1		6.21		Block Concrete	Painted
2	6/11/2012	12:42:00 PM	1	Ludlum Model 19 (SN 245026)	8				Block Concrete	Painted
3	6/11/2012	12:44:00 PM	1	Ludlum Model 19 (SN 245026)	5				Block Concrete	Painted
4	6/11/2012	12:36:00 PM	1	Ludlum Model 19 (SN 245026)	8				Block Concrete	Painted
5	6/11/2012	12:48:00 PM	1	Ludlum Model 19 (SN 245026)	4				Block Concrete	Painted
6	6/11/2012	12:49:00 PM	1	Ludlum Model 19 (SN 245026)	5				Block Concrete	Painted
7	6/11/2012	12:53:00 PM	1	Ludlum Model 19 (SN 245026)	5				Block Concrete	Painted
8	6/11/2012	12:40:00 PM	1	Ludlum Model 19 (SN 245026)	10				Block Concrete	Painted
9	6/11/2012	12:41:00 PM	1	Ludlum Model 19 (SN 245026)	8				Block Concrete	Painted
10	6/11/2012	12:46:00 PM	1	Ludlum Model 19 (SN 245026)	5				Block Concrete	Painted
11	6/11/2012	12:34:00 PM	1	Ludlum Model 19 (SN 245026)	8				Block Concrete	Painted
12	6/11/2012	12:45:00 PM	1	Ludlum Model 19 (SN 245026)	5				Block Concrete	Painted
13	6/11/2012	12:32:00 PM	1	Ludlum Model 19 (SN 245026)	8				Block Concrete	Painted
14	6/11/2012	12:38:00 PM	1	Ludlum Model 19 (SN 245026)	7				Block Concrete	Painted
1	6/11/2012	12:51:00 PM	1	Ludlum Model 19 (SN 253050)	1		5.93		Block Concrete	Painted
2	6/11/2012	12:42:00 PM	1	Ludlum Model 19 (SN 253050)	8				Block Concrete	Painted
3	6/11/2012	12:44:00 PM	1	Ludlum Model 19 (SN 253050)	5				Block Concrete	Painted
4	6/11/2012	12:36:00 PM	1	Ludlum Model 19 (SN 253050)	6				Block Concrete	Painted
5	6/11/2012	12:48:00 PM	1	Ludlum Model 19 (SN 253050)	4				Block Concrete	Painted
6	6/11/2012	12:49:00 PM	1	Ludlum Model 19 (SN 253050)	6				Block Concrete	Painted
7	6/11/2012	12:53:00 PM	1	Ludlum Model 19 (SN 253050)	5				Block Concrete	Painted
8	6/11/2012	12:40:00 PM	1	Ludlum Model 19 (SN 253050)	8				Block Concrete	Painted
9	6/11/2012	12:41:00 PM	1	Ludlum Model 19 (SN 253050)	6				Block Concrete	Painted
10	6/11/2012	12:46:00 PM	1	Ludlum Model 19 (SN 253050)	5				Block Concrete	Painted
11	6/11/2012	12:34:00 PM	1	Ludlum Model 19 (SN 253050)	8				Block Concrete	Painted
12	6/11/2012	12:45:00 PM	1	Ludlum Model 19 (SN 253050)	5				Block Concrete	Painted
13	6/11/2012	12:32:00 PM	1	Ludlum Model 19 (SN 253050)	8				Block Concrete	Painted
14	6/11/2012	12:38:00 PM	1	Ludlum Model 19 (SN 253050)	8				Block Concrete	Painted

APPENDIX E

Instrument and Check Source Calibration Certificates

Designer and Manufacturer of Scientific and Industrial Instruments

CERTIFICATE OF CALIBRATION

LUDLUM MEASUREMENTS, INC.
POST OFFICE BOX 810 PH. 325-235-5494
501 OAK STREET FAX NO. 325-235-4672
SWEETWATER, TEXAS 79556, U.S.A.

CUSTOMER US ARMY CORPS OF ENGINEERS ORDER NO. 20200290/378285

Mfg. Ludlum Measurements, Inc. Model 2360 Serial No. 138251

Mfg. Ludlum Measurements, Inc. Model 43-37-1 Serial No. PR136361

Cal. Date 23-May-12 Cal Due Date 23-May-13 Cal. Interval 1 Year Meterface 202-855

Check mark ☑ applies to applicable instr. and/or detector IAW mfg. spec. T. 73 °F RH 36 % Alt 699.8 mm Hg

☐ New Instrument Instrument Received ☑ Within Toler. +-10% ☐ 10-20% ☐ Out of Tol. ☐ Requiring Repair ☐ Other-See comments

☑ Mechanical ck. ☑ Meter Zeroed ☐ Background Subtract ☐ Input Sens. Linearity
☐ F/S Resp. ck ☑ Reset ck. ☑ Window Operation ☐ Geotropism
☑ Audio ck. ☑ Alarm Setting ck. ☑ Batt. ck. (Min. Volt) 2.2 VDC ☑ RS-232 Port OK
☐ Calibrated in accordance with LMI SOP 14.8 rev 12/05/89. ☐ Calibrated in accordance with LMI SOP 14.9 rev 02/07/97.

Instrument Volt Set 1600 V

☑ HV Readout (2 points) Ref./Inst. 500 / 505 V Ref./Inst. 2000 / 2002 V

Firmware Version: 39010v25
Alpha Threshold: 90 mv
Beta Threshold: 4 mv
Beta Window: 30 mv
Overload Checked But not set.
Instrument calibrated with a 39' cable.
High voltage set with detector not connected.

(EEPROM Settings)
User Time: 1.0
Alpha Alarm: 999999
Beta Alarm: 999999
A/B Alarm: 999999
Model 2360 Date: 5/23/2012
Calibration Date Due: 5/23/2013

COMMENTS:

Pu239 SN:7053 Size:12600cpm, Background:6cpm, Counts:5281cpm, 2pi Eff:41.86%
Tc99 SN:5280 Size:58300cpm, Background:1002cpm, Counts:26891cpm, 2pi Eff:44.40%
SrY90 SN:5281 Size:69345cpm, Background:1002cpm, Counts:25826cpm, 2pi Eff:35.79%

Gamma Calibration: GM detectors positioned perpendicular to source except for M 44-9 in which the front of probe faces source.

RANGE/MULTIPLIER	REFERENCE CAL. POINT	INSTRUMENT REC'D "AS FOUND READING"	INSTRUMENT METER READING*
x1000	400k cpm	400	400
x1000	100k cpm	100	100
x100	40k cpm	400	400
x100	10k cpm	100	100
x10	4k cpm	400	400
x10	1k cpm	100	100
x1	400 cpm	400	400
x1	100 cpm	100	100

*Uncertainty within ± 10% C.F. within ± 20% ALL **Range(s) Calibrated Electronically**

	REFERENCE CAL. POINT	INSTRUMENT RECEIVED	INSTRUMENT METER READING*
Digital Readout	400kcpm	39986(0)	39986(0)
	40kcpm	3998	3998
	4kcpm	400	400
	400cpm	40	40
	40cpm	4	4

	REFERENCE CAL. POINT	INSTRUMENT RECEIVED	INSTRUMENT METER READING*
Log Scale			

Ludlum Measurements, Inc. certifies that the above instrument has been calibrated by standards traceable to the National Institute of Standards and Technology, or to the calibration facilities of other International Standards Organization members, or have been derived from accepted values of natural physical constants or have been derived by the ratio type of calibration techniques. The calibration system conforms to the requirements of ANSI/NCSL Z540-1-1994 and ANSI N323-1978 State of Texas Calibration License No. LO-1963

Reference Instruments and/or Sources: ☐ 73410 ☐ 1131 ☐ 781 ☐ 059 ☐ 280 ☐ 60646 ☐ 70897 ☐ Ra-226 S/N Y982
Cs-137 Gamma S/N ☐ 1162 ☐ G112 ☐ M565 ☐ 5105 ☐ T1008 ☐ T879 ☐ E552 ☐ E551 ☐ 720 ☐ 734 ☐ 1616 ☐ Neutron Am-241 Be S/N T-304

☐ Alpha S/N ☐ Beta S/N ☐ Other

☑ m 500 S/N 190566 ☐ Oscilloscope S/N ☑ Multimeter S/N 86250390

Calibrated By: [signature] Date 23-May-12

Reviewed By: [signature] Date 24May12

This certificate shall not be reproduced except in full, without the written approval of Ludlum Measurements, Inc.

AC Inst. Only ☐ Passed Dielectric (Hi-Pot) and Continuity Test ☐ Failed:

Designer and Manufacturer
of
Scientific and Industrial
Instruments

LUDLUM MEASUREMENTS, INC.
POST OFFICE BOX 810 PH. 325-235-5494
501 OAK STREET FAX NO. 325-235-4672
SWEETWATER, TEXAS 79556, U.S.A.

Bench Test Data For Detector

Detector 43-37-1 Serial No. PR136361 Order #. 20200290/378285

Customer US ARMY CORPS OF ENGINEERS Alpha Input Sensitivity 90 mV

Counter 2360 Serial No. 138251 Beta Input Sensitivity 4 mV

Count Time 1Minute Beta Window 30 mV

Other Distance Source to Detector Surface

High Voltage	Background		Isotope Pu239 Size 24900dpm		Isotope Tc99 Size 93200dpm		Isotope SrY90 Size 99065dpm	
	Alpha	Beta	Alpha	Beta	Alpha	Beta	Alpha	Beta
1575	5	818	5084	1091	37	25158	3	21603
1600	6	1002	5281	1354	37	26891	3	25826
1625	4	1268	5333	1586	38	27067	9	28900
1650	9	1534	5484	2018	78	25432	58	31340

☐ Gas Proportional detector count rate decreased ≤ 10% after 15 hour static test using 39" cable.

☐ Gas proportional detector count rate decreased ≤ 10% after 5 hour static test using 39" cable and alpha/beta counter.

Signature Jason Ivie Date 23-May-12

• *Serving The Nuclear Industry Since 1962* •

ENERGYSOLUTIONS

CALIBRATION CERTIFICATE

EnergySolutions Services, Inc.
1570 Bear Creek Road
Oak Ridge, TN 37830
Phone: (877) 462-4873
Fax: (865) 220-1346

This Certificate will be accompanied by Calibration Charts or Readings where applicable

CUSTOMER INFORMATION		INSTRUMENT INFORMATION	
Customer Name: EnergySolutions Services, Inc.		Manufacturer: Ludlum	
Address: 1570 Bear Creek Road Oak Ridge, TN 37830		Model: 2360	Serial Number: 275713
Contact Name: Tony Riggs		Probe: N/A	Serial Number: N/A
Customer Purchase Order Number: N/A	Work Order Number: ~~2011-11061~~ 2011-11061	Calibration Method: Electronic	

INSTRUMENT CALIBRATION INFORMATION

Instrument Range	Calibration Standard Value	Ratemeter Response (± 10% of Standard Values)		Calibration Standard Value CPM	Time Base (minutes)	Tolerances (cpm) ± 2%	Scaler Response	
		As Found	As Left				As Found	As Left
X 1	100	100	100	1,000 CPM	0.1	90 – 110	100	100
X 1	250	250	250	1,000 CPM	0.5	450 – 550	500	500
X 1	400	400	400	1,000 CPM	1	900 – 1,100	1,002	1,002
X 10	1,000	1,000	1,000	1,000 CPM	2	1.8K–2.2K	2,003	2,003
X 10	2,500	2,500	2,500	1,000 CPM	5	4.5K-5.5K	5,008	5,008
X 10	4,000	4,000	4,000	1,000 CPM	10	9K-11K	10,015	10,015
X 100	10,000	10,000	10,000					
X 100	25,000	25,000	25,000					
X 100	40,000	40,000	40,000					
X 1000	100,000	100,000	100,000	Calibrated in accordance with OEM Technical Manual				
X 1000	250,000	250,000	250,000					
X 1000	400,000	400,000	400,000					

STATEMENT OF CERTIFICATION

We Certify that the instrument listed above was calibrated and inspected prior to shipment and that it met all the Manufacturers published operating specifications. We further certify that our Calibration Measurements are traceable to the National Institute of Standards and Technology. (We are not responsible for damage incurred during shipment or use of this instrument).

Instrument Calibrated By: M. Paul	Reviewed By: [signature] Date: 8/30/11
Calibration Date: 08/30/2011	*Calibration Due (6mo): 02/29/2012
	*Calibration Due (12mo): 08/30/2012

* Calibration due date is dependant on users regulatory requirements.

ENERGYSOLUTIONS

Model: 2360 Serial Number: 275713

M&TE				Environmental Conditions		
Volt Meter	ID# 94710023	Cal Due:	10/28/2011	Barometer	ID# 3590	Cal Due: 09/21/11
Pulser	ID# 112860	Cal Due:	04/26/2012	Thermometer	ID# 3590	Cal Due: 09/21/11
Humidity	ID# 958670	Cal Due:	06/07/2012	Temp: 22.4 °C	Pressure: 741 mmHg	Humidity: 58%

Special Test			
BAT Check	Sat (√) Unsat ( )	Geotropism	Sat (√) Unsat ( )
LCD Display Check	Sat (√) Unsat ( )	Audio Check	Sat (√) Unsat ( )
Mechanical Zero	Sat (√) Unsat ( )	Low BAT Set	Sat (√) Unsat ( )
Reset	Sat (√) Unsat ( )		
HV Analog Display	Sat (√) Unsat ( )	As Found	As Left

High Voltage Calibration (± 10%)				Alpha Sensitivity = 125 mv	Alpha Sensitivity = 120 mv
Voltage	Tolerance	As Found	As Left	Beta Sensitivity = 3.8 mv	Beta Sensitivity = 3.5 mv
500	450-550	514	514	Beta Window = 32 mv	Beta Window = 30 mv
1000	900-1100	983	983	Beta Setpoints--Pulser counts detected at 3.5mv ± 1mv and shut off at 30mv for beta. For Alpha channel counts detected at 120mv and above.	
1500	1350-1650	1,490	1,490		
H.V. Set With Detector Not Connected				Overload to be set with detector to be used	

COMMENTS

Calibrated in accordance with OEM Technical Manual

See detector certificate for High Voltage setting

Calibrated with 5ft cable

Instrument Calibrated By: M Paul	Reviewed By: [signature] Date: 8/30/11
Calibration Date: 08/30/2011	*Calibration Due (6mo): 02/29/2012
	*Calibration Due (12mo): 08/30/2012

* Calibration due date is dependant on users regulatory requirements.

ENERGY*SOLUTIONS*

CALIBRATION CERTIFICATE

Energy*Solutions* Instrument Services
1570 Bear Creek Road
Oak Ridge, TN 37830
Phone: (877) 462-4873
Email: ISFstaff@energysolutions.com

This Certificate will be accompanied by Calibration Charts or Readings where applicable

CUSTOMER INFORMATION		DETECTOR INFORMATION
Customer Name: Energy*Solutions* Instrument Services		**Manufacturer: Ludlum**
Address: 1570 Bear Creek Road Oak Ridge, TN 37830		**Detector Model: 43-37A**
Contact Name: Tony Riggs		**Serial Number: 093966**
Customer Purchase Order Number: N/A	**Work Order Number: 2011-11248**	**Evaluation Method: Source**

DETECTOR EFFICIENCY/RESPONSE/PRECISION INFORMATION

Source Nuclide: Th^{230}	Serial Number: 119738	Activity: 18,600 dpm	2 Pi Emissions: 8,640	Certification Date: 10/20/97

Parameter	As Found	As Left	Precision Test	CPM
Count 1	3,852	3,852	Count 1 (Heel)	3,514
Count 2	3,816	3,816	Count 2 (Center)	3,681
Count 3	3,652	3,652	Count 3 (Toe)	3,746
Count 4	3,773	3,773	Average	3,647
Count 5	3,594	3,594	Tolerance	±10%
Count 6	3,523	3,523	Pass/Fail	Pass
Average	3,702	3,702		
Background (CPM)	14.6	14.6		
Net Counts	3,687	3,687		
2pi Efficiency	42.7%	42.7%		
4pi Efficiency	19.8%	19.8%		

Low Sample Activity: Source #: N/A	High Sample Activity: Source #: N/A	Dead Time (DT): N/A	Calibration Constant (CC): N/A

SCALER INFORMATION			DETECTOR INFORMATION		
Model	Serial Number	Due Date	Background (cpm)	Operating Voltage	Threshold
2360	275713	08/30/2012	14.6	1700V	Alpha (120mV) Beta (3.5-30mV)

Detector Setup Report YES NO √	Barcode Report YES NO √	Voltage Plateau YES √ NO

COMMENTS

5 minute background performed Efficiency performed on contact with 5Ft. cable 1 layer mylar (0.4mg/cm2)

STATEMENT OF CERTIFICATION

We Certify that the detector listed above was evaluated for proper operation prior to shipment and that it met all the Manufacturers published operating specifications. We further certify that our Calibration Measurements are traceable to the National Institute of Standards and Technology. (We are not responsible for damage incurred during shipment or use of this detector).

Detector Certified By: M. Paul	Reviewed By: Jeff Dickinson	Date: 5/30/12
Certification Date: 05/30/2012	*Certification Due (6mo): 11/30/2012	
	* Certification Due (12mo): 05/30/2013	

* Calibration due date is dependant on users regulatory requirements.

ENERGY*SOLUTIONS*

CALIBRATION CERTIFICATE

Energy*Solutions* Instrument Services
1570 Bear Creek Road
Oak Ridge, TN 37830
Phone: (877) 462-4873
Email: ISFstaff@energysolutions.com

This Certificate will be accompanied by Calibration Charts or Readings where applicable

CUSTOMER INFORMATION		DETECTOR INFORMATION
Customer Name: Energy*Solutions* Instrument Services		**Manufacturer: Ludlum**
Address: 1570 Bear Creek Road Oak Ridge, TN 37830		**Detector Model: 43-37B**
Contact Name: Tony Riggs		**Serial Number: 093966**
Customer Purchase Order Number: N/A	**Work Order Number: 2012-12264**	**Evaluation Method: Source**

DETECTOR EFFICIENCY/RESPONSE/PRECISION INFORMATION

Source Nuclide: Tc^{99}	Serial Number: 099608	Activity: 21,312 dpm	2 Pi Emissions: 10,500	Certification Date: 08/08/96

Parameter	As Found	As Left	Precision Test	CPM
Count 1	4,539	4,539	Count 1 (Heel)	4,553
Count 2	4,468	4,468	Count 2 (Center)	4,520
Count 3	4,429	4,429	Count 3 (Toe)	4,726
Count 4	4,493	4,493	Average	4,600
Count 5	4,765	4,765	Tolerance	±10%
Count 6	4,823	4,823	Pass/Fail	Pass
Average	4,586	4,586		
Background (CPM)	714.6	714.6		
Net Counts	3,872	3,872	Calibrated in accordance with ERIN-WI-239	
2pi Efficiency	36.9%	36.9%		
4pi Efficiency	18.2%	18.2%		

Low Sample Activity: Source #: N/A	High Sample Activity: Source #: N/A	Dead Time (DT): N/A	Calibration Constant (CC): N/A

SCALER INFORMATION			DETECTOR INFORMATION		
Model	Serial Number	Due Date	Background (cpm)	Operating Voltage	Threshold
2360	275713	08/30/2012	714.6	1700 V	Alpha (120mV) Beta (3.5-30mV)

Detector Setup Report YES NO √	Barcode Report YES NO √	Voltage Plateau YES √ NO

COMMENTS

5 minute background performed Efficiency performed on contact with 5Ft. cable 1 layer mylar (0.4mg/cm2)

STATEMENT OF CERTIFICATION

We Certify that the detector listed above was evaluated for proper operation prior to shipment and that it met all the Manufacturers published operating specifications. We further certify that our Calibration Measurements are traceable to the National Institute of Standards and Technology. (We are not responsible for damage incurred during shipment or use of this detector).

Detector Certified By: M. Paul	Reviewed By: J. Dickinson	Date: 5/30/12
Certification Date: 05/30/2012	*Certification Due (6mo): 11/30/2012	
	* Certification Due (12mo): 05/30/2013	

* Calibration due date is dependant on users regulatory requirements.

ENERGY*SOLUTIONS*

CALIBRATION CERTIFICATE

Energy*Solutions* Instrument Services
1570 Bear Creek Road
Oak Ridge, TN 37830
Phone: (877) 462-4873
Email: ISFstaff@energysolutions.com

This Certificate will be accompanied by Calibration Charts or Readings where applicable

CUSTOMER INFORMATION		DETECTOR INFORMATION
Customer Name: Energy*Solutions* Instrument Services		**Manufacturer: Ludlum**
Address: 1570 Bear Creek Road Oak Ridge, TN 37830		**Detector Model: 43-37B**
Contact Name: Tony Riggs		**Serial Number: 093966**
Customer Purchase Order Number: N/A	**Work Order Number: 2012-12264**	**Evaluation Method: Source**

DETECTOR EFFICIENCY/RESPONSE/PRECISION INFORMATION

Source Nuclide: C^{14}	Serial Number: 010002	Activity: 260,460 dpm	2 Pi Emissions: N/A	Certification Date:

Parameter	As Found	As Left	Precision Test	CPM
Count 1	25,917	25,917	Count 1 (Heel)	25,671
Count 2	25,604	25,604	Count 2 (Center)	26,628
Count 3	26,697	26,697	Count 3 (Toe)	28,323
Count 4	25,882	25,882	Average	26,874
Count 5	28,245	28,245	Tolerance	±10%
Count 6	27,953	27,953	Pass/Fail	Pass
Average	26,716	26,716		
Background (CPM)	714.6	714.6		
Net Counts	26,002	26,002		
2pi Efficiency	N/A	N/A		
4pi Efficiency	10.0%	10.0%		

Low Sample Activity: Source #: N/A	High Sample Activity: Source #: N/A	Dead Time (DT): N/A	Calibration Constant (CC): N/A

SCALER INFORMATION			DETECTOR INFORMATION		
Model	Serial Number	Due Date	Background (cpm)	Operating Voltage	Threshold
2360	275713	08/30/2012	714.6	1700 V	Alpha (120mV) Beta (3.5-30mV)

Detector Setup Report YES NO √	Barcode Report YES NO √	Voltage Plateau YES √ NO

COMMENTS

5 minute background performed Efficiency performed on contact with 5Ft. cable 1 layer mylar (0.4mg/cm2)

STATEMENT OF CERTIFICATION

We Certify that the detector listed above was evaluated for proper operation prior to shipment and that it met all the Manufacturers published operating specifications. We further certify that our Calibration Measurements are traceable to the National Institute of Standards and Technology. (We are not responsible for damage incurred during shipment or use of this detector).

Detector Certified By: M. Paul	Reviewed By: Jeff Dutkinson	Date: 5/31/12
Certification Date: 05/30/2012	*Certification Due (6mo): 11/30/2012	
	* Certification Due (12mo): 05/30/2013	

* Calibration due date is dependant on users regulatory requirements.

ENERGYSOLUTIONS

CALIBRATION CERTIFICATE

EnergySolutions Services, Inc
1570 Bear Creek Road
Oak Ridge, TN 37830

Phone: (877) 462-4873
Fax: (865) 220-1346
Email: Isfstaff@energysolutions.com

http://www.energysolutions.com/

This Certificate will be accompanied by Calibration Charts or Readings where applicable

CUSTOMER INFORMATION				INSTRUMENT INFORMATION			
Customer Name:	Energy Solutions			Manufacturer:			
Address:	1570 Bear Creek Road Oak Ridge, TN 37830			Model:	2360	S.N.	275713
Contact Name:	Tony Riggs			Probe:	43-37	S.N.	093966
Customer PO No.:	N/A	Work Order Number:	2012-12264	Calibration Method:	Source		

SOURCE INFORMATION

	Isotope	Source ID	Certifcation Date	Activity (dpm)
α Source	Pu-239	019442	6/1/92	13,607
β Source	Tc-99	099608	8/8/96	21,311

Ludlum Model 43-37 Alpha Scintillation Probe

Operating Voltage	High Voltage	Background (CPM)		Alpha (CPM)		Beta (CPM)		Observed Efficiency		Efficiency (4π)	
	1,600	10.0	182.0	2,661.0	462.0	22.0	3,719.0	11.29%	0.34%	19.48%	16.60%
	1,625	8.0	250.0	2,886.0	578.0	16.0	4,239.0	12.44%	0.20%	21.15%	18.72%
	1,650	12.0	335.0	2,999.0	618.0	25.0	4,625.0	10.62%	0.30%	21.95%	20.13%
	1,675	16.0	501.0	3,080.0	642.0	28.0	4,913.0	5.47%	0.27%	22.52%	20.70%
SET	**1,700**	**15.0**	**646.0**	**3,035.0**	**743.0**	**22.0**	**4,740.0**	**4.06%**	**0.17%**	**22.19%**	**19.21%**
	1,725	11.0	733.0	3,058.0	761.0	22.0	4,858.0	1.20%	0.27%	22.39%	19.36%
	1,750	18.0	846.0	3,309.0	1,061.0	106.0	3,954.0	8.73%	2.83%	24.19%	14.58%

STATEMENT OF CERTIFICATION

We Certify that the instrument listed above was calibrated and inspected prior to shipment and that it met all the Manufacturers published operating specifications. We further certify that our Calibration Measurements are traceable to the National Institute of Standards and Technology. (We are not responsible for damage incurred during shipment or use of this instrument).

Comments:

Calibrated By: M. Paul Reviewed By: J. Dickinson Date: 5/30/12

Calibration Date: 5/30/12 Calibration Due: 5/30/13

ENERGY*SOLUTIONS*

CALIBRATION CERTIFICATE

Energy*Solutions* Services, Inc.
1570 Bear Creek Road
Oak Ridge, TN 37830
Phone: (877) 462-4873
Fax: (865) 220-1346

This Certificate will be accompanied by Calibration Charts or Readings where applicable

CUSTOMER INFORMATION		INSTRUMENT INFORMATION	
Customer Name: Energy*Solutions* Services, Inc.		**Manufacturer: Ludlum**	
Address: 1570 Bear Creek Road Oak Ridge, TN 37830		**Model: 2360**	**Serial Number: 275724**
Contact Name: Tony Riggs		**Probe: N/A**	**Serial Number: N/A**
Customer Purchase Order Number: N/A	**Work Order Number: 2011-11716**	**Calibration Method: Electronic**	

INSTRUMENT CALIBRATION INFORMATION

Instrument Range	Calibration Standard Value	Ratemeter Response (± 10% of Standard Values)		Calibration Standard Value CPM	Time Base (minutes)	Tolerances (cpm) ± 2%	Scaler Response	
		As Found	As Left				As Found	As Left
X 1	100	100	100	1,000 CPM	0.1	90 – 110	99	99
X 1	250	250	250	1,000 CPM	0.5	450 – 550	493	493
X 1	400	400	400	1,000 CPM	1	900 – 1,100	988	988
X 10	1,000	1,000	1,000	1,000 CPM	2	1.8K–2.2K	1,979	1,979
X 10	2,500	2,500	2,500	1,000 CPM	5	4.5K-5.5K	4,948	4,948
X 10	4,000	4,000	4,000	1,000 CPM	10	9K-11K	9,896	9,896
X 100	10,000	10,000	10,000					
X 100	25,000	25,000	25,000					
X 100	40,000	40,000	40,000					
X 1000	100,000	100,000	100,000	Calibrated in accordance with OEM Technical Manual				
X 1000	250,000	250,000	250,000					
X 1000	400,000	400,000	400,000					

STATEMENT OF CERTIFICATION

We Certify that the instrument listed above was calibrated and inspected prior to shipment and that it met all the Manufacturers published operating specifications. We further certify that our Calibration Measurements are traceable to the National Institute of Standards and Technology. (We are not responsible for damage incurred during shipment or use of this instrument).

Instrument Calibrated By: M. Paul	**Reviewed By:** [signature] **Date:** 10/6/11
Calibration Date: 10/06/2011	***Calibration Due (6mo): 04/06/2012**
	***Calibration Due (12mo): 10/06/2012**

* Calibration due date is dependant on users regulatory requirements.

ENERGYSOLUTIONS

Model: 2360 Serial Number: 275724

M&TE					Environmental Conditions		
Volt Meter	ID#	94710023	Cal Due:	10/28/2011	Barometer	ID# 2551	Cal Due: 10/19/2011
Pulser	ID#	120935	Cal Due:	09/29/2012	Thermometer	ID# 2551	Cal Due: 10/19/2011
Humidity	ID#	958670	Cal Due:	06/07/2012	Temp: 21.4 °C	Pressure: 747 mmHg	Humidity: 45%

Special Test

BAT Check	Sat (√) Unsat ( )	Geotropism	Sat (√) Unsat ( )
LCD Display Check	Sat (√) Unsat ( )	Audio Check	Sat (√) Unsat ( )
Mechanical Zero	Sat (√) Unsat ( )	Low BAT Set	Sat (√) Unsat ( )
Reset	Sat (√) Unsat ( )		
HV Analog Display	Sat (√) Unsat ( )	As Found	As Left

High Voltage Calibration (± 10%)			
Voltage	Tolerance	As Found	As Left
500	450-550	502	502
1000	900-1100	1,018	1,018
1500	1350-1650	1,514	1,514

Alpha Sensitivity =	128 mv	Alpha Sensitivity =	120 mv
Beta Sensitivity =	3.7 mv	Beta Sensitivity =	3.5 mv
Beta Window =	30.8 mv	Beta Window =	30 mv

Beta Setpoints--Pulser counts detected at 3.5mv ± 1mv and shut off at 30mv for beta. For Alpha channel counts detected at 120mv and above.

H.V. Set With Detector Not Connected

Overload to be set with detector to be used

COMMENTS

Calibrated in accordance with OEM Technical Manual

See detector certificate for High Voltage setting

****Calibrated with 5ft cable****

Instrument	
Calibrated By: M. Powell	**Reviewed By:** [signature] **Date:** 10/6/11
Calibration Date: 10/06/2011	***Calibration Due (6mo): 04/06/2012**
	***Calibration Due (12mo): 10/06/2012**

* Calibration due date is dependant on users regulatory requirements.

ENERGYSOLUTIONS

CALIBRATION CERTIFICATE

EnergySolutions Services, Inc
1570 Bear Creek Road
Oak Ridge, TN 37830

Phone: (877) 462-4873
Fax: (865) 220-1346
Email: Isfstaff@energysolutions.com

http://www.energysolutions.com/

This Certificate will be accompanied by Calibration Charts or Readings where applicable

CUSTOMER INFORMATION				INSTRUMENT INFORMATION			
Customer Name:	Energy Solutions			Manufacturer:			
Address:	1570 Bear Creek Road Oak Ridge, TN 37830			Model:	2360	S.N.	275724
Contact Name:	Tony Riggs			Probe:	43-37	S.N.	092501
Customer PO No.:	N/A	Work Order Number:	2012-12264	Calibration Method:	Source		

Source Information

	Isotope	Source ID	Certifcation Date	Activity (dpm)
α Source	Pu-239	019442	6/1/92	13,607
β Source	Tc-99	099608	8/8/96	21,311

Ludlum Model 43-93 High Voltage Plateau with crosstalk

Operating Voltage	High Voltage	Background		Alpha Source		Beta Source		Crosstalk		Efficiency	
		Alpha	Beta	Alpha	Beta	Alpha	Beta	α to β	β to α	α	β
	1,650	6.0	400.0	2,318.0	563.0	7.0	4,457.0	8.50%	0.02%	16.99%	19.04%
SET	**1,675**	**7.0**	**445.0**	**2,527.0**	**611.0**	**11.0**	**4,545.0**	**7.97%**	**0.10%**	**18.52%**	**19.24%**
	1,700	5.0	422.0	2,452.0	732.0	7.0	4,330.0	15.27%	0.05%	17.98%	18.34%
	1,725	10.0	805.0	2,692.0	1,047.0	12.0	4,629.0	12.82%	0.05%	19.71%	17.94%

STATEMENT OF CERTIFICATION

We Certify that the instrument listed above was calibrated and inspected prior to shipment and that it met all the Manufacturers published operating specifications. We further certify that our Calibration Measurements are traceable to the National Institute of Standards and Technology. (We are not responsible for damage incurred during shipment or use of this instrument).

Comments:

Calibrated By: _____ Reviewed By: _____ Date: 5/30/12

Calibration Date: 5/30/12 Calibration Due: 5/30/13

ENERGYSOLUTIONS

CALIBRATION CERTIFICATE

EnergySolutions Instrument Services
1570 Bear Creek Road
Oak Ridge, TN 37830
Phone: (877) 462-4873
Email: ISFstaff@energysolutions.com

This Certificate will be accompanied by Calibration Charts or Readings where applicable

CUSTOMER INFORMATION		DETECTOR INFORMATION
Customer Name: EnergySolutions Instrument Services		Manufacturer: Ludlum
Address: 1570 Bear Creek Road Oak Ridge, TN 37830		Detector Model: 43-37B
Contact Name: Tony Riggs		Serial Number: 092501
Customer Purchase Order Number: N/A	Work Order Number: 2012-12264	Evaluation Method: Source

DETECTOR EFFICIENCY/RESPONSE/PRECISION INFORMATION

Source Nuclide: C^{14}	Serial Number: 010002	Activity: 260,460 dpm	2 Pi Emissions: N/A	Certification Date:

Parameter	As Found	As Left	Precision Test	CPM
Count 1	32,658	32,658	Count 1 (Heel)	32,658
Count 2	32,097	32,097	Count 2 (Center)	32,041
Count 3	32,006	32,006	Count 3 (Toe)	33,092
Count 4	32,041	32,041	Average	32,597
Count 5	32,759	32,759	Tolerance	±10%
Count 6	33,092	33,092	Pass/Fail	Pass
Average	32,442.2	32,442.2		
Background (CPM)	503	503		
Net Counts	31,939.2	31,939.2		
2pi Efficiency	N/A	N/A		
4pi Efficiency	12.3%	12.3%		

Low Sample Activity: Source #: N/A	High Sample Activity: Source #: N/A	Dead Time (DT): N/A	Calibration Constant (CC): N/A

SCALER INFORMATION			DETECTOR INFORMATION		
Model	Serial Number	Due Date	Background (cpm)	Operating Voltage	Threshold
2360	275724	10/06/2012	503	1675V	Alpha (120mV) Beta (3.5-30mV)

Detector Setup Report YES NO √	Barcode Report YES NO √	Voltage Plateau YES √ NO

COMMENTS

5 minute background performed Efficiency performed on contact with 5Ft. cable 1 layer mylar (0.4mg/cm2)

STATEMENT OF CERTIFICATION

We Certify that the detector listed above was evaluated for proper operation prior to shipment and that it met all the Manufacturers published operating specifications. We further certify that our Calibration Measurements are traceable to the National Institute of Standards and Technology. (We are not responsible for damage incurred during shipment or use of this detector).

Detector Certified By: [signature] Reviewed By: [signature] Date: 5/30/12

Certification Date: 05/30/2012

*Certification Due (6mo): 11/30/2012

* Certification Due (12mo): 05/30/2013

* Calibration due date is dependant on users regulatory requirements.

ENERGY*SOLUTIONS*

CALIBRATION CERTIFICATE

Energy*Solutions* Instrument Services
1570 Bear Creek Road
Oak Ridge, TN 37830
Phone: (877) 462-4873
Email: ISFstaff@energysolutions.com

This Certificate will be accompanied by Calibration Charts or Readings where applicable

CUSTOMER INFORMATION		DETECTOR INFORMATION
Customer Name: Energy*Solutions* Instrument Services		Manufacturer: Ludlum
Address: 1570 Bear Creek Road Oak Ridge, TN 37830		Detector Model: 43-37A
Contact Name: Tony Riggs		Serial Number: 092501
Customer Purchase Order Number: N/A	Work Order Number: 2012-12264	Evaluation Method: Source

DETECTOR EFFICIENCY/RESPONSE/PRECISION INFORMATION

Source Nuclide: Th^{230}	Serial Number: 119738	Activity: 18,600 dpm	2 Pi Emissions: 8,640/min	Certification Date: 10/20/97

Parameter	As Found	As Left	Precision Test	CPM
Count 1	2,899	2,899	Count 1 (Heel)	2,899
Count 2	2,927	2,927	Count 2 (Center)	2,811
Count 3	2,811	2,811	Count 3 (Toe)	2,968
Count 4	3,022	3,022	Average	2,892.7
Count 5	2,968	2,968	Tolerance	±10%
Count 6	2,864	2,864	Pass/Fail	Pass
Average	2,915.2	2,915.2		
Background (CPM)	6.9	6.9		
Net Counts	2,908.3	2,908.3		
2pi Efficiency	33.7%	33.7%		
4pi Efficiency	15.6%	15.6%		

Low Sample Activity: Source #: N/A	High Sample Activity: Source #: N/A	Dead Time (DT): N/A	Calibration Constant (CC): N/A

SCALER INFORMATION			DETECTOR INFORMATION		
Model	Serial Number	Due Date	Background (cpm)	Operating Voltage	Threshold
2360	275724	10/06/2012	6.9	1675V	Alpha (120mV) Beta (3.5-30mV)

Detector Setup Report YES NO √	Barcode Report YES NO √	Voltage Plateau YES √ NO

COMMENTS

5 minute background performed Efficiency performed on contact with 5Ft. cable 1 layer mylar (0.4mg/cm2)

STATEMENT OF CERTIFICATION

We Certify that the detector listed above was evaluated for proper operation prior to shipment and that it met all the Manufacturers published operating specifications. We further certify that our Calibration Measurements are traceable to the National Institute of Standards and Technology. (We are not responsible for damage incurred during shipment or use of this detector).

Detector Certified By:	Reviewed By:	Date: 5/30/12
Certification Date: 05/30/2012	*Certification Due (6mo): 11/30/2012	
	* Certification Due (12mo): 05/30/2013	

* Calibration due date is dependant on users regulatory requirements.

ENERGY*SOLUTIONS*

CALIBRATION CERTIFICATE

Energy*Solutions* Instrument Services
1570 Bear Creek Road
Oak Ridge, TN 37830
Phone: (877) 462-4873
Email: ISFstaff@energysolutions.com

This Certificate will be accompanied by Calibration Charts or Readings where applicable

CUSTOMER INFORMATION		DETECTOR INFORMATION
Customer Name: Energy*Solutions* Instrument Services		Manufacturer: Ludlum
Address: 1570 Bear Creek Road Oak Ridge, TN 37830		Detector Model: 43-37B
Contact Name: Tony Riggs		Serial Number: 092501
Customer Purchase Order Number: N/A	Work Order Number: 2012-12264	Evaluation Metbod: Source

DETECTOR EFFICIENCY/RESPONSE/PRECISION INFORMATION

Source Nuclide: Tc^{99}	Serial Number: 099608	Activity: 21,312 dpm	2 Pi Emissions: 10,500/min	Certification Date: 08/08/96

Parameter	As Found	As Left	Precision Test	CPM
Count 1	4,820	4,820	Count 1 (Heel)	4,820
Count 2	4,983	4,983	Count 2 (Center)	4,922
Count 3	4,922	4,922	Count 3 (Toe)	5,003
Count 4	4,767	4,767	Average	4,915
Count 5	4,857	4,857	Tolerance	±10%
Count 6	5,003	5,003	Pass/Fail	Pass
Average	4,892	4,892		
Background (CPM)	503	503		
Net Counts	4,389	4,389		
2pi Efficiency	41.8%	41.8%		
4pi Efficiency	20.6%	20.6%		

Low Sample Activity: Source #: N/A	High Sample Activity: Source #: N/A	Dead Time (DT): N/A	Calibration Constant (CC): N/A

SCALER INFORMATION			DETECTOR INFORMATION		
Model	Serial Number	Due Date	Background (cpm)	Operating Voltage	Threshold
2360	275724	10/06/2012	503	1675V	Alpha (120mV) Beta (3.5-30mV)

Detector Setup Report YES NO √	Barcode Report YES NO √	Voltage Plateau YES √ NO

COMMENTS

5 minute background performed Efficiency performed on contact with 5Ft. cable 1 layer mylar (0.4mg/cm2)

STATEMENT OF CERTIFICATION

We Certify that the detector listed above was evaluated for proper operation prior to shipment and that it met all the Manufacturers published operating specifications. We further certify that our Calibration Measurements are traceable to the National Institute of Standards and Technology. (We are not responsible for damage incurred during shipment or use of this detector).

Detector Certified By:	Reviewed By:	Date: 5/30/12
Certification Date: 05/30/2012	*Certification Due (6mo): 11/30/2012	
	* Certification Due (12mo): 05/30/2013	

* Calibration due date is dependant on users regulatory requirements.

Designer and Manufacturer of Scientific and Industrial Instruments

CERTIFICATE OF CALIBRATION

LUDLUM MEASUREMENTS, INC.
POST OFFICE BOX 810 PH. 325-235-5494
501 OAK STREET FAX NO. 325-235-4672
SWEETWATER, TEXAS 79556, U.S.A.

CUSTOMER US ARMY CORPS OF ENG BALTIMORE ORDER NO. 20181694/366617

Mfg. Ludlum Measurements, Inc. Model 19 Serial No. 245026

Mfg. _____ Model _____ Serial No. _____

Cal. Date 11-Aug-11 Cal Due Date 11-Aug-12 Cal. Interval 1 Year Meterface 202-1070

Check mark ☑ applies to applicable instr. and/or detector IAW mfg. spec. T. 74 °F RH 41 % Alt 698.8 mm Hg

☐ New Instrument Instrument Received ☐ Within Toler. +-10% ☐ 10-20% ☐ Out of Tol. ☑ Requiring Repair ☐ Other-See comments

☑ Mechanical ck. ☑ Meter Zeroed ☐ Background Subtract ☐ Input Sens. Linearity
☑ F/S Resp. ck ☑ Reset ck. ☐ Window Operation ☑ Geotropism
☑ Audio ck. ☐ Alarm Setting ck. ☑ Batt. ck. (Min. Volt) 2.2 VDC

☐ Calibrated in accordance with LMI SOP 14.8 rev 12/05/89. ☑ Calibrated in accordance with LMI SOP 14.9 rev 02/07/97.

Instrument Volt Set 650 V Input Sens. 30 mV Det. Oper. _____ V at _____ mV Threshold Dial Ratio _____ = _____ mV

☐ HV Readout (2 points) Ref./Inst. _____ / _____ V Ref./Inst. _____ / _____ V

COMMENTS:

Gamma Calibration: GM detectors positioned perpendicular to source except for M 44-9 in which the front of probe faces source.

RANGE/MULTIPLIER	REFERENCE CAL. POINT	INSTRUMENT REC'D "AS FOUND READING"	INSTRUMENT METER READING*
5000	4000µR/hr	N/A	4000
5000	1000µR/hr		1000
500	400µR/hr = 76,800 cpm		400
500	100µR/hr		100
250	200µR/hr = 38,000 cpm		200
250	100µR/hr		100
50	7680 cpm		40
50	1920 cpm		10
25	3800 cpm		20
25	950 cpm		5

*Uncertainty within ± 10% C.F. within ± 20% **Range(s) Calibrated Electronically**

	REFERENCE CAL. POINT	INSTRUMENT RECEIVED	INSTRUMENT METER READING*		REFERENCE CAL. POINT	INSTRUMENT RECEIVED	INSTRUMENT METER READING*
Digital Readout				Log Scale			

Ludlum Measurements, Inc. certifies that the above instrument has been calibrated by standards traceable to the National Institute of Standards and Technology, or to the calibration facilities of other International Standards Organization members, or have been derived from accepted values of natural physical constants or have been derived by the ratio type of calibration techniques. The calibration system conforms to the requirements of ANSI/NCSL Z540-1-1994 and ANSI N323-1978 State of Texas Calibration License No. LO-1963

Reference Instruments and/or Sources: ☐ 73410 ☐ 1131 ☐ 781 ☐ 059 ☐ 280 ☐ 60646 ☐ 70897

Cs-137 Gamma S/N ☐ 1162 ☐ G112 ☑ M565 ☐ 5105 ☐ T1008 ☐ T879 ☐ E552 ☐ E551 ☐ 720 ☐ 734 ☐ 1616 ☐ Neutron Am-241 Be S/N T-304

☐ Alpha S/N _____ ☐ Beta S/N _____ ☐ Other _____

☑ m 500 S/N 94940 ☐ Oscilloscope S/N _____ ☑ Multimeter S/N 78401031

Calibrated By: Scott Strom Date 11-Aug-11

Reviewed By: Richard Hanni Date 11 Aug 11

This certificate shall not be reproduced except in full, without the written approval of Ludlum Measurements, Inc.

AC Inst. Only ☐ Passed Dielectric (Hi-Pot) and Continuity Test ☐ Failed: _____

Designer and Manufacturer of Scientific and Industrial Instruments

LUDLUM MEASUREMENTS, INC.
POST OFFICE BOX 810 PH. 325-235-5494
501 OAK STREET FAX NO. 325-235-4672
SWEETWATER, TEXAS 79556, U.S.A.

CERTIFICATE OF CALIBRATION

CUSTOMER US ARMY CORPS OF ENG BALTIMORE ORDER NO. ~~20181691/366614~~ 20121647/366617

Mfg. Ludlum Measurements, Inc. Model 19 Serial No. 253050

Mfg. _____ Model _____ Serial No. _____

Cal. Date 11-Aug-11 Cal Due Date 11-Aug-12 Cal. Interval 1 Year Meterface 202-1070

Check mark ☑ applies to applicable instr. and/or detector IAW mfg. spec. T. 74 °F RH 38 % Alt 698.8 mm Hg

☐ New Instrument Instrument Received ☑ Within Toler. +-10% ☐ 10-20% ☐ Out of Tol. ☐ Requiring Repair ☐ Other-See comments

☑ Mechanical ck. ☑ Meter Zeroed ☐ Background Subtract ☐ Input Sens. Linearity
☑ F/S Resp. ck ☑ Reset ck. ☐ Window Operation ☑ Geotropism
☑ Audio ck. ☐ Alarm Setting ck. ☑ Batt. ck. (Min. Volt) 2.2 VDC

☐ Calibrated in accordance with LMI SOP 14.8 rev 12/05/89. ☑ Calibrated in accordance with LMI SOP 14.9 rev 02/07/97.

Instrument Volt Set 686 V Input Sens. 29 mV Det. Oper. _____ V at _____ mV Threshold Dial Ratio _____ = _____ mV

☐ HV Readout (2 points) Ref./Inst. _____ / _____ V Ref./Inst. _____ / _____ V

COMMENTS:

Gamma Calibration: GM detectors positioned perpendicular to source except for M 44-9 in which the front of probe faces source.

RANGE/MULTIPLIER	REFERENCE CAL. POINT	INSTRUMENT REC'D "AS FOUND READING"	INSTRUMENT METER READING*
5000	4000µR/hr	4100	4000
5000	1000µR/hr	1100	1000
500	400µR/hr = 76,000 cpm	395	400
500	100µR/hr	95	100
250	200µR/hr = 37,600 cpm	210	200
250	100µR/hr	110	100
50	7600 cpm	39.5	40
50	1900 cpm	9.5	10
25	3760 cpm	19.5	20
25	940 cpm	4.5	5

*Uncertainty within ± 10% C.F. within ± 20%

Range(s) Calibrated Electronically

	REFERENCE CAL. POINT	INSTRUMENT RECEIVED	INSTRUMENT METER READING*		REFERENCE CAL. POINT	INSTRUMENT RECEIVED	INSTRUMENT METER READING*
Digital Readout				Log Scale			

Ludlum Measurements, Inc. certifies that the above instrument has been calibrated by standards traceable to the National Institute of Standards and Technology, or to the calibration facilities of other International Standards Organization members, or have been derived from accepted values of natural physical constants or have been derived by the ratio type of calibration techniques.
The calibration system conforms to the requirements of ANSI/NCSL Z540-1-1994 and ANSI N323-1978 State of Texas Calibration License No. LO-1963

Reference Instruments and/or Sources: ☐ 73410 ☐ 1131 ☐ 781 ☐ 059 ☐ 280 ☐ 60646 ☐ 70897

Cs-137 Gamma S/N ☐ 1162 ☐ G112 ☑ M565 ☐ 5105 ☐ T1008 ☐ T879 ☐ E552 ☐ E551 ☐ 720 ☐ 734 ☐ 1616 ☐ Neutron Am-241 Be S/N T-304

☐ Alpha S/N _____ ☐ Beta S/N _____ ☐ Other _____

☑ m 500 S/N 94940 ☐ Oscilloscope S/N _____ ☑ Multimeter S/N 78401031

Calibrated By: Scott Stone Date 11-Aug-11

Reviewed By: Richard Wine Date 11 Aug 11

This certificate shall not be reproduced except in full, without the written approval of Ludlum Measurements, Inc.

AC Inst. Only ☐ Passed Dielectric (Hi-Pot) and Continuity Test ☐ Failed: _____

EBERLINE SERVICES

CERTIFICATE OF CALIBRATION

Electroplated Alpha Standard

S.O.# 7155
P.O.# C/C

Description of Standard:

Model No. DNS-11 Serial No. 7241-11 Isotope Th-230

Electroplated on polished SS disc, 0.79 mm thick.

Total diameter of 4.77 cm and an active diameter of 4.45 cm.

The radioactive material is permanently fixed to the disc by heat treatment without any covering over the active surface.

Measurement Method:

The 2pi alpha emission rate was measured using an internal gas flow proportional chamber. Absolute counting of alpha particles emitted in the hemisphere above the active surface was verified by counting above, below, and at the operative voltage. The calibration is traceable to NIST by reference to an NIST calibrated alpha source S/N 75322-201

Measurement Result:

The observed alpha particles emitted from the surface of the disc per minute (cpm) on the calibration date was:

11,300 ± 338

The total disintegration rate (dpm) assuming 1.5% backscatter of alpha particles from the surface of the disc, was:

22,200 ± 666 (0.0100 μCi)

The uncertainty of the measurement is 3 %, which is the sum of random counting error at the 99% confidence level, and the estimated upper limit of systematic error in this measurement.

Calibrated by: ART REUST Reviewed by:

Calibration Technician: Art Reust Q.A. Manager: Lori Jordan

Calibration Date: 10-03-2011 Reviewed Date: 10/10/2011

Source Manufacturing Lab
7021 Pan American Freeway NE
Albuquerque, New Mexico 87109-4238
(505) 761-5413 Fax (505) 761-5416
art.reust@eberlineservices.com

EBERLINE SERVICES

CERTIFICATE OF CALIBRATION

Electroplated Alpha Standard

S.O.# 7155
P.O.# C/C

Description of Standard:

Model No. DNS-11 Serial No. 7242-11 Isotope Th-230

Electroplated on polished SS disc, 0.79 mm thick.

Total diameter of 4.77 cm and an active diameter of 4.45 cm.

The radioactive material is permanently fixed to the disc by heat treatment without any covering over the active surface.

Measurement Method:

The 2pi alpha emission rate was measured using an internal gas flow proportional chamber. Absolute counting of alpha particles emitted in the hemisphere above the active surface was verified by counting above, below, and at the operative voltage. The calibration is traceable to NIST by reference to an NIST calibrated alpha source S/N 75322-201

Measurement Result:

The observed alpha particles emitted from the surface of the disc per minute (cpm) on the calibration date was:

14,600 ± 438

The total disintegration rate (dpm) assuming 1.5% backscatter of alpha particles from the surface of the disc, was:

28,800 ± 863 (0.0130 μCi)

The uncertainty of the measurement is 3 %, which is the sum of random counting error at the 99% confidence level, and the estimated upper limit of systematic error in this measurement.

Calibrated by: ART REUST Reviewed by:

Calibration Technician: Art Reust Q.A. Manager: Lori Jordan

Calibration Date: 10-03-2011 Reviewed Date: 10/10/2011

Source Manufacturing Lab
7021 Pan American Freeway NE
Albuquerque, New Mexico 87109-4238
(505) 761-5413 Fax (505) 761-5416
art.reust@eberlineservices.com

EBERLINE SERVICES

CERTIFICATE OF CALIBRATION

Electroplated Alpha Standard

S.O.# 7155
P.O.# C/C

Description of Standard:

Model No. DNS-11 Serial No. 7244-11 Isotope Th-230

Electroplated on polished SS disc, 0.79 mm thick.

Total diameter of 4.77 cm and an active diameter of 4.45 cm.

The radioactive material is permanently fixed to the disc by heat treatment without any covering over the active surface.

Measurement Method:

The 2pi alpha emission rate was measured using an internal gas flow proportional chamber. Absolute counting of alpha particles emitted in the hemisphere above the active surface was verified by counting above, below, and at the operative voltage. The calibration is traceable to NIST by reference to an NIST calibrated alpha source S/N 75322-201

Measurement Result:

The observed alpha particles emitted from the surface of the disc per minute (cpm) on the calibration date was:

12,200 ± 365

The total disintegration rate (dpm) assuming 1.5% backscatter of alpha particles from the surface of the disc, was:

24,000 ± 720 (0.0108 μCi)

The uncertainty of the measurement is 3 %, which is the sum of random counting error at the 99% confidence level, and the estimated upper limit of systematic error in this measurement.

Calibrated by: ART REUST Reviewed by:

Calibration Technician: Art Reust Q.A. Manager: Lori Jordan

Calibration Date: 10-03-2011 Reviewed Date: 10/10/2011

Source Manufacturing Lab
7021 Pan American Freeway NE
Albuquerque, New Mexico 87109-4238
(505) 761-5413 Fax (505) 761-5416
art.reust@eberlineservices.com

EBERLINE SERVICES

CERTIFICATE OF CALIBRATION

Electroplated Beta Standard

S.O.# 7156
P.O.# C/C

Description of Standard:

Model No. DNS-12 Serial No. 7246-11 Isotope Tc-99

Electroplated on polished SS disc, 0.79 mm thick.

Total diameter of 4.77 cm and an active diameter of 4.45 cm.

The radioactive material is permanently fixed to the disc by heat treatment without any covering over the active surface.

Measurement Method:

The 2pi beta emission rate was measured using an internal gas flow proportional chamber. Absolute counting of beta particles emitted in the hemisphere above the active surface was verified by counting above, below, and at the operative voltage. The calibration is traceable to NIST by reference to an NIST calibrated beta source S/N 75323-201.

Measurement Result:

The observed beta count rate from the surface of the disc per minute (cpm) on the calibration date was:

11,500 ± 458

The total disintegration rate (dpm) assuming 25 % backscatter of beta particles from the surface of the disc, was:

18,300 ± 733 (0.00826 μCi)

The uncertainty of the measurement is 4 %, which is the sum of random counting error at the 99% confidence level, and the estimated upper limit of systematic error in this measurement.

Calibrated by: ART REUST Reviewed by:

Calibration Technician: Q.A. Manager:

Calibration Date: 10-03-2011 Reviewed Date: 10/10/2011

Source Manufacturing Lab
7021 Pan American Freeway NE
Albuquerque, New Mexico 87109-4238
(505) 761-5413 Fax (505) 761-5416
art.reust@eberlineservices.com

EBERLINE SERVICES

CERTIFICATE OF CALIBRATION

Electroplated Beta Standard

S.O.# 7156
P.O.# C/C

Description of Standard:

Model No. DNS-12 Serial No. 7245-11 Isotope Tc-99

Electroplated on polished SS disc, 0.79 mm thick.

Total diameter of 4.77 cm and an active diameter of 4.45 cm.

The radioactive material is permanently fixed to the disc by heat treatment without any covering over the active surface.

Measurement Method:

The 2pi beta emission rate was measured using an internal gas flow proportional chamber. Absolute counting of beta particles emitted in the hemisphere above the active surface was verified by counting above, below, and at the operative voltage. The calibration is traceable to NIST by reference to an NIST calibrated beta source S/N 75323-201.

Measurement Result:

The observed beta count rate from the surface of the disc per minute (cpm) on the calibration date was:

6,600 ± 329

The total disintegration rate (dpm) assuming 25 % backscatter of beta particles from the surface of the disc, was:

10,600 ± 527 (0.00475 μCi)

The uncertainty of the measurement is 5 %, which is the sum of random counting error at the 99% confidence level, and the estimated upper limit of systematic error in this measurement.

Calibrated by: ART REUST Reviewed by:

Calibration Technician: Art Reust Q.A. Manager: Lori Wallace

Calibration Date: 10-03-2011 Reviewed Date: 10/10/2011

Source Manufacturing Lab
7021 Pan American Freeway NE
Albuquerque, New Mexico 87109-4238
(505) 761-5413 Fax (505) 761-5416
art.reust@eberlineservices.com

EBERLINE SERVICES

CERTIFICATE OF CALIBRATION

Electroplated Beta Standard

S.O.# 7156
P.O.# C/C

Description of Standard:

Model No. DNS-12 Serial No. 7248-11 Isotope Tc-99

Electroplated on polished SS disc, 0.79 mm thick.

Total diameter of 4.77 cm and an active diameter of 4.45 cm.

The radioactive material is permanently fixed to the disc by heat treatment without any covering over the active surface.

Measurement Method:

The 2pi beta emission rate was measured using an internal gas flow proportional chamber. Absolute counting of beta particles emitted in the hemisphere above the active surface was verified by counting above, below, and at the operative voltage. The calibration is traceable to NIST by reference to an NIST calibrated beta source S/N 75323-201.

Measurement Result:

The observed beta count rate from the surface of the disc per minute (cpm) on the calibration date was:

10,800 ± 430

The total disintegration rate (dpm) assuming 25 % backscatter of beta particles from the surface of the disc, was:

17,200 ± 688 (0.00775 μCi)

The uncertainty of the measurement is 4 %, which is the sum of random counting error at the 99% confidence level, and the estimated upper limit of systematic error in this measurement.

Calibrated by: ART REUST Reviewed by:

Calibration Technician: Art Reust Q.A. Manager: Lori Jordan

Calibration Date: 10-03-2011 Reviewed Date: 10/10/2011

Source Manufacturing Lab
7021 Pan American Freeway NE
Albuquerque, New Mexico 87109-4238
(505) 761-5413 Fax (505) 761-5416
art.reust@eberlineservices.com

APPENDIX F

Instrument Quality Control Data

Instrument Setup - Chi Squared and Efficiency

Model:	2,360	**SN#**	275724	**PROBE**	43-37	**SN#**	092501	**Cal Due:**	6-Oct-12
Source:	TH-230	**SN#**	7241-11	**Activity (cpm):**	11,300	**Surf Eff**	0.25	**Cal Date:**	3-Oct-11
Source:	TC-99	**SN#**	7248-11	**Activity (cpm):**	10,800	**Surf Eff**	0.25	**Cal Date:**	3-Oct-11
								Date Performed:	**5-Jun-12**

	1 min count	
Count No.	Alpha	Beta
1	4356	4372
2	4311	4205
3	4329	4197
4	4395	4152
5	4331	4257
6	4402	4256
7	4297	4251
8	4312	4204
9	4283	4245
10	4354	4311
11	4429	4243
12	4375	4328
13	4194	4187
14	4324	4152
15	4307	4147
16	4377	4245
17	4282	4221
18	4290	4236
19	4296	4262
20	4278	4212
21	4432	4169
22	4434	4219
23	4271	4213
24	4295	4327
25	4361	4257
26	4328	4258
27	4284	4178
28	4201	4220
29	4395	4175
30	4313	4186

Average	4328	4230
Variance	3639	2978

Reduced Chi sq **0.8** **0.7** PASS

		Chi2	reduced Chi2
For 29 degrees of freedom p= 0.05, 0.95:	High	42.557	**1.5**
	Low	17.708	**0.61**

Efficiency Determination

	Alpha	Beta
Bkg (cpm)	4	319
Net	4324	3911
Ei	0.38	0.36
Es	0.25	0.25
Etot	**9.57%**	**9.05%**

Instrument Setup - Chi Squared and Efficiency

Model:	2,360	**SN#**	275713	**PROBE**	43-37	**SN#**	093966	**Cal Due:**	30-Aug-12
Source:	TH-230	**SN#**	7244-11	**Activity (cpm):**	12,200	**Surf Eff**	0.25	**Cal Date:**	3-Oct-11
Source:	TC-99	**SN#**	7245-11	**Activity (cpm):**	6,600	**Surf Eff**	0.25	**Cal Date:**	3-Oct-11
								Date Performed:	**5-Jun-12**

	1 min count	
Count No.	Alpha	Beta
1	4710	2814
2	4735	2893
3	4729	2854
4	4786	2835
5	4791	2841
6	4690	2790
7	4757	2822
8	4776	2889
9	4753	2694
10	4862	2826
11	4731	2810
12	4783	2828
13	4728	2821
14	4822	2848
15	4809	2895
16	4664	2921
17	4805	2815
18	4645	2792
19	4650	2816
20	4831	2763
21	4707	2896
22	4781	2926
23	4858	2829
24	4828	2819
25	4731	2876
26	4901	2881
27	4821	2896
28	4725	2893
29	4804	2910
30	4874	2858

Average	4770	2845
Variance	4377	2600

Reduced Chi sq **0.9** **0.9** PASS

		Chi2	reduced Chi2
For 29 degrees of freedom p= 0.05, 0.95:	High	42.557	**1.5**
	Low	17.708	**0.61**

Efficiency Determination		
	Alpha	Beta
Bkg (cpm)	2	433
Net	4768	2412
Ei	0.39	0.37
Es	0.25	0.25
Etot	**9.8%**	**9.1%**

Instrument Setup - Chi Squared and Efficiency

Model:	2,360	**SN#**	138251	**PROBE**	43-37-1	**SN#**	136631	**Cal Due:**	23-May-13
Source:	TH-230	**SN#**	7242-11	**Activity:**	14,600	**Surf Eff**	0.25	**Cal Date:**	3-Oct-11
Source:	TC-99	**SN#**	7246-11	**Activity:**	11,500	**Surf Eff**	0.25	**Cal Date:**	3-Oct-11
								Date Performed:	**5-Jun-12**


	1 min count	
Count No.	Alpha	Beta
1	6264	4313
2	6211	4288
3	6088	4360
4	6229	4336
5	6284	4416
6	6230	4294
7	6331	4396
8	6425	4329
9	6356	4421
10	6257	4530
11	6139	4423
12	6208	4529
13	6178	4407
14	6334	4374
15	6287	4337
16	6266	4542
17	6269	4317
18	6207	4407
19	6141	4511
20	6201	4435
21	6380	4347
22	6208	4397
23	6271	4315
24	6271	4344
25	6297	4420
26	6275	4363
27	6227	4356
28	6342	4474
29	6317	4392
30	6357	4392

Average	6262	4392
Variance	5728	4926


Reduced Chi sq **0.9** **1.1** PASS

		Chi2	reduced Chi2
For 29 degrees of freedom p= 0.05, 0.95:	High	42.557	**1.5**
	Low	17.708	**0.61**

Efficiency Determination		
	Alpha	Beta
Bkg (cpm)	5	528
Net	6257	3864
Ei	0.43	0.34
Es	0.25	0.25
Etot	**10.71%**	**8.40%**




Model:	19	**SN#**	245026	**PROBE**	NA	**SN#**		**Cal Due:**	8/11/2012
Source:	Cs-137	**SN#**	0906117	**Activity (uCi):**	0.256	**Surf Eff**		**Cal Date:**	8/11/2011
Mean	**+2s**	**-2s**	**+3s:**	**-3s**	**+20%**	**-20%**		**Date:**	6/5/2012
59	66	52	70	49	71	47		**Efficiency:**	
Chk.#	**Gross**	**Net**	**Chk.#**	**Gross**	**Net**	**Chk.#**	**Gross**	**Net**	**COMMENTS**
1	65	60	11	60	55	21	65	60	
2	60	55	12	70	65	22	60	55	
3	65	60	13	65	60	23	65	60	
4	70	65	14	65	60	24	65	60	
5	60	55	15	60	55	25	70	65	
6	65	60	16	65	60	26	65	60	
7	65	60	17	60	55	27	60	55	
8	60	55	18	60	55	28	70	65	
9	60	55	19	65	60	29	65	60	
10	65	60	20	70	65	30	65	60	
Bkgd:	5	uR/hr	**Mean:**	59	uR/hr	**2sigma:**	6 uR/hr	**3sigma:**	10 uR/hr




Daily Exposure Rate in uR/hr										
	Date	Gross	BKG	NET	GROSS	BKG	NET	GROSS	BKG	NET
1	6/8/2012 pre building 283	80	12	68			0			0
2	6/8/2012 post building 283	80	12	68			0			0
3	6/11/2012 pre building 1205	65	7	58			0			0
4	6/11/2012 post building 1205	70	10	60			0			0
5	6/11/2012 pre building 2540 SU 1	70	10	60			0			0
6	6/11/2012 post building 2540 SU 1	75	11	64			0			0
7	6/12/2012 pre building 2540	65	8	57			0			0
8	6/12/2012 post building 2540 SU 3	80	12	68			0			0
9	6/12/2012 post building 2540 SU 13	70	10	60			0			0
10	6/13/2012 pre building 2540	70	9	61			0			0
11	6/13/2012 pre building 2540 afternoon	75	10	65			0			0
12	6/13/2012 post building 2540	70	10	60			0			0

	afternoon									
13	6/14/2012 pre building 2540 SU 7 AM	65	12	53			0			0
14	6/14/2012 post building 2540 SU AM	75	9	66			0			0
15	6/14/2012 post building 2540 SU 14	70	8	62			0			0
16	6/14/2012 pre building 2540 afternoon	70	11	59			0			0
17	6/15/2012 pre buliding 2540 AM	75	10	65			0			0
18	6/15/2012 pre building 2540 PM	70	9	61			0			0
19	6/15/2012 post building 2540 afternoon	70	8	62			0			0
20	6/18/2012 pre buiding 2540 AM	80	11	69			0			0
21	6/18/2012 post building 2540 AM	75	10	65			0			0
22	6/18/2012 post building 2540 PM	65	8	57			0			0
23	6/19/2012 pre building 2540 AM	75	9	66			0			0
24	6/19/2012 post building 2540 PM	75	8	67			0			0
25	6/20/2012 pre building 283 AM	75	10	65			0			0
26	6/20/2012 post building 283 AM	70	10	60			0			0
27	6/20/2012 post building 2540 PM	75	9	66			0			0
28	6/21/2012 pre building 283 AM	65	9	56			0			0
29				0			0			0
30				0			0			0




Model:	19	**SN#**	253050	**PROBE**	NA	**SN#**		**Cal Due:**	8/11/2012
Source:	Cs-137	**SN#**	0906117	**Activity (uCi):**	0.256	**Surf Eff**	0.25	**Cal Date:**	8/11/2012
Mean	**+2s**	**-2s**	**+3s:**	**-3s**	**+20%**	**-20%**		**Date:**	6/5/2012
58	66	50	70	46	70	47		**Efficiency:**	
Chk.#	**Gross**	**Net**	**Chk.#**	**Gross**	**Net**	**Chk.#**	**Gross**	**Net**	**COMMENTS**
1	60	56	11	60	56	21	65	61	
2	65	61	12	55	51	22	60	56	
3	70	66	13	60	56	23	65	61	
4	60	56	14	60	56	24	60	56	
5	65	61	15	60	56	25	70	66	
6	60	56	16	65	61	26	65	61	
7	55	51	17	60	56	27	65	61	
8	60	56	18	55	51	28	60	56	
9	60	56	19	65	61	29	70	66	
10	65	61	20	60	56	30	65	61	
Bkgd:	4	uR/hr	**Mean:**	58	uR/hr	**2sigma:**	8 uR/hr	**3sigma:**	12 uR/hr




Daily Exposure Rate in uR/hr										
	Date	Gross	BKG	NET	GROSS	BKG	NET	GROSS	BKG	NET
1	6/11/2012 pre building 1205	70	8	62			0			0
2	6/11/2012 post building 1205	70	8	62			0			0
3	6/11/2012 pre building 2540 SU 1	75	10	65			0			0
4	6/11/2012 post building 2540 SU 1	70	9	61			0			0
5	6/11/2012 pre building 2540	70	9	61			0			0
6	6/12/2012 pre building 2540	70	9	61			0			0
7	6/12/2012 post building 2540 SU 13	75	10	65			0			0
8	6/13/2012 pre building 2540	70	10	60			0			0
9	6/13/2012 pre building 2540 afternoon	75	10	65			0			0
10	6/13/2012 post building 2540 afternoon	65	8	57			0			0
11	6/14/2012 pre building 2540 SU 7	70	10	60			0			0

12	6/14/2012 post building 2540 SU 7	70	10	60			0			0
13	6/14/2012 post building 2540 SU 14	75	9	66			0			0
14	6/14/2012 pre building 2540 afternoon	70	10	60			0			0
15	6/15/2012 post building 2540 AM	65	10	55			0			0
16	6/15/2012 pre building 2540 PM	75	10	65			0			0
17	6/18/2012 pre building 2540 AM	75	10	65			0			0
18	6/18/2012 post building 2540 AM	70	8	62			0			0
19	6/18/2012 post building 2540 PM	70	8	62			0			0
20	6/18/2012 pre building 2540 AM	75	8	67			0			0
21	6/18/2012 post building 2540 PM	70	8	62			0			0
22	6/20/2012 pre building 283 AM	65	10	55			0			0
23	6/20/2012 post building 283 AM	70	10	60			0			0
24	6/21/2012 pre building 283 AM	70	9	61			0			0
25				0			0			0
26				0			0			0
27				0			0			0
28				0			0			0
29				0			0			0
30				0			0			0




Model:	2,360	**SN#**	275713	**PROBE**	43-37	**SN#**	093966	**Cal Due:**	8/30/2012
Source:	TH-230	**SN#**	7244-11	**Activity (cpm):**	12,200	**Surf Eff**	0.25	**Cal Date:**	8/30/2011
Mean	**+2s**	**-2s**	**+3s:**	**-3s**	**+20%**	**-20%**		**Date:**	6/5/2012
4,768	4,900	5,239	4,966	4,569	5,721	3,814		**Efficiency:**	9.8%
Chk.#	**Gross**	**Net**	**Chk.#**	**Gross**	**Net**	**Chk.#**	**Gross**	**Net**	**COMMENTS**
1	4,710	4,708	11	4,731	4,729	21	4,707	4,705	
2	4,735	4,733	12	4,783	4,781	22	4,781	4,779	
3	4,729	4,727	13	4,728	4,726	23	4,858	4,856	
4	4,786	4,784	14	4,822	4,820	24	4,828	4,826	
5	4,791	4,789	15	4,809	4,807	25	4,731	4,729	
6	4,690	4,688	16	4,664	4,662	26	4,901	4,899	
7	4,757	4,755	17	4,805	4,803	27	4,821	4,819	
8	4,776	4,774	18	4,645	4,643	28	4,725	4,723	
9	4,753	4,751	19	4,650	4,648	29	4,804	4,802	
10	4,862	4,860	20	4,831	4,829	30	4,874	4,872	
Bkgd:	2	CPM	**Mean:**	4,768	CPM	**2sigma:**	132 CPM	**3sigma:**	198 CPM



Daily Alpha in CPM										
	Date	Gross	BKG	NET	GROSS	BKG	NET	GROSS	BKG	NET
1	6/5/2012 pre building 275	4885	1	4884			0			0
2	6/5/2012 post building 275	5101	1	5100			0			0
3	6/6/2012 pre building 292	4762	2	4760			0			0
4	6/7/2012 AM	5331	1	5330			0			0
5	6/7/2012 pre building 283	5406	4	5402			0			0
6	6/7/2012 post building 283	4729	1	4728			0			0
7	6/8/2012 pre building 283	4708	3	4705			0			0
8	6/8/2012 post building 283	4691	9	4682			0			0
9	6/11/2012 AM	4665	1	4664			0			0
10	6/11/2012 pre buliding 1205	4574	1	4573			0			0
11	6/11/2012 post building 1205	4714	4	4710			0			0
12	6/11/2012 pre building 2540 SU1	4832	1	4831			0			0


13	6/11/2012 post building 2540 SU 1	5257	9	5248			0			0
14	6/12/2012 pre building 2540	5335	2	5333			0			0
15	6/12/2012 post building 2540 SU 3	5340	16	5324			0			0
16	6/12/2012 pre building 2540 SU 12	5386	3	5383			0			0
17	6/12/2012 post building 2540 SU 13	5061	2	5059			0			0
18	6/13/2012 pre building 2540 SU 6	4978	6	4972			0			0
19	6/13/2012 post building 2540 SU 6	5126	3	5123			0			0
20	6/13/2012 pre building 2540 afternoon	5152	7	5145			0			0
21	6/13/2012 post building 2540 afternoon	5303	2	5301			0			0
22	6/14/2012 pre building 2540 SU 7	5018	7	5011			0			0
23	6/14/2012 post building 2540 SU 7 AM	5462	5	5457			0			0
24	6/14/2012 post building 2540 SU 14	5013	2	5011			0			0
25	6/14/2012 pre building 2540 afternoon	4950	1	4949			0			0
26	6/14/2012 post building 2540 afternoon	4983	4	4979			0			0
27	6/15/2012 pre building 2540 AM	4979	7	4972			0			0
28	6/15/2012 post building 2540 AM	5212	2	5210			0			0
29	6/15/2012 pre building 2540 afternoon	5246	1	5245			0			0
30	6/15/2012 post building 2540 afternoon	5324	0	5324			0			0
31	6/18/2012 pre building 2540 AM	5163	5	5158			0			0
32	6/18/2012 post building 2540 AM	5332	2	5330			0			0
33	6/18/2012 pre building 2540 PM	5545	5	5540			0			0
34	6/18/2012 post building 2540 PM	5333	2	5331			0			0
35	6/19/2012 pre building 2540 AM	5315	17	5298			0			0
36	6/19/2012 pre building 2540 PM	5318	2	5316			0			0
37	6/19/2012 post buiding 2540 PM	5360	2	5358			0			0
38	6/20/2012 pre building 283 AM	5017	2	5015			0			0
39	6/20/2012 post building 283 AM	5242	13	5229			0			0
40	6/20/2012 post building 2540 PM	5306	5	5301			0			0
41	6/21/2012 pre building 2540 AM	5248	3	5245			0			0
42				0			0			0
43				0			0			0



Model:	2360	SN#	275713	PROBE	43-37	SN#	93966	Cal Due:	30Aug12
Source:	TC-99	SN#	7245-11	Activity:	6,600	Surf eff	0.25	Cal Date:	30Aug20111
Mean	+2s	-2s	+3s:	-3s	+20%	-20%		Date:	5Jun12
2,412	2,514	2,310	2,565	2,259	2,984	1,930		Efficiency:	9.14%


Chk.#	Gross	Net	Chk.#	Gross	Net	Chk.#	Gross	Net	COMMENTS
1	2814	2381	11	2810	2377	21	2896	2463	
2	2893	2460	12	2828	2395	22	2926	2493	
3	2854	2421	13	2821	2388	23	2829	2396	
4	2835	2402	14	2848	2415	24	2819	2386	
5	2841	2408	15	2895	2462	25	2876	2443	
6	2790	2357	16	2921	2488	26	2881	2448	
7	2822	2389	17	2815	2382	27	2896	2463	
8	2889	2456	18	2792	2359	28	2893	2460	
9	2694	2261	19	2816	2383	29	2910	2477	
10	2826	2393	20	2763	2330	30	2858	2425	

Bkgd:	433	CPM	Mean:	2412	CPM	2sigma:	101 CPM	3sigma:	152 CPM



	Daily Beta Checks in CPM									
	Date	Gross	BKG	NET	GROSS	BKG	NET	GROSS	BKG	NET
1	6/5/12 pre building 275	2968	477	2491			0			0
2	6/5/12 post building 275	2874	518	2356			0			0
3	6/6/12 AM	2832	428	2404			0			0
4	6/7/2012 AM	2776	338	2438			0			0
5	6/7/2012 pre building 283	2995	568	2427			0			0
6	6/7/2012 post building 283	3067	517	2550			0			0
7	6/8/2012 pre building 283	3021	429	2592			0			0
8	6/8/2012 post building 283	3121	630	2491			0			0
9	6/112012 AM	2847	334	2513			0			0
10	6/11/2012 pre building 1205	2744	296	2448			0			0
11	6/11/2012 post tile	2923	377	2546			0			0
12	6/11/2012 post building 1205	2983	445	2538			0			0
13	6/11/2012 pre building 2540 SU1	3157	668	2489			0			0
14	6/11/2012 post building 2540 SU 1	3233	793	2440			0			0


15	6/12/2012 pre building 2540	3270	795	2475			0			0
16	6/12/2012 post building 2540	3304	816	2488			0			0
17	6/12/2012 pre building 2540 SU 12	3300	821	2479			0			0
18	6/12/2012 post building 2540 SU 13	2941	411	2530			0			0
19	6/13/2012 pre building 2540	3280	821	2459			0			0
20	6/13/2012 post building 2540 SU 6	3122	795	2327			0			0
21	6/13/2012 pre building 2540 afternoon	3296	798	2498			0			0
22	6/13/2012 post building 2540 afternoon	3041	732	2309			0			0
23	6/14/2012 pre buliding 2540 SU 7 AM	3072	794	2278			0			0
24	6/14/2012 psot buliding 2540 SU 7 AM	3167	928	2239			0			0
25	6/14/2012 post building 2540 SU 14	3232	747	2485			0			0
26	6/14/2012 pre building 2540 afternoon	3083	693	2390			0			0
27	6/14/2012 post building 2540 afternoon	3157	745	2412			0			0
28	6/15/2012 pre building 2540 AM	3241	712	2529			0			0
29	6/15/2012 post building 2540 AM	3265	820	2445			0			0
30	6/15/2012 pre building 2540 afternoon	3255	804	2451			0			0
31	6/15/2012 post building 2540 afternoon	3135	750	2385						
32	6/18/2012 pre building 2540 AM	3156	768	2388						
33	6/18/2012 post building 2540 AM	3255	783	2472						
34	6/18/2012 pre building 2540 PM	3283	814	2469						
35	6/18/2012 post building 2540 PM	3182	771	2411						
36	6/19/2012 pre building 2540 AM	3220	806	2414						
37	6/19/2012 pre building 2540 PM	3136	788	2348						
38	6/19/2012 post building 2540 PM	3097	859	2238						
39	6/20/2012 pre building 283 AM	3191	747	2444						
40	6/20/2012 post building 283 AM	3160	800	2360						
41	6/20/2012 ppost building 2540 PM	3334	790	2544						
42	6/21/2012 pre building 283 AM	3162	757	2405						



Model:	2360	SN#	275724	PROBE	43-37	SN#	092501	Cal Due:	6Oct12
Source:	TH-230	SN#	7241-11	Activity (cpm):	11,300	Surf Eff	0.25	Cal Date:	6Oct11
Mean	+2s	-2s	+3s:	-3s	+20%	-20%		Date:	5Jun12
4324	4445	4203	4505	4143	5189	3459		Efficiency:	9.57%


Chk.#	Gross	Net	Chk.#	Gross	Net	Chk.#	Gross	Net	COMMENTS
1	4356	4352	11	4429	4425	21	4432	4428	
2	4311	4307	12	4375	4371	22	4434	4430	
3	4329	4325	13	4194	4190	23	4271	4267	
4	4395	4391	14	4324	4320	24	4295	4291	
5	4331	4327	15	4307	4303	25	4361	4357	
6	4402	4398	16	4377	4373	26	4328	4324	
7	4297	4293	17	4282	4278	27	4284	4280	
8	4312	4308	18	4290	4286	28	4201	4197	
9	4283	4279	19	4296	4292	29	4395	4391	
10	4354	4350	20	4278	4274	30	4313	4309	

Bkgd:	4	CPM	Mean:	4324	CPM	2sigma:	120	3sigma:	180 CPM



	Daily Alpha Checks in CPM									
	Date	Gross	BKG	NET	GROSS	BKG	NET	GROSS	BKG	NET
1	6/7/2012 AM	3986	8	3978			0			0
2	6/7/2012 pre building 283	4209	2	4207			0			0
3	6/7/2012 post building 283	4222	9	4213			0			0
4	6/8/2012 AM	4381	5	4376			0			0
5	6/11/2012 AM	4164	10	4154			0			0
6	6/11/2012 pre building 1205	4158	6	4152			0			0
7	6/11/2012 post building 1205	4171	9	4162			0			0
8	6/11/2012 pre building 2540 SU1	4307	13	4294			0			0
9	6/11/2012 post building 2540 SU 1	4378	11	4367			0			0
10	6/12/2012 pre building 2540	4224	20	4204			0			0
11	6/12/2012 post building 2540 SU 3	4353	28	4325			0			0
12	6/12/2012 pre building 2540 SU 12	4260	3	4257			0			0


13	6/12/2012 post building 2540 SU 3	4237	5	4232			0			0
14	6/13/2012 pre buiding 2540 SU 6	4270	9	4261			0			0
15	6/13/2012 post building 2540 SU 6	4083	6	4077			0			0
16	6/13/2012 pre building 2540 afternoon	4143	7	4136			0			0
17	6/13/2012 post building 2540 afternoon	4312	12	4300			0			0
18	6/14/2012 pre building 2540 SU 7 AM	4065	6	4059			0			0
19	6/14/2012 post building 2540 SU 7 AM	4315	3	4312			0			0
20	6/14/2012 post building 2540 SU 14	4199	10	4189			0			0
21	6/14/2012 pre building 2540 afternoon	4256	4	4252			0			0
22	6/14/2012 post building 2540 afternoon	4279	8	4271			0			0
23	6/15/2012 pre building 2540 AM	4026	10	4016			0			0
24	6/15/2012 post building 2540 AM	4306	13	4293			0			0
25	6/15/2012 pre building 2540 afternoon	4357	6	4351			0			0
26	6/15/2012 post building 2540 afternoon	4418	4	4414			0			0
27	6/18/2012 pre building 2540 AM	4211	10	4201			0			0
28	6/18/2012 post buliding 2540 AM	4426	11	4415			0			0
29	6/18/2012 pre building 2540 PM	4198	4	4194			0			0
30	6/18/2012 post buliding 2540 PM	4290	9	4281			0			0
31	6/19/2012 pre building 2540 AM	4065	9	4056			0			0
32	6/19/2012 pre building 2540 PM	4219	9	4210			0			0
33	6/19/2012 post building 2540 PM	4297	9	4288			0			0
34	6/20/2012 pre buliding 283 AM	4095	9	4086			0			0
35	6/20/2012 post building 283 AM	4244	26	4218			0			0
36	6/20/2012 post building 2540 PM	4278	9	4269			0			0
37	6/21/2012 pre building 283 AM	4289	7	4282			0			0
38				0			0			0
39				0			0			0
40				0			0			0



Model:	2360	SN#	92501	PROBE	43-37	SN#	274724	Cal Due:	6Oct12
Source:	TC-99	SN#	7248-11	Activity :	10,800	Surf Eff	0.25	Cal Date:	6Oct11
Mean	+2s	-2s	+3s:	-3s	+20%	-20%		Date:	5Jun12
3911	4020	3801	4074	3747	4693	3128		Efficiency:	9.05%


Chk.#	Gross	Net	Chk.#	Gross	Net	Chk.#	Gross	Net	COMMENTS
1	4372	4053	11	4243	3924	21	4169	3850	
2	4205	3886	12	4328	4009	22	4219	3900	
3	4197	3878	13	4187	3868	23	4213	3894	
4	4152	3833	14	4152	3833	24	4327	4008	
5	4257	3938	15	4147	3828	25	4257	3938	
6	4256	3937	16	4245	3926	26	4258	3939	
7	4251	3932	17	4221	3902	27	4178	3859	
8	4204	3885	18	4236	3917	28	4220	3901	
9	4245	3926	19	4262	3943	29	4175	3856	
10	4311	3992	20	4212	3893	30	4186	3867	

Bkgd:	319	CPM	Mean:	3911	CPM	2sigma:	109	3sigma:	163 CPM



	Daily Beta Checks in CPM									
	Date	Gross	BKG	NET	GROSS	BKG	NET	GROSS	BKG	NET
1	6/6/2012 AM	4187	337	3850			0			0
2	6/7/2012 AM	4387	425	3962			0			0
3	6/7/2012 pre building 283	4615	639	3976			0			0
4	6/7/2012 post building 283	4639	605	4034			0			0
5	6/8/2012 AM	4404	455	3949			0			0
6	6/11/2012 AM	4346	415	3931			0			0
7	6/11/2012 pre building 1205	4380	348	4032			0			0
8	6/11/2012 post building 1205	4657	479	4178			0			0
9	6/11/2012 pre building 2540 SU1	4694	782	3912			0			0
10	6/11/2012 post building 2540 SU 1	4631	841	3790			0			0
11	6/12/2012 pre building 2540	4671	825	3846			0			0
12	6/12/2012 post building 2540 SU 3	4751	926	3825			0			0
13	6/12/2012 pre building 2540 SU 12	4752	823	3929			0			0


14	6/12/2012 post building 2540 SU 12	4481	529	3952			0			0
15	6/13/2012 pre building 2540 SU 6	4724	841	3883			0			0
16	6/13/2012 post buildingi 2540 SU 6	4879	764	4115			0			0
17	6/13/2012 pre building 2540 afternoon	4900	868	4032			0			0
18	6/13/2012 post building 2540 afternoon	4793	802	3991			0			0
19	6/14/2012 pre building 2540 SU 7 AM	4607	669	3938			0			0
20	6/14/2012 post building 2540 SU 7	4683	857	3826			0			0
21	6/14/2012 post buliding 2540 SU 14	4729	827	3902			0			0
22	6/14/2012 pre building 2540 afternoon	4767	812	3955			0			0
23	6/14/2012 post building 2540 afternoon	4753	845	3908			0			0
24	6/15/2012 pre building 2540 AM	4773	695	4078			0			0
25	6/15/2012 post building 2540 AM	4640	763	3877			0			0
26	6/15/2012 pre building 2540 afternoon	4818	851	3967			0			0
27	6/15/2012 post building 2540 afternoon	4798	850	3948			0			0
28	6/18/2012 pre building 2540 AM	4763	829	3934			0			0
29	6/18/2012 post building 2540 AM	4843	884	3959			0			0
30	6/18/2012 pre building 2540 PM	4919	809	4110			0			0
31	6/18/2012 post building 2540 PM	4796	820	3976			0			0
32	6/19/2012 pre building 2540 AM	4807	846	3961			0			0
33	6/19/2012 pre building 2540 PM	4702	789	3913			0			0
34	6/19/2012 post building 2540 PM	4770	822	3948			0			0
35	6/20/2012 pre building 283 AM	4786	800	3986			0			0
36	6/20/2012 post building 283 AM	4773	861	3912			0			0
37	6/20/2012 post building 2540 PM	4840	896	3944			0			0
38	6/21/2012 pre building 283 AM	4702	851	3851			0			0
39				0			0			0
40				0			0			0



Model:	2360	SN#	138251	PROBE	43-37-1	SN#	136631	Cal Due:	23May13
Source:	TH-230	SN#	7242-11	Activity:	14,600	Surf Eff	0.25	Cal Date:	23May12
Mean	+2s	-2s	+3s:	-3s	+20%	-20%		Date:	5Jun12
6257	6408	6105	6484	6030	7508	5005		Efficiency:	10.71%

Chk.#	Gross	Net	Chk.#	Gross	Net	Chk.#	Gross	Net	COMMENTS
1	6264	6259	11	6139	6134	21	6380	6375	
2	6211	6206	12	6208	6203	22	6208	6203	
3	6088	6083	13	6178	6173	23	6271	6266	
4	6229	6224	14	6334	6329	24	6271	6266	
5	6284	6279	15	6287	6282	25	6297	6292	
6	6230	6225	16	6266	6261	26	6275	6270	
7	6331	6326	17	6269	6264	27	6227	6222	
8	6425	6420	18	6207	6202	28	6342	6337	
9	6356	6351	19	6141	6136	29	6317	6312	
10	6257	6252	20	6201	6196	30	6357	6352	


Bkgd:	5	CPM	Mean:	6257	CPM	2sigma:	151	3sigma:	227 CPM



	Daily Alpha Checks in CPM									
	Date	**Gross**	**BKG**	**NET**	**GROSS**	**BKG**	**NET**	**GROSS**	**BKG**	**NET**
1	6/6/2012 AM	5952	6	5946			0			0
2	6/6/2012 pre building 292	6033	4	6029			0			0
3	6/6/2012 post building 292	6213	5	6208			0			0
4	6/7/2012 AM	6018	2	6016			0			0
5	6/8/2012 AM	5944	0	5944			0			0
6	6/11/2012 AM	5938	2	5936			0			0

7	6/11/2012 pre building 1205	5948	6	5942			0			0
8	6/11/2012 post building 1205	6010	13	5997			0			0
9	6/11/2012 pre building 2540 SU1	6021	20	6001			0			0
10	6/12/2012 pre building 2540	6114	23	6091			0			0
11	6/12/2012 post building 2540 SU 3	6281	24	6257			0			0
12	6/12/2012 pre building 2540 SU 12	6058	15	6043			0			0
13	6/12/2012 post building 2540 SU12	6255	9	6246			0			0
14	6/13/2012 pre building 2540	6089	13	6076			0			0
15	6/13/2012 post buliding 2540 SU 6	6136	6	6130			0			0
16	6/13/2012 pre building 2540 afternoon	5968	9	5959			0			0
17	6/13/2012 post building 2540 afternoon	6105	10	6095			0			0
18	6/14/2012 pre building 2540 AM	6391	5	6386			0			0
19	6/14/2012 post building 2540 AM	6071	4	6067			0			0
20	6/14/2012 pre building 2540 afternoon	6405	5	6400			0			0
21	6/14/2012 post building 2540 afternoon	6361	10	6351			0			0
22	6/15/2012 pre building 2540 AM	6245	15	6230			0			0
23	6/15/2012 post building 2540 AM	6174	7	6167			0			0
24	6/15/2012 pre building 2540 afternoon	6012	3	6009			0			0
25	6/15/2012 post building 2540 afternoon	6396	9	6387			0			0


26	6/18/2012 pre building 2540 AM	6122	13	6109			0			0
27	6/18/2012 post building 2540 AM	6268	10	6258			0			0
28	6/18/2012 post building 2540 PM	6242	7	6235			0			0
29	6/19/2012 pre building 2540 AM	6292	23	6269			0			0
30	6/19/2012 post building 2540 PM	6254	13	6241			0			0
31	6/20/2012 pre building 283 AM	6219	12	6207						
32	6/20/2012 post building 283 AM	6186	13	6173						
33	6/20/2012 post building 2540 PM	6187	12	6175						
34	6/21/2012 pre building 283 AM	6168	6	6162						



Model:	2360	SN#	136361	PROBE	43-37-1	SN#	138251	Cal Due:	23May13
Source:	TC-99	SN#	7246-11	Activity:	11,500	Surf Eff	0.25	Cal Date:	23May12
Mean	+2s	-2s	+3s:	-3s	+20%	-20%		Date:	5Jun12
3864	4005	3724	4075	3654	4637	3091		Efficiency:	8.40%

Chk.#	Gross	Net	Chk.#	Gross	Net	Chk.#	Gross	Net	COMMENTS
1	4313	3785	11	4423	3895	21	4347	3819	
2	4288	3760	12	4529	4001	22	4397	3869	
3	4360	3832	13	4407	3879	23	4315	3787	
4	4336	3808	14	4374	3846	24	4344	3816	
5	4416	3888	15	4337	3809	25	4420	3892	
6	4294	3766	16	4542	4014	26	4363	3835	
7	4396	3868	17	4317	3789	27	4356	3828	
8	4329	3801	18	4407	3879	28	4474	3946	
9	4421	3893	19	4511	3983	29	4392	3864	
10	4530	4002	20	4435	3907	30	4392	3864	

Bkgd:	528	CPM	Mean:	3864	CPM	2sigma:	140	3sigma:	210 CPM



	Daily Beta Checks in CPM									
	Date	Gross	BKG	NET	GROSS	BKG	NET	GROSS	BKG	NET
1	6/6/2012 AM	4412	638	3774			0			0
2	6/6/2012 pre buiding 292	4350	506	3844			0			0
3	6/6/2012 post building 292	4647	653	3994			0			0
4	6/7/2012 AM	4199	399	3800			0			0
5	6/8/2012 AM	4349	467	3882			0			0
6	6/11/2012 AM	4314	481	3833			0			0
7	6/11/2012 pre building 1205	4466	552	3914			0			0
8	6/11/2012 post building 1205	4365	704	3661			0			0
9	6/11/2012 pre building 2540 SU1	4953	980	3973			0			0
10	6/12/2012 pre building 2540	5156	1138	4018			0			0
11	6/12/2012 post building 2540 SU3 AM	5019	1165	3854			0			0

12	6/12/2012 pre building 2540 SU 3 PM	4733	957	3776			0			0
13	6/12/2012 post building 2540 SU 13	5078	1166	3912			0			0
14	6/13/2012 pre building 2540	5138	1133	4005			0			0
15	6/13/2012 psot building 2540 SU 6	5042	1207	3835			0			0
16	6/13/2012 pre building 2540 afternoon	4906	1229	3677			0			0
17	6/13/2012 post building 2540 afternoon	4957	1208	3749			0			0
18	6/14/2012 pre building 2540 AM	4940	1078	3862			0			0
19	6/14/2012 post building 2540 AM	4966	1185	3781			0			0
20	6/14/2012 pre building 2540 afternoon	5099	1148	3951			0			0
21	6/14/2012 post building 2540 afternoon	5297	1198	4099			0			0
22	6/15/2012 pre building 2540 AM	5112	1076	4036			0			0
23	6/15/2012 post building 2540 AM	4981	1031	3950			0			0
24	6/15/2012 pre building 2540 afternoon	4935	1080	3855			0			0
25	6/15/2012 post building 2540 afternoon	5171	1172	3999			0			0
26	6/18/2012 pre building 2540 AM	4936	1036	3900			0			0
27	6/18/2012 post building 2540 AM	5096	1205	3891			0			0
28	6/18/2012 post building 2540 PM	5275	1216	4059			0			0
29	6/19/2012 pre building 2540 AM	5203	1045	4158			0			0
30	6/19/2012 post building 2540 PM	5210	1253	3957			0			0
31	6/20/2012 pre building 283 AM	5190	1130	4060			0			0
32	6/20/2012 post building 283 AM	5120	1147	3973			0			0
33	6/20/2012 post building 2540 PM	5216	1377	3839			0			0
34	6/21/2012 pre building 283 AM	4927	1191	3736			0			0
							0			0
							0			0
							0			0

APPENDIX G

Field Notebook

CONTENTS

PAGE	REFERENCE	DATE

Rite in the Rain®
ALL-WEATHER WRITING PAPER

ALL-WEATHER
JOURNAL
FIELD BOOK

Name _____

Address _____

Phone _____

Project Ft. Monmouth
Radiological Site Assessment
Book 1

Rite in the Rain — A patented, environmentally responsible, all-weather writing paper that sheds water and enables you to write anywhere, in any weather. Using a pencil or all-weather pen, *Rite in the Rain* ensures that your notes survive the rigors of the field, regardless of the conditions.

Specifications for this book:

Page Pattern		Cover Options	
Left Page	Right Page	Polydura Cover	Fabrikoid Cover
Lined	Lined	Item No. 390N	Item No. 390NF

RiteintheRain.com

June 4th, 2012

1400 - Start - site tour w/ Alice

Bldg 283 - Squier Hall
- 1st & 2nd floor mostly carpet & tile floor
- Basement contains a "radic" room with tyvek & stripped wiring on tables.
- 1st & 2nd walls are painted block/brick/drywall
- Mostly renovated except basement.
- May update survey grid

Bldg 292
- Floorings mostly concrete, some tile, laminate tile, carpet in office area
- Painted block walls
- May upgrade survey grid

Bldg 275 - Electronics Museum
- Floorings mostly carpeting, some laminate tile
- Wood panneling on walls
- Ceramic tile in center sitting area
- Survey grid is good.

Bldg 2540
- Tile/concrete floors, minimal carpet
- Block walls and drywall.
- Room 102 has a fume hood
- Tables/chairs in both survey units
  Machine shop has large equipment we will have a hard time moving...

June 4th 2012 cont...

Bldg 2540 cont

- Furniture will be in the way of the original survey grid.
- Calibration/radiation room in Survey Unit (South West corner), has neutron absorber, Californium sign that is hand written, chart of nuclides. "Radioactive material" sign at doorway.
- Room 106 has surveyed radiation detectors and has a room w/ "radioactive material" signage. Room 13 empty.
- Room 109, entry from back of building, radioactive storage area.
- Sign outside building says no foot access without contacting site RSO.

At the end of the day we hooked one P-10 gas tank to three Ludlum 43-37 detectors in series to keep gas in them.

June 5th 2012

- 700 start, met with Alice, door key to the room we are using will be replaced today so we can lock our sources at night.

- Site Safety brief (initial), PPE will be assessed at each building. We don't expect the need to wear hard hats or safety glasses. Biggest hazards are slip/trips/falls and ladder safety when scanning. Will need to be very careful when moving/storing P-10 gas cylinders.

- Planning on setting up equipment in the morning and starting on Building 275, electronics museum.

- All three detectors were source checked and passed Chi-square test. Thirty one minute counts with both Tc-99 and Th-230 sources.

→ June 5th cont
2nd Start Bldg 275 (Electronics Museum)

Ludlum 2360 SN# 275713
Ludlum 43-37 SN# 093966
Ludlum 19 SN# 245026
Ludlum 19 SN# 253050

			END of DAY Q/C Check	
14th Bkg	1α	477 β	1α	518 β
Tc-99	3α	2968 β	2α	2874 β
Th-230	4885α	2047 β	5101 α (5th pm)	1923 β

[Limits: 315 α and 7100 β]

Location #1 (240 pm) - Carpet
7 μR 3 α 387 β

Location #2 (242 pm) - Carpet
14 μR 0 α 511 β

Location #3 (244 pm) - Wood panel
12 μR 6 α 763 β

Location #4 (246 pm) - Carpet
8 μR α 399 β

~~Location #6~~

Location #5 (248 pm) - Carpet
6 μR 5 α 417 β

Location #6 (250 pm) - Laminate Tile
8 μR 5 α 488 β

Location #7 (251 pm) - Carpet
10 μR 6 α 487 β

Location #8 (253 pm) - Carpet
8 μR 4 α 421 β

Location #9 (256 pm) - Drywall
11 μR 6 α 598 β

Location #10 (259 pm) - Drywall
12 μR 6 α 724 β

Location #11 (301 pm) - Drywall
11 μR 6 α 795 β

Location #12 (303 pm) - Wood panel
8 μR 4 α 602 β

Location #13 (305 pm) - Carpet
8 μR 4 α 486 β

→ June 5th Cont

Location #14 (311pm) - Carpet
9μR 1α 541B

Location #14-Dup (313pm) - Carpet
10μR 2α 492B

Location #15 (315pm) - Carpet
6μR 4α 448B

Location #16 (316pm) - Carpet
8μR 1α 536B

Location #17 (318pm) - Carpet
10μR 1α 508B

Location #18 (319pm) - Carpet
12μR 6α 502B

Location #19 (322pm) - Carpet
7μR 4α 462B

Location #19-Dup (323pm) - Carpet
6μR 2α 468B

Location #20 (325pm) - Carpet
12μR 8α 521B

Location #21 (330pm) - Carpet
7μR 2α 513B

Location #22 (327pm) - Carpet
10μR 4α 587B

Location #23 (331pm) - Carpet
8μR 3α 538B

Location #24 (333pm) - Carpet
10μR 1α 584B

Location #24-Dup (335pm) - Carpet
10μR 5α 541B

Location #25 (337pm) - Wood Panel
10μR 2α 542B

Location #26 (341pm) - Carpet
10μR 6α 576B


Location #27 (342pm) - Carpet
9μR 0α 517B

Location #28 (344pm) - Carpet
8μR 5α 495B

→ June 5th Cont

Location #29 (347pm) - Carpet
10μR 3α 597 β

Location #30 (350pm) - Wood Panel
10μR 7α 779 β



Display Case Map

Scanning the bottom of each display at one detector width per second (Model 43-37)

Cabinet #	Name	Highest	α	β
1	"Camp Little Silver 1917"		13	676
2	"Radio & Telegraph Go Airborne at Camp Vail"		11	757
3	"Camp Vail Radio Laboratories Ft Monmouth"		8	709
4	"Signal School at Ft Monmouth"		22	723
5	N/A - Floor to ceiling		10	621
6	N/A - Floor to ceiling		12	581
7	N/A - Full back wall			
8	"Radio Miniturization"			
9	"Satellite Development at Ft Monmouth"			
10	"Radar at Ft Monmouth"			
11	N/A			
12	"Edwin H. Armstrong - Pioneer of Radio"			
13	"Vacuum Tube Development"			
14	"Wheather School & The Radiosonde"			
15	"Night Vision Equipment"			
16	"Pigeons at Ft Monmouth"			
17	"Combat Photography"			
18	N/A			
19	N/A			
20	N/A Table Top			
21	N/A Table Top			

→ June 5th cont

Scanned the first six cases in the electronics museum. Ended scanning ~5 PM to pack up and complete end of day QC checks on detectors. Background and check source readings within the 20% limit for control charts. Tomorrow morning we will finish the museum display cabinets.

June 6th, 2012

7:00 - Building 2541 was walked with the Ft. Monmouth logistics staff for radiation protection. Dose rate measurements, alpha/beta measurements and removable smears for contamination survey of building.

- Control charts completed for all detectors
- Input all data from yesterday to digital format and calculated SOR for all survey measurements.

10:00 Continue scanning display cabinets in Bldg 275, starting at #7.

- Collecting low energy beta swipe at each of the 30 random locations from yesterday.

Ludlum 2360 # 275713
w/ 43-37 # 083966

				Afternoon	
Morning QC	Bkg	3α	567β	4α	425β
	~~Tc-99~~	7α	2826β	4α	2933β
	Th-230	5483α	1726β	5105α	1887β

→ June 6th cont

- Each systematic location (30) recieved one low E β swipe. Duplicates collected at same location as the direct read measurements (14DUP, 19DUP, 24DUP)
- The swipe samples were ~~labeled~~ labeled as follows 275-1, 275-2, . . .
- The following display cases had low energy beta swipes
  - #8 - Radio Miniaturization
  - #13 - Vacuum Tube
  - #15 - Night Vision
  - #17 - Combat Photography

13[30] Start at Building 292 - Museum Storage


Using one floor Monitor attached to cart
Ludlum 2360 # 138251
w/ 43-37-1 136361

	Pre QC		Post QC	
	α	β	α	β
Bkg	4	506	5	653
~~E~~-99	15	4350	34	4647
Th-230	6033	1987	6213	2187


	PRE QC		Post QC	
	α	β	α	β
Bkg	2	379	3	420
Th-230	4962	2138	5245	2236
Tc-99	3	3051	~~3~~ 28	~~3501~~ 20

Ludlum 2360 SN 275713
w/ 43-37 # 093966
This detector will do a one min count at each location

- Scanned 5% of floor in the cabinet storage area w/ floor Monitor



- Scanned 5% of floor in "Back Storage Area"



→ June 6th cont

- Scanned 5% of "Movable Storage Area" in a "U" shape path. This room is off the side of the Storage Cabinet/Rack room. Laminate Tile Floor

- Scanned 100% of the metal shelving located in storage cabinet #1, 2 & 3. These cabinets (in "Storage Rack Area") have the following signage.

  Dated 8-11-11

  "These 3 cabinets are being tested ~~periodically~~ presently for radioactive residual from storing radioactive (low level) artifacts. DO NOT remove until cleared with Rad Safety" - Dr. Nicholas ~~By~~ Kovitz

- Direct readings and low energy swipes collected at 30 random locations w/ 3 DUP)

  Duplicates at: 292-6D
  292-12D
  292-29D

Building 292 Direct Readings – All one min counts

	Location	7α	430 β	5 μR/hr	Cinder block
	" 2	13	607	4	Poured Concrete (PC)
	" 3	6	624	5	PC
	" 4	5	603	5	PC
	" 5	6	499	5	Carpet
DUP	" 6	13 ; 9	648 ; 595	5 ; 5	PC
	" 7	5	515	5	PC
	" 8	8	679	6	Carpet
	" 9	7	446	3	PC
	" 10	8	445	4	Carpet
	" 11	9	629	5	Laminate Tile (LT)
DUP	" 12	5 ; 9	520 ; 584	4 ; 4	PC
	" 13	5	621	5	LT
	" 14	13	522	6	LT
	" 15	3	724	4	PC
	" 16	8	473	4	PC
	" 17	8	516	7	Drywall
	" 18	2	488	5	Carpet
	" 19	11	637	4	LT
	" 20	2	513	4	LT
	" 21	15	638	6	PC
	" 22	9	658	5	Carpet
	" 23	15	551	5	PC
	" 24	8	606	4	PC
	" 25	8	535	5	PC
	" 26	16	595	4	PC

→ June 6 cont

		α	β	μR/hr	Material
Location	#27	4	445	4	LT
	#28	3	520	4	PC
DUP	#29	6 : 10	643 : 614	4 : 4	Carpet
	#30	8	478	6	LT

5:15 End of work day

June 7th, 2012

7:00 Started morning QC check on detectors and finished inputing all data collected to date on our electronic forms

9:00 • Walk through of building 283 (Spanier Hall) to identify areas where a former wet laboratory would have been and confirm the layout of both floors

• Brought site electricians out to the building to identify which outlets were grounded so we can use a shop vac in the old "radio room" located in the basement.

• Dose rate meter was brought through every room in 283 and nothing unusual was identified. Everything was below 10-15 μR/hr.

1:00 • Start to lay out 30 survey measurement grid in 283 and clean the shelf and table top area in "radio room" with a shopvac. Room is VERY dusty.

→ June 7th cont:

Two floor monitors

2360 SN ~~275731~~ JD 275713 (2nd Floor)
w/ 43-37 SN# 095966

Pre QC	α	β	Post QC	α	β
Bkg:	4	568	Bkg:	1	517
Tc99:	+3 JD	~~3447~~ 2427 JD	Tc99:	4	3067
Th230:	~~5410~~ 5406 JD	~~2020~~ 1452 JD	Th230:	4729	2153

2360 SN 275724 (1st Floor)
w/ 43-37 SN# 068422

Pre QC	α	β	Post QC	α	β
Bkg:	2	639	Bkg:	9	605
Tc99:	~~13~~ 11 JD	~~4615~~ 3976 JD	Tc99:	17	4639
Th230:	4209	1972	Th230:	4222	1902

α - 3459 to 5187
β - 3128 +/- 4693

Ludlum 19 SN 253050

Building 283 Direct Measurements

Location #	α (cpm)	Bkg (cpm)	uR/hr	Time: Material
DUP 1	4/1	~~584~~ ~~589~~	12/12	Carpet 334
2	2	637	12	Carpet 327
3	3	528	9	Carpet 351
4	13	516	4	Laminate Tile 332
5	1	579	11	Carpet 341
6	10	432	5	Carpet 338
7	8	756	14	Tile 348
8	~~15~~ 2	~~543~~ 592	~~14~~ 12	Carpet ET 321
9	15	513	4	LT 320
DUP 10	7/3	576/552	10/10	Carpet 319
11	9	777	10	Drywall 359
12	26	444	4	Carpet 341
13	4	643	10	Drywall 343
14	9	850	15	Drywall 405
15	1	540	8	Carpet 389
16	~~8~~ 16	~~579~~ 655	4	Drywall 348
17	8	574	4	Carpet 335
18	16	463	5	Carpet 344
19	3	562	10	Carpet 345
DUP 20	~~16~~ 14	655 : 689	5/5	Blackwall 320 321
21	17	493	4	LT 325
22	5	557	10	LT 327
23	5	523	9	Carpet 353

→ June 7th cont

Location #	α (cpm)	β (cpm)	mR/hr	Material
24	3	634	14	Wood Wall 325
25	15	476	4	Carpet 340
26	15	598	10	Carpet 464
27	19	796	5	LT 355
28	11	584	9	Carpet 401
29	20	538	6	LT 351
30	11	565	8	Carpet 354

- James Moore was on-site today.

June 8th, 2012

7:00 QC check instrument and calculate SOR from past building scans.

Ludlum 2360 SN 275713
w/ 43-37 SN 095966

Pre QC	α	β	Post QC	α	β
Bkg	3	429	Bkg	9	630
Tc99	8	3021	Tc99	8	3121
Th230	4708	2038	Th230	4691	2167

Ludlum Model 19 SN 245026
Prior Checksource ~~800~~ μR/hr
After Checksource ~80μR/hr

- Scanning floor area of sinks we moved detector around floor and did a one min count at the area we thought was highest (cpm).

	α	β	Material	Time
Main Star Case Bathroom	13	999	Ceramic Tile	907 AM
Second Floor West Wing	19	769	Granite Tile	910 AM
First Floor West Wing	15	726	Granite Tile	913 AM
Room 129 Back Sink	20	354	Poured Concrete	920 AM

→ June 8th cont'

Basement Radio Room	α	β	Time/Motif
Floor 1 (65') Concrete	11	559	1006
Floor 2 (+10') Concrete	11	510	1007
Floor 3 (+45') Concrete	14	562	1008
Floor 4 (+20') Concrete	10	551	1010
Tabletop 1	Wood	14	360	1015
Tabletop 2	Wood	16	366	1017

10:00 Collected "sludge" samples from drains in the main staircase bathroom and second floor west wing. The other two ~~bathrooms~~ sinks have to be sampled after we get a plumber out to open the traps.

- Collated missed swipe (Low E-F) in Bldg 275.
- Finished Bldg 283 (Squire Hall) dose rate measurements on 2nd floor random locations and started collecting low energy beta swipes. We do not have enough to finish all. Duplicate swipes at the following
  4DUP 16DUP 23DUP

27, 28, 29, 30 will be swiped next week.

June 11th, 2012

7:00 Started filling detectors w/ P-10 gas checked updated QC sheets that were made on Friday afternoon.
Ludlum model 43-37 (PR093866)
and
Ludlum model 43-37 (PR092501)

We were not using the right sources for the daily QC checks (i.e. control chart used a different source than our dailys).

- Building 1205 – Military Academy Prep School
  ★ Reference Background Area ★
  First Hallway – 289' x 4.8' laminate tile
  ↳ Generate 14 random points to collect background w/ each detector (all at same locations)

June 11th cont 2360

43-37 SN# 093966 SN# 275713

	Pre QC α	Pre QC β	Post QC α	Post QC β
Bkg	1	296	4	443
Tc99	3	2744	7	2983
Th230	4574	1841	4714	2009

43-37 SN# 092501 2360 SN# 275724

	Pre QC α	Pre QC β	Post QC α	Post QC β
Bkg	6	348	9	479
Tc99	10	4380	9	4657
Th230	4158	1854	4171	1831

43-37-1 SN# 136361 2360 SN# 138251

	Pre QC α	Pre QC β	Post QC α	Post QC β
Bkg	6	552	13	704
Tc99	17	4466	31	4365
Th230	2128	5948	6010	2072

50*

Model 19 SN# 253050

Pre QC-Bkg: 8 Post QC-Bkg: 8

Cs137: 70 Cs137: 70

Model 19 SN# 245026

Pre QC-Bkg: 7 Post QC-Bkg: 10

Cs137: 65 Cs137: 70

* 5948 α
2128 β

June 11 cont

Model 2241-3 SN# 287350

w/ 4393 SN# 311206

Pre-QC Post-QC

	Pre-QC
Bkg	~~SD~~ 76
Tc99	1716

Laminate Building 1205

Begin scans @ 1030 Donnakowski

Tile	138251		275724		time
Point	α	β	α	β	
13	5	412	8	395	SD ~~1032~~
11	8	406	10	438	SD ~~1035~~ 1032
10	9	442	14	399	SD ~~1038~~ 1035
12	5	358	9	379	1038
3	12	405	6	402	1040
7	8	538	12	497	1042
8	10	431	8	411	1044
1	5	420	7	391	1047
9	9	418	7	366	1050
5	8	437	7	386	1052
4	8	381	9	385	1055
2	2	447	2	366	1057
14	8	466	13	391	1100
6	10	461	9	455	1102
	Probe SN 136361		Probe 092501		1105

Hallway

June 11 cont

~~point 43-83 235050 245026~~

Laminate | Building 1205 | Donakowski

Tile

point	cpm 43-83	µR/hr 235050	µR/hr 245026	time
6	67	5	4	1111
13	72	4	4	1113
11	63	4	4	1115
10	72	4	4	1124
12	58	3	4	1126
3	55	4	4	1127
7	71	8	7	1130
8	56	5	4	1132
1	66	3	3	1134
9	51	4	3	1136
5	55	4	5	1138
4	57	5	5	1140
2	58	5	4	1142
14	63	4	4	1144

Cafeteria

June 11 cont

Ceramic Tile | Donakowski

point	cpm 43-93	µR/hr 235050	µR/hr 245026	time
9	220	7	8	1147
10	255	8	8	1149
12	258	10	8	1151
8	237	10	7	1153
3	262	9	8	1155
11	232	10	10	1157
7	227	11	10	1158
~~10~~ 5 min	249	8	9	1159
1	273	8	8	1201
13	249	10	10	1203
2	234	8	8	1205
4	219	9	8	1206
6	239	10	9	1207
14	207	8	8	1209

Basement Floor

Jurell cont

poured concrete

Donakowski

Point	cpm 43-83	μR/hr 235050	μR/hr 245026	time
1	75	4	4	1211
13	81	4	4	1213
8	74	4	4	1215
10	67	4	5	1217
11	77	4	5	1218
5	81	5	5	1219
6	88	4	4	1220
7	90	6	5	1222
4	76	5	6	1223
3	73	4	4	1224
14	72	5	6	1226
12	69	5	5	1227
9	68	4	4	1229
2	79	4	4	1230

Basement Wall

Jurell cont

concrete block

Donakowski

point	cpm 43-83	μR/hr 235050	μR/hr 245026	time
13	118	8	8	1232
11	127	8	8	1234
4	69	6	8	1236
14	120	8	7	1238
8	123	8	10	1240
9	116	6	8	1241
2	107	8	8	1242
3	73	5	5	1244
12	69	5	5	1245
10	91	5	5	1246
5	78	4	4	1248
6	61	6	5	1249
1	59	4	4	1251
7	64	5	5	1253

→ June 11 cont

- Background study completed in Building 1205. This building was chosen as a reference background area based on non-impacted past use as the Military Prep-academy.

Material: Laminate Tile, Ceramic Tile Painted poured concrete, Painted block concrete.

We chose 3 rooms which contained our reference material and laid out 14 random locations in a grid to collect one min counts. We took 14 measurements per material per detector. We did this for ALL of our Meters.

- Moved to building 2540 to start griding & sampling one of the class 1 areas.

PRE POST

Building 2540 SU 1 ~1650

June 11th cont

275713 β pre SU1 w/ 43-37

	α	β
bkg	~~6~~ 1	668
Tc	5	3157
Th	4832	2203

	α	β
bkg	9	793
Tc	15	3233
Th	5257	2288

13825.1 pre SU1 w/ 43-37-1

	α	β
bkg	20	980
Tc	18	4953
Th	6021	2450

	α	β
bkg		
Tc		
Th		

275724 pre SU1 w/ 43-37

	α	β
bkg	13	782
Tc	13	4694
Th	4307	1975

	α	β
bkg	11	~~84~~ 841
Tc	21	4631
Th	4378	2104

245026 μR meter

bkg - 10
cs - 70

bkg - 11
cs - 75

~~245~~ 20 253050 μR meter

bkg - 10
cs - 75

bkg - 9
cs - 70

→June 11th cont.

- We started in Survey unit #1 in building 2540. This is called the "radiation room" on floor plans.

- Downloaded all background data from each instrument and started to calculate average material specific backgrounds for each instrument.

- We completed the 30 random measurement locations in Survey Unit #1. Our extra swipes will arrive on Wednesday or Thursday, so we cannot collect Low Energy β swipes until then.

- Will use floor Monitor for 100% scanning in SU #1 tomorrow Morning.

→June 11th cont

237350 w/ 43-93

bkg 100

Tc 1749

End day @ 1715

June 12th, 2012

Arrive on site ~0700. Cloudy and overcast, potential for storms

Begin QC checks @ ~0715

275713 w/ 43-37

pre		α	β
bkg		20	795
α	Tc	28	3270
β	Th	5335	2111

post check

	α	β
bkg	16	816
Tc	19	3304
Th	5324	2169

275724 w/ 43-37

pre	α	β
bkg	20	825
Tc	38	4671
Th	4224	2204

post check

	α	β
bkg	28	726
Tc	33	4751
Th	4353	2132

138251 w/ 43-37-1

pre	α	β
bkg	23	1138
Tc	45	5156
Th	6114	2663

post check

	α	β
bkg	24	1165
Tc	43	5019
Th	6281	2642

6/12/12

19-245026 μR meter

bkg 8 pre check
cs 65

bkg 12 post check
cs 80

19-253050
bkg 9 pre check
cs 70

NOT USED

43-93 311206 NOT USED
bkg 121
tc 1831 pre check

245026 μR meter

S41 Bins - 35 α 979 β
w/ 275724 12 μR/hr

S42 Bins - 34 α 1026 β
w/ 275724 18 μR/hr

Building 2540 SU2 - Duplicates (Nim)

point	meter	α	β	μR	time
13D	275713	27	1016	13	1105
12D	275713	29	1038	15	1107
8D	275713	29	1098	16	1109
6D	275713	19	1083	14	1111

6/12/12

Begin survey of SU2 at ~0845

Floors are laminate tile

245026

point	meter	α	β	μR	time
1	275713	41	1199	16	~~0845~~ 0850
~~2~~	~~275713~~	~~39~~	~~1177~~	~~18~~	~~0848~~
3	275713	39	1139	15	0853
4	275713	40	1091	16	0855
5	275713	22	1126	15	0901
6	275713	38	1081	14	0903
7	275713	34	1070	15	0905
8	275713	32	1072	16	0907
9	275713	38	1094	15	0909
10	275713	33	1067	12	0912
11	275713	42	1105	14	0914
12	275713	35	1120	13	0916
13	275724	35	1078	14	0911
14	275724	26	1021	14	0909
15	275724	26	1059	15	0907
16	275724	37	1089	14	0905
17	275724	29	1015	16	0859
18	275724	33	1029	15	0857
19	275724	33	999	15	0851
20	275724	30	1081	15	0848
21	275724	45	1008	15	0846
2	275713	37	1179	19	0852

Nothing significant noted during static counts.

Begin wall scans @ ~0930

Watters + ~~Dankowski~~ surveyors.

All walls poured concrete.

SU3

point	meter	α	β	μR	time
1	275713	32	1031	16	0933
2	275713	34	1093	14	0955
3	275713	35	1169	20	0957
4	275713	37	1127	18	0958
5	275713	46	1005	16	1000
6	275713	39	1011	15	1002
7	275713	31	1004	20	1004
8	275713	24	985	14	1006
9	275713	33	981	15	1009
10	275713	31	913	15	1011
11	275713	27	818	15	1014
12	275713	26	783	15	1017
13	275713	33	810	15	1020
14	275713	29	999	15	1028
15	275713	29	959	12	1030
16	275713	29	926	14	1032
17	275713	29	871	12	1035
18	275713	29	852	12	1037

36 862

point	meter	α	β	μR	time
19*	275713	~~73~~ 30	~~808~~ 38	11	~~1051~~ 1056
20	275713	39	910	15	1054
21	275713	38	937	13	1058
22	275713	48	950	14	1101
23	275713	38	992	16	~~1025~~ 1103
24	275724	39	1017	15	1023
25	275724	38	931	12	1021
26	275724	50	968	12	1019
27	275724	50	932	13	1017
28	275724	42	1037	15	1015
29	275724	54	1029	15	~~1007~~ 1013
30	275724	51	1001	17	1005
31	275724	50	1002	16	1003
32	275724	52	970	15	1001
33	275724	37	993	16	0959
34	275724	46	1030	15	0957
35	275724	40	1026	15	0955
36	275724	38	1033	15	0953
37	275724	50	907	14	0951
38	275724	47	1025	14	0949
39	275724	47	936	13	0947
40	275724	34	844	10	0946
41	275724	51	867	10	0944
42	275724	47	855	12	0941

* toc book done initially low for α

point	meter	α	β	uR	time
43	275724	46	991	15	0938
44	275724	43	932	14	0937
45	275724	55	968	12	0935
46	275724	43	1052	16	0933
47	275724	49	942	14	0931
2D	275713	40	1140	15	0959
8D	275713	38	984	15	1008
13D	275713	31	838	14	1025
41D	275724	42	843	13	1026
44D	275724	58	976	12	1027
33D	275724	58	1034	15	1029

6/12/12 SU-12 poured concrete

Donahowski begin dose rate survey in SU 12
Meter # 253050

point	meter	α	β	uR	time
1	275713	4	539	5	1445
2	275713	3	533	5	1447
3	275713	5	617	4	1449
4	275713	#5	~~569*~~ 624	4	~~1436~~
5	275713	5	596	4	1430
6	275713	4	569	3	1436
7	275713	6	596	4	1438
8	275713	6	638	5	1440
9	275713	3	600	4	1425
10	275713	6	588	4	1423
11	275713	5	600	4	1421
12	275713	5	564	4	1419
13	275713	4	614	4	1451
14	275713	4	589	5	1453
15	275713	7	565	4	1454
16	275713	7	624	5	1455
17	275713	5	589	4	1456
18	275713	2	567	5	1457
19	275713	5	592	4	1459
~~20~~	275724	13	587	5	1450
#21	275724	6	483	5	1422

*624 β @ 4

point	meter	α	β	gR	Hinc
22	275713	6	571	4	1503
23	275724	8	633	4	1447
24	275724	13	620	5	1440
↓25	275724	10	491	4	1419
↓26	275724	~~4~~ 9	~~4~~ 470	4	1418
27	275724	3	649	3	1449
28	275724	7	653	3	1438
↓29	275724	~~47~~ 6 JD	~~6~~ JD 471	4	1420
30	275724	6	608	5	1451
31	275724	13	474	5	1436
5D	275713	7	~~7~~ 549	4	1433
24D	275724	13	582	5	1442
9D	275713	6	575	4	1444
32	275724	5	651	5	1446

6/12/2012

Break for lunch @ ~1300

Return to Building 2540 @ ~1340. Slight rain.

Switch gas cylinder for 275724 & 275713 @ 1650

Begin QC checks @ 1345

275724 pre

	α	β
bkg	7	823
Tc	~~5~~ 15	~~3300~~ 4752
Th	5386	2207

275724 post

	α	β
bkg	5	529
Tc	17	4481
Th	4237	1807

275713 pre

	α	β
bkg	3	821
Tc	5	3300
Th	4260	2138

JD

275713 post

	α	β
bkg	2	411
Tc	3	2941
Th	5061	1935

138251 pre

	α	β
bkg	15	957
Tc	13	4733
Th	6058	2475

138251 post

	α	β
bkg	9	1166
Tc	20	5078
Th	6255	2645

SU 13 walls 3D concrete block

*20, 36, 37 drywall, ~~34 metal door~~, 38 metal cabinet

point	meter	α	β	μR	time
01	275713	4	541	5	1624
02	275713	7	569	4	1626
03	275713	5	545	4	1628
04	275713	7	545	4	1630
05	275713	4	541	6	1632
06	275713	4	546	5	1634
7	275713	5	570	4	1636
8	275713	3	725	5	1638
9	275713	3	547	5	1640
10	275713	11	538	4	1642
11	275713	6	575	4	1644
12	275724	8	570	4	1644
13	275724	14	535	5	1642
14	275724	10	533	5	1640
15	275724	10	542	5	1638
16	275724	16	589	4	1636
X 17	275724	14	437	3	1634
18	275724	11	523	5	1559
19	275724	10	585	5	1601
20	275724	13	463	4	1520
21	275724	8	561	5	1526
22	275724	14	555	4	1539
22D	275724	10	503	4	1541

point	meter	α	β	μR	time
~~22D~~				5	
23	275724	9	582	4	1543
24	275724	5	501	5	1545
25	275724	5	547	4	1617
26	275724	10	629	5	1620
27	275724	8	537	4	1622
27D	275724	7	525	4	1624
28	275724	13	542	3	1626
29	275724	9	533	5	1628
30	275724	6	580	4	1630
31	275724	11	506	5	1603
32	275724	8	526	3	1605
33	275724	4	612	5	1607
~~34~~	275724	9	577	4	1609
~~35 3D~~	~~275724~~	~~12~~	~~466~~	~~5~~	~~1522~~
~~37 5D~~	~~275724~~	~~7~~	~~504~~	~~4~~	~~1524~~
36	275724	7	477	3	1557
37	275724	15	470	3	1555
38	275724	9	421	3	1553
39	275724	12	469	4	1551
40	275724	8	614	4	1547
40D	275724	7	568	4	1549
~~3D 41~~					
~~3D 42~~					
~~39~~ 35	275724	13	522	5	1611
35D	275724	11	573	4	1613

JD

~~Points 34 and 35 were plotted in both the small server room and main room. 34 and 35 are from small server room and 41 and 42 are located at 34 and 35 in large room.~~

Point locations identified and colrected.

Finish scans at 1645, nothing significant noted.

o 1, 2, 3, 4, 5 & 6 are poured concrete walls

x 17 is a metal door.

Neil Miller completed walkover scan of floor.

6/12/2012

1650 start end of day QC checks.

~~258~~ 253050
bkg 10 cs 75

245026
bkg 10 cs 70

1720 end of day, leave site. Weather still overcast with light rain.

Neil has imported data.

Tomorrow continue building 2540.

6/13/2012

Pre Floor Monitor (SN 138231)

	α	β
Tile:	α-10	β-913
Carpet:	α-13	β-1157

Post Tile: α β

Carpet: α-6 β-960

QC Check - Post SWO6 walkover

	α	β
Bkg	10	1208
Tc99	29	4957
Th-230	6105	2704

End of day.

6/14/12

Arrive on site ~0700. Sunny.
Mike and Hans on site.

NRC will be visiting today.

Begin QC checks at 0730.

245026 exposure rate meter

bkg	12	bkg	9
cs137	65	cs137	75

253050 exposure rate meter

bkg	10	bkg	10
cs137	70	cs137	70

311206 α/β meter

bkg	127	bkg	131
tc99	1924	tc99	1780

275713 w/ 43-37 post AM

	α	β
bkg	7	794
^{99}Tc	6	3072
^{230}Th	5018	2123

	α	β
bkg	5	928
^{99}Tc	10	3167
^{232}Th	5462	2166

275724 w/ 43-37 post AM

	α	β
bkg	6	669
^{99}Tc	10	4607
^{230}Th	4065	2106

	α	β
bkg	3	857
^{99}Tc	4	4683
^{230}Th	4315	2121

E38251 w/ 43-37-1 Post SU08 QC

	α	β
bkg	5	1678
^{99}Tc	13	4940
^{230}Th	6391	2496

	α	β
Bkg	4	1185
^{99}Tc	13	4966
^{230}Th	6071	2675

275724 appeared to have a bad cable. Replaced cable and instrument response returned to normal.

SU7 Drywall (office) α 13 β 1157
43-37-1

6/14/12

Begin exposure rate surveys in SU7.

location	x
1	10
2	11
3	8
4	7
5	6
6	7
7	9
8	7
9	7
10	8
11	9
12	9
13	9
14	6
15	8
16	7
17	8
18	11
19	9
20	6
21	6
22	7


meter 253050

location	X	meter
23	5	253050
24	7	
25	6	
26	6	
27	7	
28	8	
29	7	
30	6	
31	9	
32	8	
33	9	
34	8	
35	6	
36	7	
37	7	
38	8	
39	10	
40	9	
41	8	
42	7	
43	6	
44	6	
45	7	
46	9	
47	7	
32D	8	

location	X	meter
48	5	253050
49	7	253050
10D	8	
15D	8	
23D	5	

Laminate Tile Ambient α-4 B-542
in SV08 w/ Ludlum 43-37-1
SN 138251 (2360)

2nd Ambient 1.5 hr later
α-6 B-562



6/14/2012 cont.

Begin SH 14 @ 1235

powered concrete

ambient background one minute counts

pad	shed
275713	275724
α: 1	α: 4
β: 459	β: 533

location	meter	α	β	ΔR	time
1	275713	51	668	4	1240
2	275713	55	767	5	1242
3	275713	69	757	5	1244
4	275713	56	711	4	1245
5	275713	45	693	3	1247
6	275713	44	739	4	1248
7	275713	38	723	5	1250
8	275713	51	745	4	1252
9	275724	12	528	4	1253
10	275724	7	555	4	1254
11	275724	9	581	4	1256
12	275724	13	609	4	1249
13	275724	11	510	4	1246
14	275724	14	580	4	1245
15	275724	18	591	5	1241
16	275724	12	571	3	1243

6/14/12

location	meter	α	β	MR	time
17	275724	10	574	3	1244
18	275724	14	535	6	~~1252~~ 1256
19	275724	8	488	5	~~1254~~ 1258
20	275724	9	534	5	1300
21	275724	7	492	3	1302
21D	275724	9	496	3	1304
22	275713	5	444	5	1305
23	275713	9	502	5	1304
24	275713	10	541	4	1302
25	275713	7	686	4	~~1254~~ 1301
26*	275713	7	365	3	~~1252~~ 1259
27	275713	4	509	4	~~1251~~ 1258
5D	275713	52	627	3	1250
13D	275724	12	584	5	1248

#1-8 were pad locations and seemed to be a different kind of concrete.

#18-27 were walls, painted concrete blocks.

*#26 is painted metal door

6/14/12

· Exposure rates taken w/ 245026

Finish, begin QC @ 1300

275713

	α	β
bkg	2	747
tc99	6	3232
th232	513	2216

275724

	α	β
bkg	10	~~827~~
~~tc99~~	15	4729
th232	4199	2141

13825

	α	β
bkg		
α		
β		

NOT USED

253050 exposure rate meter

bkg 9

cs137 75

245026 exposure rate meter

bkg 8

cs137 70

Break for lunch @ 1345

Return @ 1445

275713

	α	β
bkg	1	693
tc99	1	3083
th230	4950	2247

Post QC @ 1705

	α	β
bkg	4	745
tc99	3	3157
th230	4983	2119

275724

	α	β
bkg	4	812
tc99	13	4767
th230	4256	2073

	α	β
bkg	8	845
tc99	12	4753
th230	4279	2135

PRE 138251 (~~4357-1~~)

	α	β
bkg	5	1148
tc99	22	5099
th230	6405	2724

Post QC

	α	β
Bkg	10	1198
Tc99	26	5297
th230	6361	2777

253050 exposure rate meter
bkg 10
cs 137 70

245026 exposure rate meter
bkg 11
cs 137 70

2360 Data lost for SU07 & SU14 data comprimized during transfer and software crashed.

for SU14 the room ambient background used for metal door background subtraction ~~-WM~~

SU14 with floor/wall scaner
ambient lwim cont = 3α | 604β
2360 SN 138251

1730 - Leave site for the day. Weather is sunny and warm.

6/15/12

0700 Arrive @ site. Sunny and mild.

0710 Begin instrument QC checks.

245026 exposure rate meter
bkg 10
cs 137 75

253050 exposure rate meter
bkg 10
cs137

311206 43 -93 α/β meter
bkg
tc 99

AM QC

275713

	α	β
bkg	7	712
tc99	3	3241
th230	2103	4979

30

275724

	α	β
bkg	10	695
tc99	14	4773
th230	4026	2136

138251

	α	β
bkg	15	1076
tc99	18	5112
th230	6245	2603

Post AM QC

	α	β
bkg	~~2~~	820
tc99	5	3265
th230	5212	2199

	α	β
bkg	13	763
tc99	15	4740
th231	4306	2143

	α	β
bkg	7	1031
tc99	12	4981
th230	6174	2556

6/18/12

- Arrive on site (Donakowske Miller) @ ~0700. Eric Barbour will be on site today.

Weather is sunny and mild.

Begin instrument QC checks.

253050 exposure rate meter
bkg 10
cs137 75

245026
bkg 11
cs 137 80

311206 α/β probe
bkg 108
tc99 1834

6/18/2012

275713 ~1 43-37

Pre QC	α	β
bkg	5	768
Tc99	3156	8
Th230	5163	2138

Post QC	α	β
Bkg	2	783
Tc99	2	3255
Th230	5332	2152

275724 ~1 43-37 * needs to have gas flow longer

	α	β		α	β
bkg	10	829	Bkg	11	884
Tc99	14	4763	Tc99	14	4843
Th230	4211	2128	Th230	4426	1974

138231 ~1 43-37-1

	α	β	Post QC	α	β
bkg	13	1036	Bkg	10	1205
Tc99	11	4936	Tc99	29	5096
Th230	6122	2568	Th230	6268	2749

Guard cell - (848) 248-3194

6/18/12

Miller and Downtown, Li begin wall scanning of machine shop walls.

Leave site @ ~1245

Return to site @~1325

Begin after noon QC

275713

	α	β
bkg	5	814
Tc99	3	3283
Th230	5545	2142

275724

	α	β
bkg	4	809
Tc99	12	4919
Th230	4198	2025

138251

	α	β
bkg		
Tc99		
Th230		

6/18/12

1510 Drinkwater + Waters

begin SU4 and SU5

SU4 - laminate tile

253050 meter

location	meter	α	β	x	time
1	275724	6	967	14	1607
2	275724	10	947	14	1609
3	275724	7	855	10	1611
4	275724	5	761	9	1613
5	275724	6	818	10	1615
6	275724	14	759	8	1617
7	275724	11	822	11	1605
8	275724	8	853	8	1157
9	275724	7	831	10	1601
10	275724	6	819	10	1603
11	275724	10	853	10	1556
12	275724	11	747	9	1554
13	275724	11	855	10	1553
14	275724	10	851	9	1551
15	275724	12	833	12	1544
16	275724	10	816	10	1546
17	275724	9	843	10	1549
18	275724	6	820	8	1550
19	275724	12	829	10	1542
20	275724	10	860	10	1541
21	275724	7	827	9	1539

location	meter	α	β	x	time
22	275724	12	816	8	1537
23	275724	10	818	12	1530
24	275724	9	852	9	1531
25	275724	8	871	10	1534
26	275724	7	812	9	1535
27	275724	14	824	10	1526
28	275724	8	857	10	1524
29	275724	8	853	9	1520
30	275724	18	836	8	1518
29D	275724	4	832	9	1522
SU4-B1	275724	8	825	10	1528
24D	275724	6	871	9	1532
16D	275724	7	833	10	1547
8D	275724	10	860	8	1559

275713 meter

SU5 drywall + metal doors

location	meter	α	β	χ	time
1 o	275713	7	921	15	1514
2	275713	7	728	14	1516
3*	275713	10	528	10	1518
4	275713	6	616	9	1520
5	275713	4	607	10	1522
6	275713	4	552	9	1524
7	275713	6	692	10	1526
8*	275713	0	569	8	1528
9	275713	2	658	9	1530
10*	275713	7	774	8	1531
11	275713	4	688	13	1532
12	275713	2	686	12	1534
13	275713	2	594	12	1535
14	275713	3	708	10	1537
15	275713	2	695	11	1538
16	275713	3	689	14	1539
17*	27513	6	630	12	1541
18 o	275713	7	964	13	1542
19 o	275713	9	891	15	1544
20	275713	3	685	11	1545
21	275713	7	670	10	1546
23	275713	5	444	7	1548
23	275713	3	652	10	1550

location	meter	α	β	χ	time
24	275713	4	569	8	1553
25	275713	4	~~797~~ 504	7	1554
26	275713	2	479	8	1556
27	275713	5	569	8	1557
28	275713	3	673	10	1559
29	275713	3	694	8	1601
30	275713	4	682	11	1603
31	275713	3	686	11	1604
32	275713	1	670	11	1608
33	275713	7	651	10	1610
34	275713	5	610	12	1611
35*	275713	4	663	10	1613
36	275713	2	761	10	1606
SU5-B1	275713	2	620	7	1551
16D	275713	1	629	14	1615
7D	275713	5	643	10	1617
11D	275713	5	670	12	1619
29D	275713	3	693	8	1621

Ambient w/ 275713 — 2 — 13

6 — 749

0 1, 18 & 14 are poured concrete

* 3, 8, 10, 17 & 35 are metal doors

6/19/12

Lunch @ 1200

Return to site @ 1245

Afternoon QC checks

275713

	α	β		α	β
bkg	2	788	bkg		
tc99	2	3136	tc99		
th230	5318	2099	th230		

275724

	α	β		α	β
bkg	9	789	bkg		
tc99	16	4702	tc99		
th230	4219	2136	th230		

1255 Begin static counts in SGs 10 + 11

Exposure rates w/ 253058

6/19/12 SG-10 paved concrete

location	meter	α	β	x	time
1	275713	9	621	4	1258
2	275713	7	563	5	1300
3	275713	~~5~~ 4	567	4	1304
4	275713	10	648	5	1306
5	275713	10	601	4	1308
6	275713	11	676	4	1310
7	275713	3	668	5	1312
8	275713	7	~~663~~ 640 50	5	1314
9	275713	8	772	6	1316
10	275713	6	736	3	1319
11	275713	6	645	4	1320
12	275713	3	630	4	1324
13	275713	7	623	5	1326
14	275713	8	634	5	1328
15	275713	9	616	5	1330
16	275713	8	632	5	1332
17	275713	5	638	4	1334
18	275713	10	654	6	1336
19	275713	3	667	5	1338
20	275713	5	639	5	1340
21	275713	8	560	5	1342
22	275713	11	674	6	1346
23	275713	9	689	5	1348
24	275713	9	729	6	1350

6/19/13

location	meter	α	β	x	time
2D	275713	5	629	5	1302
ambient	275713	3	542	4	1354
9D	275713	7	704	5	1317
10Bing-1	275713	6	657	5	1322
21D	275713	8	594	4	1344
24D	275713	6	679	4	1352

SU-11 concrete block ~~floor~~ paint

location	meter	α	β	x	time
*1	275724	8	402	5	1257
2	275724	5	484	6	1259
3	275724	11	598	4	1301
4	275724	11	538	4	1303
5	275724	8	573	5	1305
6	275724	8	699	4	1307
7	275724	10	581	5	1309
8	275724	9	573	4	1311
9	275724	11	506	4	1313
10	275724	15	552	3	1315
11	275724	14	514	5	1317
12	275724	6	530	4	1319
13	275724	13	495	4	1321
14	275724	7	509	5	1323
15	275724	3	546	5	1325
16	275724	11	530	4	1327
17	275724	5	546	4	1329
18	275724	5	520	5	1331
19*	275724	9	418	4	1333
20	275724	6	502	5	1335
21	275724	9	503	4	1337
22	275724	12	630	5	1339
23	275724	9	663	5	1341
24	275724	13	555	5	1343

*1 is metal door, 19 is metal door

6/19/12

location	meter	α	β	χ	time
25	275724	11	477	4	1345
26	275724	11	613	5	1347
27	275724	10	517	4	1349
28	275724	11	538	5	1351
29	275724	8	483	6	1353
30	275724	12	519	5	1355
31	275724	13	553	4	1357
32	275724	7	480	5	1401
33	275724	13	574	5	1403
34	275724	10	505	4	1411
35	275724	13	569	4	1413
36	275724	11	517	4	1415
37	275724	12	~~4~~501	4	1417
38	275724	12	~~4~~503	4	1419
39	275724	12	~~5~~472	5	1418
ambient	275724	4	545	5	1306
11 Bias-1	275724	13	494	5	1359
40	275724	9	529	5	1405
41	275724	8	510	5	1407
42	275724	9	549	4	1409
23D	275724	13	646	6	1422
20D	275724	5	530	4	1424
2D	275724	10	522	6	1426
12D	275724	8	535	4	1428
6D	275724	10	661	6	1430

SU7 - Machine Shop Bias 2
meter - 275724
time - 1435
α - 33 5 minute count
β - 3084
χ - 8

SU 14 - Back shed Bias 1
meter - 275724
time - 1445
α - 11
β - 598
χ - 4

6/21/12

Arrive on site @ 0700.

Begin QC checks.

245026 exposure rate 253050 exposure rate
bkg 9 bkg 9
csm 65 csm 70

6/21/12

311206 α/β
bkg 110
t_c 99 1787

275713 ~1 43-37

	α	β
bkg	3	757
t_c99	3	3162
t+220	5248	2167

275724 ~1 43-37

	α	β
bkg	7	851
t_c99	13	4702
t+220	4289	2155

138251 ~1 43-37-1

	α	β
bkg	6	1191
t_c99	36	4927
t+220	6168	2656

6/21/12

Dave, Wayne & Jough head to Squire Hall to sample drains @ 0830

283 253050 exposure rate meter

		x̄
Point 6 @ 0913		3
Point 25 @ 0915		5
Point 12 @ 0918		4
Point 17 @ 0925		6
Point 18 @ 0930		5
Point 30 @ 0936		10
Point 28 @ 0940		10
Floor drain next to 0943	28	5 Room 102 ~~B N A~~
Point 26 @ 0949		9
Point 8 @ 0952		15 - drain grated in no sample taken
Point 10 @ 0955		14
Point 2 @ 0958		14
Point 1 @ 1000		10
Floor drain next to 1 @ 1002 - 1004 wet and dry smears 5 μR/h -		
Point 19 @ 1003		11
Point 5 @ 1005		9
Point 14 @ 1007		10

	x
Point 30 @ 1010	10
Point 29 @ 1012	11

Leave Square @ 1030

★ Survey Unit 6 & 7 Ambient ★

5 min Counts

	α	β
275724	43	3675

	α	β
275713	25	3417

Leave site @ 1745 ← 6121/12

CONTENTS

PAGE	REFERENCE	DATE

Rite in the Rain
ALL-WEATHER WRITING PAPER

ALL-WEATHER
JOURNAL
FIELD BOOK

Name _____

Address _____

Phone _____

Project Fort Monmouth Radiological Survey
Field Book #2

Rite in the Rain — A patented, environmentally responsible, all-weather writing paper that sheds water and enables you to write anywhere, in any weather. Using a pencil or all-weather pen, *Rite in the Rain* ensures that your notes survive the rigors of the field, regardless of the conditions.

Specifications for this book

Page Pattern		Cover Options	
Left Page	Right Page	Polydura Cover	Fabrikoid Cover
Lined	Lined	Item No. 390N	Item No. 390NF

RiteintheRain.com

June 11th, 2012

Building 1205 - Reference Background Area

Laminate Tile (E-W Hallway)
X = 4.8' Y = 289'

	X	Y
1-	0	151
2-	1	185
3-	4	65
4-	4	179
5-	0	174
6-	0	11
7-	4	94
8-	4	112
9-	4	166
10-	1	45
11-	4	32
12-	4	64
13-	1	17
14-	3	226

Ceramic Tile (Cafeteria - Windows to Column)
X = 48.6' Y = 21.1'

	X	Y
1-	7	5
2-	28	20
3-	4	4
4-	~~4~~ 32	~~7~~ 16
5-	2	12
6-	31	13
7-	4	7
8-	4	3
9-	40	0
10-	6	7
11-	4	5
12-	~~4~~ 25	3
13-	13	9
14-	44	12

Painted Poured Concrete (Basement Room B-5)

X = 56.6' Y = 21.6'

	X	Y
1-	47	1
2-	55	3
3-	14	9
4-	8	7
5-	18	17
6-	19	12
7-	1	9
8-	52	13
9-	25	6
10-	47	7
11-	52	16
12-	14	20
13-	49	5
14-	2	20

Painted Block Concrete Wall (B-5)

X = 56.5 Y = 6'

	X	Y
1-	7	4
2-	23	1
3-	17	0
4-	33	5
5-	12	3
6-	12	5
7-	3	4
8-	27	4
9-	26	2
10-	14	4
11-	49	4
12-	14	3
13-	46	1
14-	30	3

Ceramic Tile Results (Handheld SLCTXX)

	α	β	Time	α	β
1	28	1563	11:50	21	1261
2	40	1669	11:44	20	1244
3	30	1579	12:07	18	1270
4	25	1525	11:40	19	1253
5	24	1643	12:~~12~~	20	1230
6	20	1470	11:43	19	1314
7	39	1641	12:04	16	1282
8	31	1582	12:09	12	1255
9	34	1543	11:57	18	1341
10	26	1593	11:51	15	1288
11	22	1630	12:06	18	1328
12	30	1600	11:46	23	1277
13	29	1571	11:48	15	1318
14	35	1602	1138	14	1193

43-37-1 SN 136361
w SN 138251
"Big"

43-37 SN 092501
w/ SN 275724
"Small"

Painted Poured Concrete (Handheld SLPPCXX)

	α	β	Time	α	β
1-	4	527	1237	4	468
2-	8	622	1248	9	510
3-	9	507	1230	8	448
4-	11	540	1228	6	472
5-	11	463	1234	14	461
6-	12	562	1238	11	466
7-	8	588	12:24	11	534
8-	6	611	1244	8	469
9-	7	593	1235	7	485
10-	11	561	1239	12	448
11-	7	532	1246	3	459
12-	13	453	1232	12	426
13-	8	512	1242	9	440
14-	14	526	12:26	7	452

43-37-1 SN 136361
w/ SN 138251
"BIG"

43-37 SN 092501
w/ SN 275724
"SMALL"

Painted Block Concrete (B-5 Wall)

	α	β	Time	α	β
1	13	522	1318	11	388
2	10	893	1307	8	692
3	12	547	1309	6	443
4	10	846	1302	4	649
5	7	583	1317	9	410
6	12	533	1315	4	421
7	13	455	1320	5	414
8	15	912	1304	7	720
9	15	875	1306	9	716
10	10	509	1311	17	445
11	12	868	1255	15	706
12	2	496	1313	7	442
13	13	931	1258	11	652
14	9	898	1259	12	685

~~43-37~~-1 SN 136361
w/ SN 138251
"Big"

α	β
5	499

43-37 SW 092501
w/ SN 275724

α	β
12	410

6/11/2012 PM

Survey unit 1 in Building 2540 was gridded and measurement points identified at ~1600.

Measurements on laminate tile and at 1m for exposure rates

43-37 SW 093166 ⇒ 245026

location	probe	α	β	μR	time
1	275713	17	1031	14	1613
2	275713	21	1024	16	1615
3	275713	17	945	15	1617
4	275713	13	907	15	1619
5	275713	20	1146	14	1621
6	275713	13	982	16	1623
7	275713	25	955	15	1625
8	275713	16	976	13	1627
9	275713	17	1023	15	1628
10	275713	17	975	15	1630
11	275713	12	959	11	1632
12	275713	24	1001	14	1633
13	275713	21	946	13	1635
14	275713	17	1016	15	1636
15	275713	22	964	16	1638
16	275713	19	912	15	1639
16D	275713	20	988	15	1641

4357 SN# 092501

988

245026

Location	probe	α	β	mr/hr	time
17	275713	21	~~1009~~ 3D	12	1640
18	275724	17	1080	15	1640
19	275724	24	900	13	1638
20	275724	17	947	14	1636
21	275724	23	956	14	1635
22	275724	27	893	14	1633
23	275724	21	1087	14	1632
24	275724	24	904	13	1630
25	275724	27	820	14	1628
26	275724	26	790	12	1627
27	275724	17	983	10	1625
28	275724	18	810	13	1623
29	275724	21	828	12	1621
30	275724	19	800	10	1619
31	275724	16	820	11	1617
32	275724	16	935	12	1615
19D	275724	19	936	12	1691
3D	275713	17	978	14	1643

Surveyed by Watters & Donakowski

6/13/12

Arrive on site @ ~0700.
Weather cloudy w/ some light rain.

Begin gas flow in meters and QC checks.

Need to finish walls SQ 13.

245026 exposure rate meter
bkg 9
cs 70

253050 exposure rate mtr.
bkg 10
cs 70

311206 43-93 α/β
bkg 123
Tc-99 1864

275713 pre

	α	β
bkg	6 ~~4~~ SD	~~632~~ SD 821
tc	3	3230
th	4978	2262

* gas low on 1st background, allowed gas to flow + recounted

275724 pre

	α	β
bkg	~~3~~ SD ~~11~~ 9	~~748~~ SD 841
tc	13	4724
th	~~4040~~ SD 4270	~~2128~~ SD 2127

* gas low on 1st background, allowed gas to flow and recounted


~~27~~ 138251 pre

	α	β
bkg	25 ~~13~~ SD	~~811~~ SD 1133
tc	20	5138
th	6089	2505

5406

* gas low on 1st background, allowed gas to flow + recounted

o gas low during count, allowed gas to flow and recounted



6/13/12

Begin static counting in 546 @ 0900 Carpet 1, 2, 3, 6, 7, 8

5 minute counts

location	probe	α	β	μR	time
bkg carpet	275713	32	3417	10	0900 ring
bkg carpet	275724	28	3366	10	0900 ring
1	275713	45	3352	10	0910 ring
2	275713	41	3636	7	0920 ring
3	275713	52	3448	7	0927 ring
4	275724	46	3855	6	1001 tile
5	275724	49	3803	8	1007 tile
6	275724	58	3676	10	0926 ring
7	275724	71	3435	10	0911 ring
8	275724	49	3412	9	0920 ring
80	275724	66	3364	9	0933 ring
bkg tile	275713	17	3263	8	~~0946~~ 0959 tile
bkg tile	275724	34	3503	8	~~0944~~ 0956 tile
9	275724	58	3689	8	0955 tile
10	275724	SD ~~3~~ 48	4745	7	1012 tile
11	275724	49	3828	7	1018 tile
12	275724	44	3539	6	~~1024~~ 1037 tile
13	275724	62	3513	7	1043 tile
14	275724	45	3607	7	1050 tile
15	275724	44	3929	8	1100 tile
150	275724	47	3918	8	1105 tile

location	probe	α	β	ER	time
16	275724	60	3738	7	1111 t:le
17	275724	55	3522	6	1117 t:le
18	275724	47	3612	6	1123 t:le
19	275713	25	3713	7	1127 t:le
20	275713	21	3735	7	1121 t:le
21D	275713	28	3720	9	1109 t:le
22	275713	23	3491	6	1104 t:le
23	275713	39	3668	6	1058 t:le
24	275713	32	4002	8	1023 t:le
25	275713	45	3816	8	1038 t:le
26	275713	35	3693	9	1044 t:le
27	275713	26	3562	7	1050 t:le
28	275713	33	3987	8	1017 t:le
29	275713	38	3939	8	1011 t:le
30	275724	63	3834	9	0944 t:le
31	275713	23	3506	7	1006 t:le
32	275713	38	3657	6	0946 t:le
32D	275713	37	3674	6	0951 t:le
21D	275713	33	3761	9	1115 t:le

6/13/12

Backgrounds taken in each room as ambient background, i.e. probe pointing at ceiling instead of in contact w/ surface.

SU06 Post QC

275713

	α	β
Bkg	3	795
Tc99	3	3122
Th230	5126	2249

275724

	α	β
Bkg	6	764
Tc99	9	4829
Th230	4063	2009

SU03 (will scan Post QC)

138251

	α	β 120 t
Bkg	6	
Tc99	19	5042
Th230	6156	2649

Break for lunch. Raining.

1st PicoQC before SU06 walkdown

138251

	α	E
Bkg	9	1229
Tc99	21	4906
Th230	5968	2660

1st QC

138251

	α	β
Bkg	10	1208
Tc99	29	4957
Th230	6105	2704

275724

	α	β
bkg	7	868
Tc99	15	4900
Th230	4143	2142

275724

	α	β
Bkg	12	802
Tc99	11	4793
Th230	4312	2064

275713

	α	β
bkg	7	798
Tc99	1	3296
Th230	5152	2243

275713

	α	β
Bkg	7	732
Tc99	4	3041
Th230	5303	2105

3' x .75

.8 ft²

6/13/12

1415 Begin floor scanning in SU6 w/ 43-7-1.

- One minute ambient background (i.e. detector facing ceiling, not in contact w/ surface) counts taken on tile and carpet

~~Carpet background~~

Tile β - 913 α - 16 } w/ 43-37-1

rug β - 1159 α - 13

Begin wall static counts in SU7. Walls are drywall.

location	probe	α	β	cR	time
1	~~275713~~	26	3515	10	0845 14 June
2	~~275713~~ 275713	29	3540	11	0855 14 June
3	275724	51	4250	8	0911 14 June
4	275724	34	2928	7	0917 14 June
5	~~275713~~	~~29~~	~~3282~~	~~6~~	~~0962 14 June~~
6	275724	40	2867	7	1627
7	275724	38	2873	9	1622
8	275724	40	3034	7	1555
9	275724	26	3174	7	1535

location	probe	∠	B	kR	time
10	275724	38	3408	8	1510
10D	275724	33	3599	8	~~1510~~ 1517
11	275724	40	3526	9	1446
12	275724	40	3288	9	1440
13	275713	20	3039	9	1539
14	275713	15	3590	6	1557
15	275713	~~29~~	3282	8	~~0911~~ 0902 14 June
15D	275713	27	3310	8	0920 14June
16	275713	23	2442	7	0957 14June
17	275713	26	3461	8	1005 14June
18 o	275724	41	4382	11	1017 14June
19	275724	42	3047	9	1009 14June
20	275724	36	2772	6	0959 14June
21	275724	43	2682	6	0948 14June
22	275724	33	2810	7	1635
23	275724	52	2645	5	1605
23D	275724	35	2639	5	1610
24	275724	38	2828	7	~~1604~~ 1600
25	275724	49	3075	6	1328
26	275724	41	3344	6	1502
27	275724	58	3252	7	1454
28*	275713	18	2772	8	1638
29	275713	17	2731	7	1545
30*	275713	19	2739	6	1043 14June

*28 is a metal door

Location	probe	∠	B	kR	time
31	275713	13	3175	6	0950 14June
32	275713	17	3257	9	0935 14June
32D	275713	12	3512	8	0940 14June
33	275713	15	3161	9	0927 14June
34*	275724	49	2807	8	0926 14 June
35	275715	14	3201	6	1056 14June
36	275713	18	3019	7	1030 14June
37	275724	39	2945	7	1045 14 Ju
38	~~0934~~ 275713	28	3419	8	0910 14June
39	275724	37	3452	10	1104 June
40	275713	19	3181	9	1010 14June
41	275724	32	3480	8	1027 14June
42	275713	19	3066	7	1020 14June
43	275724	44	3054	6	1036 14June
44	275713	11	2923	6	1617
45	275713	15	2619	7	1623
46*	275724	38	2969	9	0932 14June
47	275713	13	3278	7	1054 14June
48	275713	13	3026	5	1103 14June
49	275724	38	2742	7	~~1045~~ loss 14 June
5	275724	42	2937	6	0939 14June

*34 + 46 are metal door, 30 is metal door
o 18 is poured concrete block

~1715 Finish QC checks, will resume wall scans of SU7 tomorrow.

Hans flanerlah on route, will be in in the evening.

NRC will be on site tomorrow.

Leave site ~1730.

- SU7-1 drywall
- SU8-1 laminate tile
- SU8-2 laminate tile
- SU3-1 poured concrete wall
- SU6-1 laminate tile
- SU6-2 laminate tile
- SU12-1 poured concrete floor
- SU12-2 poured concrete floor
- SU13-1 concrete brick wall
- SU8-3 laminate tile

bias sample material list 6/13

SU8 tile ambient	275713		275724	
	α	10	α	30
	β	1979	β	2247

~~6/13/12~~ 6/14/12

WR SN: 245026

~1500 Begin bias sampling.

Location	meter	α	β	ΔR	Time
~~SU7~~					
SU7-1	275713	27	2789	10	1520 - 5min
~~SU83-1~~	275724	35	917	14	1521 - 1min
SU06-1	275724	49	~~3385~~ 3885*	8	1524 - 5min
SU06-2	275713	~~22~~	3164	7	1526 - 5min
~~SU08-1~~	~~275713~~	~~11~~	~~608~~	~~4~~	~~1534 - 5min~~
~~SU08-2~~	~~275713~~			~~4~~	~~1536~~
SU12-1	275724	10	600	4	1534
SU12-2	275724	15	603	4	1536
SU13-1	275724	10	540	4	1540
SU8-1	275713	11	2002	5	1534 - 5min
SU8-2	275713	13	2052	5	1540 - 5min
SU8-3	275713	10	1979	4	1631 - 5min

*3885 α

6/14/12

Begin 548

μR 245026

laminate tile

location	meter	α	β	N	μR	time
1	275724	28	2410		4	1541
2	275724	50	2370		4	1547
3	275724	36	2303		4	1621
4	275724	35	2271		4	1609
5	275724	34	2320		3	1615
6	275724	30	2153		4	0833 - 6/15
7	275724	37	2175		4	0851 - 6/15
8	275724	40	2334		4	1552
9	275724	44	2363		4	1557
10	275724	29	2327		3	1650
11	275724	40	2253		3	1644
12	275724	37	2291		3	1633
13	275724	43	1781		4	~~0851~~ 0906 - 6/15
14	275724	33	1746		3	0912 - 6/15
15	275724	23	1537		4	0917 - 6/15
16	275724	34	2325		5	1603
17	275713	13	2136		4	1600
18	275713	9	1922		5	1642
19	275713	11	1998		4	1649
*20	275713	14	1803		3	1657
21	275713	10	2207		4	0927 - 6/15
22	275713	20	2214		4	0922 - 6/15


*20 : counter top


6/14/12

location	meter	α	β	μR	time
23	275713	5	2049	4	1548
24	275713	14	2004	5	1554
25	275713	9	2072	3	1607
26	275713	13	2011	4	1613
27	275713	13	1965	4	1620
28	275713	18	2350	4	0905 6/15
29	275713	22	2265	4	0856 6/15
30	275713	18	2160	4	0844 6/15
25D	275713	14	2017	4	1626
5D	275724	32	2269	4	1627
30D	275713	14	2144	4	0850 6/15
6D	275724	38	1942	4	0857 6/15
548B2	275713	12	2383	5	1449 6/18
548B-1	275724	31	2391	4	1452 6/18
548B-3	275713	23	2318	3	1455 6/18

6/15/12

S408





6/15/12

- Begin floor static counts in S408 @ ~0840. Will then perform wall statics in ~~S408~~ S409 JD Donakowski surveying.

location	meters		α	β	x̄	time
1	275713	9		1987	4	1539
2	275713	29		2305	5	1448
3	275713	17		2399	5	1415
4	275713	17		1997	4	1425
5	275713	29		2091	5	1012
6	275713	30		2287	4	1021
7	275713	34		2375	5	1027
8	~~275734~~	~~64~~		~~2128~~		~~1050~~
9	275713	52		2922	4	0916
10	275713	42		2608	4	0935
11	275713	18		2764	4	0941
12	275713	25		2631	4	0949
13	275713	32		3145	4	0957
14	275713	15		2614	5	~~1633~~ 1433
15	275713	23		2471	4	1439
16	275713	29		2473	4	1530
17	275713	30		2516	4	1523
18	275713	36		2665	3	1517
19	275713	38		3456	3	1501
19D	275713	37		3333	3	1509

location	meter	α	β	x	time
20	275713	24	3011	4	1455
21	275713	17	2080	4	1025 6/18
22	275713	22	2174	3	1107 6/18
23	275713	21	2248	4	1100 6/18
24	275713	24	2218	3	1212 6/18
25	275713	25	2158	4	1402 6/18
26	275713	26	~~3010~~ 1801	4	
27	275713	30	3130	4	1037
28	275713	28	2355	4	1046
28D	275713	33	2290	5	1078
29	275713	40	2570	4	1053
30	275713	32	2586	4	1850
31	275713	26	2420	5	1101
31D	275713	22	2419	5	1129
32	275713	30	2471	4	1620
33	275713	9	1695	4	1419
34	275713	33	2692	4	1204 6/18
35	275713	14	3344	4	1158 6/18
36	275713	27	2010	3	0951 6/18
37	275713	57	3180	4	0945 6/18
38	275713	49	2633	5	0957 6/18
39	275713	26	2722	4	1007 6/18
40	275713	42	2865	3	1017 6/18
41	275713	33	2312	4	1058 6/18

location	meter	α	β	x	time
42	275713	39	2295	3	1044 6/18
42D	275713	34	2282	3	1051 6/18
43	275713	34	2205	3	1038 6/18
44	275713	22	1887	4	1032 6/18
45	275713	16	2217	4	1150 6/18
46	275713	26	2233	4	1136 6/18
46D	275713	26	2255	4	1143 6/18
47	275713	13	2341	4	1130 6/18
48	275713	17	1986	4	1123 6/18
49	275724	34	2131	4	1212
50	275724	61	2236	3	1205
51	~~275734~~	63	2286	3	1200
52	275724	47	2294	3	1150
53	275724	59	2236	4	1408 6/18
54	275724	39	2287	4	1111
55	275724	55	2212	4	1119
56	275724	41	2282	4	1127
57	275724	61	2286	5	1400 6/18
58	275724	43	2224	4	1418 6/18
58D	275724	61	2295	3	1424 6/18
59	275713	34	2279	3	1425 6/18
60	275724	44	2252	4	1043
61	275724	39	2413	5	1515
61D	275724	45	2565	5	1522

continued on pg 30

SU 9 material list

1 metal door
2 drywall
3 drywall
4 metal door
5 drywall
6 drywall
7 drywall
8 metal conduit
9 concrete block
10 concrete block
11 concrete block
12 concrete block
13 concrete block
14 concrete block
15 concrete block
16 concrete block
17 concrete block
18 concrete block
19 concrete block
20 concrete block
21 metal door
22 drywall
23 drywall
24 drywall
25 metal door
26 metal door
27 concrete block
28 concrete block
29 concrete block
30 concrete block
31 concrete block
32 concrete blocks
33 ~~concrete block~~ frame hood
34 Concrete block
35 concrete block
36 glass window
37 Concrete block
38 concrete block
39 Concrete block
40 concrete block
41 dry wall
42 dry wall
43 dry wall
44 metal door
45 dry wall
46 dry wall

47 drywall
48 metal door
49 frame hood plastic
50 drywall
51 drywall
52 drywall
53 drywall
54 drywall
55 drywall
56 drywall
57 drywall
58 dry wall
59 dry wall
60 dry wall
61 drywall
62 drywall
63 metal door
64 dry wall
65 dry wall
66 metal door
67 metal cabinet
68 metal cabinet
69 metal cabinet
70 dry wall
71 dry wall
72 dry wall
73 dry wall
74 dry wall
75 dry wall
76 metal conduit
77 metal conduit
78 metal conduit
79 dry wall
80 dry wall
SU9B dry wall

check data file?

location	meter	α	β	x	time
62	275724	53	2512	4	1507
63	275724	55	2199	5	1527
64	275724	41	2365	4	~~1616~~ 1416
65	275724	42	2621	4	1425
66	275724	43	2231	3	1434
67	275724	34	2131	4	1454
68	275724	?33	2124	3	1447
69	275724	46	2285	3	1441
70	275724	78	2373	4	1436 6/18
70D	275724	56	2292	4	1442 6/18
~~70~~ 71	275724	38	2175	5	0955
72	275724	44	2250	5	1010
73	275724	34	2140	4	1004
74	275724	35	2185	3	0931
75	275724	29	2263	5	0940
76	275724	46	2023	4	1020
77	275724	64	2128	4	1050
78	275724	58	2098	3	1026
79	275724	36	2158	4	0948
80	275724	43	2222	4	1057
80D	275724	49	2250	4	~~10~~ 1104
8	275713	41	1826	4	1441 6/18
549B	275713	43	2215	5	1435 6/18

6/15/12 Afternoon QC

~~257~~ 275713 ~ 143-37 Post

B	α	β
bkg	1	804
tc99	8	3255
th230	5246	2152

	α	β
bkg	0	750
tc99	7	3135
th230	5324	2234

275724 ~ 143-37

	α	β
bkg	6	851
tc99	7	4818
th230	4357	2152

	α	β
bkg	4	850
~~tc~~99	10	4798
th230	4418	2062

138251 ~ 143-37-1

	α	β
bkg	3	1080
tc99	22	4935
th230	6012	2614

	α	β
bkg	9	1172
tc99	17	5181
th230	6396	2780

Begin surveys @ ~~8~~ 1415
Dombrowski + Watkins

Perform post survey QC checks at 1600.

Leave site @ 1630

Perform QC checks @ 1635

253050 exposure rate meter
bkg 8
cs 137 70

~~25~~ 245026 exposure rate meter
bkg 8
cs137 65

311206 α / β probe
bkg 130
tc99 180

275713 ~ / 43-37

	α	β
bkg	2	771
tc99	1	3182
th230	5333	2177

275724 ~ / 43-37

	α	β
bkg	9	820
tc99	14	4796
th230	4290	2060

~~27~~ 138251

	α	β
bkg	7	1216
tc99	27	5275
th230	6242	2795

Leave site @ 1730

6/19/12

Arrive on site @ 0700.
Cloudy and overcast.

Begin QC chats.

311206 α/β probe
bkg 111
tc99 1713

245026 exposure rate meter
bkg 9
cs137 75

253650 exposure rate meter
bkg 8
cs137 75

6/19/12

275713 w/ 43-37

	α	β
bkg	17	806
t_c99	8	3220
th230	5315	2061

275724 w/ 43-37

	α	β
bkg	9	846
t_c99	13	4807
th230	4065	2168

138251 w/ 43-37-1

	α	β
bkg	23	1045
t_c99	26	5203
th230	6292	2604

0845 Begin surveys in 2541
Domanski & Miller.

Exposure rates w/ 253050.

Backgrounds seem high for alpha-potential radon?

2541 - 541 - poured concrete floor

location	meter	α	β	t	time
1	275713	8	653	4	0857
2	275713	13	696	5	0857
3	275713	14	682	5	0856
4	275713	20	694	4	0854
5	275713	15	640	5	0852
6	275713	34	730	4	0900
7	275713	33	767	4	0901
8	275713	20	683	5	0903
9	275713	17	639	4	0904
10	275713	15	668	4	0906
11	275713	10	706	4	0907
12	275713	15	784	4	0909
13	275713	14	650	4	0910
14	275713	17	663	3	0912
15	275713	18	697	3	0913
16	275713	11	647	3	0915
17	275713	14	679	4	0916
~~18~~	~~275713~~	~~2041~~	~~827~~	~~5~~	~~0918~~
19	275713	41	827	4	0918
20	275713	16	731	5	0920
21	275713	16	675	4	0921
22	275713	8	687	3	0923
23	275713	15	728	3	0924
24	275713	16	728	4	0926

6/19/12

location	meter	α	β	x	time
25	275713	24	673	4	0930
26	275713	17	684	3	0932
27	275713	10	712	4	0933
28	275713	20	697	3	0934
29	275713	14	695	3	0935
30	275713	14	706	3	0937
18	275713	36	752	5	0929
19D	275713	36	742	5	0939
7D	275713	52	782	5	0941
3D	275713	17	760	4	0942
SW2B	275713	10	725	4	0944

2541 SW2 - metal

reading	meter	α	β	x	time
1	275724	10	459	5	0851
2	275724	21	433	3	0853
3	275724	13	415	3	0855
4	275724	8	410	3	0856
5	275724	10	449	3	0858
6	275724	5	398	4	0859
7	275724	5	406	5	0900
8	275724	10	430	4	0902
9	275724	13	422	4	0903
10	275724	14	434	4	0905
11	275724	6	400	5	0906
12	275724	8	403	3	0908
13	275724	8	404	4	0909
14	275724	16	413	4	0911
15	275724	20	429	3	0913
16	275724	16	419	4	0914
17	275724	10	398	3	0916
18	275724	20	461	4	0917
19	275724	9	421	3	0919
20	275724	16	401	4	0920
21	275724	14	402	4	0922
22	275724	~~8~~ 14	~~6~~ 427	4	~~0923~~ 0927
23	275724	7	408	4	0924
24	275724	8	420	3	0931

6/19/2012

Location	meter	α	β	χ	Time
25	275724	12	434	3	0933
26	275724	15	404	4	0934
27	275724	6	454	4	0935
28	275724	7	405	4	0937
29	275724	10	384	4	0938
30	275724	18	404	4	0940
29D	275724	7	469	4	0941
100	275724	11	434	4	0943
28D	275724	5	408	4	0944
542 B	275724	13	390	4	0946

6/19/2012

Building 2541 - ambient α/β

2360 SN 275724 α = 6
43-37 #092501 β = 525

2360 SN 275713 α = 2
43-37 #093966 β = 500

6/19/2012 Post QC

275713 β

Lower Site @ 1700

bkg	α 2	β 854
tc99	4	3097
th230	5360	2058

275724

	α	β
bkg	9	822
tc99	6	4770
th230	4297	2059

138251

	α	β
bkg	13	1253
tc99	32	5210
th230	6254	2759

6/20/2012

25713	Pre QC α	Pre QC β	Post QC α	Post QC β
Bkg	2	747	13	800
Tc99	4	3191	11	3660
Th230	5017	2158	5242	2310

275724	α	β	α	β
Bkg	9	800	26	861
Tc99	7	4786	23	4773
Th230	4015	2047	4244	2091

138251	α	β	α	β
Bkg	12	1130		
Tc99	15	5190		
Th230	6219	2808		

0950 Head to Squire Hall to perform static counts on points with carpet removed,

Weather is sunny and hot.

NRC will be on Site today.

6/20/12

283 Squire Hall under carpet survey

253050

location	meter	∠	β	x	time
x28	275724	13	643	10	1021
x 1 *	275724	11	853	10	1141
x 2	275724	20	859	14	1132
x 3	275724	23	800	9	1112
x4					
x5	275724	29	870	11	1117
x6	275724	18	571	4	1053
7					
x8 *	275724	19	819	10	1127
9					
x10	275724	17	852	12	1130
11					
x12	275724	25	506	4	1050
13					
14					
x15	275724	29	965	12	1155
16					
x17	275724	21	641	6	1047
x18	275724	30	584	6	1048
X19	275724	~~24~~ 17	~~370~~ 894	10	1120
20	~~275~~				

* discovered drain under carpet

6/20/12

location	meter	∠	β	x	time
21					
22					
x23	275724	22	806	10	1108
24					
x25	275724	16	615	5	1056
x26	275724	17	836	~~836~~ 11	1028
27					
29					
x30	275724	11	642	9	1034
~~x20~~ 26D	275724	16	792	11	1030
x180	275724	22	593	5	1042
x190	275724	20	828	11	1122
x1D	275724	25	799	11	1147
x15D	275724	23	870	12	1157

6/20/2012

Leave Squire Hall @ 1210.

Leave for lunch @ 1330.

Return to site @ 1400.

253050

Donchenski begin surveying admin area @ 1430. Tile and carpet. Ambient is post-283 QC checks.

location	meter	α	β	χ	time
1	275724	8	922	15	1451
2	275713	5	465	7	1506
3	275724	16	1018	12	1442
4	275713	12	1014	13	1453
5	275713	11	1038	12	1445
6	275724	17	1007	12	1446
7	275724	15	527	5	1509
8	~~275724~~ 275713	9	1076	10	1448
9	275724	22	1051	14	1449
10	275713	5	434	4	1508
11	275713	16	968	14	1434
12	275713	15	1178	12	1451
13	275724	14	1112	13	1510
14	275724	14	939	10	1457
15	275724	8	492	4	1504

*: nearest to mural (CF-252 room
o: furthest from mural (CF-252 room

location	meter	α	β	χ	time
16	275724	18	482	7	1507
17	275713	6	809	10	1502
18	275713	14	1068	12	1441
19	275713	24	1083	13	1439
20	275713	8	869	13	1504
21	275724	12	888	10	1502
22	275724	20	1171	14	1444
23	275724	14	991	12	1501
24	275724	7	969	9	1505
25	275724	15	980	12	1455
26	275713	13	855	11	1500
27	275724	13	1019	13	1453
28	275724	23	1009	11	1500
29	275713	10	901	13	1457
30	275724	24	1062	10	1440
11D	275713	15	1001	12	1436
8D	275713	12	1102	10	1449
4D	275713	16	1025	12	1455
15-Bing-Hall	275724	9	496	7	1610
carp Amb	275713	13	800		
carp Amb	275724	26	861		
tile Amb*	275713	6	734		
tile Amb*	275724	14	762		
tile Amb o	275713	4	450		
tile Amb o	275724	11	483		

used these values for carpet background in spreadsheet

SU 15 materials list

1 carpet
2 blue tile
3 carpet
4 carpet
5 carpet
6 carpet
7 blue tile
8 carpet
9 carpet
10 blue tile
11 carpet
12 carpet
13 carpet
14 carpet
15 blue tile
16 blue tile
17 white tile
18 carpet
19 carpet
20 white tile
21 white tile
22 carpet
23 carpet

24 white tile
25 carpet
26 carpet
27 carpet
28 carpet
29 carpet
30 carpet
bias - blue tile

275713 w/ 43-37

	α	β
bkg	65	790
tc	6	3334
th	5306	2115

275724 w/ 43-37

	α	β
bkg	9	896
tc	14	4840
th	4278	2049

245026
bkg 9
cs 75

253050
bkg 10
cs 70

6120/12

13825 | ~143-37-1

	α	β
bkg	12	1377
^{232}Th	31	5216
^{238}U	6187	2811

SU 6 Ambient

	α	β
275713	1	625
275724	9	746

APPENDIX H

Scan Data

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 275	1	Scan	Cabinet	Miller/Watters	6/5/2012	4:29:55 PM	2.00	Ludlum 43-37-1 (SN 136361)	821	3	534	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:29:57 PM	"	Ludlum 43-37 (SN 093966)	584	2	508	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:29:59 PM	"	Ludlum 43-37 (SN 093966)	584	13	505	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:30:01 PM	"	Ludlum 43-37 (SN 093966)	584	9	509	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:30:03 PM	"	Ludlum 43-37 (SN 093966)	584	6	554	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:30:05 PM	"	Ludlum 43-37 (SN 093966)	584	3	530	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:30:07 PM	"	Ludlum 43-37 (SN 093966)	584	2	559	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:30:09 PM	"	Ludlum 43-37 (SN 093966)	584	1	676	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:30:11 PM	"	Ludlum 43-37 (SN 093966)	584	1	632	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:30:13 PM	"	Ludlum 43-37 (SN 093966)	584	0	529	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:30:15 PM	"	Ludlum 43-37 (SN 093966)	584	0	566	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:30:17 PM	"	Ludlum 43-37 (SN 093966)	584	0	537	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:30:19 PM	"	Ludlum 43-37 (SN 093966)	584	0	586	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:30:21 PM	"	Ludlum 43-37 (SN 093966)	584	0	556	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:30:23 PM	"	Ludlum 43-37 (SN 093966)	584	0	585	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:30:25 PM	"	Ludlum 43-37 (SN 093966)	584	0	525	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:30:27 PM	"	Ludlum 43-37 (SN 093966)	584	0	483	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:30:29 PM	"	Ludlum 43-37 (SN 093966)	584	0	516	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:30:31 PM	"	Ludlum 43-37 (SN 093966)	584	0	522	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:30:33 PM	"	Ludlum 43-37 (SN 093966)	584	0	565	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:30:35 PM	"	Ludlum 43-37 (SN 093966)	584	0	536	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:30:37 PM	"	Ludlum 43-37 (SN 093966)	584	0	490	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:30:39 PM	"	Ludlum 43-37 (SN 093966)	584	0	565	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:30:41 PM	"	Ludlum 43-37 (SN 093966)	584	9	567	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:30:43 PM	"	Ludlum 43-37 (SN 093966)	584	6	550	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:30:45 PM	"	Ludlum 43-37 (SN 093966)	584	3	511	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:30:47 PM	"	Ludlum 43-37 (SN 093966)	584	2	506	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:30:49 PM	"	Ludlum 43-37 (SN 093966)	584	1	488	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:30:51 PM	"	Ludlum 43-37 (SN 093966)	584	1	462	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:30:53 PM	"	Ludlum 43-37 (SN 093966)	584	0	510	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:30:55 PM	"	Ludlum 43-37 (SN 093966)	584	0	559	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:30:57 PM	"	Ludlum 43-37 (SN 093966)	584	0	502	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:30:59 PM	"	Ludlum 43-37 (SN 093966)	584	0	536	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:31:01 PM	"	Ludlum 43-37 (SN 093966)	584	0	565	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:31:03 PM	"	Ludlum 43-37 (SN 093966)	584	0	546	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:31:05 PM	"	Ludlum 43-37 (SN 093966)	584	0	541	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:31:07 PM	"	Ludlum 43-37 (SN 093966)	584	0	528	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:31:09 PM	"	Ludlum 43-37 (SN 093966)	584	0	544	Wood
Building 275	1	Scan	Cabinet	Miller/Watters	6/5/2012	4:37:27 PM	2.00	Ludlum 43-37 (SN 093966)	584	0	594	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:37:31 PM	"	Ludlum 43-37 (SN 093966)	584	0	579	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:37:35 PM	"	Ludlum 43-37 (SN 093966)	584	0	629	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:37:39 PM	"	Ludlum 43-37 (SN 093966)	584	0	644	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:37:43 PM	"	Ludlum 43-37 (SN 093966)	584	0	608	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:37:47 PM	"	Ludlum 43-37 (SN 093966)	584	0	697	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:37:51 PM	"	Ludlum 43-37 (SN 093966)	584	0	757	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:37:55 PM	"	Ludlum 43-37 (SN 093966)	584	11	599	Wood

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 275	1	Scan	Cabinet	"	6/5/2012	4:37:59 PM	"	Ludlum 43-37 (SN 093966)	584	4	599	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:38:03 PM	"	Ludlum 43-37 (SN 093966)	584	2	606	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:38:07 PM	"	Ludlum 43-37 (SN 093966)	584	0	555	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:38:11 PM	"	Ludlum 43-37 (SN 093966)	584	7	618	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:38:15 PM	"	Ludlum 43-37 (SN 093966)	584	10	528	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:38:19 PM	"	Ludlum 43-37 (SN 093966)	584	10	605	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:38:23 PM	"	Ludlum 43-37 (SN 093966)	584	4	586	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:38:27 PM	"	Ludlum 43-37 (SN 093966)	584	2	522	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:38:31 PM	"	Ludlum 43-37 (SN 093966)	584	0	579	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:38:35 PM	"	Ludlum 43-37 (SN 093966)	584	0	641	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:38:39 PM	"	Ludlum 43-37 (SN 093966)	584	0	613	Wood
Building 275	1	Scan	Cabinet	Miller/Watters	6/5/2012	4:42:23 PM	2.00	Ludlum 43-37 (SN 093966)	584	0	678	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:42:27 PM	"	Ludlum 43-37 (SN 093966)	584	0	649	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:42:31 PM	"	Ludlum 43-37 (SN 093966)	584	0	619	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:42:35 PM	"	Ludlum 43-37 (SN 093966)	584	0	709	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:42:39 PM	"	Ludlum 43-37 (SN 093966)	584	0	649	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:42:43 PM	"	Ludlum 43-37 (SN 093966)	584	8	623	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:42:47 PM	"	Ludlum 43-37 (SN 093966)	584	3	639	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:42:51 PM	"	Ludlum 43-37 (SN 093966)	584	1	544	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:42:55 PM	"	Ludlum 43-37 (SN 093966)	584	0	558	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:42:59 PM	"	Ludlum 43-37 (SN 093966)	584	0	588	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:43:03 PM	"	Ludlum 43-37 (SN 093966)	584	0	588	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:43:07 PM	"	Ludlum 43-37 (SN 093966)	584	0	493	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:43:11 PM	"	Ludlum 43-37 (SN 093966)	584	0	459	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:43:15 PM	"	Ludlum 43-37 (SN 093966)	584	0	551	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:43:19 PM	"	Ludlum 43-37 (SN 093966)	584	0	584	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:43:23 PM	"	Ludlum 43-37 (SN 093966)	584	0	548	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:43:27 PM	"	Ludlum 43-37 (SN 093966)	584	0	530	Wood
Building 275	1	Scan	Cabinet	Miller/Watters	6/5/2012	4:46:25 PM	2.00	Ludlum 43-37 (SN 093966)	584	0	648	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:46:27 PM	"	Ludlum 43-37 (SN 093966)	584	0	621	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:46:29 PM	"	Ludlum 43-37 (SN 093966)	584	0	594	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:46:31 PM	"	Ludlum 43-37 (SN 093966)	584	0	572	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:46:33 PM	"	Ludlum 43-37 (SN 093966)	584	0	574	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:46:35 PM	"	Ludlum 43-37 (SN 093966)	584	0	628	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:46:37 PM	"	Ludlum 43-37 (SN 093966)	584	22	636	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:46:39 PM	"	Ludlum 43-37 (SN 093966)	584	14	622	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:46:41 PM	"	Ludlum 43-37 (SN 093966)	584	9	635	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:46:43 PM	"	Ludlum 43-37 (SN 093966)	584	15	691	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:46:45 PM	"	Ludlum 43-37 (SN 093966)	584	10	690	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:46:47 PM	"	Ludlum 43-37 (SN 093966)	584	7	655	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:46:49 PM	"	Ludlum 43-37 (SN 093966)	584	16	559	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:46:51 PM	"	Ludlum 43-37 (SN 093966)	584	11	558	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:46:53 PM	"	Ludlum 43-37 (SN 093966)	584	7	552	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:46:55 PM	"	Ludlum 43-37 (SN 093966)	584	4	485	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:46:57 PM	"	Ludlum 43-37 (SN 093966)	584	12	521	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:46:59 PM	"	Ludlum 43-37 (SN 093966)	584	8	506	Wood

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 275	1	Scan	Cabinet	"	6/5/2012	4:47:01 PM	"	Ludlum 43-37 (SN 093966)	584	5	537	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:47:03 PM	"	Ludlum 43-37 (SN 093966)	584	3	517	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:47:05 PM	"	Ludlum 43-37 (SN 093966)	584	2	560	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:47:07 PM	"	Ludlum 43-37 (SN 093966)	584	1	567	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:47:09 PM	"	Ludlum 43-37 (SN 093966)	584	11	613	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:47:11 PM	"	Ludlum 43-37 (SN 093966)	584	7	716	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:47:13 PM	"	Ludlum 43-37 (SN 093966)	584	5	723	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:47:15 PM	"	Ludlum 43-37 (SN 093966)	584	3	705	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:47:17 PM	"	Ludlum 43-37 (SN 093966)	584	2	635	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:47:19 PM	"	Ludlum 43-37 (SN 093966)	584	1	613	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:47:21 PM	"	Ludlum 43-37 (SN 093966)	584	1	673	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:47:23 PM	"	Ludlum 43-37 (SN 093966)	584	0	701	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:47:25 PM	"	Ludlum 43-37 (SN 093966)	584	0	619	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:47:27 PM	"	Ludlum 43-37 (SN 093966)	584	0	588	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:47:29 PM	"	Ludlum 43-37 (SN 093966)	584	0	573	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:47:31 PM	"	Ludlum 43-37 (SN 093966)	584	0	566	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:47:33 PM	"	Ludlum 43-37 (SN 093966)	584	0	622	Wood
Building 275	1	Scan	Cabinet	Miller/Watters	6/5/2012	4:51:03 PM	2.00	Ludlum 43-37 (SN 093966)	584	0	436	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:51:05 PM	"	Ludlum 43-37 (SN 093966)	584	0	518	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:51:07 PM	"	Ludlum 43-37 (SN 093966)	584	0	492	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:51:09 PM	"	Ludlum 43-37 (SN 093966)	584	0	472	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:51:11 PM	"	Ludlum 43-37 (SN 093966)	584	0	485	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:51:13 PM	"	Ludlum 43-37 (SN 093966)	584	0	520	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:51:15 PM	"	Ludlum 43-37 (SN 093966)	584	0	496	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:51:17 PM	"	Ludlum 43-37 (SN 093966)	584	0	472	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:51:19 PM	"	Ludlum 43-37 (SN 093966)	584	0	472	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:51:21 PM	"	Ludlum 43-37 (SN 093966)	584	0	565	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:51:23 PM	"	Ludlum 43-37 (SN 093966)	584	0	494	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:51:25 PM	"	Ludlum 43-37 (SN 093966)	584	0	494	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:51:27 PM	"	Ludlum 43-37 (SN 093966)	584	0	512	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:51:29 PM	"	Ludlum 43-37 (SN 093966)	584	10	547	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:51:31 PM	"	Ludlum 43-37 (SN 093966)	584	6	621	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:51:33 PM	"	Ludlum 43-37 (SN 093966)	584	4	594	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:51:35 PM	"	Ludlum 43-37 (SN 093966)	584	3	533	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:51:37 PM	"	Ludlum 43-37 (SN 093966)	584	2	473	Wood
Building 275	1	Scan	Cabinet	Miller/Watters	6/5/2012	4:54:21 PM	2.00	Ludlum 43-37 (SN 093966)	584	2	483	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:54:23 PM	"	Ludlum 43-37 (SN 093966)	584	1	498	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:54:25 PM	"	Ludlum 43-37 (SN 093966)	584	1	452	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:54:27 PM	"	Ludlum 43-37 (SN 093966)	584	0	492	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:54:29 PM	"	Ludlum 43-37 (SN 093966)	584	0	544	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:54:31 PM	"	Ludlum 43-37 (SN 093966)	584	0	574	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:54:33 PM	"	Ludlum 43-37 (SN 093966)	584	0	567	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:54:35 PM	"	Ludlum 43-37 (SN 093966)	584	0	514	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:54:37 PM	"	Ludlum 43-37 (SN 093966)	584	0	498	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:54:39 PM	"	Ludlum 43-37 (SN 093966)	584	0	409	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:54:41 PM	"	Ludlum 43-37 (SN 093966)	584	0	491	Wood

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 275	1	Scan	Cabinet	"	6/5/2012	4:54:43 PM	"	Ludlum 43-37 (SN 093966)	584	12	439	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:54:45 PM	"	Ludlum 43-37 (SN 093966)	584	8	426	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:54:47 PM	"	Ludlum 43-37 (SN 093966)	584	5	502	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:54:49 PM	"	Ludlum 43-37 (SN 093966)	584	3	540	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:54:51 PM	"	Ludlum 43-37 (SN 093966)	584	2	551	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:54:53 PM	"	Ludlum 43-37 (SN 093966)	584	1	581	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:54:55 PM	"	Ludlum 43-37 (SN 093966)	584	1	527	Wood
Building 275	1	Scan	Cabinet	"	6/5/2012	4:54:57 PM	"	Ludlum 43-37 (SN 093966)	584	0	444	Wood
Building 275	1	Scan	Cabinet	Miller/Watters	6/6/2012	10:41:55 AM	2.00	Ludlum 43-37 (SN 093966)	584	4	618	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:41:57 AM	"	Ludlum 43-37 (SN 093966)	584	2	553	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:41:59 AM	"	Ludlum 43-37 (SN 093966)	584	1	556	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:42:01 AM	"	Ludlum 43-37 (SN 093966)	584	1	626	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:42:03 AM	"	Ludlum 43-37 (SN 093966)	584	0	554	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:42:05 AM	"	Ludlum 43-37 (SN 093966)	584	0	550	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:42:07 AM	"	Ludlum 43-37 (SN 093966)	584	0	534	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:42:09 AM	"	Ludlum 43-37 (SN 093966)	584	0	555	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:42:11 AM	"	Ludlum 43-37 (SN 093966)	584	0	585	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:42:13 AM	"	Ludlum 43-37 (SN 093966)	584	0	568	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:42:15 AM	"	Ludlum 43-37 (SN 093966)	584	0	578	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:42:17 AM	"	Ludlum 43-37 (SN 093966)	584	0	589	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:42:19 AM	"	Ludlum 43-37 (SN 093966)	584	0	544	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:42:21 AM	"	Ludlum 43-37 (SN 093966)	584	9	570	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:42:23 AM	"	Ludlum 43-37 (SN 093966)	584	6	577	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:42:25 AM	"	Ludlum 43-37 (SN 093966)	584	3	560	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:42:27 AM	"	Ludlum 43-37 (SN 093966)	584	2	595	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:42:29 AM	"	Ludlum 43-37 (SN 093966)	584	1	606	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:42:31 AM	"	Ludlum 43-37 (SN 093966)	584	11	604	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:42:33 AM	"	Ludlum 43-37 (SN 093966)	584	7	555	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:42:35 AM	"	Ludlum 43-37 (SN 093966)	584	14	571	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:42:37 AM	"	Ludlum 43-37 (SN 093966)	584	9	566	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:42:39 AM	"	Ludlum 43-37 (SN 093966)	584	6	530	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:42:41 AM	"	Ludlum 43-37 (SN 093966)	584	3	476	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:42:43 AM	"	Ludlum 43-37 (SN 093966)	584	2	451	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:42:45 AM	"	Ludlum 43-37 (SN 093966)	584	1	518	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:42:47 AM	"	Ludlum 43-37 (SN 093966)	584	1	478	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:42:49 AM	"	Ludlum 43-37 (SN 093966)	584	0	509	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:42:51 AM	"	Ludlum 43-37 (SN 093966)	584	12	581	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:42:53 AM	"	Ludlum 43-37 (SN 093966)	584	8	632	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:42:55 AM	"	Ludlum 43-37 (SN 093966)	584	5	623	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:42:57 AM	"	Ludlum 43-37 (SN 093966)	584	3	678	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:42:59 AM	"	Ludlum 43-37 (SN 093966)	584	2	658	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:43:01 AM	"	Ludlum 43-37 (SN 093966)	584	1	665	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:43:03 AM	"	Ludlum 43-37 (SN 093966)	584	1	680	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:43:05 AM	"	Ludlum 43-37 (SN 093966)	584	0	636	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:43:07 AM	"	Ludlum 43-37 (SN 093966)	584	0	608	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:43:09 AM	"	Ludlum 43-37 (SN 093966)	584	0	560	Wood

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 275	1	Scan	Cabinet	"	6/6/2012	10:43:11 AM	"	Ludlum 43-37 (SN 093966)	584	10	547	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:43:13 AM	"	Ludlum 43-37 (SN 093966)	584	6	513	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:43:15 AM	"	Ludlum 43-37 (SN 093966)	584	4	467	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:43:17 AM	"	Ludlum 43-37 (SN 093966)	584	3	558	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:43:19 AM	"	Ludlum 43-37 (SN 093966)	584	2	504	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:43:21 AM	"	Ludlum 43-37 (SN 093966)	584	10	552	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:43:23 AM	"	Ludlum 43-37 (SN 093966)	584	6	552	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:43:25 AM	"	Ludlum 43-37 (SN 093966)	584	4	482	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:43:27 AM	"	Ludlum 43-37 (SN 093966)	584	3	455	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:43:29 AM	"	Ludlum 43-37 (SN 093966)	584	2	530	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:43:31 AM	"	Ludlum 43-37 (SN 093966)	584	1	495	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:43:33 AM	"	Ludlum 43-37 (SN 093966)	584	0	488	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:43:35 AM	"	Ludlum 43-37 (SN 093966)	584	0	464	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:43:37 AM	"	Ludlum 43-37 (SN 093966)	584	0	448	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:43:39 AM	"	Ludlum 43-37 (SN 093966)	584	0	530	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:43:41 AM	"	Ludlum 43-37 (SN 093966)	584	0	608	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:43:43 AM	"	Ludlum 43-37 (SN 093966)	584	0	611	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:43:45 AM	"	Ludlum 43-37 (SN 093966)	584	10	684	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:43:47 AM	"	Ludlum 43-37 (SN 093966)	584	6	611	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:43:49 AM	"	Ludlum 43-37 (SN 093966)	584	4	529	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:43:51 AM	"	Ludlum 43-37 (SN 093966)	584	3	572	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:43:53 AM	"	Ludlum 43-37 (SN 093966)	584	2	563	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:43:55 AM	"	Ludlum 43-37 (SN 093966)	584	1	585	Wood
Building 275	1	Scan	Cabinet	Miller/Watters	6/6/2012	10:47:57 AM	2.00	Ludlum 43-37 (SN 093966)	584	3	607	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:47:59 AM	"	Ludlum 43-37 (SN 093966)	584	2	581	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:48:01 AM	"	Ludlum 43-37 (SN 093966)	584	1	611	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:48:03 AM	"	Ludlum 43-37 (SN 093966)	584	1	621	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:48:05 AM	"	Ludlum 43-37 (SN 093966)	584	0	578	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:48:07 AM	"	Ludlum 43-37 (SN 093966)	584	0	506	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:48:09 AM	"	Ludlum 43-37 (SN 093966)	584	0	503	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:48:11 AM	"	Ludlum 43-37 (SN 093966)	584	0	518	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:48:13 AM	"	Ludlum 43-37 (SN 093966)	584	0	532	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:48:15 AM	"	Ludlum 43-37 (SN 093966)	584	0	514	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:48:17 AM	"	Ludlum 43-37 (SN 093966)	584	11	575	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:48:19 AM	"	Ludlum 43-37 (SN 093966)	584	7	584	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:48:21 AM	"	Ludlum 43-37 (SN 093966)	584	4	647	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:48:23 AM	"	Ludlum 43-37 (SN 093966)	584	14	595	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:48:25 AM	"	Ludlum 43-37 (SN 093966)	584	9	669	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:48:27 AM	"	Ludlum 43-37 (SN 093966)	584	6	714	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:48:29 AM	"	Ludlum 43-37 (SN 093966)	584	3	675	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:48:31 AM	"	Ludlum 43-37 (SN 093966)	584	2	600	Wood
Building 275	1	Scan	Cabinet	Miller/Watters	6/6/2012	10:50:26 AM	2.00	Ludlum 43-37 (SN 093966)	584	7	506	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:50:28 AM	"	Ludlum 43-37 (SN 093966)	584	4	524	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:50:30 AM	"	Ludlum 43-37 (SN 093966)	584	3	582	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:50:32 AM	"	Ludlum 43-37 (SN 093966)	584	2	610	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:50:34 AM	"	Ludlum 43-37 (SN 093966)	584	10	526	Wood

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 275	1	Scan	Cabinet	"	6/6/2012	10:50:36 AM	"	Ludlum 43-37 (SN 093966)	584	6	514	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:50:38 AM	"	Ludlum 43-37 (SN 093966)	584	4	541	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:50:40 AM	"	Ludlum 43-37 (SN 093966)	584	3	524	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:50:42 AM	"	Ludlum 43-37 (SN 093966)	584	2	543	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:50:44 AM	"	Ludlum 43-37 (SN 093966)	584	1	615	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:50:46 AM	"	Ludlum 43-37 (SN 093966)	584	0	663	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:50:48 AM	"	Ludlum 43-37 (SN 093966)	584	0	625	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:50:50 AM	"	Ludlum 43-37 (SN 093966)	584	0	573	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:50:52 AM	"	Ludlum 43-37 (SN 093966)	584	10	523	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:50:54 AM	"	Ludlum 43-37 (SN 093966)	584	6	539	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:50:56 AM	"	Ludlum 43-37 (SN 093966)	584	4	575	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:50:58 AM	"	Ludlum 43-37 (SN 093966)	584	13	526	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:51:00 AM	"	Ludlum 43-37 (SN 093966)	584	18	521	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:51:02 AM	"	Ludlum 43-37 (SN 093966)	584	12	401	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:51:04 AM	"	Ludlum 43-37 (SN 093966)	584	8	428	Wood
Building 275	1	Scan	Cabinet	Miller/Watters	6/6/2012	10:53:05 AM	2.00	Ludlum 43-37 (SN 093966)	584	6	675	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:53:07 AM	"	Ludlum 43-37 (SN 093966)	584	3	647	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:53:09 AM	"	Ludlum 43-37 (SN 093966)	584	2	587	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:53:11 AM	"	Ludlum 43-37 (SN 093966)	584	1	551	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:53:13 AM	"	Ludlum 43-37 (SN 093966)	584	1	552	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:53:15 AM	"	Ludlum 43-37 (SN 093966)	584	0	687	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:53:17 AM	"	Ludlum 43-37 (SN 093966)	584	0	667	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:53:19 AM	"	Ludlum 43-37 (SN 093966)	584	0	693	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:53:21 AM	"	Ludlum 43-37 (SN 093966)	584	0	649	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:53:23 AM	"	Ludlum 43-37 (SN 093966)	584	0	588	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:53:25 AM	"	Ludlum 43-37 (SN 093966)	584	0	563	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:53:27 AM	"	Ludlum 43-37 (SN 093966)	584	12	531	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:53:29 AM	"	Ludlum 43-37 (SN 093966)	584	16	459	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:53:31 AM	"	Ludlum 43-37 (SN 093966)	584	11	470	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:53:33 AM	"	Ludlum 43-37 (SN 093966)	584	7	513	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:53:35 AM	"	Ludlum 43-37 (SN 093966)	584	4	502	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:53:37 AM	"	Ludlum 43-37 (SN 093966)	584	14	521	Wood
Building 275	1	Scan	Cabinet	Miller/Watters	6/6/2012	10:56:44 AM	2.00	Ludlum 43-37 (SN 093966)	584	3	497	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:56:46 AM	"	Ludlum 43-37 (SN 093966)	584	2	596	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:56:48 AM	"	Ludlum 43-37 (SN 093966)	584	12	594	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:56:50 AM	"	Ludlum 43-37 (SN 093966)	584	8	565	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:56:52 AM	"	Ludlum 43-37 (SN 093966)	584	5	664	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:56:54 AM	"	Ludlum 43-37 (SN 093966)	584	15	599	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:56:56 AM	"	Ludlum 43-37 (SN 093966)	584	10	575	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:56:58 AM	"	Ludlum 43-37 (SN 093966)	584	6	587	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:57:00 AM	"	Ludlum 43-37 (SN 093966)	584	13	598	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:57:02 AM	"	Ludlum 43-37 (SN 093966)	584	8	551	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:57:04 AM	"	Ludlum 43-37 (SN 093966)	584	5	557	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:57:06 AM	"	Ludlum 43-37 (SN 093966)	584	14	541	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:57:08 AM	"	Ludlum 43-37 (SN 093966)	584	19	549	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:57:10 AM	"	Ludlum 43-37 (SN 093966)	584	12	539	Wood

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 275	1	Scan	Cabinet	"	6/6/2012	10:57:12 AM	"	Ludlum 43-37 (SN 093966)	584	8	538	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:57:14 AM	"	Ludlum 43-37 (SN 093966)	584	5	523	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:57:16 AM	"	Ludlum 43-37 (SN 093966)	584	15	545	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	10:57:18 AM	"	Ludlum 43-37 (SN 093966)	584	10	575	Wood
Building 275	1	Scan	Cabinet	Miller/Watters	6/6/2012	11:04:21 AM	2.00	Ludlum 43-37 (SN 093966)	584	12	464	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:04:23 AM	"	Ludlum 43-37 (SN 093966)	584	8	492	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:04:25 AM	"	Ludlum 43-37 (SN 093966)	584	5	542	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:04:27 AM	"	Ludlum 43-37 (SN 093966)	584	3	511	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:04:29 AM	"	Ludlum 43-37 (SN 093966)	584	2	453	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:04:31 AM	"	Ludlum 43-37 (SN 093966)	584	1	539	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:04:33 AM	"	Ludlum 43-37 (SN 093966)	584	1	520	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:04:35 AM	"	Ludlum 43-37 (SN 093966)	584	0	484	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:04:37 AM	"	Ludlum 43-37 (SN 093966)	584	10	449	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:04:39 AM	"	Ludlum 43-37 (SN 093966)	584	6	474	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:04:41 AM	"	Ludlum 43-37 (SN 093966)	584	4	473	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:04:43 AM	"	Ludlum 43-37 (SN 093966)	584	3	490	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:04:45 AM	"	Ludlum 43-37 (SN 093966)	584	14	424	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:04:47 AM	"	Ludlum 43-37 (SN 093966)	584	9	487	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:04:49 AM	"	Ludlum 43-37 (SN 093966)	584	6	638	Wood
Building 275	1	Scan	Cabinet	Miller/Watters	6/6/2012	11:06:48 AM	2.00	Ludlum 43-37 (SN 093966)	584	20	534	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:06:50 AM	"	Ludlum 43-37 (SN 093966)	584	13	496	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:06:52 AM	"	Ludlum 43-37 (SN 093966)	584	8	469	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:06:54 AM	"	Ludlum 43-37 (SN 093966)	584	5	468	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:06:56 AM	"	Ludlum 43-37 (SN 093966)	584	3	482	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:06:59 AM	"	Ludlum 43-37 (SN 093966)	584	11	484	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:07:00 AM	"	Ludlum 43-37 (SN 093966)	584	18	551	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:07:02 AM	"	Ludlum 43-37 (SN 093966)	584	11	491	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:07:04 AM	"	Ludlum 43-37 (SN 093966)	584	7	550	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:07:06 AM	"	Ludlum 43-37 (SN 093966)	584	14	486	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:07:08 AM	"	Ludlum 43-37 (SN 093966)	584	9	489	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:07:10 AM	"	Ludlum 43-37 (SN 093966)	584	14	461	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:07:12 AM	"	Ludlum 43-37 (SN 093966)	584	9	485	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:07:14 AM	"	Ludlum 43-37 (SN 093966)	584	6	482	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:07:16 AM	"	Ludlum 43-37 (SN 093966)	584	4	480	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:07:18 AM	"	Ludlum 43-37 (SN 093966)	584	2	450	Wood
Building 275	1	Scan	Cabinet	Miller/Watters	6/6/2012	11:10:38 AM	2.00	Ludlum 43-37 (SN 093966)	584	0	409	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:10:40 AM	"	Ludlum 43-37 (SN 093966)	584	9	408	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:10:42 AM	"	Ludlum 43-37 (SN 093966)	584	6	424	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:10:44 AM	"	Ludlum 43-37 (SN 093966)	584	14	464	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:10:46 AM	"	Ludlum 43-37 (SN 093966)	584	9	487	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:10:48 AM	"	Ludlum 43-37 (SN 093966)	584	6	455	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:10:50 AM	"	Ludlum 43-37 (SN 093966)	584	15	486	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:10:52 AM	"	Ludlum 43-37 (SN 093966)	584	9	513	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:10:54 AM	"	Ludlum 43-37 (SN 093966)	584	16	464	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:10:56 AM	"	Ludlum 43-37 (SN 093966)	584	10	515	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:10:58 AM	"	Ludlum 43-37 (SN 093966)	584	7	550	Wood

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 275	1	Scan	Cabinet	"	6/6/2012	11:11:00 AM	"	Ludlum 43-37 (SN 093966)	584	13	494	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:11:02 AM	"	Ludlum 43-37 (SN 093966)	584	20	522	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:11:04 AM	"	Ludlum 43-37 (SN 093966)	584	25	460	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:11:22 AM	"	Ludlum 43-37 (SN 093966)	584	2	453	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:11:24 AM	"	Ludlum 43-37 (SN 093966)	584	1	432	Wood
Building 275	1	Scan	Cabinet	Miller/Watters	6/6/2012	11:13:26 AM	2.00	Ludlum 43-37 (SN 093966)	584	14	439	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:13:28 AM	"	Ludlum 43-37 (SN 093966)	584	9	360	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:13:30 AM	"	Ludlum 43-37 (SN 093966)	584	6	383	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:13:32 AM	"	Ludlum 43-37 (SN 093966)	584	4	398	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:13:34 AM	"	Ludlum 43-37 (SN 093966)	584	2	444	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:13:36 AM	"	Ludlum 43-37 (SN 093966)	584	1	492	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:13:38 AM	"	Ludlum 43-37 (SN 093966)	584	1	513	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:13:40 AM	"	Ludlum 43-37 (SN 093966)	584	0	434	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:13:42 AM	"	Ludlum 43-37 (SN 093966)	584	0	468	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:13:44 AM	"	Ludlum 43-37 (SN 093966)	584	0	473	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:13:46 AM	"	Ludlum 43-37 (SN 093966)	584	0	404	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:13:48 AM	"	Ludlum 43-37 (SN 093966)	584	0	405	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:13:50 AM	"	Ludlum 43-37 (SN 093966)	584	0	505	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:13:52 AM	"	Ludlum 43-37 (SN 093966)	584	0	490	Wood
Building 275	1	Scan	Cabinet	Miller/Watters	6/6/2012	11:19:38 AM	2.00	Ludlum 43-37 (SN 093966)	584	2	556	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:19:40 AM	"	Ludlum 43-37 (SN 093966)	584	13	465	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:19:42 AM	"	Ludlum 43-37 (SN 093966)	584	8	497	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:19:44 AM	"	Ludlum 43-37 (SN 093966)	584	5	549	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:19:46 AM	"	Ludlum 43-37 (SN 093966)	584	3	542	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:19:48 AM	"	Ludlum 43-37 (SN 093966)	584	2	569	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:19:50 AM	"	Ludlum 43-37 (SN 093966)	584	11	521	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:19:52 AM	"	Ludlum 43-37 (SN 093966)	584	7	510	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:19:54 AM	"	Ludlum 43-37 (SN 093966)	584	16	607	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:19:56 AM	"	Ludlum 43-37 (SN 093966)	584	11	592	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:19:58 AM	"	Ludlum 43-37 (SN 093966)	584	7	555	Wood
Building 275	1	Scan	Cabinet	Miller/Watters	6/6/2012	11:21:52 AM	2.00	Ludlum 43-37 (SN 093966)	584	1	499	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:21:54 AM	"	Ludlum 43-37 (SN 093966)	584	0	485	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:21:56 AM	"	Ludlum 43-37 (SN 093966)	584	0	497	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:21:58 AM	"	Ludlum 43-37 (SN 093966)	584	0	472	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:22:00 AM	"	Ludlum 43-37 (SN 093966)	584	0	563	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:22:02 AM	"	Ludlum 43-37 (SN 093966)	584	0	553	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:22:04 AM	"	Ludlum 43-37 (SN 093966)	584	0	637	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:22:06 AM	"	Ludlum 43-37 (SN 093966)	584	0	578	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:22:08 AM	"	Ludlum 43-37 (SN 093966)	584	0	538	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:22:10 AM	"	Ludlum 43-37 (SN 093966)	584	0	535	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:22:12 AM	"	Ludlum 43-37 (SN 093966)	584	0	525	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:22:14 AM	"	Ludlum 43-37 (SN 093966)	584	0	504	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:22:16 AM	"	Ludlum 43-37 (SN 093966)	584	0	516	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:22:18 AM	"	Ludlum 43-37 (SN 093966)	584	0	563	Wood
Building 275	1	Scan	Cabinet	Miller/Watters	6/6/2012	11:24:36 AM	2.00	Ludlum 43-37 (SN 093966)	584	3	466	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:24:38 AM	"	Ludlum 43-37 (SN 093966)	584	2	501	Wood

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 275	1	Scan	Cabinet	"	6/6/2012	11:24:40 AM	"	Ludlum 43-37 (SN 093966)	584	11	576	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:24:42 AM	"	Ludlum 43-37 (SN 093966)	584	16	563	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:24:44 AM	"	Ludlum 43-37 (SN 093966)	584	10	528	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:24:46 AM	"	Ludlum 43-37 (SN 093966)	584	28	532	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:24:48 AM	"	Ludlum 43-37 (SN 093966)	584	29	526	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:24:50 AM	"	Ludlum 43-37 (SN 093966)	584	30	531	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:24:52 AM	"	Ludlum 43-37 (SN 093966)	584	19	526	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:24:54 AM	"	Ludlum 43-37 (SN 093966)	584	22	538	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:24:56 AM	"	Ludlum 43-37 (SN 093966)	584	15	598	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:24:58 AM	"	Ludlum 43-37 (SN 093966)	584	9	589	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:25:00 AM	"	Ludlum 43-37 (SN 093966)	584	6	537	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:25:02 AM	"	Ludlum 43-37 (SN 093966)	584	4	558	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:25:04 AM	"	Ludlum 43-37 (SN 093966)	584	2	513	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:25:06 AM	"	Ludlum 43-37 (SN 093966)	584	1	492	Wood
Building 275	1	Scan	Cabinet	Miller/Watters	6/6/2012	11:26:31 AM	2.00	Ludlum 43-37 (SN 093966)	584	2	491	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:26:33 AM	"	Ludlum 43-37 (SN 093966)	584	25	570	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:26:35 AM	"	Ludlum 43-37 (SN 093966)	584	16	487	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:26:37 AM	"	Ludlum 43-37 (SN 093966)	584	11	502	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:26:39 AM	"	Ludlum 43-37 (SN 093966)	584	7	481	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:26:41 AM	"	Ludlum 43-37 (SN 093966)	584	4	551	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:26:43 AM	"	Ludlum 43-37 (SN 093966)	584	3	556	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:26:45 AM	"	Ludlum 43-37 (SN 093966)	584	2	570	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:26:47 AM	"	Ludlum 43-37 (SN 093966)	584	1	626	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:26:49 AM	"	Ludlum 43-37 (SN 093966)	584	11	579	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:26:51 AM	"	Ludlum 43-37 (SN 093966)	584	7	593	Wood
Building 275	1	Scan	Cabinet	Miller/Watters	6/6/2012	11:15:40 AM	2.00	Ludlum 43-37 (SN 093966)	584	13	695	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:15:42 AM	"	Ludlum 43-37 (SN 093966)	584	8	791	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:15:44 AM	"	Ludlum 43-37 (SN 093966)	584	5	770	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:15:46 AM	"	Ludlum 43-37 (SN 093966)	584	14	826	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:15:48 AM	"	Ludlum 43-37 (SN 093966)	584	19	848	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:15:50 AM	"	Ludlum 43-37 (SN 093966)	584	12	906	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:15:52 AM	"	Ludlum 43-37 (SN 093966)	584	8	792	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:15:54 AM	"	Ludlum 43-37 (SN 093966)	584	5	772	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:15:56 AM	"	Ludlum 43-37 (SN 093966)	584	3	797	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:15:58 AM	"	Ludlum 43-37 (SN 093966)	584	24	917	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:16:00 AM	"	Ludlum 43-37 (SN 093966)	584	15	744	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:16:02 AM	"	Ludlum 43-37 (SN 093966)	584	22	626	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:16:04 AM	"	Ludlum 43-37 (SN 093966)	584	14	553	Wood
Building 275	1	Scan	Cabinet	Miller/Watters	6/6/2012	11:16:51 AM	2.00	Ludlum 43-37 (SN 093966)	584	0	515	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:16:53 AM	"	Ludlum 43-37 (SN 093966)	584	11	493	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:16:55 AM	"	Ludlum 43-37 (SN 093966)	584	7	553	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:16:57 AM	"	Ludlum 43-37 (SN 093966)	584	4	583	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:16:59 AM	"	Ludlum 43-37 (SN 093966)	584	3	525	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:17:01 AM	"	Ludlum 43-37 (SN 093966)	584	2	488	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:17:03 AM	"	Ludlum 43-37 (SN 093966)	584	20	480	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:17:05 AM	"	Ludlum 43-37 (SN 093966)	584	23	537	Wood

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 275	1	Scan	Cabinet	"	6/6/2012	11:17:07 AM	"	Ludlum 43-37 (SN 093966)	584	15	535	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:17:09 AM	"	Ludlum 43-37 (SN 093966)	584	10	606	Wood
Building 275	1	Scan	Cabinet	"	6/6/2012	11:17:11 AM	"	Ludlum 43-37 (SN 093966)	584	6	605	Wood
Building 283	1	Scan	Basement Radio Room	Miller	6/8/2012	9:55:14 AM	2.00	Ludlum 43-37 (SN 093966)	584	10	489	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:55:16 AM		Ludlum 43-37 (SN 093966)	584	7	567	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:55:18 AM	"	Ludlum 43-37 (SN 093966)	584	4	570	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:55:20 AM	"	Ludlum 43-37 (SN 093966)	584	3	516	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:55:22 AM	"	Ludlum 43-37 (SN 093966)	584	2	495	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:55:24 AM	"	Ludlum 43-37 (SN 093966)	584	1	527	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:55:26 AM	"	Ludlum 43-37 (SN 093966)	584	0	558	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:55:28 AM	"	Ludlum 43-37 (SN 093966)	584	0	566	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:55:30 AM	"	Ludlum 43-37 (SN 093966)	584	12	648	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:55:32 AM	"	Ludlum 43-37 (SN 093966)	584	18	606	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:55:34 AM	"	Ludlum 43-37 (SN 093966)	584	21	538	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:55:36 AM	"	Ludlum 43-37 (SN 093966)	584	14	474	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:55:38 AM	"	Ludlum 43-37 (SN 093966)	584	9	475	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:55:40 AM	"	Ludlum 43-37 (SN 093966)	584	6	507	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:55:42 AM	"	Ludlum 43-37 (SN 093966)	584	23	544	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:55:44 AM	"	Ludlum 43-37 (SN 093966)	584	15	597	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:55:46 AM	"	Ludlum 43-37 (SN 093966)	584	21	614	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:55:48 AM	"	Ludlum 43-37 (SN 093966)	584	13	600	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:55:50 AM	"	Ludlum 43-37 (SN 093966)	584	19	588	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:55:52 AM	"	Ludlum 43-37 (SN 093966)	584	13	592	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:55:54 AM	"	Ludlum 43-37 (SN 093966)	584	8	558	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:55:56 AM	"	Ludlum 43-37 (SN 093966)	584	5	559	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:55:58 AM	"	Ludlum 43-37 (SN 093966)	584	3	476	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:56:00 AM	"	Ludlum 43-37 (SN 093966)	584	13	440	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:56:02 AM	"	Ludlum 43-37 (SN 093966)	584	8	457	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:56:04 AM	"	Ludlum 43-37 (SN 093966)	584	5	499	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:56:06 AM	"	Ludlum 43-37 (SN 093966)	584	3	524	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:56:08 AM	"	Ludlum 43-37 (SN 093966)	584	24	517	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:56:10 AM	"	Ludlum 43-37 (SN 093966)	584	15	564	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:56:12 AM	"	Ludlum 43-37 (SN 093966)	584	10	458	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:56:14 AM	"	Ludlum 43-37 (SN 093966)	584	7	436	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:56:16 AM	"	Ludlum 43-37 (SN 093966)	584	14	421	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:56:18 AM	"	Ludlum 43-37 (SN 093966)	584	9	486	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:56:20 AM	"	Ludlum 43-37 (SN 093966)	584	25	488	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:56:22 AM	"	Ludlum 43-37 (SN 093966)	584	16	486	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:56:24 AM	"	Ludlum 43-37 (SN 093966)	584	19	536	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:56:26 AM	"	Ludlum 43-37 (SN 093966)	584	13	465	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:56:28 AM	"	Ludlum 43-37 (SN 093966)	584	19	406	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:56:30 AM	"	Ludlum 43-37 (SN 093966)	584	12	526	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:56:32 AM	"	Ludlum 43-37 (SN 093966)	584	8	509	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:56:34 AM	"	Ludlum 43-37 (SN 093966)	584	5	512	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:56:36 AM	"	Ludlum 43-37 (SN 093966)	584	3	492	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:56:38 AM	"	Ludlum 43-37 (SN 093966)	584	2	519	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:56:40 AM	"	Ludlum 43-37 (SN 093966)	584	1	532	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:56:42 AM	"	Ludlum 43-37 (SN 093966)	584	1	502	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:56:44 AM	"	Ludlum 43-37 (SN 093966)	584	12	546	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:56:46 AM	"	Ludlum 43-37 (SN 093966)	584	50	476	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:56:48 AM	"	Ludlum 43-37 (SN 093966)	584	44	397	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:56:50 AM	"	Ludlum 43-37 (SN 093966)	584	28	474	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:56:52 AM	"	Ludlum 43-37 (SN 093966)	584	18	494	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:56:54 AM	"	Ludlum 43-37 (SN 093966)	584	12	498	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:56:56 AM	"	Ludlum 43-37 (SN 093966)	584	8	478	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:56:58 AM	"	Ludlum 43-37 (SN 093966)	584	5	470	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:57:00 AM	"	Ludlum 43-37 (SN 093966)	584	13	476	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:57:02 AM	"	Ludlum 43-37 (SN 093966)	584	18	470	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:57:04 AM	"	Ludlum 43-37 (SN 093966)	584	12	596	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:57:06 AM	"	Ludlum 43-37 (SN 093966)	584	30	542	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:57:08 AM	"	Ludlum 43-37 (SN 093966)	584	20	462	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:57:10 AM	"	Ludlum 43-37 (SN 093966)	584	35	484	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:57:12 AM	"	Ludlum 43-37 (SN 093966)	584	22	581	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:57:14 AM	"	Ludlum 43-37 (SN 093966)	584	47	566	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:57:16 AM	"	Ludlum 43-37 (SN 093966)	584	31	433	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:57:18 AM	"	Ludlum 43-37 (SN 093966)	584	30	524	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:57:20 AM	"	Ludlum 43-37 (SN 093966)	584	19	556	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:57:22 AM	"	Ludlum 43-37 (SN 093966)	584	23	581	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:57:24 AM	"	Ludlum 43-37 (SN 093966)	584	26	580	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:57:26 AM	"	Ludlum 43-37 (SN 093966)	584	35	560	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:57:28 AM	"	Ludlum 43-37 (SN 093966)	584	23	464	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:57:30 AM	"	Ludlum 43-37 (SN 093966)	584	15	472	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:57:32 AM	"	Ludlum 43-37 (SN 093966)	584	10	563	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:57:34 AM	"	Ludlum 43-37 (SN 093966)	584	17	506	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:57:36 AM	"	Ludlum 43-37 (SN 093966)	584	29	528	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:57:38 AM	"	Ludlum 43-37 (SN 093966)	584	27	490	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:57:40 AM	"	Ludlum 43-37 (SN 093966)	584	18	521	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:57:42 AM	"	Ludlum 43-37 (SN 093966)	584	12	478	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:57:44 AM	"	Ludlum 43-37 (SN 093966)	584	16	556	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:57:46 AM	"	Ludlum 43-37 (SN 093966)	584	20	517	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:57:48 AM	"	Ludlum 43-37 (SN 093966)	584	13	590	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:57:50 AM	"	Ludlum 43-37 (SN 093966)	584	8	481	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:57:52 AM	"	Ludlum 43-37 (SN 093966)	584	5	443	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:57:54 AM	"	Ludlum 43-37 (SN 093966)	584	22	444	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:57:56 AM	"	Ludlum 43-37 (SN 093966)	584	14	446	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:57:58 AM	"	Ludlum 43-37 (SN 093966)	584	9	521	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:58:00 AM	"	Ludlum 43-37 (SN 093966)	584	6	537	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:58:02 AM	"	Ludlum 43-37 (SN 093966)	584	4	519	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:58:04 AM	"	Ludlum 43-37 (SN 093966)	584	2	431	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:58:06 AM	"	Ludlum 43-37 (SN 093966)	584	1	380	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:58:08 AM	"	Ludlum 43-37 (SN 093966)	584	10	450	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:58:10 AM	"	Ludlum 43-37 (SN 093966)	584	6	475	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:58:12 AM	"	Ludlum 43-37 (SN 093966)	584	14	474	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:58:14 AM	"	Ludlum 43-37 (SN 093966)	584	18	384	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:58:16 AM	"	Ludlum 43-37 (SN 093966)	584	11	485	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:58:18 AM	"	Ludlum 43-37 (SN 093966)	584	19	524	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:58:20 AM	"	Ludlum 43-37 (SN 093966)	584	21	478	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:58:22 AM	"	Ludlum 43-37 (SN 093966)	584	32	469	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:58:24 AM	"	Ludlum 43-37 (SN 093966)	584	21	513	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:58:26 AM	"	Ludlum 43-37 (SN 093966)	584	14	527	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:58:28 AM	"	Ludlum 43-37 (SN 093966)	584	18	500	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:58:30 AM	"	Ludlum 43-37 (SN 093966)	584	11	506	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:58:32 AM	"	Ludlum 43-37 (SN 093966)	584	7	558	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:58:34 AM	"	Ludlum 43-37 (SN 093966)	584	14	530	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:58:36 AM	"	Ludlum 43-37 (SN 093966)	584	9	547	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:58:38 AM	"	Ludlum 43-37 (SN 093966)	584	6	490	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:58:40 AM	"	Ludlum 43-37 (SN 093966)	584	3	535	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:58:42 AM	"	Ludlum 43-37 (SN 093966)	584	23	591	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:58:44 AM	"	Ludlum 43-37 (SN 093966)	584	15	555	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:58:46 AM	"	Ludlum 43-37 (SN 093966)	584	10	510	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:58:48 AM	"	Ludlum 43-37 (SN 093966)	584	17	468	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:58:50 AM	"	Ludlum 43-37 (SN 093966)	584	21	465	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:58:52 AM	"	Ludlum 43-37 (SN 093966)	584	14	414	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:58:54 AM	"	Ludlum 43-37 (SN 093966)	584	9	363	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:58:56 AM	"	Ludlum 43-37 (SN 093966)	584	6	462	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:58:58 AM	"	Ludlum 43-37 (SN 093966)	584	3	489	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:59:00 AM	"	Ludlum 43-37 (SN 093966)	584	2	543	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:59:02 AM	"	Ludlum 43-37 (SN 093966)	584	13	547	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:59:04 AM	"	Ludlum 43-37 (SN 093966)	584	21	653	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:59:06 AM	"	Ludlum 43-37 (SN 093966)	584	23	632	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:59:08 AM	"	Ludlum 43-37 (SN 093966)	584	15	562	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:59:10 AM	"	Ludlum 43-37 (SN 093966)	584	10	567	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:59:12 AM	"	Ludlum 43-37 (SN 093966)	584	18	638	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:59:14 AM	"	Ludlum 43-37 (SN 093966)	584	12	578	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:59:16 AM	"	Ludlum 43-37 (SN 093966)	584	8	573	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:59:18 AM	"	Ludlum 43-37 (SN 093966)	584	16	566	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:59:20 AM	"	Ludlum 43-37 (SN 093966)	584	10	523	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:59:22 AM	"	Ludlum 43-37 (SN 093966)	584	7	531	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:59:24 AM	"	Ludlum 43-37 (SN 093966)	584	4	488	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:59:26 AM	"	Ludlum 43-37 (SN 093966)	584	3	530	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:59:28 AM	"	Ludlum 43-37 (SN 093966)	584	2	588	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:59:30 AM	"	Ludlum 43-37 (SN 093966)	584	1	626	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:59:32 AM	"	Ludlum 43-37 (SN 093966)	584	0	634	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:59:34 AM	"	Ludlum 43-37 (SN 093966)	584	0	616	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:59:36 AM	"	Ludlum 43-37 (SN 093966)	584	12	563	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:59:38 AM	"	Ludlum 43-37 (SN 093966)	584	8	598	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:59:40 AM	"	Ludlum 43-37 (SN 093966)	584	5	566	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:59:42 AM	"	Ludlum 43-37 (SN 093966)	584	3	532	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:59:44 AM	"	Ludlum 43-37 (SN 093966)	584	24	555	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:59:46 AM	"	Ludlum 43-37 (SN 093966)	584	15	510	Poured Concrete
Building 283	1	Scan	Basement Radio Room	"	6/8/2012	9:59:48 AM	"	Ludlum 43-37 (SN 093966)	584	32	512	Poured Concrete
Building 292	1	Scan	Back Storage Room	Miller	6/6/2012	2:57:32 PM	1.00	Ludlum 43-37-1 (SN 136361)	821	4	615	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:57:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	668	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:57:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	631	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:57:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	590	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:57:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	660	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:57:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	695	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:57:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	679	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:57:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	629	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:57:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	636	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:57:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	661	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:57:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	628	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:57:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	566	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:57:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	630	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:57:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	635	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:57:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	568	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:57:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	610	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:57:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	677	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:57:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	675	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:57:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	630	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:57:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	635	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:57:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	605	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:57:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	572	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:57:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	580	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:57:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	592	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:57:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	604	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:57:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	603	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:57:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	636	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:57:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	547	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	524	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	597	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	607	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	615	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	577	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	592	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	606	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	624	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	598	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	611	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	584	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	570	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	556	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	691	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	696	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	687	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	670	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	644	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	719	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	693	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	617	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	616	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	533	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	626	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	598	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	551	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	482	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	552	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	595	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	629	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	624	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	667	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	641	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	554	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	519	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	536	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	603	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	544	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	577	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	581	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	607	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	593	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	582	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	618	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	582	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	551	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	604	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	566	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	629	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	715	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	688	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	671	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	683	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	701	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	657	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	613	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	577	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	616	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	568	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:58:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	566	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	620	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	626	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	553	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	564	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	538	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	573	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	603	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	602	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	657	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	694	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	712	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	634	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	571	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	580	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	584	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	643	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	649	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	594	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	537	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	523	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	582	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	606	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	666	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	711	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	749	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	39	774	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	709	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	678	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	687	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	738	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	756	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	726	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	701	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	667	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	735	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	719	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	605	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	637	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	597	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	608	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	620	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	672	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	649	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	640	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	609	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	552	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	561	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	523	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	513	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	597	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	608	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	640	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	667	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	689	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	649	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	672	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	655	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	608	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	638	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	2:59:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	631	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	603	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	626	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	609	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	585	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	622	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	709	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	688	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	638	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	597	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	641	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	690	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	800	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	843	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	819	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	828	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	751	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	734	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	754	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	715	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	736	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	690	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	715	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	693	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	673	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	675	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	675	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	626	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	657	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	623	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	656	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	645	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	706	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	721	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	630	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	668	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	668	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	575	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	545	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	531	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	566	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	666	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	675	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	658	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	683	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	633	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	637	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	676	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	716	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	684	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	633	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	580	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	596	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	667	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	697	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	698	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	656	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	700	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	648	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	36	626	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:00:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	648	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	640	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	666	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	719	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	707	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	713	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	726	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	729	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	727	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	748	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	696	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	645	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	649	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	641	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	575	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	556	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	496	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	490	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	511	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	437	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	477	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	488	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	512	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	572	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	554	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	585	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	41	579	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	547	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	600	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	42	599	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	633	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	638	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	655	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	691	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	722	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	683	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	685	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	659	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	602	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	613	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	641	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	612	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	645	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	645	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	644	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	682	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	680	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	641	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	664	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	663	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	593	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	585	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	630	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	566	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	595	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	594	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	571	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	623	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	653	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	598	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:01:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	682	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	688	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	670	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	631	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	569	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	576	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	559	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	577	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	572	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	608	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	597	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	599	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	701	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	624	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	628	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	588	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	626	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	610	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	657	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	602	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	627	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	576	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	655	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	613	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	620	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	627	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	633	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	582	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	627	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	675	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	657	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	705	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	674	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	682	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	702	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	625	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	599	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	41	622	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	686	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	723	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	686	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	715	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	694	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	698	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	690	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	640	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	635	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	630	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	645	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	637	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	667	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	702	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	719	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	638	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	644	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	669	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	611	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	722	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	761	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	787	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:02:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	796	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	727	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	670	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	623	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	663	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	637	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	630	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	39	634	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	596	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	651	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	675	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	659	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	718	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	694	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	687	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	648	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	638	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	711	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	702	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	680	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	607	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	573	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	727	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	740	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	681	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	666	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	697	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	645	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	743	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	659	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	681	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	710	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	685	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	635	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	594	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	605	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	40	557	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	541	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	551	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	527	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	506	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	503	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	43	573	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	566	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	619	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	629	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	38	555	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	530	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	519	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	465	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	534	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	579	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	607	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	618	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	615	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	635	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	603	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	614	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	682	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	646	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:03:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	582	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	675	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	740	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	700	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	691	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	717	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	682	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	623	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	631	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	611	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	608	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	609	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	586	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	564	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	548	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	593	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	582	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	629	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	554	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	619	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	675	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	670	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	712	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	38	712	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	644	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	694	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	663	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	619	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	637	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	39	687	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	44	659	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	683	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	41	701	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	739	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	754	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	824	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	796	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	804	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	732	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	682	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	668	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	687	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	648	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	55	664	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	45	639	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	36	630	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	41	601	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	565	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	39	526	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	42	600	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	598	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	621	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	652	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	691	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	606	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	616	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	602	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	696	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	702	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	705	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:04:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	707	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	708	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	720	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	745	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	777	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	731	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	684	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	645	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	639	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	642	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	748	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	799	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	780	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	722	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	697	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	723	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	783	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	746	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	755	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	713	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	747	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	757	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	753	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	714	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	36	714	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	40	669	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	44	664	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	36	685	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	676	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	684	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	715	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	705	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	639	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	665	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	650	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	653	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	639	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	698	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	710	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	678	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	674	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	649	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	653	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	830	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	880	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	816	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	841	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	900	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	931	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	869	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	881	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	841	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	842	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	796	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	808	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	790	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	743	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	705	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	38	698	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	657	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:05:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	48	612	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:06:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	51	630	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:06:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	41	645	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:06:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	624	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:06:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	574	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:06:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	626	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:06:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	599	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:06:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	623	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:06:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	607	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:06:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	633	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:06:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	648	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:06:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	682	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:06:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	768	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:06:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	701	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:06:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	646	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:06:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	659	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:06:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	638	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:06:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	599	Poured Concrete
Building 292	1	Scan	Back Storage Room	"	6/6/2012	3:06:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	38	610	Poured Concrete
Building 292	1	Scan	Moveable Storage Area	Miller	6/6/2012	3:12:09 PM	1.00	Ludlum 43-37-1 (SN 136361)	821	18	562	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	490	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	474	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	532	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	499	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	535	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	502	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	560	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	523	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	517	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	499	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	450	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	452	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	470	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	460	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	521	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	562	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	546	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	556	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	542	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	610	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	630	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	615	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	579	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	583	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	641	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	554	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	518	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	522	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	546	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	547	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	532	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	523	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	534	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	488	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	430	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	452	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	388	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	453	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	460	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	486	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	451	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	512	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	549	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	503	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	513	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	475	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	430	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	371	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	390	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:12:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	363	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	362	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	371	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	379	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	411	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	413	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	494	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	502	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	478	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	455	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	516	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	485	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	460	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	465	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	38	422	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	409	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	376	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	394	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	386	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	404	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	419	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	405	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	422	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	503	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	510	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	525	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	551	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	537	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	575	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	544	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	557	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	529	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	545	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	523	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	567	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	517	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	511	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	525	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	529	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	506	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	480	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	470	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	506	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	444	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	464	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	521	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	536	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	549	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	570	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	562	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	570	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	599	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	633	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	567	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	551	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	561	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	558	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	567	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	551	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	582	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:13:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	528	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	485	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	497	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	493	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	465	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	548	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	593	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	675	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	660	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	660	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	625	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	541	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	542	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	484	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	498	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	485	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	506	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	479	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	480	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	456	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	529	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	585	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	705	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	729	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	702	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	626	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	596	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	551	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	563	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	546	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	521	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	562	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	526	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	625	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	622	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	606	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	603	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	559	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	519	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	522	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	483	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	469	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	483	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	516	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	473	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	464	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	501	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	497	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	512	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	505	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	506	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	522	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	490	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	499	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	507	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	561	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	48	603	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	38	533	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	43	566	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	584	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:14:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	51	611	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	41	563	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	604	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	39	605	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	549	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	537	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	550	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	36	548	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	568	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	575	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	556	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	543	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	555	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	562	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	591	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	551	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	574	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	580	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	562	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	549	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	592	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	570	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	496	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	525	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	610	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	644	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	636	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	595	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	552	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	560	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	592	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	569	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	552	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	630	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	657	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	624	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	640	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	38	647	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	627	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	645	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	580	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	549	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	580	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	563	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	513	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	449	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	524	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	524	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	516	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	463	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	558	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	579	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	581	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	563	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	561	Laminate Tile
Building 292	1	Scan	Moveable Storage Area	"	6/6/2012	3:15:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	568	Laminate Tile
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:31:47 PM	1.00	Ludlum 43-37-1 (SN 136361)	821	10	525	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:31:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	528	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:31:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	563	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:31:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	617	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:31:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	588	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:31:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	592	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:31:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	651	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:31:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	654	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:31:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	674	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:31:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	647	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:31:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	612	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:31:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	656	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:31:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	700	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	658	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	634	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	641	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	659	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	680	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	677	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	697	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	738	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	655	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	687	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	730	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	713	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	678	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	674	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	652	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	722	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	630	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	715	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	671	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	631	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	648	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	648	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	651	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	664	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	644	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	674	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	748	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	756	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	726	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	702	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	698	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	783	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	756	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	765	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	822	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	827	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	793	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	713	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	740	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	761	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	764	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	718	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	704	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	749	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	776	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	806	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	775	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	36	719	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	722	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	709	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	710	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	769	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	772	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	782	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	809	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	749	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	752	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	780	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	768	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:32:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	755	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	737	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	678	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	687	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	701	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	736	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	780	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	784	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	828	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	829	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	776	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	752	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	736	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	742	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	814	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	787	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	750	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	721	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	813	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	842	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	898	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	910	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	876	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	900	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	901	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	870	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	865	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	905	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	41	834	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	804	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	785	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	820	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	799	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	46	795	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	49	802	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	40	801	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	783	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	803	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	790	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	768	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	784	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	792	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	873	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	878	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	863	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	826	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	786	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	741	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	781	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	778	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	805	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	753	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	780	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	895	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	907	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	886	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	794	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	749	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	812	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	795	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:33:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	828	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	796	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	812	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	782	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	830	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	835	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	802	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	789	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	743	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	754	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	733	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	673	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	749	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	776	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	766	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	859	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	798	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	781	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	780	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	790	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	774	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	729	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	685	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	680	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	36	679	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	695	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	783	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	40	748	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	43	719	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	764	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	837	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	767	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	734	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	708	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	696	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	777	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	804	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	788	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	739	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	781	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	725	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	761	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	787	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	830	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	789	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	810	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	841	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	924	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	932	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	859	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	832	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	833	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	856	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	819	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	859	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	854	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	900	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	927	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1056	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	970	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:34:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	970	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	923	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	966	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	911	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	877	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	893	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	863	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	901	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	910	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	899	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	889	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	882	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	859	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	855	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	782	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	749	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	789	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	833	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	845	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	801	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	831	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	833	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	790	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	894	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	857	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	909	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	862	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	943	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	911	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	891	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	822	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	805	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	856	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	831	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	924	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	864	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	815	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	863	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	894	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	980	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	1000	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	52	1038	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	63	907	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	51	868	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	42	887	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	913	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	39	932	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	922	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	861	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	779	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	805	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	836	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	850	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	815	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	828	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	784	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	737	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	723	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	698	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	727	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:35:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	691	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	673	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	752	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	782	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	774	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	47	822	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	38	813	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	773	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	763	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	742	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	733	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	833	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	766	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	801	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	818	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	900	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	865	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	862	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	821	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	766	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	721	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	676	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	641	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	691	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	731	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	685	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	667	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	633	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	659	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	761	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	787	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	844	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	830	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	844	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	854	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	796	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	735	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	717	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	765	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	802	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	731	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	730	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	761	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	808	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	782	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	724	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	733	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	806	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	827	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	804	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	36	867	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	900	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	36	876	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	53	835	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	53	938	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	43	898	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	884	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	913	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	853	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	828	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:36:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	866	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	842	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	832	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	842	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	805	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	835	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	800	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	777	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	764	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	755	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	761	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	766	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	803	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	780	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	804	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	775	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	784	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	770	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	704	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	674	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	739	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	726	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	668	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	647	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	659	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	718	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	740	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	669	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	687	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	713	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	746	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	730	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	746	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	741	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	783	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	805	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	848	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	802	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	790	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	802	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	789	Poured Concrete
Building 292	1	Scan	Storage Cabinet Area	"	6/6/2012	2:37:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	718	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:41:47 PM	1.00	Ludlum 43-37-1 (SN 136361)	821	13	765	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:41:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	805	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:41:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	814	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:41:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	828	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:41:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	797	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:41:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	769	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:41:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	781	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:41:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	759	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:41:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	719	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:41:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	711	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:41:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	734	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:41:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	717	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:41:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	696	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	758	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	46	763	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	800	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	53	749	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	43	711	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	721	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	40	676	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	741	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	715	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	672	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	659	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	647	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	694	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	754	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	715	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	672	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	634	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	717	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	46	617	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	788	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	751	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	727	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	692	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	663	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	618	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	662	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	625	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	611	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	676	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	652	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	687	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	716	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	705	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	625	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	644	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	622	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	685	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	682	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	699	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	744	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	803	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	742	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	659	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	648	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	592	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	604	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	567	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	576	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	616	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	590	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	627	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	608	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	540	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	526	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	560	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	622	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	663	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	694	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	666	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:42:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	617	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	692	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	734	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	734	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	675	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	669	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	693	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	660	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	624	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	597	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	636	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	671	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	689	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	751	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	802	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	878	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	847	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	825	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	780	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	743	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	693	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	723	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	41	714	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	659	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	39	611	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	677	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	664	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	653	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	639	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	574	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	559	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	603	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	613	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	567	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	597	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	601	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	635	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	615	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	623	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	700	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	683	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	737	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	718	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	752	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	746	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	743	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	658	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	771	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	757	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	831	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	787	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	705	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	752	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	724	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	712	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	702	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	729	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	679	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	652	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	699	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:43:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	668	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	732	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	791	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	686	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	647	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	651	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	645	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	667	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	633	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	570	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	543	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	541	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	518	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	512	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	518	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	533	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	547	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	547	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	521	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	514	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	542	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	530	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	590	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	556	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	612	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	645	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	651	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	653	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	600	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	586	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	566	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	604	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	623	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	718	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	638	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	574	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	509	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	515	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	570	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	540	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	609	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	558	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	578	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	592	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	558	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	520	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	502	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	540	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	629	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	601	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	602	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	613	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	638	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	653	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	622	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	629	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	634	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	627	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	637	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	638	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:44:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	620	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	628	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	590	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	591	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	616	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	647	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	712	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	690	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	663	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	640	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	610	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	608	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	562	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	524	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	494	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	509	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	514	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	577	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	526	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	551	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	562	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	587	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	553	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	562	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	580	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	605	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	639	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	748	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	719	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	671	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	714	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	681	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	725	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	712	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	623	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	657	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	650	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	662	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	744	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	683	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	632	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	653	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	666	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	655	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	644	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	648	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	626	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	618	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	592	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	614	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	617	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	628	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	657	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	601	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	581	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	39	561	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	511	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	548	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	572	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	521	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:45:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	571	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	583	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	607	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	686	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	645	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	603	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	638	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	665	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	572	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	623	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	573	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	488	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	506	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	466	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	467	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	490	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	500	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	588	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	628	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	690	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	708	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	746	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	738	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	689	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	728	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	684	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	705	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	673	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	751	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	712	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	725	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	701	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	741	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	769	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	726	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	655	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	692	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	687	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	705	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	629	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	613	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	633	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	637	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	633	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	707	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	617	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	580	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	591	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	571	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	597	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	642	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	659	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	669	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	726	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	749	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	766	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	813	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	878	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	827	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	842	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:46:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	853	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:47:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	842	Poured Concrete
Building 292	1	Scan	Storage Cabinet Room "U"	"	6/6/2012	2:47:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	769	Poured Concrete
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:26:26 PM	1.00	Ludlum 43-37-1 (SN 136361)	821	12	517	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:26:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	521	Metal

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:26:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	477	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:26:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	501	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:26:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	498	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:26:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	503	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:26:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	512	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:26:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	508	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:26:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	572	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:26:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	551	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:26:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	527	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:26:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	496	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:26:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	519	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:26:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	511	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:26:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	516	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:26:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	474	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:26:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	512	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:26:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	495	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:26:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	507	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:26:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	445	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:26:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	492	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:26:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	477	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:26:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	489	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:26:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	490	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:26:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	486	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:26:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	505	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:26:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	532	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:26:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	581	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:26:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	540	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:26:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	507	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:26:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	556	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:26:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	581	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:26:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	586	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:26:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	579	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:27:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	560	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:27:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	578	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:27:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	560	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:27:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	568	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:27:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	551	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:27:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	538	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:27:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	580	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:27:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	559	Metal
Building 292	1	Scan	Storage Cabinet 1	"	6/6/2012	3:27:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	543	Metal
Building 292	1	Scan	Storage Cabinet 2	"	6/6/2012	3:28:50 PM	1.00	Ludlum 43-37-1 (SN 136361)	821	22	493	Metal
Building 292	1	Scan	Storage Cabinet 2	"	6/6/2012	3:28:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	516	Metal
Building 292	1	Scan	Storage Cabinet 2	"	6/6/2012	3:28:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	452	Metal
Building 292	1	Scan	Storage Cabinet 2	"	6/6/2012	3:28:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	401	Metal
Building 292	1	Scan	Storage Cabinet 2	"	6/6/2012	3:28:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	406	Metal

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 292	1	Scan	Storage Cabinet 2	"	6/6/2012	3:28:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	388	Metal
Building 292	1	Scan	Storage Cabinet 2	"	6/6/2012	3:28:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	404	Metal
Building 292	1	Scan	Storage Cabinet 2	"	6/6/2012	3:28:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	439	Metal
Building 292	1	Scan	Storage Cabinet 2	"	6/6/2012	3:28:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	479	Metal
Building 292	1	Scan	Storage Cabinet 2	"	6/6/2012	3:28:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	489	Metal
Building 292	1	Scan	Storage Cabinet 2	"	6/6/2012	3:29:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	510	Metal
Building 292	1	Scan	Storage Cabinet 2	"	6/6/2012	3:29:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	457	Metal
Building 292	1	Scan	Storage Cabinet 2	"	6/6/2012	3:29:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	488	Metal
Building 292	1	Scan	Storage Cabinet 2	"	6/6/2012	3:29:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	450	Metal
Building 292	1	Scan	Storage Cabinet 2	"	6/6/2012	3:29:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	476	Metal
Building 292	1	Scan	Storage Cabinet 2	"	6/6/2012	3:29:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	490	Metal
Building 292	1	Scan	Storage Cabinet 2	"	6/6/2012	3:29:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	524	Metal
Building 292	1	Scan	Storage Cabinet 2	"	6/6/2012	3:29:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	569	Metal
Building 292	1	Scan	Storage Cabinet 2	"	6/6/2012	3:29:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	596	Metal
Building 292	1	Scan	Storage Cabinet 2	"	6/6/2012	3:29:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	584	Metal
Building 292	1	Scan	Storage Cabinet 2	"	6/6/2012	3:29:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	542	Metal
Building 292	1	Scan	Storage Cabinet 2	"	6/6/2012	3:29:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	552	Metal
Building 292	1	Scan	Storage Cabinet 2	"	6/6/2012	3:29:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	537	Metal
Building 292	1	Scan	Storage Cabinet 2	"	6/6/2012	3:29:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	490	Metal
Building 292	1	Scan	Storage Cabinet 2	"	6/6/2012	3:29:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	487	Metal
Building 292	1	Scan	Storage Cabinet 2	"	6/6/2012	3:29:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	487	Metal
Building 292	1	Scan	Storage Cabinet 3	"	6/6/2012	3:30:23 PM	1.00	Ludlum 43-37-1 (SN 136361)	821	3	591	Metal
Building 292	1	Scan	Storage Cabinet 3	"	6/6/2012	3:30:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	559	Metal
Building 292	1	Scan	Storage Cabinet 3	"	6/6/2012	3:30:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	570	Metal
Building 292	1	Scan	Storage Cabinet 3	"	6/6/2012	3:30:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	552	Metal
Building 292	1	Scan	Storage Cabinet 3	"	6/6/2012	3:30:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	597	Metal
Building 292	1	Scan	Storage Cabinet 3	"	6/6/2012	3:30:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	585	Metal
Building 292	1	Scan	Storage Cabinet 3	"	6/6/2012	3:30:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	588	Metal
Building 292	1	Scan	Storage Cabinet 3	"	6/6/2012	3:30:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	532	Metal
Building 292	1	Scan	Storage Cabinet 3	"	6/6/2012	3:30:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	532	Metal
Building 292	1	Scan	Storage Cabinet 3	"	6/6/2012	3:30:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	500	Metal
Building 292	1	Scan	Storage Cabinet 3	"	6/6/2012	3:30:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	544	Metal
Building 292	1	Scan	Storage Cabinet 3	"	6/6/2012	3:30:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	545	Metal
Building 292	1	Scan	Storage Cabinet 3	"	6/6/2012	3:30:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	579	Metal
Building 292	1	Scan	Storage Cabinet 3	"	6/6/2012	3:30:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	560	Metal
Building 292	1	Scan	Storage Cabinet 3	"	6/6/2012	3:30:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	510	Metal
Building 292	1	Scan	Storage Cabinet 3	"	6/6/2012	3:30:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	525	Metal
Building 292	1	Scan	Storage Cabinet 3	"	6/6/2012	3:30:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	449	Metal
Building 292	1	Scan	Storage Cabinet 3	"	6/6/2012	3:30:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	467	Metal
Building 292	1	Scan	Storage Cabinet 3	"	6/6/2012	3:30:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	457	Metal
Building 2540	1	Scan	Survey Unit 01	Miller	6/12/2012	9:03:38 AM	1.00	Ludlum 43-37-1 (SN 136361)	821	52	1129	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:03:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	65	1096	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:03:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	65	1231	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:03:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1182	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:03:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1293	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:03:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	79	1277	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:03:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	64	1250	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:03:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1263	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:03:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1227	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:03:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1197	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:03:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1224	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:03:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	1165	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:03:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	1057	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:03:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1106	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:03:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	1192	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:03:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	1253	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:03:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	1240	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:03:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	1270	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:03:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	1326	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:03:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	1307	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:03:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	1315	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:03:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	49	1321	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1433	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	66	1354	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1296	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1312	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	1268	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	1247	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	1238	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	1174	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	1156	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	1152	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	1134	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1076	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1051	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1103	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1180	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1137	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	1141	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1164	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	1227	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	1163	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	1126	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	1140	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1137	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	1126	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	1136	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	1237	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	1151	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	1261	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	1260	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	1202	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1201	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	1247	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	1216	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1259	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1357	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1353	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1379	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1373	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1500	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	1417	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1388	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	1305	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	1293	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1290	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	67	1344	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	66	1422	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	64	1322	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	64	1308	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1371	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1404	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1413	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	57	1382	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	57	1413	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	58	1359	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1342	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	49	1323	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	63	1289	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	75	1261	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	84	1296	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:04:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	68	1280	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	67	1402	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1410	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	67	1395	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1342	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	79	1258	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	75	1254	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	61	1251	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	60	1235	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	59	1195	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1181	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1253	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	63	1249	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1182	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1184	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1141	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1130	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1250	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	57	1230	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	58	1260	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1338	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	1324	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	1287	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	1233	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	1237	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	1189	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1217	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	63	1239	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1257	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1290	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1372	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	68	1347	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	88	1386	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	71	1426	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	57	1405	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1397	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1309	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1264	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1323	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1302	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1234	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	1185	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	1197	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1246	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1251	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1214	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1270	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1324	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	1348	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1218	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1247	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1321	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1286	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1243	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1268	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1335	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	62	1263	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	62	1278	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1296	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	62	1344	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:05:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	72	1260	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	58	1305	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1309	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	49	1269	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1270	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1228	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1111	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1147	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1121	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1102	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1121	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1112	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1130	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	65	1096	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	63	1123	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	62	1163	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1161	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	63	1193	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	117	1158	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	95	1108	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	77	1078	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	73	1101	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	70	1109	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1115	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1107	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1082	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1095	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	73	1102	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	59	1078	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	94	1066	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	86	1055	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	82	1177	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	78	1237	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	75	1263	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	85	1272	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	69	1327	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1303	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1294	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1194	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	1104	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1122	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1105	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1068	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1160	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1122	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1084	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	1097	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1107	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	71	1113	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	91	1039	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	74	1046	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	60	1050	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1071	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	1013	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1034	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1088	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	1016	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:06:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1006	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	1089	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	1044	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	1052	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1056	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1027	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1044	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	1079	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1046	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	49	1105	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1193	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	66	1194	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	76	1241	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	83	1149	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	79	1137	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	76	1067	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	73	998	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	70	968	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	69	965	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	68	996	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	898	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	897	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	939	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	897	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	874	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	888	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	900	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	924	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	989	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1051	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1181	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	65	1206	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	65	1245	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1156	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	66	1128	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1096	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1089	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1145	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1118	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1130	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	57	1172	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	78	1166	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	63	1196	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1217	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1217	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1264	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1127	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:10:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1132	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	63	1065	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	63	1094	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1135	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1088	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1016	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1082	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	967	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1091	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	1146	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1078	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1112	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1129	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1173	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	1097	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1187	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1131	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1187	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	60	1236	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	84	1163	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	68	1162	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	67	1099	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1086	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1087	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1176	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1046	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1210	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	1263	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	1242	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1282	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1257	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1305	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	1219	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	1215	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	1157	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	1170	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	1236	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	1217	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	1259	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	1239	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	1412	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	1397	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	1299	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1337	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	49	1228	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1130	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1089	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1146	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	67	1154	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1187	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1192	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	59	1191	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1214	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	1190	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1328	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	1335	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1308	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	1254	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	1379	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	1297	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:11:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	1246	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	1213	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	1184	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	1263	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	1262	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	1320	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	1308	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	1288	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	1240	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	1127	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	1198	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1154	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1154	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1185	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1108	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1105	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1115	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1188	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	61	1332	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	71	1259	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	57	1282	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1197	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1150	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1171	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1167	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	60	1255	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	72	1315	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	58	1359	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	59	1378	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	81	1265	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	90	1218	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	95	1155	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	77	1192	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	97	1182	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	91	1215	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	84	1154	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	68	1184	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1187	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	79	1224	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	64	1233	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	64	1109	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1067	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1058	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1142	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	68	1202	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1097	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1105	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1042	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	58	1128	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	59	1105	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	58	1092	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	59	1113	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1165	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	49	1211	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1203	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1201	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	1204	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1178	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1241	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	1376	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:12:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	1310	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1212	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	1259	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1202	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	1156	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	1203	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1197	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1234	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	69	1204	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	67	1205	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	65	1338	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1218	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1264	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	1288	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	1258	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	1305	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	1308	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1301	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	1217	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	1166	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1138	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1134	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	1122	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1205	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1215	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1259	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1185	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	1153	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	58	1196	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	58	1164	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1150	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1125	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	62	1102	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	73	1084	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	70	1159	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	78	1119	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	74	1145	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	83	1188	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	79	1179	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	64	1177	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1213	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1152	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	77	1189	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	74	1231	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	72	1263	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	58	1215	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	59	1222	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1191	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	62	1147	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1170	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1265	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1294	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	1345	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	87	1303	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	71	1327	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	57	1391	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1328	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	49	1293	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1286	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1199	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:13:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	1222	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	1234	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	1288	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	1297	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	1264	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1357	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1398	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1323	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	1291	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	1242	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1282	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	1227	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	1291	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	58	1244	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	58	1301	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	68	1317	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1321	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	69	1308	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1369	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1265	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1223	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1320	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1374	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	58	1407	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1323	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	1388	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1350	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1456	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1455	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1373	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	58	1272	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	71	1144	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	57	1133	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1172	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1178	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1191	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1147	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	65	1149	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1087	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1121	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	1066	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	1003	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1007	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1143	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1098	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1072	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1016	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1065	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	57	1118	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1109	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1078	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1052	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1082	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1025	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1096	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	1059	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1086	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1031	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1084	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1058	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:14:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1036	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1044	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1084	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1038	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1058	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1075	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1154	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1137	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	81	1172	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	77	1237	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	73	1107	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	71	1088	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	80	1150	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	77	1178	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	75	1239	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	60	1162	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	61	1221	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	60	1215	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1188	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	1172	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	1153	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1209	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1176	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1260	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	66	1192	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	64	1218	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	63	1211	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	83	1249	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	67	1211	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	67	1129	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	77	1102	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	74	1123	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	60	1127	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1115	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	1195	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1231	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	1250	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	1196	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	1229	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1188	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1201	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1214	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1346	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1335	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1262	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1318	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1387	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	1339	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	1404	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	1365	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	1278	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1275	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1286	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1335	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1263	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1273	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1228	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1261	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1261	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1184	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:15:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	1213	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	1242	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	1150	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	1207	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	1204	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	1132	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1112	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	1144	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	1179	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1160	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1189	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1223	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	1242	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	1326	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	1406	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1364	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	1298	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	66	1235	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1187	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	67	1267	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	65	1380	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1319	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	65	1284	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1291	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1257	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	1142	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1201	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	1190	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	1170	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	1240	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	59	1187	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1173	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	1156	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	1107	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1157	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1185	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	1086	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	1118	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	1237	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	1243	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1326	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1416	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1412	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	66	1418	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1308	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1357	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	66	1247	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1275	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	65	1226	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	87	1166	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	104	1167	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	84	1176	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	80	1197	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	86	1228	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	82	1245	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	90	1245	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	73	1316	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	70	1328	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	57	1324	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1344	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:16:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1296	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1221	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1186	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1188	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1251	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1297	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1278	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1236	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1310	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1198	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	1278	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	1231	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	1212	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	1211	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1257	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	78	1287	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	63	1286	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	62	1247	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1241	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1140	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	66	1199	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1196	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1176	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	67	1099	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	65	1189	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	63	1137	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	62	1142	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	62	1174	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1158	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1111	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1183	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	1171	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	1052	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1070	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1140	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1183	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1137	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1036	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1001	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	960	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	984	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1034	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	1095	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	1057	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1026	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	1040	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	1026	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	1035	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	1020	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	1078	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1078	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	1045	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	1039	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	1108	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	1067	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	1048	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	1032	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	1053	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	1042	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	994	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:17:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	965	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1023	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1016	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1029	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1070	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1042	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1036	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1023	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	984	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	911	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	960	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	67	943	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	944	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1026	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1076	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1123	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1071	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1172	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1220	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1185	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	1283	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	1255	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	1320	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1250	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	1160	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	1110	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1198	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1220	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1156	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1121	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	1080	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	1095	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	1151	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	1177	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1143	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	1101	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	1115	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	1198	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1179	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	77	1187	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	63	1286	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1279	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	76	1320	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	61	1263	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	49	1215	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1175	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	67	1190	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1204	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1151	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1136	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1161	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1251	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1263	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1245	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	49	1257	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1283	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1266	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1262	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1298	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1291	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:18:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1326	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1320	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	64	1264	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	64	1288	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1285	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1235	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1310	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	1278	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1370	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1426	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1371	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	1295	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	65	1380	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	65	1311	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	65	1376	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1319	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1377	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1302	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1190	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1143	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1210	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1207	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1263	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	1328	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	1353	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1325	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1241	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	1221	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	1256	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	1240	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1235	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1310	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	60	1208	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	49	1125	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	1145	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	1063	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1065	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	1104	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1100	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1134	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1077	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1114	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1066	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1156	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	61	1184	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	60	1162	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	49	1179	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1181	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	63	1285	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	94	1237	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	87	1267	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	107	1323	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	109	1310	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	88	1230	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	95	1206	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	89	1156	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	84	1118	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	68	1121	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	67	1122	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	76	1146	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:19:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	73	1091	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	60	1180	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	59	1168	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	58	1117	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	69	1134	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	67	1189	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	65	1167	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	64	1245	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1263	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1298	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1282	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	67	1175	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1165	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	65	1150	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	77	1078	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	74	1042	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	71	1095	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	92	1205	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	75	1168	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	60	1246	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	49	1229	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	1209	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1226	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	1274	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1236	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1217	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1168	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1193	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1228	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1209	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1144	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1066	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1109	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1024	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1096	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	1117	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1065	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1066	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1112	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	67	1151	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	64	1103	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	75	1076	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	61	1132	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	83	1038	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	67	1100	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	65	1060	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	63	1087	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	73	1121	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	70	1121	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1098	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1148	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1173	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1098	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1090	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	1241	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1139	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1139	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	1082	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1164	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1182	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:20:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1149	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1166	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1171	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	1196	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	1199	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	1173	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	1197	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1162	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	1184	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	1161	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	1136	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1170	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1118	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1096	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	1106	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	1149	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	1125	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	1148	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	1168	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	1186	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	1171	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	1087	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	1108	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1126	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1165	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1146	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1235	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1207	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	1230	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1190	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1223	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	1289	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1288	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	1377	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	1312	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1310	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	1142	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	1062	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	1016	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1188	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1156	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1215	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	1259	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	1421	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1391	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	1375	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	1273	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	1335	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1263	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	81	1310	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	65	1382	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	65	1291	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	64	1260	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	76	1307	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	62	1315	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1339	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1266	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1300	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1292	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1207	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:21:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1194	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1139	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1115	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1165	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	1196	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	1233	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	1238	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	1250	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	1280	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1236	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	1171	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	1202	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	1249	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	1397	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1369	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	1362	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1324	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1290	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1443	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1405	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1468	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	67	1410	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	65	1484	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	64	1463	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	63	1401	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1397	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1302	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1327	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1247	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1260	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1286	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1256	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	1231	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1167	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	1158	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	1168	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	1217	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	1203	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	1212	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	1314	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	1240	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1281	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	68	1219	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1246	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1292	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1342	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1316	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	1225	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1125	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	1229	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1191	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1138	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1181	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1176	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1136	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1219	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1226	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	63	1210	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1160	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1113	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:22:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1105	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1152	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1163	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1133	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1144	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	1133	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	1100	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1142	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1151	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1094	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	1127	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1179	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1092	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	977	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	983	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1081	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1080	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1057	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1015	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	66	1015	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	65	1039	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	77	1051	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	62	1046	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	62	1029	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1120	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1102	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	66	1004	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1089	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1106	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1123	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1159	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1224	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1197	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1249	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	60	1213	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	49	1224	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	1252	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	1208	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	1117	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	1075	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1132	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1057	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1146	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1247	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1216	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	1188	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	1260	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	67	1215	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1236	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	66	1174	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	76	1177	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	85	1178	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	68	1272	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1309	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1319	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	59	1251	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	69	1196	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1215	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	57	1227	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	58	1311	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:23:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	58	1387	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1399	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	1440	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	1476	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	1469	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	1292	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	1275	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	1226	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1218	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	1192	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	1135	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	1035	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	1068	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	49	1134	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1019	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1066	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1145	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1028	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1116	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1133	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	62	1151	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	62	1055	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	61	1151	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	49	1147	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1120	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1112	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1167	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1179	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1177	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	84	1207	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	91	1203	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	86	1302	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	69	1319	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	67	1308	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	65	1369	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	85	1394	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	81	1359	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	76	1318	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	74	1322	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	60	1331	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	59	1444	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1340	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	49	1331	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1316	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1360	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1299	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1334	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1330	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1292	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	57	1367	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1371	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1303	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	71	1316	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	58	1352	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	68	1384	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	66	1430	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	86	1375	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	80	1356	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	77	1404	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	74	1320	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:24:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	71	1342	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	68	1371	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1325	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	57	1403	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1422	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	67	1353	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	89	1338	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	72	1358	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	59	1400	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	59	1319	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1308	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1325	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1300	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1234	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1273	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	49	1326	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1234	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	64	1319	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	86	1319	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	80	1307	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	65	1208	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	64	1297	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	63	1211	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1162	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1100	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1120	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	67	1069	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1028	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1093	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	57	1080	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	58	1111	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1132	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1202	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	62	1122	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	61	1125	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	61	1162	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1237	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1213	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	1238	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	1275	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1385	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	1351	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	1286	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	1303	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	1262	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	1297	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1323	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1323	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1270	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1306	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1386	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1356	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	1313	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	1351	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	1387	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	1436	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1391	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1353	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1350	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1387	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:25:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	1400	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1446	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1432	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1379	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1325	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1264	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1254	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1222	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1209	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	69	1289	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	102	1273	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	93	1283	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	86	1277	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	82	1309	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	77	1297	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	62	1234	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1226	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1234	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	79	1330	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	63	1324	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	62	1310	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1347	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1274	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1241	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1297	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1327	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1349	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	1354	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	1369	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	1357	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	1397	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1403	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1349	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1419	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	1398	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1388	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1297	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	1306	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	1263	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	1214	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	1299	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	1308	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	1345	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1292	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	1353	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	1393	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	1387	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1340	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	104	1383	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	84	1383	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	90	1372	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	97	1356	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	89	1351	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	72	1313	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	70	1379	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	68	1339	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	78	1379	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	75	1435	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	106	1419	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	98	1520	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:26:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	101	1533	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	82	1412	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	110	1504	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	89	1573	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	118	1585	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	118	1511	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	107	1492	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	86	1502	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	70	1443	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	78	1338	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	63	1306	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	63	1283	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1290	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1316	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1356	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	68	1297	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1259	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	66	1282	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1256	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1155	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	1220	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	1280	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	1208	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	1151	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1159	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	1154	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	1160	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	1190	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	1256	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	1304	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1375	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1353	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1336	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	1400	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1326	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1389	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1383	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	1336	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1357	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	57	1431	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1421	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1470	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	72	1419	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	59	1401	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1315	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	49	1320	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1395	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	1357	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	1374	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	1411	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	1347	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1510	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1393	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1431	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1328	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1297	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1223	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	1208	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1183	Laminate Tile
Building 2540	1	Scan	Survey Unit 01	"	6/12/2012	9:27:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1212	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:33:28 AM	1.00	Ludlum 43-37-1 (SN 136361)	821	69	1233	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:33:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	67	1214	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:33:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1174	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:33:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1181	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:33:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1347	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:33:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	72	1225	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:33:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	59	1338	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:33:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	58	1337	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:33:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1320	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:33:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1417	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:33:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1387	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:33:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1421	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:33:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1276	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:33:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	1282	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:33:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	1231	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:33:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	1235	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:33:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	1220	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:33:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	1251	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:33:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1146	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:33:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	1236	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:33:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	61	1272	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:33:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	61	1237	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:33:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1263	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:33:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1240	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:33:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1207	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:33:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1151	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:33:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	57	1309	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:33:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1322	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:33:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1286	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:33:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	1294	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:33:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	1276	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:33:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1319	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1376	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	1393	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1390	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1375	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	70	1410	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	79	1429	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	64	1431	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	75	1315	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	72	1294	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	83	1291	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	79	1267	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	75	1357	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	60	1352	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	49	1336	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	62	1382	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1298	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1302	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1263	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	57	1330	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	69	1319	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	80	1341	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	75	1428	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	61	1409	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	72	1368	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	81	1313	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	88	1226	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	82	1162	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	79	1263	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	63	1260	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	62	1251	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	61	1259	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	49	1218	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	63	1152	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1209	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	64	1371	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	76	1428	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	72	1362	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	81	1392	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	76	1399	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	85	1409	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	68	1349	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1331	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	67	1283	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1200	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	66	1246	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1218	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	67	1205	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	65	1282	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	74	1323	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	72	1263	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	58	1264	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1290	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	1400	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	1302	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	1349	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	1344	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1358	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1306	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1365	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:34:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1497	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1520	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1462	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1369	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	1428	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1330	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1283	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	49	1287	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1240	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1271	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1260	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	1228	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	1351	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1309	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1373	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	72	1405	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	81	1388	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	78	1394	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	63	1322	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1401	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1328	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1294	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1289	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1227	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	1292	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1275	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	1319	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	60	1284	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	59	1244	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	81	1285	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	66	1360	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	65	1340	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	63	1394	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	74	1404	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	60	1390	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	70	1424	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	69	1439	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1439	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	68	1487	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	67	1502	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1469	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	65	1404	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	76	1376	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	73	1380	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	82	1301	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	78	1346	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	75	1385	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	72	1397	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	58	1356	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	71	1407	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	57	1324	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1338	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1425	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1428	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1410	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1352	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1376	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1353	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1344	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	58	1306	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:35:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	59	1287	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	82	1393	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	91	1399	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	74	1449	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	71	1368	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	79	1498	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	75	1547	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	61	1597	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	72	1524	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	58	1447	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	58	1357	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	71	1341	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	68	1328	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	67	1406	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	65	1332	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	65	1322	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1343	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1240	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1223	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1237	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1232	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1281	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1255	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1278	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1241	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1247	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	64	1250	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	75	1217	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	60	1218	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	60	1227	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1258	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	61	1201	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	61	1236	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	72	1374	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	58	1475	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	58	1379	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	69	1381	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	67	1427	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	78	1470	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	63	1478	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1421	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	64	1392	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	64	1415	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	64	1397	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	62	1398	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1392	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	75	1456	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	60	1356	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	49	1268	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	61	1246	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	71	1213	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	57	1164	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	57	1259	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1300	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1247	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1285	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1407	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1437	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	1427	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1365	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:36:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1323	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	1324	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	1398	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	1362	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	1331	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	1245	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	1263	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	1230	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1289	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	1361	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	1294	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1370	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	1334	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	1313	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1294	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1373	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1397	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1322	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	65	1359	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	65	1361	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1344	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1338	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	1457	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1443	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1386	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1359	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1316	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	57	1465	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1550	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	61	1518	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	49	1494	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1451	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1502	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	1454	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	1440	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	1485	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	1348	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1271	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1346	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1320	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	85	1333	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	79	1363	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	64	1411	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	110	1388	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	89	1421	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	72	1322	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	58	1283	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	58	1222	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	70	1331	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1260	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	68	1215	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	67	1212	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	65	1298	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	100	1353	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	81	1507	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	77	1472	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	63	1434	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1526	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1555	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1548	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:37:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	49	1515	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1467	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	1394	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	49	1449	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	74	1460	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	60	1453	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	49	1517	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	62	1421	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1379	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	63	1302	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	74	1331	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	72	1388	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	58	1358	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	70	1383	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1351	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1344	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	49	1351	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1328	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1442	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1488	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1502	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1424	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1384	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	69	1383	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1499	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1525	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1453	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1499	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	1442	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1569	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1614	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1560	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1515	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	1431	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	1498	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	1490	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	1444	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	1490	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	1506	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	1534	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	1673	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1552	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	58	1566	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1509	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	1462	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	1414	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	1349	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	1382	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	1301	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1277	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1404	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	1356	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	1362	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1319	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1234	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1284	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1207	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	78	1253	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	63	1280	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	63	1333	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:38:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	62	1302	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1321	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1383	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1378	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1302	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	1260	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	67	1200	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	78	1174	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	75	1223	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	83	1312	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	79	1277	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	75	1406	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	71	1415	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	79	1339	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	64	1464	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	87	1507	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	93	1406	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	86	1386	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	82	1399	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	78	1360	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	63	1317	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1394	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1393	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1367	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	67	1419	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	66	1471	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1465	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	66	1451	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	78	1391	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	63	1380	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	75	1319	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	60	1285	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	60	1320	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1283	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	1257	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1281	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1218	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1214	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1303	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	1241	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	1233	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1319	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1368	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	73	1376	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	59	1341	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	81	1299	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	76	1330	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	62	1327	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1359	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	85	1371	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	103	1352	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	96	1442	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	78	1397	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	63	1386	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	61	1305	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	62	1342	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1313	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1351	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1255	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1254	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:39:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	1327	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1293	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	57	1381	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1312	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1324	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1326	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	86	1312	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	82	1265	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	66	1274	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1206	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1213	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	1143	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	1131	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1156	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1130	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1253	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	68	1242	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	66	1288	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	65	1289	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	65	1341	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	63	1367	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1404	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1350	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1288	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1279	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	63	1310	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1425	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1465	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	66	1461	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1511	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1598	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1533	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1527	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1558	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	49	1568	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1537	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1518	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1481	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	1430	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	1414	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	61	1421	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	61	1403	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	62	1386	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	61	1338	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	49	1252	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1325	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	1386	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	1402	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	1447	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	1363	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	1526	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1510	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1463	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1487	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	1469	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	1407	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	1353	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	1290	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	1308	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	1425	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:40:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	1339	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1322	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	1380	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1391	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	1423	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	1469	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1419	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1295	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	57	1353	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	57	1245	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	68	1169	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1339	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	68	1463	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1409	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	57	1345	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1526	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	60	1498	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	106	1602	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	108	1684	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	111	1730	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	90	1638	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	94	1556	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	76	1626	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	62	1603	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	73	1675	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	59	1583	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1626	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	49	1551	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	64	1564	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	63	1496	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	86	1525	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	70	1522	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	68	1606	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	114	1567	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	92	1593	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	108	1655	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	99	1539	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	80	1363	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	64	1446	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1410	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	65	1440	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	63	1481	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	62	1471	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	61	1323	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	49	1368	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	64	1292	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1288	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1290	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1449	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1449	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	49	1422	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1453	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1477	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1378	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	67	1426	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1407	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1474	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1451	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1438	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	1417	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:41:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	1408	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	1354	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	69	1356	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	67	1391	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1502	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1409	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	1411	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1329	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1297	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1371	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1443	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1485	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1532	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	1446	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	1392	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	1378	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1420	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	1428	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1362	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1358	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1362	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1281	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1366	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1319	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	1203	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	1215	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1221	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	60	1138	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	49	1172	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1308	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	1253	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	1165	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	1192	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	1274	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1290	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1238	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	1199	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1288	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	1320	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	49	1193	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1382	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1360	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1252	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1287	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1337	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1402	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1342	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1308	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	49	1301	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	1406	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1402	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1364	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	1481	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	67	1440	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1413	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1428	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1283	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	57	1254	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1216	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1260	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:42:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	1227	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1196	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	84	1210	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	80	1220	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	75	1274	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	73	1272	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	59	1214	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	60	1314	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	72	1358	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	59	1420	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1392	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1342	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1327	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1476	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1379	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	72	1359	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	58	1312	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	59	1373	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1387	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	1410	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	1482	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1438	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1435	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	1469	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1530	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1470	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	1383	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1458	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1396	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1391	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1470	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1527	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1518	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	1446	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	1338	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	1297	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1303	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1279	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	57	1356	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	58	1373	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1407	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	1388	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1443	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1413	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	69	1370	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	1382	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1449	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1423	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1406	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	1355	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1305	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1262	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	1274	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	1433	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	1398	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	1444	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	1512	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	1544	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	1506	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	1491	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:43:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	59	1524	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	60	1532	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	60	1493	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	61	1538	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	72	1476	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	58	1492	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1376	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1469	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	1477	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	63	1518	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	75	1503	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	73	1509	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	103	1461	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	95	1434	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	77	1473	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	108	1448	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	88	1503	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	71	1424	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	92	1346	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	85	1336	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	93	1325	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	87	1324	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	83	1222	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	67	1250	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	66	1183	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	65	1150	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	1228	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	1211	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1211	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1252	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1331	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	1331	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	1316	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	1309	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	1416	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	1419	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	1356	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	1315	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1271	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	1325	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1401	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	1321	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1321	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	58	1257	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	1189	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	1167	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	1219	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	1309	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	1320	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	1339	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	1313	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	1391	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1375	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	62	1431	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1351	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	62	1252	Laminate Tile
Building 2540	2	Scan	Survey Unit 02	"	6/12/2012	9:44:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	1152	Laminate Tile
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:09:47 PM	N/A	Ludlum 43-37-1 (SN 136361)	821	21	1210	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:09:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1127	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:09:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1036	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:09:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1078	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:09:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	1081	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:09:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1126	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:09:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1072	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:09:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1095	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:09:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1159	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:09:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1168	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:09:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1209	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:09:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1196	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:09:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1173	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1123	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1092	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1147	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1156	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1150	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1147	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1170	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1173	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1185	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1128	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1077	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1088	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1119	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1151	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1128	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1220	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1287	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1325	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1373	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1319	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1282	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	1339	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1362	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1455	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1361	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1425	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1369	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1394	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	38	1245	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	1268	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	1290	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1215	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	1202	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1249	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	41	1282	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	44	1228	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	36	1456	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	40	1410	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	1335	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1341	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	1343	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1326	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1324	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	1402	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1372	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1395	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	1356	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1346	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1402	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1332	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	1348	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	1391	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	1354	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1425	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1415	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1488	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1456	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1416	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1452	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:10:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1429	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1410	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1357	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1391	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1343	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1284	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1260	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1179	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1172	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1190	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1177	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1229	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	1315	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	1296	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	1278	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1310	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1413	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	1350	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1313	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1270	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1224	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1238	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1252	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1207	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1253	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1273	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1245	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1238	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1275	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1273	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1313	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1341	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1429	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1470	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1406	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1357	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1283	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1220	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1248	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1272	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1321	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1368	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1448	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	1417	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1342	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1267	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1334	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1320	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	1251	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	38	1285	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	1278	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	1332	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	1340	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	1276	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1319	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1389	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1319	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1270	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1211	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1197	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:11:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1250	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1248	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1221	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1238	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1311	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1291	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1331	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1380	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1338	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1313	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1289	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1236	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1277	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1272	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1177	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	1217	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1317	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	1350	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1275	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1337	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	1340	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	36	1383	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	41	1269	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	1198	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	1188	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	1201	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	48	1269	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	39	1232	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	1301	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	1314	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1339	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1375	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1344	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1440	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1429	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1500	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1434	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1390	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1457	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1440	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1413	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1397	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1311	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1286	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1225	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1291	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1272	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1249	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1229	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1185	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1122	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1153	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1117	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1176	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1169	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1186	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1186	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1108	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1160	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1119	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:12:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1213	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1219	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1172	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1131	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1131	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1141	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	38	1131	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	42	1121	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	1206	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	1178	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1245	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1305	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1298	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1279	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1251	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1217	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1192	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	1226	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	1237	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	1230	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	1124	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	1137	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	1070	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1186	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1107	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1145	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1192	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1160	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1165	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1186	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1209	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1252	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1257	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1197	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1200	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1236	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1249	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1193	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1203	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1157	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1209	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1174	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1133	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1124	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1127	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1119	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1194	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1219	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1184	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	1281	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	1312	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	42	1260	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	1257	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	39	1295	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	1348	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	1322	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	1348	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1311	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1259	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1287	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:13:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1280	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:14:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1225	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:14:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1129	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:14:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1106	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:14:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1245	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:14:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1225	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:14:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1174	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:14:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1201	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:14:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1179	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:14:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1232	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:14:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1170	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:14:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1252	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:14:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1321	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:14:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1286	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:14:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1248	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:14:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1226	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:14:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1209	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:14:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1187	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:14:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1268	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:14:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1200	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:14:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1201	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:14:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1155	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:14:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1197	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:14:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1177	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:14:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1170	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:14:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1152	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1213	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1246	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1251	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1248	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1273	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1142	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1133	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1219	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1261	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1278	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1251	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1205	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1195	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1267	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1227	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1303	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1291	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1295	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1320	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1271	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	1239	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1217	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1203	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1156	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1222	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1269	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	40	1167	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	1116	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	38	1203	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	43	1215	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	1212	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	1207	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1215	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1217	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	1341	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	1291	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1209	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	1245	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	1178	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1149	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1172	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	1106	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1121	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:18:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1105	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	1181	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	1188	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1154	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1105	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1142	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1199	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1271	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1218	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1156	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1083	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1127	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1177	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1184	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1185	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1132	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1067	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1169	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1179	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1092	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1086	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1134	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1133	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1067	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	1104	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1204	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	1144	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1146	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	1177	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	1121	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1114	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1132	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1112	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1051	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	965	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	943	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1007	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	962	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	984	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	968	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1000	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	972	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1047	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1104	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1146	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1167	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1114	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1104	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	1102	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	1076	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	1143	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1120	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1068	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1074	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1173	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1132	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1143	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1030	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1007	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1055	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:19:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1062	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1046	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1086	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1129	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1131	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1200	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	1139	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1151	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	1200	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1164	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1116	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1072	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	1014	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	1038	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	977	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	937	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	886	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	959	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	993	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	940	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	943	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	957	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1034	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1009	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1014	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1048	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	965	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	940	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1001	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	980	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	944	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	1005	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	36	1088	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	1059	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1026	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1046	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1109	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1079	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1046	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1006	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	995	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	975	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	940	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	962	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	953	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	979	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1043	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	992	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1076	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1062	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1068	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1115	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1120	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1100	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1131	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1077	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1032	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1065	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1068	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1094	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:20:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1097	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1095	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1079	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1012	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1060	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1201	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1129	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1120	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1020	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1131	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1086	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1089	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1087	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1004	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1038	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1031	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1073	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1130	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1181	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1178	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1152	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1105	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1203	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1133	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1066	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	1182	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1266	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1236	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1184	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1171	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1120	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1104	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1091	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1112	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1284	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1303	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1309	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1267	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1263	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1330	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1412	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1431	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1359	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1350	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1323	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1363	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1263	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1245	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1169	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1224	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1228	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1211	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1267	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1245	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1270	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1152	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1139	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	1060	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	1079	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1112	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:21:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1073	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1095	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1195	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1155	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1305	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1293	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1285	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1237	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1263	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1197	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1151	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1080	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1022	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	974	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	898	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	864	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	850	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	824	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	783	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	816	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	912	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	993	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1132	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1272	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1238	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1246	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1330	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1263	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1234	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1102	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1165	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1100	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1029	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1006	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1001	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1006	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	941	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	42	1027	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	1075	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	1176	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1103	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	41	1145	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	44	1078	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	58	1083	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	69	1213	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	56	1228	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	45	1127	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	36	1018	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	51	997	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	63	1068	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	51	1062	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	41	938	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	875	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	39	938	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	42	919	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	1020	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	952	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1008	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	1013	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1012	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:22:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1098	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1029	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1049	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1035	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	52	1000	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	42	958	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	932	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	1016	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	879	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	916	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	948	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	990	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	40	950	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	43	927	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	46	954	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	990	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	938	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	923	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	906	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	36	941	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	856	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	864	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	885	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	924	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	897	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	920	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	909	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	885	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	850	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	907	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	943	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1012	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	957	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	986	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	962	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	1066	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	1102	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	1093	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1058	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	1036	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1023	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	967	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	968	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1034	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1004	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	1016	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1074	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1014	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1126	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1218	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1207	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1151	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1174	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1121	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1093	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1144	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1099	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1063	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1099	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	1106	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:23:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1115	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1095	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1123	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1025	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	1052	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	994	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	949	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	937	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	961	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	1040	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	1014	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	40	971	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	43	990	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	989	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	901	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	962	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	39	905	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	881	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	899	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	899	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	968	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1020	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	1028	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	1026	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	1072	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1025	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1015	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	992	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1050	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	986	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1047	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	951	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	943	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	878	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	844	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	1001	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	36	1010	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	40	957	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	983	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	967	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	974	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	994	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	918	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1041	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1002	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1110	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	1061	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	1008	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	978	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	963	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	991	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	952	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	978	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	1044	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1028	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1026	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	1040	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	1046	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	984	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	993	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:24:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	986	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	947	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	939	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	1048	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	982	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	998	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1013	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1057	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1077	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	996	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	1091	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	1073	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	1075	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	44	1096	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	36	1044	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	1014	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	948	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	927	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	921	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	894	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	838	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	883	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	873	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	892	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	977	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	916	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	892	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	892	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	933	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	905	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	833	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	801	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	784	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	812	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	841	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	897	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	965	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	884	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	896	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	976	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1014	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1053	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1150	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1048	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	1023	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1066	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	995	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	952	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	929	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	913	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	944	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	963	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:25:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1002	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1015	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	991	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1087	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1121	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1043	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1081	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1053	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1129	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1153	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1141	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1073	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1014	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	960	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	935	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	956	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	960	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1020	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1000	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	968	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1001	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1039	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1001	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1028	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1019	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1050	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1011	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	1023	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	975	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	971	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1066	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1181	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1143	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1176	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1207	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1184	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1217	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1208	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1206	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1203	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1262	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:27:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1250	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1135	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1176	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1225	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1094	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1054	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1072	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1080	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1209	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1198	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1245	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1228	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1289	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1340	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1269	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	1311	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1166	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1248	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1229	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1289	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1258	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1217	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	1231	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	1216	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	1200	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1236	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1241	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1236	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1171	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1106	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1098	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1094	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1065	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1172	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1155	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1178	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1114	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1145	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1204	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1241	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1085	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1124	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	1161	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	1147	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	1168	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	1208	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	1114	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1117	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1181	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1300	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1260	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1246	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1239	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1308	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1365	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1318	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1256	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1219	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1192	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1193	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:28:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1229	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:29:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1226	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:29:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1212	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:29:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1200	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:29:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1199	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:29:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1151	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:29:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1250	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:29:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1217	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:29:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	1169	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:29:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1284	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:29:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1214	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:29:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1228	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:29:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1235	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:29:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1236	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:29:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1140	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:29:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1105	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:29:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	997	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:29:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1144	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:29:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1134	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:29:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1202	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:29:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	1238	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:29:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	1194	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:29:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	39	1152	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:29:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	1144	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:29:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	1192	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:29:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	1165	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:29:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1069	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:29:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1093	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:29:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	988	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:29:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1087	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:29:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1123	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:29:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1103	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:29:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1132	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:29:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1078	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:29:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1180	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	2:29:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1155	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	791	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	856	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	781	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	771	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	735	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	731	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	718	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	746	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	762	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	757	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	763	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	786	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	837	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	824	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	736	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	746	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	708	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	768	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	759	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	760	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	739	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	734	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	698	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	749	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	822	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	756	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	735	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	662	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	685	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	623	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	697	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	689	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	706	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	676	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	675	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	735	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	698	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	702	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	744	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	694	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	676	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	721	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	755	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	774	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:45:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	817	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	867	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	883	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	844	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	909	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	828	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	840	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	826	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	827	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	761	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	740	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	724	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	715	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	670	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	669	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	689	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	604	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	655	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	620	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	604	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	659	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	614	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	635	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	619	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	616	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	613	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	587	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	622	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	610	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	611	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	735	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	673	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	709	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	632	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	593	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	595	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	628	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	603	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	634	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	641	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	701	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	637	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	676	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	672	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	660	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	612	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	618	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	672	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	679	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	666	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	741	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	738	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	656	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	647	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	654	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	599	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	588	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	651	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	654	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	632	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:46:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	637	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	628	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	688	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	683	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	703	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	663	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	629	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	717	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	683	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	704	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	740	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	771	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	789	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	755	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	723	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	689	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	592	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	616	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	648	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	569	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	541	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	505	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	39	561	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	579	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	48	631	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	39	611	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	44	666	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	46	695	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	49	723	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	40	691	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	662	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	591	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	638	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	561	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	533	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	639	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	633	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	640	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	679	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	664	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	628	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	643	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	659	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	670	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	701	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	671	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	670	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	643	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	601	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	636	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	638	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	576	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	556	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	562	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	545	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	622	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	650	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	709	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	688	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	717	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:47:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	692	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	709	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	733	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	697	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	690	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	731	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	684	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	678	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	655	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	645	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	611	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	596	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	551	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	571	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	620	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	592	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	595	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	539	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	504	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	486	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	461	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	487	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	532	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	498	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	553	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	560	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	695	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	720	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	676	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	662	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	693	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	674	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	673	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	707	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	720	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	688	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	739	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	42	725	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	723	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	678	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	757	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	716	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	829	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	740	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	687	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	715	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	680	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	666	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	628	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	624	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	647	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	569	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	657	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	683	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	692	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	696	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	735	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	729	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	768	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	712	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:48:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	798	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	783	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	759	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	763	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	791	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	731	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	781	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	712	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	747	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	766	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	710	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	746	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	751	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	38	781	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	757	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	36	854	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	876	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	858	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	832	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	822	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	878	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	903	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	905	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	40	894	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	43	838	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	783	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	40	796	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	826	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	888	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	934	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	891	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	935	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	936	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	939	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	862	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	905	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	859	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	809	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	792	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	777	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	734	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	823	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	792	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	768	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	747	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	729	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	693	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	769	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	702	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	707	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	719	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	778	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	729	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	658	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	636	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	658	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	637	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	689	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	648	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	696	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:49:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	689	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	742	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	728	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	724	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	667	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	36	619	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	648	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	731	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	715	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	660	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	748	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	723	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	766	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	801	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	776	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	778	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	780	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	789	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	864	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	780	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	756	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	737	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	722	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	666	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	747	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	720	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	44	711	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	47	711	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	49	760	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	40	732	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	707	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	807	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	713	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	727	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	46	761	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	845	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	53	890	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	55	823	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	44	780	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	36	794	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	40	822	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	816	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	784	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	772	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	738	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	676	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	728	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	843	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	810	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	747	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	742	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	727	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	740	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	749	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	802	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	889	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	870	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	817	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	842	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	831	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:50:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	898	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	956	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	880	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	838	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	871	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	810	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	818	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	869	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	941	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	911	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	949	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	916	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	926	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	807	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	804	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	810	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	804	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	820	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	847	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	835	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	859	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	946	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	920	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	985	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	933	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	870	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	817	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	47	810	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	38	803	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	802	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	776	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	801	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	741	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	756	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	804	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	837	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	892	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	847	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	918	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	854	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	886	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	817	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	843	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	895	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	853	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	773	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	752	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	699	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	668	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	644	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	647	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	662	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	660	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	663	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	688	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	725	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	771	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	783	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	761	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	729	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:51:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	765	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	846	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	829	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	852	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	816	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	742	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	787	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	750	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	723	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	744	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	821	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	827	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	851	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	846	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	801	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	776	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	738	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	699	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	739	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	783	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	806	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	766	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	746	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	797	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	768	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	725	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	789	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	856	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	830	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	787	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	765	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	799	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	770	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	726	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	768	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	795	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	861	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	820	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	869	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	829	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	922	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	906	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	951	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	967	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	931	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	995	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	934	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	960	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	946	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	945	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	938	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	907	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	870	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	901	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	880	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	871	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	847	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	895	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	925	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	873	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:52:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	814	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	820	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	832	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	831	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	834	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	825	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	853	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	824	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	862	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	945	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	915	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	945	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	903	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	825	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	827	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	829	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	798	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	785	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	773	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	798	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	783	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	726	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	648	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	814	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	819	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	801	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	772	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	851	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	841	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	794	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	834	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	791	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	765	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	696	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	747	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	695	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	696	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	746	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	733	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	673	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	703	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	727	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	760	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	763	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	744	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	771	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	749	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	722	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	767	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	802	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	785	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	727	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	875	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	897	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	977	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	994	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1042	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1051	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1068	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	1082	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:53:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1048	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	984	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	954	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	945	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	925	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	958	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	903	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	822	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	792	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	776	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	732	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	818	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	798	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	759	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	725	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	727	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	747	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	766	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	769	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	738	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	779	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	792	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	688	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	814	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	795	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	901	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	854	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	830	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	851	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	850	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	825	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	794	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	760	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	39	740	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	722	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	721	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	677	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	693	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	791	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	842	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	798	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	738	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	749	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	744	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	741	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	705	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	766	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	804	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	784	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	809	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	769	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	702	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	716	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	831	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	859	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	925	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	909	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	882	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	908	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	855	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:54:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	864	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	838	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	826	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	751	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	767	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	771	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	829	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	827	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	805	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	812	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	829	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	787	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	786	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	753	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	786	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	782	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	814	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	786	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	762	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	769	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	837	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	779	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	802	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	833	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	810	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	791	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	802	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	821	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	848	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	825	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	773	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	782	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	796	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	736	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	725	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	743	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	750	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	755	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	739	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	832	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	837	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	850	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	791	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	712	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	735	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	765	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	790	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	753	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	775	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	788	Poured Concrete
Building 2540	3	Scan	Survey Unit 03	"	6/12/2012	3:55:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	767	Poured Concrete
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:19:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1068	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:19:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1046	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:19:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1148	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:19:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1167	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:19:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1185	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:19:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1176	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:19:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1145	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:19:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1179	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:19:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1177	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:19:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1121	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:19:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1112	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:19:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1083	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:19:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1015	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:19:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1110	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:19:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1068	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:19:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1051	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:19:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1117	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:19:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1064	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:19:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	952	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:19:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	974	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:19:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	914	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:19:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	958	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:19:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1001	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:19:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1017	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:19:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1004	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1002	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	978	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	918	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	936	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	999	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1015	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1075	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1124	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1047	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1066	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1068	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	1093	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	1099	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1093	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	1113	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1144	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1156	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1222	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1227	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1186	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1110	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	39	1105	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	1144	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	1131	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	1055	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1105	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1102	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1051	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	48	1038	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	50	1083	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	53	1101	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	43	1142	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	1232	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	40	1204	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	43	1265	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	45	1221	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	1219	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	1236	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1323	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1266	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1208	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1115	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1087	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1028	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1106	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1157	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1061	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1029	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1042	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1060	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1084	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1064	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1057	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1047	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1088	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1155	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1138	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1055	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	946	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:20:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	923	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	995	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	963	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	929	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	935	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1050	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1045	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1096	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1083	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1049	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1044	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1048	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1054	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1022	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	976	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1020	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	986	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1040	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1000	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1025	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	999	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1005	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1064	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1049	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1127	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1155	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1119	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1019	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	992	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1008	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	919	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	907	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	913	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	951	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	920	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	961	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1036	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1030	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	957	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	955	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	946	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	937	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	987	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	913	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	912	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	841	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	873	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	936	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1040	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1014	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	997	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	978	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	991	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1065	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1080	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1038	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1098	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1115	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1041	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	968	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:21:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	922	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	882	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	849	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	871	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	830	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	899	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	795	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	791	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	765	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	754	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	748	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	754	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	855	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	854	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	838	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	931	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	947	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	984	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1014	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	1018	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1020	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	987	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	984	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1046	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	948	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	931	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	871	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	863	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	883	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	872	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	855	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	888	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	881	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	847	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	846	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	778	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	712	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	756	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	750	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	701	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	753	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	735	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	817	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	808	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	797	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	888	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	869	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	900	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	900	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	831	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	900	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	896	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	940	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	875	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	859	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	922	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	860	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	873	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	810	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	893	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:22:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	837	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	932	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	947	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	939	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	38	920	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	43	961	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	45	968	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	964	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	872	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	797	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	807	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	791	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	768	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	747	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	729	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	703	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	627	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	635	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	665	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	596	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	566	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	583	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	585	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	608	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	664	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	721	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	709	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	724	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	869	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	888	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	902	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	949	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	921	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	860	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	854	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	805	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	754	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	750	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	732	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	674	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	844	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	902	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	899	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	856	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	854	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	840	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	888	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	840	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	840	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	890	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	962	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	908	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	904	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	960	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	903	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	923	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	916	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	881	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	841	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	852	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:23:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	917	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	982	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	957	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	937	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	871	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	819	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	807	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	810	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	860	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	877	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	893	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	838	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	837	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	792	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	755	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	723	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	750	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	749	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	768	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	769	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	768	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	750	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	763	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	823	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	860	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	867	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	863	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	858	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	852	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	918	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	867	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	951	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	917	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	882	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	865	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	888	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	947	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	847	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	811	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	850	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	927	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	944	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	935	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	964	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	964	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	896	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	968	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	963	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	920	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	972	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	912	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	980	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	944	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	889	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	843	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	799	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	827	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	841	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	795	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	782	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:24:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	871	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	901	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	959	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	937	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	920	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	845	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	810	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	795	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	805	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	809	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	804	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	798	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	789	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	767	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	681	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	679	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	755	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	762	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	788	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	765	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	719	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	856	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	945	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	894	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	849	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	860	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	856	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	818	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	877	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	850	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	794	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	803	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	766	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	766	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	700	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	670	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	706	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	707	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	695	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	711	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	757	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	832	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	751	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	734	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	825	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	819	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	918	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	914	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	912	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	970	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1053	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	982	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	945	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	879	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	836	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	830	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	806	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	847	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	823	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	826	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:25:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	830	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:26:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	853	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:26:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	858	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:26:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	798	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:26:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	751	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:26:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	699	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:26:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	645	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:26:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	661	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:26:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	743	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:26:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	828	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:26:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	786	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:26:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	787	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:26:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	764	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:26:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	817	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:26:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	802	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:26:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	840	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:26:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	828	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:26:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	908	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:26:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	871	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:26:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	832	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:26:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	872	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:26:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	888	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:26:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	865	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:26:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	918	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:26:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	892	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:26:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	838	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:26:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	954	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:26:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	956	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:26:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	877	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:26:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	902	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:26:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	912	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:26:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	910	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:26:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	851	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:26:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	825	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:26:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	829	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:26:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	886	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:26:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	940	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:26:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	929	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1054	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1078	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1217	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1146	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1138	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1067	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1036	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1024	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1070	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1028	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1082	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1095	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1083	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1124	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1072	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1018	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1042	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1027	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1046	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1026	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	944	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	982	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	945	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	968	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1065	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	40	1140	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	1127	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1081	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1079	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1058	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	1055	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	990	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1056	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	977	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	988	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	40	1086	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	1038	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	968	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	982	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	39	1011	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	1127	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	1121	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1076	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1045	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1033	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1032	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	983	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1023	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:33:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1003	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1026	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	945	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	901	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	911	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	933	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	939	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1055	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1026	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	973	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	980	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	986	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	979	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1042	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1175	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1150	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1134	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1117	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1155	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1177	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1144	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1044	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1066	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1158	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1084	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1099	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	978	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1086	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1131	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1112	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1028	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1016	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	995	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	918	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	981	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1050	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1037	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1033	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1074	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1075	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1066	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1057	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1016	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1022	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	930	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	950	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1013	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1025	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	990	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	994	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	963	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	941	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	953	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	964	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	969	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	945	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	862	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	882	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	965	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1002	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:34:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1025	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1075	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1129	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1081	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1118	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1142	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1130	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1213	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1141	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1141	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1138	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1092	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1009	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	966	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	964	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	907	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	825	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	874	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	899	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	897	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	969	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	945	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	976	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	940	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	945	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1003	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	994	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	943	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	957	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	991	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	987	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	980	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1002	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1046	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	917	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	950	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	940	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	918	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	956	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	934	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	948	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1017	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	936	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1009	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1067	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1114	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1142	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1214	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1142	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1070	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1089	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	948	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	916	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	947	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	891	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	893	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	932	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	881	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	888	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	856	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:35:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	875	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	881	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	884	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	941	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	976	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	973	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	992	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	983	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	1011	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	1045	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	39	1090	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	1045	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	1086	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	1098	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	1127	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1016	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	972	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	1059	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	42	1121	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	1089	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	995	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1112	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1202	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1121	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1157	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	1164	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1125	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1068	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1060	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1133	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1123	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1035	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1060	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1078	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1094	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1104	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1053	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1051	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1009	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1068	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1061	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1006	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1017	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	36	1005	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	1087	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1041	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1058	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1039	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1053	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1072	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1110	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1038	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	999	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	972	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1012	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1013	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	923	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	951	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	997	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1014	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:36:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1080	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	991	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	996	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	989	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1033	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1044	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1001	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1016	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1018	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	994	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1009	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1010	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1080	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1045	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1056	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	948	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	938	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	921	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	884	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	971	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1039	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	979	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1017	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1005	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	995	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	932	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	966	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	941	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	899	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	954	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	999	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	938	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	908	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	920	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	949	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1012	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	988	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	967	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	954	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	965	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	936	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	957	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	969	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	962	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	923	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	930	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	902	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	857	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	784	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	756	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	806	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	866	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	883	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	872	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	855	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	832	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	847	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	754	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	793	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	778	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:37:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	846	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	797	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	829	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	852	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	870	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	881	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	848	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	861	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	813	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	874	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	936	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	838	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	852	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	863	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	910	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1015	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	974	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	948	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	915	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	912	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	887	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	979	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	875	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	903	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	880	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	827	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	806	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	757	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	803	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	845	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	911	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	952	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	933	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	986	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	971	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	887	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	955	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	908	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	913	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	954	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	920	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	926	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	874	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	893	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	929	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	867	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	919	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	943	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	936	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	977	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	977	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	994	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	966	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	930	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	912	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1013	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	972	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	913	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	922	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1104	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:38:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1163	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1115	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1108	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1099	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1080	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	954	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	967	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1095	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1045	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	1029	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1075	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1103	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1087	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1202	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	1159	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1252	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1224	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1172	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1188	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1088	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1018	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	973	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1014	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1073	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1043	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1153	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1139	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1127	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1096	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1049	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1080	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1065	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1126	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1149	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1158	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1112	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1002	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1016	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1040	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	945	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	961	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	961	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	952	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	896	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	942	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	865	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	914	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	877	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	912	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	931	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	915	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	934	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	915	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	886	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	908	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	929	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	958	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	904	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	960	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	915	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:39:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	868	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	899	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	867	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	955	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1026	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	1001	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	994	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	36	951	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	894	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	918	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	957	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	948	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	880	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	42	849	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	861	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	858	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	925	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	969	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	991	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	995	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1109	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1124	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1093	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1100	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1059	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1061	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1097	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1035	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1094	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1047	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	970	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1014	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1011	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1023	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1035	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1121	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1042	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	968	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	996	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1071	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1134	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1079	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1080	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1046	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	970	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	959	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	970	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	925	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1003	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	981	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	968	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	923	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	887	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	842	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	927	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	977	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1062	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1076	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1141	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1207	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:40:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1199	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1139	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1183	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1172	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1132	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1121	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	999	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1073	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1041	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1014	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	958	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	975	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	940	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	884	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	892	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	850	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	780	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	745	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	762	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	786	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	774	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	776	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	879	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	856	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	897	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	861	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	892	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	927	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	958	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	958	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	41	945	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	1017	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	974	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1038	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	1045	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	990	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	918	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	946	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	947	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	860	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	833	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	857	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	957	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	978	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	916	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	885	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	909	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	911	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	952	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	988	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	918	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	945	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	923	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	931	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1030	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1005	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	973	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1045	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1061	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1006	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:41:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1055	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1013	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	947	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	881	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	825	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	839	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	839	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	746	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	696	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	644	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	750	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	814	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	856	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	915	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	951	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1008	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1046	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	986	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	963	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1055	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	983	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1025	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1013	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1025	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	976	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1017	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	958	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	982	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1046	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1008	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1000	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	981	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1004	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	984	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	977	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	997	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1034	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1075	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1038	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1001	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	945	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	984	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1021	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1065	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	967	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1011	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	920	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	928	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	889	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	903	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	926	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	943	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1015	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1073	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1028	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1026	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1015	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1049	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1087	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1053	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:42:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1105	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1079	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1078	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1030	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	993	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1012	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1038	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1114	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1085	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1026	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1094	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1094	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1135	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1087	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1095	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1015	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	982	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1003	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1008	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1000	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	949	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	920	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	889	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	938	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	971	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1060	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1046	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	959	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	1009	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	941	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	877	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	844	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	843	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	842	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	878	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	880	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	875	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	892	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	904	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	901	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	832	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	856	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	909	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	999	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	969	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1038	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1080	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1133	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1104	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1078	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1030	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1014	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1004	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1008	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1031	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1057	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1025	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1035	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1012	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	943	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:43:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	935	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1008	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1042	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	982	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1002	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1049	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1003	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	958	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1038	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	990	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	982	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	908	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	840	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	797	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	853	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:14 PM	1.00	Ludlum 43-37-1 (SN 136361)	821	20	791	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	868	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	895	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1021	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1027	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1003	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	987	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	962	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	973	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	999	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	934	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	881	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	907	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	850	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	913	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	864	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	956	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1035	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1044	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1051	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	978	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	934	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	1048	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	984	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	41	969	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	932	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	997	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1034	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	976	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	919	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	950	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	908	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	925	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	900	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	869	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	886	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	949	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	42	941	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	918	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	961	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	976	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	997	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	945	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	983	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	998	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:44:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	924	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	942	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	887	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	831	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	940	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1002	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	971	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	970	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	971	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1036	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1036	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	986	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	990	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	997	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1128	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1060	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1076	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1120	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1123	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1088	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1106	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1057	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1076	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1034	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1049	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	987	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1040	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	1059	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1028	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1005	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1030	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	972	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1086	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1004	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1004	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	965	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	906	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	932	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1008	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	950	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	954	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	982	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	990	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1010	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1025	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1048	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1067	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1033	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1011	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1066	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1126	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1066	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1079	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1164	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	1151	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1093	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1100	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	1053	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1024	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1013	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:45:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1100	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1016	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	973	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	968	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	933	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	951	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	992	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1036	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1036	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1030	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	994	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	951	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1080	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1093	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1068	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1038	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1058	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1099	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1056	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1093	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1125	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1071	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1038	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1035	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	994	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1001	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	934	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	939	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	899	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	918	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	950	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	994	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	974	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	920	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	836	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	903	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	916	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	891	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	924	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	888	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	923	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	985	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	995	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	954	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	987	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1047	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1018	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1053	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1039	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	965	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	986	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	994	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	956	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	935	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	964	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1033	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	961	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1031	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1066	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1036	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:46:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	985	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:47:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1129	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:47:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1037	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:47:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	943	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:47:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	945	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:47:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	937	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:47:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	859	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:47:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	871	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:47:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	810	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:47:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	848	Laminate Tile
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:51:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	982	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:51:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1026	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:51:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	969	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:51:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	948	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:51:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	942	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:51:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	976	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:51:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1063	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:51:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1065	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:51:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1025	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:51:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1071	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:51:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1049	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:51:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1087	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:51:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1039	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:51:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1062	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:51:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1092	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:51:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1065	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:52:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1103	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:52:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1140	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:52:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1140	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:52:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1142	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:52:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1119	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:52:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1120	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:52:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1106	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:53:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1007	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:53:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	914	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:53:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	935	Carpet

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:53:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	858	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:53:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	925	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:53:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	940	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:53:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	910	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:53:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	887	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:53:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	951	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:53:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	995	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:53:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	957	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:53:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	900	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:53:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	863	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:53:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	885	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:53:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	874	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:53:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	982	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:53:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1000	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:53:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1048	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:53:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1046	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:53:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1017	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:53:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1055	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:53:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	978	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:53:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	939	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:53:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	900	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:53:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	920	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:53:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	953	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:53:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	864	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:53:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	962	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:53:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	942	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:53:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	901	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:53:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	845	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	885	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	862	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	821	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	957	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	923	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	981	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1004	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	975	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	984	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1026	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1013	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1002	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1060	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	982	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1171	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1140	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1062	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	999	Carpet

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	957	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	912	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	926	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	865	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	920	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	928	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	865	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	812	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	808	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	857	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	796	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	826	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	772	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	761	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	867	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	873	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	913	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	867	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	895	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	899	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	925	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	888	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	883	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	870	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	854	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	972	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	956	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1024	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1038	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1009	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	977	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	929	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	901	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	966	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1000	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	971	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1002	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	959	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	881	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	885	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	842	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:54:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	899	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	969	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	949	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	955	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	931	Carpet

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	970	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1084	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1071	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1075	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1064	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1059	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1036	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	933	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	918	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	846	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	776	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	766	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	814	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	896	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	954	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	907	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	882	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	914	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	900	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	926	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	920	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	931	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	843	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	876	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	845	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	903	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	866	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	941	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1015	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	936	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	968	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	945	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	944	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	833	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	917	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	919	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	941	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	936	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	851	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	904	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	983	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	930	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	887	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	854	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	852	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	982	Carpet

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	989	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	904	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	883	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	966	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	943	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	937	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	954	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	955	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	919	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:55:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	881	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	882	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	896	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	922	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	988	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	980	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	988	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	937	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	871	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	843	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	915	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	943	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	891	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	951	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	882	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	806	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	824	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	838	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	880	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	941	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	912	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	873	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	898	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	986	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	903	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	913	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	934	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	961	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	997	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	979	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	990	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1039	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	913	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	913	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	910	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	871	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	900	Carpet

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	921	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	950	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	907	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	916	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	856	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	885	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	985	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	992	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	951	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1009	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1048	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1103	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1110	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1077	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1058	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	972	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	843	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	762	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	778	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	776	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	880	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	906	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	880	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:56:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	870	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	817	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	833	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	844	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	821	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	775	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	826	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	876	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	859	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	888	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	911	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	911	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	935	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	943	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	993	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	948	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	984	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	935	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	825	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	827	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	923	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	917	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	880	Carpet

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	859	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	866	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	850	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	894	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	918	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	994	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	999	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1015	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	977	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1040	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1045	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1041	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1105	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	1111	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1094	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	1064	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1039	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1059	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	38	1016	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	42	971	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	978	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	983	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	923	Carpet
Building 2540	6	Scan	Survey Unit 06	"	6/13/2012	2:57:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	882	Carpet
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	559	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	543	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	528	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	531	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	549	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	568	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	567	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	585	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	623	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	700	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	623	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	639	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	621	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	595	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	584	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	587	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	612	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	611	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	599	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	634	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	602	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	566	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	527	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	553	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	629	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	657	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	656	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	633	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	592	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	639	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	656	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	633	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	675	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	683	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	728	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	727	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	723	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	689	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	705	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	742	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	808	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	795	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	771	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	738	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	747	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	815	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	810	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	757	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	771	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	727	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	647	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	593	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	638	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	620	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	607	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	584	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	588	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	581	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:25:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	630	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	635	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	618	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	593	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	586	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	519	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	545	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	545	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	543	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	508	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	456	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	493	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	490	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	502	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	571	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	576	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	637	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	653	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	652	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	661	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	651	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	707	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	697	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	693	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	684	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	622	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	617	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	659	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	647	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	663	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	629	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	650	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	747	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	753	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	758	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	726	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	693	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	685	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	681	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	644	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	577	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	579	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	546	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	593	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	629	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	625	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	619	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	640	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	631	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	670	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	600	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	601	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	602	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	611	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	578	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	607	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	629	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	612	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	599	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	588	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:26:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	617	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	633	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	592	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	593	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	549	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	638	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	638	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	620	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	547	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	567	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	560	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	533	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	592	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	583	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	551	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	538	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	536	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	503	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	570	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	521	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	522	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	538	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	615	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	689	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	674	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	670	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	690	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	664	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	662	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	639	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	622	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	631	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	602	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	579	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	537	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	568	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	541	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	507	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	548	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	591	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	582	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	629	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	656	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	677	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	628	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	610	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	539	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	526	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	559	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	556	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	519	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	570	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	588	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	601	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	554	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	564	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	616	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	534	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	465	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	501	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:27:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	509	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	489	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	500	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	489	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	511	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	528	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	581	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	576	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	569	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	560	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	579	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	570	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	540	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	529	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	599	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	564	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	570	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	625	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	573	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	579	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	596	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	542	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	591	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	640	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	604	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	558	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	520	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	500	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	518	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	544	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	519	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	502	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	555	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	566	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	527	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	530	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	551	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	597	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	576	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	620	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	615	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	612	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	673	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	638	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	634	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	626	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	610	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	653	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	623	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	641	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	665	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	642	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	634	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	630	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	601	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	589	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	579	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	526	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	597	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	589	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:28:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	579	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	558	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	543	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	574	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	591	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	618	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	647	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	628	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	678	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	640	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	633	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	629	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	670	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	715	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	649	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	648	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	630	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	669	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	598	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	609	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	561	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	569	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	551	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	560	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	577	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	572	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	599	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	579	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	607	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	594	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	646	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	615	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	657	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	634	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	652	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	639	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	590	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	649	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	617	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	682	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	665	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	655	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	587	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	533	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	544	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	543	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	554	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	588	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	592	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	579	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	571	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	566	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	549	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	548	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	557	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	645	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	626	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	573	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	609	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	596	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:29:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	588	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	592	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	573	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	596	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	542	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	608	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	642	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	589	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	544	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	544	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	523	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	577	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	602	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	593	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	617	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	615	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	628	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	597	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	577	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	525	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	507	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	503	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	578	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	601	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	567	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	587	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	659	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	648	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	629	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	631	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	603	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	568	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	576	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	513	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	567	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	699	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	668	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	654	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	609	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	608	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	697	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	689	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	714	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	693	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	654	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	712	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	745	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	717	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	702	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	727	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	693	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	675	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	693	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	745	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	781	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	769	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	747	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	708	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	732	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	755	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:30:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	724	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	679	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	675	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	675	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	670	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	737	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	725	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	676	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	647	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	663	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	632	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	588	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	578	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	572	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	532	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	500	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	531	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	502	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	520	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	546	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	619	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	647	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	593	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	572	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	541	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	527	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	578	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	647	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	640	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	622	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	620	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	557	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	509	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	549	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	581	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	574	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	602	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	647	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	662	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	672	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	612	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	651	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	619	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	591	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	568	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	484	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	666	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	678	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	637	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	656	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	577	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	596	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	634	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	627	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	587	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	533	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	547	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	605	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	549	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	548	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:31:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	616	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	589	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	578	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	582	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	622	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	571	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	567	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	573	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	603	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	663	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	674	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	657	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	609	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	586	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	587	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	647	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	674	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	661	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	706	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	710	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	735	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	685	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	693	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	666	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	619	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	614	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	590	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	603	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	590	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	618	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	619	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	659	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	625	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	669	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	645	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	635	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	629	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	598	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	598	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	554	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	585	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	566	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	594	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	591	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	580	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	571	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	563	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	558	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	531	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	545	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	660	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	617	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	613	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	577	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	628	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	625	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	574	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	513	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	506	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	519	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:32:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	561	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	591	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	666	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	723	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	701	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	684	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	657	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	599	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	575	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	569	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	643	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	635	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	559	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	605	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	647	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	721	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	664	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	652	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	629	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	645	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	606	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	595	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	651	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	628	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	621	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	603	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	580	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	610	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	597	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	596	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	573	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	634	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	615	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	613	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	595	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	621	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	595	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	561	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	487	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	486	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	519	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	512	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	471	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	495	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	480	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	514	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	519	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	547	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	523	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	535	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	501	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	521	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	543	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	597	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	641	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	579	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	537	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	491	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	537	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	583	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:33:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	629	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	611	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	666	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	645	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	668	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	645	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	684	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	680	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	700	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	705	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	661	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	672	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	694	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	710	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	698	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	705	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	662	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	651	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	634	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	595	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	691	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	694	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	754	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	757	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	691	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	709	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	664	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	661	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	627	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	564	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	606	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	637	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	619	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	652	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	628	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	625	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	597	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	643	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	656	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	629	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	555	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	588	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	543	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	551	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	581	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	617	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	617	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	593	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	620	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	594	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	660	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	613	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	598	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	597	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	665	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	711	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	691	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	709	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	711	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	688	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:34:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	705	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	660	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	684	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	702	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	673	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	648	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	660	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	666	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	629	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	636	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	631	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	625	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	641	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	655	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	38	734	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	675	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	753	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	721	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	707	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	707	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	732	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	797	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	781	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	689	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	671	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	615	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	672	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	657	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	656	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	612	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	596	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	618	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	594	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	586	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	591	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	601	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	597	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	573	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	532	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	627	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	677	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	663	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	617	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	671	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	751	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	743	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	681	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	665	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	641	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	623	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	595	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	562	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	569	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	599	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	587	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	670	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	657	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	643	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	577	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	513	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:35:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	508	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	505	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	522	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	539	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	530	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	566	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	562	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	607	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	701	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	707	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	734	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	630	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	680	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	653	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	633	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	690	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	731	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	695	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	696	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	720	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	651	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	691	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	735	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	755	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	748	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	708	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	701	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	659	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	634	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	650	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	618	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	649	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	701	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	658	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	659	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	667	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	631	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	673	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	706	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	743	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	784	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	773	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	705	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	664	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	677	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	706	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	689	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	650	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	650	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	604	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	592	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	616	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	558	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	507	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	539	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	584	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	588	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	592	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	639	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	643	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:36:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	610	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	617	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	579	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	626	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	609	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	630	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	581	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	574	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	602	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	696	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	733	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	673	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	643	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	623	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	701	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	627	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	565	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	616	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	625	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	601	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	566	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	625	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	607	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	560	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	578	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	604	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	594	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	616	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	670	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	722	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	735	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	697	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	679	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	733	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	739	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	770	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	751	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	699	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	659	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	684	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	705	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	687	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	681	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	704	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	675	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	638	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	663	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	674	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	669	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	621	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	619	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	670	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	623	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	666	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	608	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	595	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	596	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	611	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	621	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	594	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:37:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	583	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	632	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	719	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	702	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	671	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	666	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	650	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	651	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	651	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	661	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	595	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	568	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	588	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	601	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	625	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	608	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	605	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	625	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	621	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	583	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	597	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	611	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	598	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	631	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	636	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	571	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	602	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	611	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	623	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	644	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	613	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	587	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	613	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	597	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	630	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	690	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	629	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	566	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	527	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	566	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	598	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	608	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	682	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	663	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	663	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	640	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	642	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	645	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	611	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	562	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	558	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	601	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	601	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	590	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	566	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	568	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	577	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	674	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	683	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	734	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:38:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	685	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	668	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	630	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	648	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	675	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	638	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	650	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	627	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	575	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	533	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	513	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	496	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	524	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	572	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	573	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	522	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	546	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	568	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	647	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	652	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	664	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	664	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	617	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	635	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	631	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	673	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	649	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	687	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	646	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	706	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	628	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	579	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	562	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	582	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	540	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	585	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	666	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	677	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	685	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	738	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	736	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	675	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	659	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	627	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	634	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	687	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	683	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	716	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	659	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	593	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	594	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	560	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	570	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	626	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	621	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	607	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	560	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	543	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	576	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	534	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:39:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	579	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	580	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	583	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	599	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	587	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	576	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	648	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	650	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	595	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	597	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	576	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	557	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	498	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	486	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	519	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	607	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	548	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	524	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	585	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	569	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	495	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	549	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	572	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	705	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	674	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	614	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	614	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	599	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	611	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	669	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	667	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	675	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	672	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	650	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	584	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	572	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	588	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	647	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	604	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	618	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	614	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	613	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	623	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	597	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	611	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	674	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	744	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	717	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	673	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	675	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	704	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	663	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	640	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	596	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	588	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	671	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	783	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	693	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	673	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	657	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:40:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	644	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	690	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	663	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	685	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	749	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	733	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	706	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	674	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	660	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	695	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	711	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	740	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	723	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	698	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	702	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	660	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	670	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	677	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	712	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	736	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	701	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	701	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	731	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	728	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	782	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	749	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	653	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	585	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	636	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	641	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	680	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	675	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	643	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	620	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	649	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	595	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	584	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	669	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	665	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	663	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	706	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	710	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	713	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	714	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	693	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	632	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	682	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	656	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	686	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	712	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	702	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	783	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	848	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	791	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	764	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	765	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	782	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	735	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	689	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	612	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:41:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	629	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:42:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	609	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:42:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	36	642	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:42:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	622	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:42:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	549	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:42:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	675	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:42:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	637	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:42:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	665	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:42:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	651	Poured Concrete
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:43:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	492	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:43:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	525	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:43:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	539	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:43:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	505	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:43:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	479	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:43:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	457	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:43:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	483	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:43:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	516	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:43:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	519	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:43:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	580	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:43:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	581	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:43:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	562	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	521	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	514	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	473	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	465	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	478	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	469	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	468	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	517	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	523	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	491	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	455	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	437	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	422	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	444	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	452	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	502	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	519	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	537	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	550	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	549	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	525	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	573	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	603	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	570	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	597	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	530	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	545	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	500	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	531	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	486	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	464	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	464	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	469	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	485	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	460	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	474	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	510	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	471	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	439	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	456	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	413	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	424	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	402	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	488	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	474	Laminate Tile
Building 2540	12	Scan	Survey Unit 12	"	6/12/2012	4:44:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	476	Laminate Tile
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	527	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	559	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	615	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	623	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	639	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	664	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	595	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:22 AM	1.00	Ludlum 43-37-1 (SN 136361)	821	18	562	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	590	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	511	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	493	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	572	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	555	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	617	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	705	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	779	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	849	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	810	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	757	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	668	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	653	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	631	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	591	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	653	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	691	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	693	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	730	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	705	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	684	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	712	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	691	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	707	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	722	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	654	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	621	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	649	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	652	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	598	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	594	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	607	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	632	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	649	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	650	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	573	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:07:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	592	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	605	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	579	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	572	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	730	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	694	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	735	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	757	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	805	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	743	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	758	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	770	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	753	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	737	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	813	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	763	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	742	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	715	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	657	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	677	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	649	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	595	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	608	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	569	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	574	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	600	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	642	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	598	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	649	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	608	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	615	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	612	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	577	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	559	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	556	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	552	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	558	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	532	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	521	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	446	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	439	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	424	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	435	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	466	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	436	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	486	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	484	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	461	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	454	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	490	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	596	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	608	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	586	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	531	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	537	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	522	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	526	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	529	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	534	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	523	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:08:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	528	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	521	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	524	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	536	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	537	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	515	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	541	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	539	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	662	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	626	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	621	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	639	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	573	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	600	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	649	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	626	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	634	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	651	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	631	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	604	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	679	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	667	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	608	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	607	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	628	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	589	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	615	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	667	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	598	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	589	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	590	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	638	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	561	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	605	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	570	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	589	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	646	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	684	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	657	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	634	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	664	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	641	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	648	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	663	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	649	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	719	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	745	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	749	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	765	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	720	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	732	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	787	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	790	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	705	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	764	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	778	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	767	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	782	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	763	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	766	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:09:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	720	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	729	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	661	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	671	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	680	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	634	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	603	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	577	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	615	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	692	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	727	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	682	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	728	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	738	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	760	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	707	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	685	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	717	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	695	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	709	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	678	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	618	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	605	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	638	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	656	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	687	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	656	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	660	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	674	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	658	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	612	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	622	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	687	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	702	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	720	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	718	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	764	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	812	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	784	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	814	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	840	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	770	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	725	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	750	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	804	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	802	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	760	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	766	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	780	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	709	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	699	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	701	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	729	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	682	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	677	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	741	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	725	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	746	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	753	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	748	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:10:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	686	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	737	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	721	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	688	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	703	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	764	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	742	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	746	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	752	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	718	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	641	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	669	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	723	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	743	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	737	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	765	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	806	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	776	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	697	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	647	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	638	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	639	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	586	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	622	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	631	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	577	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	637	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	641	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	631	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	659	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	648	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	673	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	640	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	619	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	684	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	668	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	608	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	711	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	655	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	643	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	669	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	663	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	640	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	737	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	783	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	764	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	786	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	720	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	676	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	694	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	723	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	804	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	774	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	787	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	753	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	678	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	718	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	715	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	670	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	670	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:11:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	699	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	691	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	739	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	757	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	760	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	729	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	741	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	780	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	750	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	632	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	634	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	685	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	646	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	683	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	680	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	670	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	659	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	613	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	623	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	641	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	635	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	649	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	653	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	655	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	714	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	766	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	780	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	837	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	817	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	728	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	787	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	751	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	781	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	795	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	780	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	725	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	643	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	655	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	653	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	675	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	694	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	663	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	667	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	700	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	725	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	656	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	655	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	667	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	696	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	699	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	706	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	699	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	723	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	746	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	728	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	749	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	689	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	778	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	742	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	714	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:12:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	706	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	631	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	615	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	602	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	569	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	666	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	651	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	652	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	688	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	727	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	797	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	842	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	761	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	753	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	755	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	668	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	677	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	709	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	655	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	620	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	591	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	567	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	596	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	638	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	699	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	655	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	576	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	591	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	617	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	629	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	624	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	651	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	604	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	589	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	556	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	604	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	579	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	571	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	519	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	510	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	530	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	520	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	557	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	578	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	617	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	670	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	656	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	602	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	601	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	589	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	637	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	607	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	609	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	615	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	658	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	708	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	676	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	707	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	675	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	692	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:13:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	675	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	705	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	721	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	687	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	749	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	756	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	761	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	773	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	738	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	690	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	706	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	768	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	747	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	767	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	745	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	696	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	691	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	639	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	624	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	606	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	664	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	707	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	709	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	745	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	810	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	736	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	690	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	735	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	697	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	751	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	723	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	643	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	609	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	559	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	580	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	527	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	505	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	61	499	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	60	495	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	61	577	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	49	625	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	662	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	559	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	604	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	561	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	579	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	629	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	646	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	676	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	730	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	705	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	616	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	590	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	615	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	599	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	575	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	581	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	539	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	589	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	535	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:14:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	531	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	544	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	676	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	684	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	714	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	692	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	688	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	645	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	650	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	688	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	648	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	662	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	745	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	731	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	749	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	730	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	729	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	659	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	727	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	712	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	739	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	729	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	738	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	664	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	654	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	633	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	663	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	605	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	603	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	600	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	608	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	683	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	700	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	656	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	632	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	672	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	704	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	696	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	758	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	785	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	748	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	832	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	789	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	730	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	684	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	685	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	727	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	704	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	617	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	645	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	616	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	613	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	667	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	630	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	633	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	659	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	49	714	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	763	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	744	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	648	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:15:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	684	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	712	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	677	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	652	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	656	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	579	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	546	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	592	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	560	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	580	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	617	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	616	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	566	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	573	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	608	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	636	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	662	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	720	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	740	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	722	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	767	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	759	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	750	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	740	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	705	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	744	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	719	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	726	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	714	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	781	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	735	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	710	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	653	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	712	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	734	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	778	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	790	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	773	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	765	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	805	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	756	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	737	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	734	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	753	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	749	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	754	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	714	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	690	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	673	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	636	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	629	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	615	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	600	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	587	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	682	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	802	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	806	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	734	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	706	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	776	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:16:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	779	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	712	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	680	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	643	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	636	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	698	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	729	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	692	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	742	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	761	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	706	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	673	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	704	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	682	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	662	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	686	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	680	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	607	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	596	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	597	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	668	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	726	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	722	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	709	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	675	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	633	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	612	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	563	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	583	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	538	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	563	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	615	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	632	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	618	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	592	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	650	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	697	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	723	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	702	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	728	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	706	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	653	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	653	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	628	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	689	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	635	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	628	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	614	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	656	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	658	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	656	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	657	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	647	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	636	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	641	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	690	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	662	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	764	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	793	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	839	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:17:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	757	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	761	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	718	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	757	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	737	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	743	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	706	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	699	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	647	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	647	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	672	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	698	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	760	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	673	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	727	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	690	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	751	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	792	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	753	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	756	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	725	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	713	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	714	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	702	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	691	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	765	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	725	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	759	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	716	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	741	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	714	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	738	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	737	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	741	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	739	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	732	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	720	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	733	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	756	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	828	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	764	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	776	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	835	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	811	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	802	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	751	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	813	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	752	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	803	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	786	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	705	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	685	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	677	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	673	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	670	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	713	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	727	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	705	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	718	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	752	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:18:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	746	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	832	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	798	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	819	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	764	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	742	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	758	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	743	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	678	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	762	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	815	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	815	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	786	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	729	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	693	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	654	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	653	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	623	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	688	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	670	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	666	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	643	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	703	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	748	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	836	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	777	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	779	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	779	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	821	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	788	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	796	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	790	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	764	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	744	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	690	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	744	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	720	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	744	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	727	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	733	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	708	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	691	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	731	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	752	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	779	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	733	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	672	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	614	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	600	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	589	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	556	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	531	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	520	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	467	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	468	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	505	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	581	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	666	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	654	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	632	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:19:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	580	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	596	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	663	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	660	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	680	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	663	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	606	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	644	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	635	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	696	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	686	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	683	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	686	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	671	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	725	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	726	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	690	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	744	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	730	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	684	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	670	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	644	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	601	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	622	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	606	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	547	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	588	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	628	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	645	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	638	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	645	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	612	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	599	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	598	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	667	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	642	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	746	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	739	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	713	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	679	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	753	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	713	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	645	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	780	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	757	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	704	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	691	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	638	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	597	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	655	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	702	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	709	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	653	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	610	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	713	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	689	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	748	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	697	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	723	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	722	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:20:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	778	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	699	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	748	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	708	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	757	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	807	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	851	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	927	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	842	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	817	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	865	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	848	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	866	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	806	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	765	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	736	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	771	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	795	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	794	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	798	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	853	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	861	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	865	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	846	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	825	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	796	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	800	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	898	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	877	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	971	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	1002	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	1048	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	995	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	1054	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	1027	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	966	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	996	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1092	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1053	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	997	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	945	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	922	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	961	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	938	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	912	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	1001	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	1014	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1044	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	972	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	986	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	974	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	973	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	902	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	776	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	709	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	658	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	624	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	648	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	637	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	676	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:21:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	625	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	598	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	562	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	628	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	634	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	666	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	642	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	717	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	727	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	762	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	743	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	748	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	813	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	782	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	805	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	835	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	789	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	742	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	728	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	749	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	779	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	734	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	780	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	768	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	863	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	858	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	867	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	828	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	786	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	801	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	776	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	784	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	795	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	764	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	767	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	758	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	716	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	717	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	800	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	901	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	854	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	792	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	733	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	748	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	744	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	696	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	757	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	683	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	611	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	643	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	657	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	735	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	685	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	722	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	758	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	726	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	745	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	819	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	743	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	749	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:22:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	734	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	732	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	779	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	781	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	723	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	710	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	711	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	691	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	725	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	716	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	680	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	677	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	761	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	764	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	699	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	796	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	817	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	810	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	725	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	690	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	729	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	762	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	746	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	705	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	639	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	632	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	590	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	611	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	631	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	683	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	758	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	746	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	709	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	675	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	715	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	796	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	814	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	923	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	926	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	1011	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	1036	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	1035	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	994	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	1023	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	1077	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1055	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	1037	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	1059	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1073	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	1050	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	979	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	915	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	919	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	905	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	858	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	787	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	754	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	713	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	680	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	689	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:23:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	707	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	755	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	749	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	802	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	846	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	774	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	817	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	823	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	804	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	825	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	804	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	722	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	717	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	710	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	680	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	712	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	681	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	710	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	732	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	719	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	697	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	689	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	700	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	786	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	819	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	744	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	731	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	726	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	745	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	801	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	726	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	713	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	737	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	805	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	788	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	763	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	769	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	725	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	712	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	656	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	600	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	657	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	684	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	656	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	687	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	680	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	710	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	711	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	678	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	743	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	769	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	773	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	783	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	815	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	753	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	800	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	737	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	700	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	775	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	698	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:24:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	722	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:25:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	697	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:25:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	700	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:25:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	656	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:25:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	586	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:25:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	648	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:25:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	750	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:25:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	770	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:25:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	804	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:25:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	755	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:25:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	792	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:25:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	746	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:25:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	763	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:25:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	812	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:25:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	850	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:25:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	806	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:25:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	792	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:25:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	746	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:25:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	800	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:25:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	851	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:25:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	862	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:25:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	811	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:25:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	849	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:25:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	744	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:25:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	777	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:25:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	763	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:25:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	663	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:25:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	617	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:27:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	663	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:27:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	626	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:27:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	586	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:27:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	579	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:27:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	535	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:27:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	605	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:27:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	591	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:27:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	581	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:27:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	561	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:27:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	545	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:27:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	614	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:27:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	603	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:27:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	602	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:27:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	532	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:27:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	580	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:27:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	641	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:27:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	671	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:27:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	664	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:27:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	736	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	718	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	707	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	776	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	775	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	838	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	814	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	811	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	847	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	810	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	768	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	757	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	725	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	679	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	759	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	729	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	679	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	675	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	695	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	780	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	736	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	770	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	785	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	816	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	800	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	715	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	682	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	656	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	601	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	598	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	598	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	576	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	615	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	626	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	680	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	745	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	726	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	736	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	708	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	732	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	719	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	754	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	725	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	746	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	789	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	765	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	735	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	723	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	765	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	711	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	690	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	807	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	753	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	689	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	695	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	701	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	667	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	736	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	756	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	724	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:28:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	699	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	688	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	728	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	688	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	761	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	753	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	796	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	785	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	738	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	749	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	699	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	736	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	710	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	715	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	692	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	697	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	677	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	640	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	624	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	584	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	566	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	604	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	616	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	704	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	730	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	713	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	705	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	629	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	624	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	598	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	598	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	552	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	593	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	527	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	569	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	574	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	591	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	558	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	589	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	615	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	637	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	645	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	626	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	624	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	654	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	724	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	688	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	697	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	748	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	722	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	723	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	743	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	730	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	763	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	742	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	693	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	699	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	758	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	830	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	798	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:29:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	751	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:30:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	711	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:30:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	693	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:30:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	675	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:30:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	614	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:30:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	666	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:30:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	699	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:30:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	644	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:30:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	614	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:30:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	591	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:30:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	606	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:30:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	618	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:30:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	605	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:30:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	570	Concrete Block
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	765	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	783	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	794	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	756	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	695	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	710	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	724	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	689	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	696	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	703	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	706	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	700	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	747	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	694	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	674	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	602	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	569	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	598	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	574	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	588	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	568	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	585	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	644	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	681	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	688	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	731	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	717	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	637	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	660	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	720	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	745	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	808	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	883	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	908	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	862	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	904	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	891	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	961	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	941	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:33:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	966	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	915	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	846	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	822	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	732	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	716	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	692	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	663	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	694	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	687	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	668	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	702	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	703	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	674	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	682	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	712	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	659	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	700	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	681	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	645	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	602	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	648	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	640	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	679	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	697	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	710	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	631	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	650	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	730	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	727	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	681	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	711	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	666	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	653	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	680	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	718	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	706	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	730	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	730	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	714	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	670	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	655	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	633	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	728	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	738	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	749	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	664	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	719	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	776	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	722	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	709	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	688	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	691	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	686	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	733	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	706	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	697	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	720	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	700	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	690	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:34:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	722	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	676	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	718	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	683	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	708	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	735	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	720	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	745	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	753	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	747	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	742	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	691	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	738	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	737	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	763	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	729	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	694	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	735	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	654	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	610	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	549	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	584	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	575	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	558	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	591	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	619	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	615	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	627	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	642	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	610	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	609	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	598	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	658	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	613	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	532	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	600	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	574	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	613	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	631	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	613	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	625	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	612	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	622	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	653	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	631	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	626	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	607	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	596	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	654	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	630	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	646	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	601	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	613	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	607	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	549	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	513	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	621	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	652	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	649	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	648	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:35:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	581	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	676	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	742	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	703	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	659	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	635	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	629	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	648	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	628	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	622	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	696	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	768	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	744	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	705	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	717	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	730	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	728	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	670	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	668	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	642	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	683	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	669	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	739	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	690	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	659	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	599	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	611	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	664	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	662	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	603	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	668	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	676	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	685	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	678	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	662	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	708	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	747	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	808	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	818	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	835	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	799	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	759	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	726	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	757	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	774	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	878	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	847	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	914	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1024	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	965	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	860	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	798	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	759	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	788	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	741	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	713	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	689	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	693	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	731	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	756	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:36:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	769	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	749	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	724	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	714	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	705	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	746	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	674	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	647	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	707	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	662	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	661	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	635	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	616	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	621	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	585	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	689	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	704	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	696	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	684	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	668	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	699	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	701	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	715	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	739	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	747	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	731	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	712	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	704	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	697	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	724	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	745	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	743	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	708	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	640	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	666	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	681	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	64	653	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	619	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	590	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	568	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	618	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	660	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	727	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	736	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	666	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	665	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	641	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	668	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	652	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	574	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	602	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	683	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	679	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	665	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	733	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	709	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	699	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	655	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	713	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	726	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:37:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	783	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:38:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	749	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:38:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	787	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:38:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	727	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:38:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	765	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:38:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	758	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:38:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	795	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:38:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	699	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:38:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	726	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:38:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	756	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:38:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	781	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:38:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	725	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:38:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	692	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:38:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	731	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:38:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	795	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:38:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	716	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:38:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	739	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:38:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	759	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:38:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	740	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:38:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	666	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:38:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	611	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:38:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	643	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:38:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	600	Poured Concrete
Building 2540	13	Scan	Survey Unit 13	"	6/13/2012	9:38:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	590	Poured Concrete
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	527	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	482	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	460	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	477	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	477	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	467	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	483	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	494	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	540	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	582	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	586	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	555	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	595	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	586	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	551	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	562	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	580	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	562	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	546	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	556	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	608	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	582	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	599	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	555	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	573	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	510	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	506	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	500	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	507	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	535	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	556	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	543	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	519	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	510	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	504	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	465	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	446	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	486	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	469	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	505	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	510	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	491	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	490	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	485	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:00:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	427	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	451	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	466	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	469	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	508	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	547	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	593	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	549	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	635	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	560	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	555	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	575	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	524	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	561	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	652	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	654	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	551	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	615	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	604	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	568	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	565	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	649	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	639	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	607	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	652	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	619	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	627	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	543	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	544	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	508	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	502	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	509	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	539	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	516	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	496	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	468	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	493	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	494	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	482	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	535	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	582	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	583	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	608	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	585	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	555	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	542	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	495	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	495	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	502	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	532	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	474	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	440	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	414	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	429	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	435	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	442	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	439	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	435	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	489	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	509	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:01:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	472	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	487	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	461	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	396	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	436	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	420	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	523	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	527	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	517	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	524	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	595	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	628	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	636	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	619	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	616	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	578	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	593	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	604	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	590	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	557	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	519	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	491	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	499	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	482	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	469	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	505	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	575	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	660	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	604	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	600	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	565	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	549	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	624	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	586	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	551	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	561	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	639	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	621	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	594	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	583	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	585	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	585	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	625	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	588	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	579	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	665	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	701	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	638	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	663	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	584	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	578	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	548	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	488	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	462	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	476	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	489	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	474	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	440	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	525	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	523	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:02:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	503	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	521	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	547	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	513	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	482	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	517	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	532	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	522	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	561	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	560	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	569	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	607	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	608	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	585	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	564	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	594	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	586	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	644	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	637	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	583	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	517	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	486	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	486	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	473	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	486	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	499	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	506	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	514	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	485	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	485	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	494	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	469	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	482	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	495	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	528	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	497	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	482	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	480	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	503	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	478	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	500	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	540	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	552	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	551	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	560	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	498	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	544	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	578	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	593	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	595	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	597	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	606	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	569	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	573	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	609	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	570	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	563	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	558	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	509	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	513	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:03:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	518	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	508	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	477	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	409	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	458	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	518	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	535	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	536	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	595	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	551	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	551	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	491	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	525	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	561	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	591	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	579	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	525	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	471	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	486	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	542	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	574	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	579	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	615	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	592	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	560	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	518	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	535	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	537	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	502	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	536	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	536	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	514	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	498	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	518	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	511	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	505	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	534	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	501	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	589	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	590	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	568	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	531	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	566	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	586	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	555	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	540	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	528	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	555	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	585	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	608	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	562	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	558	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	589	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	553	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	539	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	481	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	513	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	586	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	588	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	624	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:04:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	621	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	580	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	480	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	560	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	566	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	604	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	607	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	536	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	547	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	535	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	512	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	517	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	465	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	516	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	511	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	605	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	545	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	548	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	503	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	452	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	458	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	496	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	525	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	495	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	505	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	498	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	530	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	533	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	536	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	551	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	561	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	546	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	566	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	573	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	542	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	530	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	487	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	485	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	482	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	494	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	550	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	596	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	608	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	539	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	613	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	622	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	573	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	572	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	553	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	551	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	566	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	539	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	571	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	575	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	555	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	576	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	559	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	590	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	603	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	569	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:05:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	564	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	501	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	497	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	463	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	467	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	506	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	510	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	503	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	508	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	558	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	532	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	568	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	551	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	572	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	555	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	596	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	585	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	562	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	545	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	558	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	529	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	588	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	579	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	663	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	618	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	558	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	521	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	548	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	523	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	536	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	528	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	507	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	499	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	528	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	528	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	591	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	525	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	486	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	463	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	466	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	481	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	492	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	503	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	490	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	475	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	547	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	615	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	600	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	613	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	634	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	621	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	567	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	562	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	532	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	590	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	585	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	519	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	498	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	548	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	591	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:06:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	572	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	510	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	577	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	559	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	520	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	510	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	519	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	571	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	578	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	558	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	556	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	569	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	561	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	639	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	639	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	629	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	603	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	558	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	554	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	555	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	597	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	576	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	614	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	578	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	538	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	504	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	547	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	557	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	623	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	630	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	615	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	646	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	660	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	648	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	596	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	594	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	632	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	674	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	624	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	607	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	596	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	620	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	558	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	570	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	518	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	475	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	531	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	501	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	529	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	533	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	560	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	542	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	563	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	536	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	546	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	580	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	530	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	555	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	567	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	506	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:07:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	480	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	447	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	489	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	545	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	521	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	510	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	518	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	536	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	530	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	519	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	476	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	474	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	512	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	508	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	535	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	561	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	500	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	496	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	529	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	578	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	628	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	613	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	633	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	604	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	615	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	588	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	522	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	566	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	583	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	552	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	573	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	564	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	560	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	560	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	636	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	581	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	550	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	515	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	576	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	650	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	616	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	547	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	559	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	604	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	626	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	610	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	612	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	611	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	619	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	655	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	612	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	611	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	599	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	565	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	548	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	534	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	572	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	554	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	559	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	590	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:08:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	602	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	570	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	596	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	594	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	559	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	590	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	570	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	541	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	573	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	564	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	604	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	614	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	578	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	629	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	626	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	587	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	610	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	628	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	577	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	652	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	634	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	581	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	585	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	589	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	604	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	568	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	550	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	524	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	512	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	539	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	517	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	499	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	472	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	493	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	489	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	466	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	377	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	398	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	427	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	389	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	442	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	424	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	423	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	446	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	479	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	466	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	513	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	517	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	477	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	544	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	588	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	568	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	551	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	559	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	509	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	529	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	485	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	506	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	468	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	517	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:09:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	487	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	498	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	529	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	521	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	550	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	513	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	449	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	440	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	439	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	470	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	471	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	448	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	521	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	515	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	533	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	523	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	560	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	569	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	553	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	618	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	593	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	608	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	618	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	688	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	648	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	581	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	629	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	612	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	597	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	570	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	578	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	629	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	608	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	582	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	516	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	577	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	559	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	553	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	569	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	540	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	528	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	611	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	598	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	541	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	554	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	540	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	530	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	579	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	559	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	568	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	563	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	536	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	558	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	567	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	581	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	513	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	527	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	596	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	605	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	537	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:10:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	515	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	543	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	566	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	585	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	484	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	498	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	516	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	474	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	454	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	501	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	495	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	494	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	505	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	536	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	572	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	611	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	598	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	589	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	603	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	567	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	563	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	571	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	542	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	565	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	582	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	584	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	543	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	519	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	601	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	593	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	640	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	634	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	607	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	584	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	563	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	592	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	513	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	541	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	519	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	548	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	533	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	555	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	585	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	573	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	520	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	536	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	566	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	562	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	524	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	517	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	525	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	550	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	550	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	593	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	556	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	556	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	542	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	506	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	502	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	473	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:11:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	496	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	482	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	517	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	536	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	548	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	547	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	499	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	563	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	547	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	510	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	529	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	611	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	608	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	603	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	636	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	615	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	568	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	604	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	592	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	549	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	567	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	536	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	525	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	508	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	570	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	540	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	516	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	574	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	534	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	577	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	570	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	645	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	600	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	577	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	671	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	633	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	650	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	619	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	603	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	646	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	638	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	630	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	601	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	590	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	569	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	541	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	508	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	469	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	482	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	556	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	532	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	581	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	563	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	569	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	596	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	621	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	595	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	538	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	586	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	562	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:12:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	593	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	574	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	567	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	540	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	527	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	494	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	489	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	488	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	489	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	488	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	463	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	482	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	526	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	493	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	524	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	493	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	605	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	697	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	667	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	653	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	587	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	557	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	542	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	576	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	573	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	534	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	479	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	480	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	536	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	491	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	499	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	494	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	468	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	413	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	448	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	465	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	500	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	518	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	535	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	548	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	511	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	482	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	562	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	573	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	641	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	645	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	612	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	630	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	612	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	654	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	598	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	566	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	538	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	513	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	553	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	527	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	541	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	527	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	519	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	556	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:13:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	576	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	513	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	483	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	483	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	504	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	533	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	559	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	569	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	543	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	507	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	500	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	495	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	492	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	489	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	544	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	566	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	590	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	550	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	561	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	534	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	502	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	521	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	512	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	515	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	567	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	553	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	573	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	580	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	621	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	619	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	601	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	592	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	524	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	515	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	495	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	541	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	586	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	551	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	557	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	518	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	577	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	572	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	587	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	590	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	546	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	544	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	545	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	575	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	576	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	617	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	569	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	608	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	577	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	536	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	512	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	585	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	574	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	576	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	590	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	623	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:14:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	584	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	540	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	564	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	559	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	498	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	459	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	428	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	475	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	465	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	446	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	455	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	426	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	436	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	422	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	410	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	445	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	489	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	464	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	436	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	463	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	512	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	530	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	519	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	522	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	491	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	543	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	591	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	570	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	542	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	551	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	505	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	508	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	527	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	561	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	627	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	587	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	555	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	496	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	494	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	467	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	449	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	454	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	455	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	517	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	474	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	440	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	480	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	502	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	489	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	476	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	584	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	565	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	549	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	559	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	523	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	481	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	504	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	522	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	550	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	636	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:15:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	683	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	679	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	655	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	680	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	743	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	648	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	640	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	598	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	613	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	641	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	576	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	603	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	649	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	580	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	597	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	541	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	496	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	493	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	482	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	460	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	485	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	482	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	472	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	516	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	476	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	498	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	496	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	471	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	480	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	457	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	476	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	522	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	544	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	522	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	527	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	470	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	528	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	518	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	488	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	509	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	518	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	510	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	583	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	586	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	543	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	611	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	619	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	567	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	571	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	561	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	626	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	585	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	544	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	603	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	534	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	570	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	517	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	524	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	550	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	571	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:16:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	531	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	486	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	439	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	448	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	473	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	484	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	495	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	504	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	489	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	589	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	563	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	558	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	562	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	499	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	519	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	488	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	476	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	526	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	561	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	524	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	514	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	508	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	493	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	503	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	476	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	466	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	454	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	467	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	437	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	445	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	417	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	437	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	515	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	591	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	638	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	619	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	571	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	564	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	571	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	519	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	557	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	599	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	544	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	543	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	518	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	454	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	492	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	512	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	469	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	427	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	487	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	442	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	471	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	452	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	502	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	476	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	486	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	498	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	538	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	535	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:17:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	538	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	552	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	573	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	570	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	554	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	482	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	521	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	537	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	559	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	576	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	637	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	605	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	525	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	481	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	548	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	522	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	540	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	486	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	440	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	461	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	486	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	463	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	505	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	510	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	529	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	522	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	468	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	539	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	518	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	464	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	454	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	413	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	438	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	422	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	548	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	555	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	565	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	549	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	570	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	589	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	590	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:18:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	576	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	593	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	593	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	594	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	618	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	603	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	557	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	577	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	570	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	544	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	544	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	556	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	509	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	468	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	515	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	558	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	495	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	549	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	545	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	544	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	555	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	574	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	583	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	582	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	596	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	507	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	533	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	558	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	522	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	507	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	489	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	546	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	522	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	506	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	488	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	517	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	534	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	526	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	527	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	507	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	510	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	506	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	485	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	495	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	457	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	532	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	568	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	566	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	528	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	517	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	509	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	490	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:26:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	509	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	515	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	566	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	583	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	584	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	588	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	554	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	587	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	533	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	556	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	610	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	561	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	613	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	530	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	483	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	497	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	515	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	474	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	518	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	536	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	525	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	517	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	464	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	509	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	549	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	538	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	550	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	522	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	536	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	480	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	551	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	528	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	588	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	534	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	560	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	534	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	476	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	453	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	479	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	501	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	509	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	547	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	556	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	542	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	585	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	540	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	569	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	577	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	536	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	467	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	487	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	450	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	434	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	488	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	533	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	510	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	514	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	578	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	592	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	547	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:27:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	501	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	510	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	561	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	567	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	537	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	480	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	511	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	506	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	512	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	507	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	544	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	632	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	592	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	572	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	555	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	575	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	591	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	592	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	627	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	650	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	652	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	665	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	607	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	640	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	586	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	542	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	542	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	518	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	589	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	500	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	517	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	501	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	464	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	443	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	450	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	469	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	549	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	538	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	503	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	543	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	568	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	631	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	658	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	670	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	618	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	601	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	543	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	575	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	577	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	548	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	547	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	568	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	527	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	553	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	573	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	555	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	594	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	628	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	598	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	596	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:28:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	618	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	641	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	597	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	598	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	584	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	507	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	527	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	509	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	528	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	451	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	537	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	547	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	569	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	543	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	532	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	580	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	576	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	591	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	582	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	537	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	535	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	538	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	516	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	546	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	557	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	484	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	518	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	500	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	539	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	597	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	573	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	542	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	518	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	535	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	523	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	493	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	500	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	517	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	543	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	588	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	603	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	569	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	554	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	531	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	474	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	487	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	474	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	499	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	451	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	409	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	444	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	543	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	541	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	552	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	595	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	515	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	582	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	620	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	650	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	656	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:29:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	643	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	565	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	557	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	554	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	564	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	523	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	510	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	573	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	554	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	572	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	555	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	515	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	508	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	504	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	531	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	532	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	500	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	507	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	503	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	477	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	511	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	483	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	507	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	523	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	493	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	526	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	514	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	486	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	448	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	499	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	495	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	526	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	537	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	547	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	514	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	564	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	546	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	531	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	553	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	575	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	577	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	548	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	538	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	583	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	575	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	512	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	492	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	557	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	600	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	645	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	603	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	603	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	544	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	554	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	552	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	549	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	525	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	611	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	597	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	584	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:30:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	562	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	499	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	543	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	509	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	480	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	526	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	519	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	534	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	597	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	613	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	624	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	685	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	715	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	694	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	630	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	590	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	582	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	573	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	593	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	587	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	555	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	529	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	476	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	475	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	487	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	473	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	506	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	468	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	553	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	528	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	554	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	548	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	523	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	459	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	461	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	454	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	413	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	439	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	470	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	494	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	513	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	473	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	474	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	485	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	461	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	454	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	449	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	420	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	397	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	368	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	411	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	422	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	408	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	494	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	479	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	512	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	508	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	489	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	555	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	538	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:31:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	483	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	507	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	492	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	443	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	427	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	400	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	438	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	469	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	448	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	456	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	468	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	529	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	553	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	542	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	562	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	512	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	494	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	513	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	506	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	546	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	579	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	501	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	461	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	485	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	508	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	527	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	484	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	508	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	536	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	540	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	590	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	532	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	507	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	525	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	616	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	592	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	595	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	517	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	541	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	494	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	511	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	481	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	501	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	506	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	444	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	430	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	464	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	470	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	482	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	491	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	503	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	488	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	555	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	530	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	519	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	468	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	470	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	496	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	480	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	447	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:32:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	428	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	473	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	416	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	420	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	476	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	557	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	507	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	567	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	609	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	559	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	556	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	561	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	553	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	551	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	589	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	567	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	541	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	550	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	548	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	604	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	612	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	530	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	543	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	563	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	607	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	539	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	517	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	511	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	502	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	475	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	475	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	465	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	467	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	437	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	476	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	524	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	593	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	605	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	616	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	602	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	637	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	664	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	675	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	602	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	600	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	599	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	553	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	538	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	538	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	604	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	570	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	624	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	563	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	524	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	518	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	477	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	499	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	483	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	542	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	543	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:33:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	475	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	542	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	518	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	555	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	549	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	616	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	558	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	575	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	604	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	568	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	541	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	542	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	606	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	571	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	572	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	564	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	512	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	515	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	517	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	529	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	578	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	569	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	571	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	561	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	559	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	580	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	624	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	574	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	637	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	715	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	647	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	638	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	641	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	554	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	562	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	556	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	577	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	646	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	672	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	588	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	577	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	513	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	520	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	487	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	439	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	524	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	549	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	534	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	531	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	488	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	508	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	523	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	446	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	420	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	420	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	409	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	422	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	423	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	442	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	505	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:34:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	520	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	547	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	488	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	579	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	617	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	582	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	585	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	609	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	587	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	570	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	542	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	516	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	510	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	538	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	492	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	467	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	484	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	496	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	503	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	486	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	506	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	533	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	530	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	543	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	472	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	439	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	412	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	435	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	452	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	481	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	536	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	513	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	475	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	474	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	534	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	561	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	638	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	593	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	562	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	535	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	499	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	507	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	488	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	591	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	536	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	536	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	561	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	523	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	500	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	540	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	528	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	518	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	535	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	522	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	515	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	588	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	509	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	470	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	438	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	469	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:35:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	538	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	539	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	540	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	515	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	486	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	426	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	453	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	480	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	491	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	513	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	507	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	500	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	529	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	473	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	495	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	492	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	524	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	504	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	558	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	541	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	575	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	543	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	510	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	548	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	502	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	494	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	538	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	517	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	556	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	495	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	538	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	574	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	536	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	512	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	518	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	497	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	494	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	446	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	440	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	481	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	467	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	516	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	521	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	481	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	490	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	500	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	538	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	559	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	579	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	583	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	562	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	603	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	652	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	673	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	670	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	601	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	576	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	523	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	574	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	614	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:36:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	579	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	547	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	558	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	567	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	631	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	567	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	596	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	549	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	535	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	549	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	571	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	588	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	649	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	605	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	567	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	539	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	563	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	563	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	535	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	511	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	550	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	522	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	491	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	557	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	541	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	554	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	540	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	516	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	485	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	530	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	521	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	515	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	497	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	461	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	537	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	534	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	512	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	460	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	443	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	477	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	501	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	512	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	528	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	518	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	545	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	508	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	494	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	514	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	612	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	613	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	612	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	655	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	588	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	536	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	500	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	484	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	575	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	592	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	533	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	524	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:37:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	506	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	533	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	536	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	526	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	564	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	637	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	639	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	618	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	653	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	629	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	611	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	597	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	594	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	603	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	568	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	519	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	443	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	407	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	420	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	441	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	480	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	491	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	465	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	489	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	488	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	461	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	524	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	503	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	547	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	510	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	491	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	487	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	557	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	544	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	567	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	572	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	590	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	543	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	543	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	552	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	538	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	513	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	485	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	518	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	464	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	467	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	446	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	417	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	418	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	542	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	587	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	635	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	663	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	672	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	604	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	662	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	629	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	609	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	541	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	474	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:38:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	555	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	532	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	523	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	491	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	568	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	529	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	621	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	623	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	645	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	634	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	594	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	627	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	552	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	564	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	535	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	456	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	460	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	439	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	455	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	449	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	452	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	457	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	426	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	423	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	431	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	404	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	462	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	488	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	462	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	463	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	423	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	439	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	449	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	465	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	467	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	493	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	582	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	574	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	535	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	546	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	557	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	580	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	570	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	543	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	576	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	535	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	571	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	588	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	601	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	511	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	517	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	546	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	577	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	534	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	445	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	472	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	485	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	530	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	557	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	520	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:39:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	492	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	487	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	556	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	544	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	554	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	494	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	536	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	549	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	526	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	541	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	574	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	579	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	592	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	596	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	564	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	527	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	484	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	529	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	498	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	471	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	437	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	471	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	451	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	490	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	601	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	605	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	627	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	690	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	605	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	558	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	511	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	540	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	552	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	573	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	602	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	639	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	564	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	491	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	528	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	530	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	613	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	598	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	576	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	568	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	605	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	604	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	581	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	596	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	552	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	575	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	579	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	527	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	598	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	656	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	590	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	546	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	510	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	482	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	481	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	525	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:40:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	471	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	426	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	424	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	457	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	560	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	590	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	569	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	484	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	530	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	565	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	605	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	614	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	636	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	597	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	597	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	564	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	549	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	547	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	593	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	574	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	543	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	575	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	569	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	530	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	523	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	568	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	527	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	530	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	570	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	598	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	601	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	648	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	642	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	645	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	636	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	660	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	680	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	631	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	660	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	648	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	603	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	557	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	497	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	496	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	468	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	491	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	512	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	482	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	491	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	566	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	537	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	570	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	598	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	620	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	548	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	559	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	532	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	523	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	504	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	546	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:41:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	556	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	539	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	585	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	561	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	601	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	600	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	624	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	530	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	506	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	501	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	541	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	562	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	547	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	535	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	546	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	486	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	485	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	517	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	524	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	530	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	596	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	564	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	558	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	539	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	530	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	541	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	486	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	484	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	549	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	515	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	529	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	474	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	518	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	512	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	544	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	522	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	506	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	467	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	480	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	504	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	478	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	456	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	473	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	552	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	517	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	499	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	519	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	478	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	493	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	555	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	562	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	549	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	535	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	488	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	508	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	538	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	516	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	486	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	462	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	491	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:42:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	466	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	470	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	458	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	449	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	453	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	458	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	428	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	462	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	419	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	464	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	469	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	457	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	532	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	522	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	572	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	521	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	503	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	475	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	454	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	501	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	520	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	491	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	490	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	512	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	520	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	533	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	583	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	587	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	542	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	562	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	545	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	560	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	591	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	592	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	591	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	605	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	616	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	566	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	546	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	497	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	514	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	498	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	496	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	495	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	527	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	532	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	534	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	489	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	487	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	485	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	506	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	488	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	500	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	542	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	561	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	614	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	611	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	619	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	657	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	622	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:43:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	655	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	599	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	567	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	586	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	586	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	586	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	597	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	527	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	520	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	499	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	508	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	512	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	560	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	578	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	515	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	521	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	488	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	475	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	431	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	509	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	502	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	566	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	529	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	579	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	572	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	545	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	520	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	468	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	480	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	445	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	505	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	526	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	520	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	547	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	578	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	572	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	613	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	600	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	556	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	530	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	535	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	545	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	512	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	472	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	439	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	435	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	455	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	496	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	483	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	473	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	486	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	440	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	404	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	450	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	423	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	402	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	473	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	523	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	491	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	489	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:44:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	554	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:45:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	597	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:45:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	596	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	9:45:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	539	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	630	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	579	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	549	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	489	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	474	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	502	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	501	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	441	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	448	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	500	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	463	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	479	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	535	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	502	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	512	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	471	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	495	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	494	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	549	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	526	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	630	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	691	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	628	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	638	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	655	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	667	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	621	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	649	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	606	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	549	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	536	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	584	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	575	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	615	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	591	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	571	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	532	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	602	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	626	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	597	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:02:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	576	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	555	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	553	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	496	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	536	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	526	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	516	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	603	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	558	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	566	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	540	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	552	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	505	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	513	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	578	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	571	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	553	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	537	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	562	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	535	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	525	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	532	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	533	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	546	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	536	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	536	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	526	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	552	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	516	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	599	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	568	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	508	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	492	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	522	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	528	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	531	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	500	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	498	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	540	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	529	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	542	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	520	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	489	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	522	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	490	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	499	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	531	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	521	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	559	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	614	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	622	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	550	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	514	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	565	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	553	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	565	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	572	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	637	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	597	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	562	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:03:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	589	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	548	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	583	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	597	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	607	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	627	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	563	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	594	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	526	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	560	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	615	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	600	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	598	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	612	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	541	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	551	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	536	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	513	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	551	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	493	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	492	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	523	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	537	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	538	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	576	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	546	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	547	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	525	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	515	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	518	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	477	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	480	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	513	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	528	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	577	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	478	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	511	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	528	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	485	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	539	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	606	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	596	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	595	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	539	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	517	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	465	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	424	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	448	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	538	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	619	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	582	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	585	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	566	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	537	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	631	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	568	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	550	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	512	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	483	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	471	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:04:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	435	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	429	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	498	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	470	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	483	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	502	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	510	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	550	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	523	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	540	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	504	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	488	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	487	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	521	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	539	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	540	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	547	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	560	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	487	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	464	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	513	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	594	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	584	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	610	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	573	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	548	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	538	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	517	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	521	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	479	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	492	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	477	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	512	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	531	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	589	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	645	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	577	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	595	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	596	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	622	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	550	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	537	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	592	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	537	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	538	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	502	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	463	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	430	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	406	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	435	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	469	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	483	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	472	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	540	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	538	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	654	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	632	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	618	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	554	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	518	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:05:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	476	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	537	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	539	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	517	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	535	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	502	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	486	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	464	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	501	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	440	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	493	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	469	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	447	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	441	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	482	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	492	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	517	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	497	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	493	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	498	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	469	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	496	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	505	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	536	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	481	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	411	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	518	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	496	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	528	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	579	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	537	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	525	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	520	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	500	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	528	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	505	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	498	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	529	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	610	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	561	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	521	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	525	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	538	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	516	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	485	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	542	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	554	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	551	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	586	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	576	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	560	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	541	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	600	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	566	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	607	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	612	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	585	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	587	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	557	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	563	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:06:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	525	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	517	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	529	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	516	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	487	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	451	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	446	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	441	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	481	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	445	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	461	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	474	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	428	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	413	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	440	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	446	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	463	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	487	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	508	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	516	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	559	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	546	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	510	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	551	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	514	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	541	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	566	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	528	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	567	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	552	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	503	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	498	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	504	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	510	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	515	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	496	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	504	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	570	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	564	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	585	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	625	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	599	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	580	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	575	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	636	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	609	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	607	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	594	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	616	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	580	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	571	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	551	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	524	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	527	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	557	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	590	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	593	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	538	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	515	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	507	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:07:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	534	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	562	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	560	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	600	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	574	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	603	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	570	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	564	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	581	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	566	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	502	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	557	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	522	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	492	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	478	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	513	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	473	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	486	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	499	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	516	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	544	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	541	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	520	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	499	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	482	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	491	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	489	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	521	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	517	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	541	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	503	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	485	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	503	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	543	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	544	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	556	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	551	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	504	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	603	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	556	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	497	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	507	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	502	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	519	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	544	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	612	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	607	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	539	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	560	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	558	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	496	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	450	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	457	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	484	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	515	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	530	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	530	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	578	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	572	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	590	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:08:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	556	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	575	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	589	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	633	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	615	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	635	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	595	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	576	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	672	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	658	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	647	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	657	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	660	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	690	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	731	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	694	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	661	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	647	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	626	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	621	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	570	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	608	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	605	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	618	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	648	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	583	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	600	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	598	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	578	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	593	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	672	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	669	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	698	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	677	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	709	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	656	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	633	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	693	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	664	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	683	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	723	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	666	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	629	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	611	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	641	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	599	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	554	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	541	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	571	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	608	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	539	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	573	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	558	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	633	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	591	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	583	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	562	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	546	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	521	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	522	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:09:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	525	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	525	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	493	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	469	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	439	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	425	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	412	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	437	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	501	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	522	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	536	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	546	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	556	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	637	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	619	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	583	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	573	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	556	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	540	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	540	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	550	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	582	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	573	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	587	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	601	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	567	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	518	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	532	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	532	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	523	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	539	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	514	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	552	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	573	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	545	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	542	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	474	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	516	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	483	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	472	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	461	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	485	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	508	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	503	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	542	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	518	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	512	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	539	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	560	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	545	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	475	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	488	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	510	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	492	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	482	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	493	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	529	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	508	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	570	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	483	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:10:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	462	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	463	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	489	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	464	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	467	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	423	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	455	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	457	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	531	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	488	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	476	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	543	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	543	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	562	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	489	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	474	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	428	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	416	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	382	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	435	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	411	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	431	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	372	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	451	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	434	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	455	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	423	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	411	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	448	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	445	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	509	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	526	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	565	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	631	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	633	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	581	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	619	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	514	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	486	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	450	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	445	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	463	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	456	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	425	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	410	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	497	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	479	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	454	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	502	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	500	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	451	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	454	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	459	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	406	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	395	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	436	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	446	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	439	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	483	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	435	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:11:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	433	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	454	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	437	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	435	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	443	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	470	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	472	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	441	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	459	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	442	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	435	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	431	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	450	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	446	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	518	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	581	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	618	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	569	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	553	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	543	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	554	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	561	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	488	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	486	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	474	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	486	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	564	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	561	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	637	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	583	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	600	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	623	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	584	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	587	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	557	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	545	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	567	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	537	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	583	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	567	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	551	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	553	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	530	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	508	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	558	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	564	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	538	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	541	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	543	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	564	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	592	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	513	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	539	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	549	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	595	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	551	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	527	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	520	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	513	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	494	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:12:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	468	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	502	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	485	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	473	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	546	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	489	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	466	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	467	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	460	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	443	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	487	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	499	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	540	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	514	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	532	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	522	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	571	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	532	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	490	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	513	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	563	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	525	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	538	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	536	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	489	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	450	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	445	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	464	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	522	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	490	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	521	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	479	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	469	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	507	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	468	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	517	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	453	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	446	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	477	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	467	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	436	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	487	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	461	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	462	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	480	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	517	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	523	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	500	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	518	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	525	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	538	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	553	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	574	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	645	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	635	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	650	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	596	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	574	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	569	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	516	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:13:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	508	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	488	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	473	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	430	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	449	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	526	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	549	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	607	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	537	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	540	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	539	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	540	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	480	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	445	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	464	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	444	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	460	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	463	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	514	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	498	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	481	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	505	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	465	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	458	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	487	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	485	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	463	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	418	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	442	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	438	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	445	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	439	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	399	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	425	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	413	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	377	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	430	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	483	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	483	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	526	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	540	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	483	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	541	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	622	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	550	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	556	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	576	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	568	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	551	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	572	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	600	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	529	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	566	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	502	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	461	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	476	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	464	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	458	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	440	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	505	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:14:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	454	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	482	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	446	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	451	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	491	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	477	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	464	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	443	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	438	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	447	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	465	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	425	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	489	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	456	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	445	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	408	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	399	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	368	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	430	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	483	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	507	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	539	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	517	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	509	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	516	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	497	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	514	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	519	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	508	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	547	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	558	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	577	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	569	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	599	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	588	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	569	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	527	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	484	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	487	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	452	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	503	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	520	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	578	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	514	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	474	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	487	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	512	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	483	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	457	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	464	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	444	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	484	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	545	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	560	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	636	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	593	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	568	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	539	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	562	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	547	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:15:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	557	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	608	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	539	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	481	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	493	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	482	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	471	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	493	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	465	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	481	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	505	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	535	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	502	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	508	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	458	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	461	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	477	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	556	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	578	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	580	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	593	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	559	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	511	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	507	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	490	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	534	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	489	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	496	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	493	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	457	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	553	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	482	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	471	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	494	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	457	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	525	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	528	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	461	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	441	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	509	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	517	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	523	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	516	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	498	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	520	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	513	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	532	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	568	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:16:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	610	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:20:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	516	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:20:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	507	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:20:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	491	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:20:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	420	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:20:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	442	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:20:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	438	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:20:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	504	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:20:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	526	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:20:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	540	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:20:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	570	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:20:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	541	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:20:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	552	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:20:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	526	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:20:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	561	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:20:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	547	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:20:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	601	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:20:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	520	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:20:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	526	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:20:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	540	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:20:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	548	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:20:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	533	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:20:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	510	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:20:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	460	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:20:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	510	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	540	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	590	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	512	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	527	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	493	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	501	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	501	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	509	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	490	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	464	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	466	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	444	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	473	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	474	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	522	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	556	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	486	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	484	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	539	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	540	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	494	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	517	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	543	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	472	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	484	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	539	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	528	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	462	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	443	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	441	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	423	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	470	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	461	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	534	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	478	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	468	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	448	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	479	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	514	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	495	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	516	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:21:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	530	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	525	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	507	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	493	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	515	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	519	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	501	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	510	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	472	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	461	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	555	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	552	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	548	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	502	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	579	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	642	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	600	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	564	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	546	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	586	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	555	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	496	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	485	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	532	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	510	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	515	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	464	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	444	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	382	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	376	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	450	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	492	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	499	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	505	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	501	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	553	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	562	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	592	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	525	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	503	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	499	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	508	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	480	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	480	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	561	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	559	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	532	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	511	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	506	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	537	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	481	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	477	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	463	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	443	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	496	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	585	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	584	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	586	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	555	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	576	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:22:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	591	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	661	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	628	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	565	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	579	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	515	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	534	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	545	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	592	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	699	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	613	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	577	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	606	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	578	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	593	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	584	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	619	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	559	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	577	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	615	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	589	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	582	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	619	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	662	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	682	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	657	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	611	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	612	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	622	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	653	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	584	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	585	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	530	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	507	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	547	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	600	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	555	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	552	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	583	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	585	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	565	Laminate Tile
Building 2540	8	Scan	Survey Unit 08	"	6/14/2012	10:23:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	539	Laminate Tile
Building 2540	14	Scan	Survey Unit 14	Miller	6/14/2012	3:47:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	709	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	732	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	751	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	733	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	732	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	785	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	853	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	817	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	751	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	689	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	686	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	671	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	679	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	652	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	610	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	597	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	599	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	623	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	662	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	676	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	651	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	695	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	688	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	639	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	688	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	635	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	661	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	626	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	634	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	667	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	645	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	682	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	657	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	670	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	666	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	652	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	690	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	652	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	654	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	633	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	635	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	662	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	627	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	636	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	617	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	616	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	635	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	617	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	603	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	619	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	618	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	649	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	693	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	719	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	685	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:47:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	566	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	654	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	688	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	728	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	716	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	707	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	764	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	767	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	725	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	713	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	771	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	804	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	774	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	740	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	714	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	693	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	697	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	675	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	693	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	699	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	747	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	686	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	667	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	686	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	611	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	551	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	549	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	604	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	650	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	628	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	659	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	644	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	622	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	712	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	688	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	660	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	649	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	707	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	734	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	687	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	613	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	565	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	550	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	569	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	607	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	630	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	590	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	558	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	692	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	699	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	723	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	710	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	736	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	756	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	726	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	677	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	702	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	671	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	724	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	666	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:48:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	744	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	753	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	815	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	785	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	795	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	818	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	845	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	833	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	743	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	716	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	754	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	735	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	722	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	745	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	718	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	637	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	641	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	612	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	679	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	663	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	628	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	651	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	663	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	686	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	636	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	654	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	634	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	660	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	707	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	672	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	737	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	702	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	672	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	601	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	634	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	672	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	690	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	741	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	748	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	752	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	736	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	756	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	751	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	733	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	719	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	756	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	806	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	836	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	905	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	866	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	862	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	791	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	799	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	716	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	725	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	665	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	663	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	651	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	699	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	691	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:49:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	658	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	656	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	724	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	735	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	731	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	718	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	673	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	684	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	646	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	691	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	685	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	656	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	684	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	647	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	690	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	661	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	675	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	668	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	688	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	697	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	657	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	565	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	634	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	650	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	683	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	773	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	782	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	770	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	740	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	720	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	674	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	636	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	675	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	662	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	602	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	616	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	617	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	626	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	742	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	718	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	729	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	658	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	670	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	689	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	791	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	786	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	774	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	683	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	692	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	651	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	688	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	706	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	673	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	660	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	706	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	712	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	692	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	705	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	695	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	746	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:50:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	748	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	799	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	786	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	818	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	739	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	677	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	638	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	691	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	729	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	762	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	744	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	704	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	627	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	657	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	728	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	715	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	681	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	746	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	754	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	737	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	827	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	806	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	791	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	790	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	730	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	811	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	748	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	697	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	736	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	666	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	629	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	620	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	664	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	677	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	686	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	679	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	728	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	736	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	668	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	666	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	698	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	716	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	671	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	637	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	638	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	620	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	616	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	623	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	615	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	587	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	593	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	586	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	591	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	559	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	610	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	644	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	590	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	594	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	584	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	603	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:51:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	626	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	576	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	616	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	643	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	613	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	644	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	717	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	707	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	699	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	700	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	633	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	658	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	628	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	626	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	699	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	690	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	660	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	661	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	648	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	660	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	647	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	660	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	682	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	700	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	649	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	648	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	721	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	712	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	746	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	743	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	764	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	771	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	736	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	709	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	754	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	785	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	703	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	695	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	665	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	734	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	782	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	747	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	776	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	734	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	822	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	804	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	846	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	822	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	874	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	906	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	951	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1003	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1018	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	986	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	925	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	966	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	952	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	860	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	913	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	967	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:52:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1008	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1022	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1010	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	990	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1008	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1000	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1049	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1080	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1165	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1182	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1243	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1407	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1515	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1498	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1523	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1554	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1469	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1486	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1465	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1515	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1328	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1177	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1055	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	981	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	931	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	849	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	746	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	696	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	641	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	600	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	611	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	607	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	583	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	560	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	512	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	504	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	512	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	459	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	462	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	499	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	484	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	449	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	465	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	513	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	505	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	524	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	528	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	463	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	502	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	544	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	543	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	543	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	553	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	550	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	594	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	640	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	643	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	680	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	675	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	683	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:53:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	667	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	667	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	679	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	642	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	657	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	714	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	771	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	737	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	697	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	669	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	633	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	632	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	616	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	637	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	629	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	692	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	765	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	737	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	766	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	803	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	843	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	889	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	973	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	988	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1014	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	956	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	956	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	979	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	953	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	953	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	897	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	843	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	798	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	752	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	665	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	594	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	630	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	611	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	623	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	573	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	601	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	555	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	576	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	548	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	537	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	616	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	680	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	725	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	700	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	637	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	691	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	682	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	619	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	648	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	615	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	716	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	742	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	740	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	703	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	671	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:54:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	644	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	638	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	666	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	688	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	658	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	683	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	723	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	744	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	740	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	689	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	702	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	684	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	711	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	744	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	696	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	734	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	729	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	659	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	644	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	623	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	702	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	772	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	693	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	664	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	617	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	682	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	703	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	706	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	778	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	766	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	789	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	822	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	826	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	817	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	778	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	756	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	717	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	694	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	698	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	748	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	742	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	690	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	651	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	663	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	630	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	620	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	605	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	604	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	749	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	838	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	885	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	935	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	929	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	822	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	745	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	804	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	766	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	712	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	715	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	693	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:55:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	676	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	672	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	644	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	705	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	708	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	791	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	733	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	693	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	731	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	716	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	668	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	690	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	730	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	671	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	669	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	655	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	608	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	630	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	712	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	751	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	780	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	730	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	704	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	671	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	680	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	711	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	690	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	742	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	770	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	830	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	845	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	832	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	776	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	834	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	846	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	776	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	793	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	720	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	733	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	764	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	710	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	698	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	727	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	703	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	699	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	669	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	623	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	698	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	718	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	742	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	760	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	813	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	772	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	765	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	815	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	841	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	779	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	825	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	840	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	795	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:56:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	801	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	762	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	730	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	748	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	742	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	703	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	683	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	689	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	710	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	735	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	686	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	702	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	695	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	663	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	677	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	648	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	682	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	666	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	688	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	647	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	659	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	671	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	681	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	744	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	728	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	784	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	704	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	676	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	650	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	596	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	631	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	623	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	608	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	652	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	630	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	587	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	647	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	660	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	680	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	619	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	639	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	587	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	624	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	574	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	605	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	600	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	646	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	647	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	580	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	550	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	524	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	551	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	548	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	593	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	628	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	622	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	649	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	651	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	597	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	553	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:57:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	608	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:58:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	584	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:58:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	532	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:58:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	558	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:58:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	598	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:58:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	645	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:58:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	670	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:58:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	659	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:58:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	602	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:58:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	535	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:58:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	512	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:58:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	447	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:58:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	442	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	3:58:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	463	Concrete Block
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:11:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	856	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:11:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	891	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:11:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	797	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:11:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	750	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:11:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	688	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:11:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	672	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:11:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	752	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:11:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	756	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:11:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	778	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:11:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	791	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:11:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	801	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:11:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	738	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:11:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	824	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:11:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	831	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:11:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	812	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:11:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	829	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:11:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	765	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:11:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	802	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:11:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	787	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:11:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	753	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:11:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	727	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:11:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	645	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:11:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	647	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:11:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	649	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:11:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	652	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:11:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	639	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:11:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	658	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:11:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	604	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:11:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	45	647	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	47	697	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	50	700	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	41	649	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	710	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	706	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	753	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	702	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	719	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	766	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	723	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	727	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	764	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	789	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	731	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	702	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	802	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	810	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	824	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	868	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	807	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	756	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	851	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	777	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	765	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	804	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	789	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	823	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	782	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	769	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	712	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	737	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	678	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	708	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	744	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	751	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	677	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	721	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	754	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	752	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	791	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	799	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	736	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	720	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	741	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	749	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	729	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	752	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	746	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	765	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	747	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	742	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	691	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	673	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	634	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	649	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	696	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	769	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	779	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	722	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:12:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	710	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	665	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	607	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	585	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	644	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	613	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	588	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	578	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	548	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	594	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	552	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	538	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	538	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	586	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	624	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	587	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	564	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	607	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	606	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	638	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	607	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	652	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	666	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	698	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	727	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	714	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	783	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	745	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	787	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	788	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	799	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	782	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	734	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	651	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	674	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	627	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	645	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	658	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	601	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	671	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	692	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	720	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	722	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	711	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	738	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	778	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	722	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	766	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	732	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	776	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	733	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	753	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	701	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	651	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	742	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	761	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	674	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	648	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	661	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	634	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:13:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	686	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	693	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	718	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	728	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	747	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	661	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	648	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	649	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	641	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	610	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	631	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	660	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	658	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	637	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	622	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	696	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	681	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	721	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	719	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	683	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	713	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	725	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	646	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	637	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	653	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	644	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	658	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	695	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	755	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	724	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	698	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	659	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	702	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	705	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	720	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	704	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	731	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	761	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	753	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	727	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	821	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	766	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	769	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	792	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	824	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	871	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	864	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	802	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	784	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	814	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	750	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	754	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	758	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	708	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	710	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	732	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	726	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	870	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	887	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	865	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:14:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	805	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	812	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	805	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	786	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	806	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	782	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	748	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	729	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	733	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	719	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	661	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	706	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	674	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	685	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	645	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	694	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	675	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	767	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	823	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	814	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	819	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	798	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	807	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	711	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	757	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	704	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	729	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	734	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	801	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	806	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	757	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	771	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	795	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	815	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	858	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	808	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	811	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	804	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	831	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	36	807	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	836	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	818	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	738	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	680	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	663	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	697	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	667	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	718	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	694	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	734	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	780	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	817	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	859	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	845	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	834	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	904	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	869	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	845	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	857	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	820	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:15:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	858	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	823	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	802	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	808	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	732	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	638	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	664	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	731	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	735	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	745	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	715	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	748	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	850	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	860	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	833	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	765	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	747	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	752	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	724	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	698	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	680	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	662	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	617	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	663	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	683	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	671	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	750	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	701	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	713	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	672	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	705	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	673	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	670	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	645	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	635	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	639	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	666	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	734	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	762	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	742	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	710	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	653	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	607	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	548	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	603	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	590	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	627	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	635	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	618	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	674	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	726	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	745	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	626	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	665	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	650	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	662	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	658	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	713	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	692	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	685	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:16:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	711	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	703	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	717	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	637	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	687	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	738	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	709	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	689	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	705	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	757	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	716	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	740	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	792	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	742	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	726	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	681	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	684	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	769	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	818	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	839	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	827	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	807	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	957	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	920	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	940	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	839	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	782	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	760	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	773	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	739	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	691	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	678	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	675	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	606	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	638	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	687	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	719	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	763	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	697	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	739	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	704	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	744	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	807	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	791	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	778	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	733	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	752	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	723	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	665	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	663	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	684	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	668	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	771	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	798	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	763	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	769	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	792	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	800	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	788	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	846	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:17:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	844	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:18:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	900	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:18:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	870	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:18:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	809	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:18:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	812	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:18:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	739	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:18:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	735	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:18:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	711	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:18:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	654	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:18:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	634	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:18:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	661	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:18:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	626	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:18:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	583	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:18:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	620	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:18:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	655	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:18:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	644	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:18:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	650	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:18:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	699	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:18:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	693	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:18:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	667	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:18:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	674	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:18:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	692	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:18:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	778	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:18:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	789	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:18:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	698	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:18:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	736	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:18:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	758	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:18:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	795	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:18:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	746	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:18:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	752	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:21:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	774	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:21:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	766	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:21:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	779	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:21:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	734	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:21:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	825	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:21:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	798	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:21:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	877	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:21:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	881	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:21:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	859	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:21:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	887	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:21:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	854	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:21:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	52	828	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	52	830	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	53	858	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	54	934	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	44	985	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	47	952	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	38	1083	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	1116	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	60	1030	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	48	1051	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	51	1069	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	64	1091	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	52	1035	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	42	984	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	921	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	49	895	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	52	871	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	65	875	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	64	856	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	63	854	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	63	841	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	51	795	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	41	931	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	57	1019	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	46	987	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	48	923	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	50	961	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	40	984	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	946	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1001	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	970	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	48	1015	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	50	1037	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	41	1045	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	69	1018	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	56	985	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	68	982	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	67	928	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	76	925	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	72	899	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	70	932	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	57	949	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	81	952	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	110	963	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	89	882	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	83	887	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	90	890	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	73	890	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	70	869	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	67	795	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	54	812	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	44	805	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	60	802	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	59	854	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	48	844	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	39	854	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	54	867	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	44	783	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	46	783	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	745	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:22:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	728	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	782	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	772	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	820	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	825	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	782	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	759	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	763	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	744	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	738	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	749	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	730	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	818	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	798	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	771	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	39	705	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	721	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	730	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	751	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	743	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	44	707	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	68	732	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	91	719	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	74	814	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	71	787	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	79	834	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	64	823	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	64	863	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	63	846	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	51	861	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	64	777	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	63	787	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	63	787	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	75	797	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	61	828	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	49	933	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	51	963	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	41	988	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	1028	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	1105	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1045	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	51	1087	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	52	1154	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	53	1087	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	55	970	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	44	1010	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	36	965	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	52	1008	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	42	947	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	45	918	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	72	952	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	70	954	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	68	984	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	67	979	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	65	919	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	52	996	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	42	1001	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	968	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	1016	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	45	968	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:23:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	48	946	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	61	881	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	60	973	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	60	961	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	49	974	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	40	983	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	44	979	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	57	967	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	58	885	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	58	1002	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	47	938	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	38	883	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	862	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	851	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	75	841	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	72	874	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	58	866	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	47	937	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	49	1026	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	63	992	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	51	927	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	86	920	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	92	885	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	86	900	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	69	957	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	80	969	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	65	991	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	63	996	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	75	1031	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	61	1007	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	61	1031	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	72	1078	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	59	1025	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	47	1025	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	50	991	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	41	1009	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	80	976	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	87	913	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	103	895	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	83	881	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	67	896	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	55	829	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	55	888	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	56	788	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	58	869	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	57	909	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	46	952	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	1001	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	52	937	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	66	1010	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	64	1001	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	52	1056	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	42	1036	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	46	980	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	48	1001	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	51	1007	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	41	1043	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	56	988	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	56	914	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	57	908	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:24:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	46	1000	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	49	967	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	40	922	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	43	927	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	58	940	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	47	883	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	38	864	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	881	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	861	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	836	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	872	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	875	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	857	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	933	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	59	847	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	60	939	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	60	873	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	49	956	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	39	1000	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	44	924	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	46	892	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	48	880	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	85	979	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	68	978	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	67	891	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	55	891	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	44	861	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	36	954	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	991	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	966	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	42	1000	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	957	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	61	946	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	60	926	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	48	1001	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	75	1002	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	84	983	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	68	992	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	55	1005	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	56	947	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	68	927	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	78	875	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	63	892	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	51	870	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	53	898	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	77	879	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	85	938	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	69	1033	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	56	965	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	67	961	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	54	1019	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	56	1004	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	56	1022	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	57	1009	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	46	1034	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	1045	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	41	995	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	968	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	908	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	826	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:25:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	849	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	916	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	888	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	957	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	915	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	936	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	978	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	987	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	916	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	857	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	829	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	808	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	783	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	828	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	925	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	54	980	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	56	1019	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	56	995	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	67	1024	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	78	957	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	86	903	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	80	926	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	100	920	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	81	889	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	87	996	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	81	895	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	66	966	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	64	949	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	52	986	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	54	1037	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	56	988	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	45	1074	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	36	997	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	52	998	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	65	982	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	65	990	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	52	991	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	53	1049	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	43	950	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	45	951	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	49	965	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	39	961	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	924	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	941	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	1014	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	49	937	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	40	851	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	67	826	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	66	879	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	75	926	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	94	987	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	101	993	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	127	1062	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	103	975	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	95	997	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	77	957	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	62	923	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	50	894	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	52	898	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	42	864	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:26:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	880	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	918	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	995	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1014	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	959	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	958	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1053	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	968	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	965	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	56	964	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	79	1029	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	64	1041	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	63	992	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	72	1023	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	81	970	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	66	938	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	65	932	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	75	914	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	73	896	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	114	911	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	103	984	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	96	954	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	110	930	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	100	863	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	93	872	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	86	902	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	80	926	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	65	899	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	52	944	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	54	935	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	56	973	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	56	1004	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	56	950	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	45	894	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	861	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	54	886	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	43	818	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	46	808	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	49	818	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	40	884	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	43	919	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	915	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	1037	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	989	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	50	976	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	63	960	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	51	947	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	63	941	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	74	1027	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	70	1038	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	68	999	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	66	1050	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	86	1043	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	80	1049	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	65	1046	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	64	1025	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	64	956	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	76	992	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	61	1030	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	60	1019	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:27:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	49	985	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	40	968	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	975	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	911	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	954	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	957	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1012	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1025	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1083	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	1058	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	63	1040	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	74	1029	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	60	1018	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	48	1010	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	51	946	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	41	892	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	880	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	38	927	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	55	862	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	67	854	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	78	820	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	74	802	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	82	787	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	77	854	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	62	882	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	50	976	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	41	937	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	56	910	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	67	930	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	86	936	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	82	963	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	66	905	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	66	949	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	53	940	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	66	952	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	64	883	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	75	897	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	82	878	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	66	904	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	64	914	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	64	933	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	52	938	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	53	1026	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	53	957	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	54	960	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	44	953	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	1011	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	1069	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1028	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	40	1081	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	54	1038	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	44	1037	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	997	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	41	990	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	940	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	941	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	915	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	920	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	918	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	952	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:28:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	941	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	946	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	868	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	58	852	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	59	806	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	48	815	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	38	879	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	844	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	810	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	55	839	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	45	883	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	36	875	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	63	886	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	51	918	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	41	869	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	57	955	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	58	922	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	71	928	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	70	945	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	67	932	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	54	1005	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	44	936	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	1042	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	53	1002	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	53	985	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	54	1003	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	44	976	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	973	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	1001	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	995	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	978	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1006	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	998	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	36	1022	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	927	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	36	925	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	53	1045	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	43	1096	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	57	1078	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	46	1068	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	1105	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	1076	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	1078	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1082	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1024	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1001	Poured Concrete
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	994	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	14	Scan	Survey Unit 14	"	6/14/2012	4:29:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	918	Poured Concrete
Building 2540	4	Scan	Survey Unit 04	Miller	6/15/2012	10:38:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	1023	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:38:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	1043	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:38:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	969	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:38:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	899	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:38:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	939	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:38:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	941	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:38:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	977	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:38:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	985	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:38:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	982	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:38:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	944	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:38:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	935	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:38:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	935	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:38:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	965	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:38:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	998	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:38:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1023	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:38:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1021	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:38:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	1081	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:38:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	1103	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:38:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1138	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:38:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	1104	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:38:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	1065	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:38:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1031	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:38:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	1023	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:38:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	1066	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:38:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	1020	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:38:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	1057	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:38:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1148	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:38:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	1112	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:38:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	1076	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:38:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1098	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:38:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1107	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:38:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1124	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:38:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	1075	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1132	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1062	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	1044	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	1059	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	1052	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	1047	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1052	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1068	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1074	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1124	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1220	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	1185	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	1234	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	1124	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	1147	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	1136	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	1059	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1105	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	1074	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	973	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1005	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	976	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	930	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	902	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	948	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	981	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	1006	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	992	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	955	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	1001	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	948	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	972	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	922	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	951	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	967	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	975	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	1027	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	925	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	928	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	977	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	951	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	936	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	988	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	933	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	959	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	993	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1010	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1019	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1018	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	971	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	983	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	1002	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	1141	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1061	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	1071	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	1108	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	1092	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	1025	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	919	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:39:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	891	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	981	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	990	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	926	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	892	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	918	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	1011	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	967	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	932	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	866	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	962	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	909	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	939	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	895	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	931	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	866	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	849	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	875	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	834	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	877	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	859	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	869	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	830	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	813	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	803	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	822	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	813	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	860	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	902	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	851	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	850	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	855	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	922	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	954	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	912	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	908	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	872	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	936	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	975	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1100	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1077	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1019	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1057	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1043	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	983	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	970	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	980	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	931	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	937	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	973	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1054	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1004	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	904	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	948	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1021	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1030	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	969	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	987	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	900	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	881	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:40:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	978	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	966	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	1002	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	937	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	910	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	965	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	939	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	995	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	1057	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	1018	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	936	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	1004	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	997	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1008	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	917	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	942	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	952	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	975	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	1057	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	983	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	977	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	1101	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	1096	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1006	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	941	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	979	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	896	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	908	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	1024	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1022	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	965	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	988	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	1003	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	927	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	901	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	958	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1038	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	1008	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	1057	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1041	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	1052	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	1092	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1239	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1117	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1076	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1017	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1005	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	984	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1018	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	973	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1058	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1064	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1079	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1105	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1009	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	1018	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	982	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	953	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1040	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	954	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:41:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	968	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	948	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	999	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	1013	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	955	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	999	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	960	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	996	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1002	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	945	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	991	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	993	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	949	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	949	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	1023	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	989	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	957	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	986	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	1027	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	1050	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	1020	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	954	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	978	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	1057	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	993	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	989	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	1075	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	1076	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	929	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	889	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	972	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1041	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	1091	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	1098	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1060	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	1018	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	982	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	967	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	1105	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	1086	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	1059	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	1072	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	1086	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1061	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1015	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1099	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1119	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1088	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	1075	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	1136	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1124	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	1084	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1072	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	1083	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	1119	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	1008	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1043	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	1107	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	1035	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	1037	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:42:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	1069	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	1090	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	1052	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1174	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	1169	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	1267	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	1221	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1183	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	1108	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	1011	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1046	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1025	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1033	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1019	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1041	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	989	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	983	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	941	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	921	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1046	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	966	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	941	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	944	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	970	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1050	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1011	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	1011	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	897	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	866	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	926	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	932	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	857	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	865	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	986	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1059	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1026	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1050	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1100	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1106	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1117	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1084	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1016	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1064	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1057	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1019	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	952	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	968	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	956	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1045	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1006	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1029	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1024	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1092	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1068	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1025	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1058	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1051	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	988	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	938	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	929	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:43:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	967	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	936	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	871	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	832	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	858	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	878	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1044	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1005	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	997	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	954	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1019	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1029	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	1091	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	1078	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1036	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	988	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	1029	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	1106	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	1078	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	1089	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1031	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1099	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1099	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1083	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	1131	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	1067	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1093	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	1145	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	1099	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	1118	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	1007	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	1022	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1033	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	1076	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1055	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	1058	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	1041	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	946	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	925	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	934	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	937	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	964	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	986	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	950	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	931	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	832	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	867	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	863	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	913	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1091	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	1065	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	1044	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1064	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1026	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1047	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1045	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	959	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	946	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	992	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1006	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:44:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1013	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1016	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1016	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1003	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1064	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1010	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1048	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1113	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1173	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	1155	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	1128	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1122	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	1058	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	1010	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	989	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	938	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	976	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	980	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1043	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1006	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1023	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	956	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	876	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	909	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	995	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	998	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	978	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	1008	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	987	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	1002	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	1027	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	1028	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	1039	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	1011	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1048	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	951	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	928	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	914	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	966	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	961	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	925	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	885	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	899	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	901	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	841	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	853	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	910	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	903	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	888	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	926	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	882	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	918	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	925	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	971	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	901	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	922	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	983	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	945	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	946	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	939	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:45:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	912	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	817	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	821	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	813	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	809	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	881	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	898	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	915	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1019	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	1030	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1050	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	1113	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	1138	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1079	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	1048	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1099	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1015	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	987	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1005	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1087	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1154	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	1085	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	1131	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1098	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1059	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1054	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1037	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	975	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	972	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1001	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	993	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	1043	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	996	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	946	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	965	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	930	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	904	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	869	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	905	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1049	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1139	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	1023	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	978	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	1075	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	1142	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1158	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	1189	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	1077	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1074	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1056	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1039	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	981	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1023	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1054	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1011	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	945	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	982	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	1141	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	1142	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1024	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:46:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	1049	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	1045	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	996	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	932	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	974	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	989	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	1022	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1033	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	998	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	1002	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1007	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1011	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	976	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1005	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	966	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	928	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	976	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	973	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	1031	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	1031	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	997	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	966	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	982	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	986	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	1001	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1056	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	1059	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	1125	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1088	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1145	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1143	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1200	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1097	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	989	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1018	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1066	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1044	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1108	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1168	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	1245	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	1271	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1157	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	1040	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	932	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	947	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	927	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1006	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1024	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1049	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	985	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	1063	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	986	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	923	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	918	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	901	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	954	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	931	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	926	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	952	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	950	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:47:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	984	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	956	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	947	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	1015	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1006	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	992	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	954	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1021	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	905	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	1053	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	1044	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1095	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	1023	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	996	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1060	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	1078	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	1102	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1110	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1063	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1069	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1037	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1025	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1069	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1082	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1093	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1025	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	999	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1028	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	961	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	994	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	976	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	900	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	946	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	971	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	925	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	886	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	969	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	1048	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	983	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1028	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	932	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1051	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	1030	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	974	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	995	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	1082	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1143	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	1116	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1042	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	997	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	987	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1080	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1243	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1243	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1200	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1129	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1121	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1057	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1005	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	999	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:48:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	1026	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	1091	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	1088	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	1067	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1029	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	1067	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	989	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1017	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1063	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	986	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	956	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	922	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	896	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	907	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1007	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1076	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	1087	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1095	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	1058	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1061	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1052	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1037	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	974	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1018	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	1019	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	1031	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1005	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	953	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	969	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	1004	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	995	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	976	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	916	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	870	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	912	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	920	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1021	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	973	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	949	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	941	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1059	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1062	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1087	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1053	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1077	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1069	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1064	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1012	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1028	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	995	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	930	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	910	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	886	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	889	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	959	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	910	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	933	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1025	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1124	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	1206	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:49:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	1166	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1127	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1117	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1082	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1103	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1090	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1139	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1069	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1060	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1004	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1054	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1016	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	971	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1015	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1032	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1006	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1056	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1075	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	1020	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	1076	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1041	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1059	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1063	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1097	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1003	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	949	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	963	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	959	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	936	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	942	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	991	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1011	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	956	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	1125	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	1165	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	1102	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1083	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	1121	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	1102	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	1146	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	1159	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	1235	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	1137	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1170	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	1232	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	1160	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	1190	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	1171	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	1168	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	1164	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	1174	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1166	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	1210	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	1172	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	1177	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	1109	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1092	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	998	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	990	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	995	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:50:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	975	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	972	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	1040	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	1060	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	1008	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1023	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	1071	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	1094	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	999	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1002	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1039	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	1145	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	1224	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	1208	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1298	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1268	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1369	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1257	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1272	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	1362	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1388	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1260	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	1147	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	1145	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	1124	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1137	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	1068	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	1031	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	1027	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1012	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	911	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	851	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	894	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	870	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	953	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	999	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	1073	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1080	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	1102	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	1088	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1098	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1092	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	1078	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	1099	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	1073	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	1034	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	1118	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	1099	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	969	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	1035	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1032	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1114	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	1155	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	1180	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1195	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	1184	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	1142	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	1083	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1061	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	996	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:51:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	1072	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:52:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	1061	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:52:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	1063	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:52:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1016	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:52:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1047	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:52:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	1090	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:52:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	1019	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:52:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	1125	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:52:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1073	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:52:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1089	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:52:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	1075	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:52:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1031	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:52:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	997	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:52:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	966	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:52:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	1090	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:52:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	1054	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:52:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1130	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:52:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	1029	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:52:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	993	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:52:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	965	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:52:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	917	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:52:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	925	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:52:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	955	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:52:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	948	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:52:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	951	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:52:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	952	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:52:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	973	Laminate Tile
Building 2540	4	Scan	Survey Unit 04	"	6/15/2012	10:52:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	961	Laminate Tile
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	1076	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1017	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1012	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	965	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	941	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	945	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1008	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	976	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1087	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1078	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	1064	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1079	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	1012	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	966	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1019	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	1095	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1209	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1274	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1202	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1145	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1165	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1148	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1052	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1021	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	998	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	954	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	955	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	951	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	989	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	969	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1045	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	1028	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	1098	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	1061	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	1050	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	1005	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	972	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	944	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	968	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	900	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	866	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:14:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	851	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	871	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	857	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	880	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	839	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	894	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	886	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	810	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	936	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	976	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	966	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	955	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	964	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	986	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	957	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	956	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	910	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	953	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	976	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	869	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	815	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	763	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	834	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	880	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	903	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	913	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	912	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	932	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	938	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	940	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	873	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	934	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1019	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	991	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	996	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	1033	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	963	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	946	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1007	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	976	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	915	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	886	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	885	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	855	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	839	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	986	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	970	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	923	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1034	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	905	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	970	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1019	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1032	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	982	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	943	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	888	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	980	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	999	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	899	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	899	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:15:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	876	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	869	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	875	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	889	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	867	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	886	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	870	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	890	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	880	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	860	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	942	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	866	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	861	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	881	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	863	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	882	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	853	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	875	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	890	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	958	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1002	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	984	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1017	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	978	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	988	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	1019	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	983	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1059	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	972	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	937	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	907	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	895	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	904	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	870	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	970	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	968	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	919	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	951	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	917	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	902	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	877	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	929	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	887	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	820	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	742	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	855	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	874	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	912	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	887	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	810	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	836	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	924	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	954	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	986	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	994	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	965	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	939	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	940	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	817	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	849	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:16:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	917	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	936	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	969	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1009	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	967	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	982	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	985	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	969	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	988	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	968	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	977	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	941	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	953	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	895	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	886	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	822	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	859	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	915	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	979	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	972	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	974	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	948	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	913	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	894	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	948	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	905	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	929	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	867	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	852	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	893	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	871	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	866	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	894	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	859	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	829	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	900	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	956	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	913	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	889	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	873	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	854	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	816	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	845	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	870	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	900	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	897	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	831	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	835	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	801	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	784	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	840	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	737	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	747	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	707	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	779	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	746	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	797	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	785	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	831	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	778	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:17:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	764	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	749	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	832	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	810	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	827	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	783	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	802	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	924	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1055	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1071	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1106	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	1065	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	1057	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	961	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	971	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	961	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	891	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	894	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	892	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	893	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	961	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	985	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	1004	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	1042	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	990	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	903	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	911	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	916	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	937	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	937	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	955	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	840	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	885	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	907	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	941	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	922	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	885	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	945	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	949	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	927	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	932	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	956	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	980	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1098	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1077	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1054	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	1002	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	984	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	947	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	983	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	1000	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	1027	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1107	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1081	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1053	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	991	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	963	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	965	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	990	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1004	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:18:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	961	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	958	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1017	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1006	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1000	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1020	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1008	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1040	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1105	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1088	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1133	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1068	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1035	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	999	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	960	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	949	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	918	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	914	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	932	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1031	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	945	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1027	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	1015	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	912	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	826	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	866	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	903	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	891	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	984	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	934	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	917	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	925	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	968	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	936	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	894	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	873	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	875	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	967	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	967	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	894	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	872	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	855	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	898	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	842	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	865	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	845	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	821	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	848	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	881	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	885	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	898	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	899	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	862	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	822	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	794	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	870	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	831	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	844	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	823	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	813	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:19:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	786	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	786	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	788	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	822	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	861	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	984	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	976	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	981	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	942	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	877	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	858	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	900	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	945	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	918	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1021	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	1045	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	1019	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	954	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	943	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	904	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	979	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1081	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1092	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1023	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1008	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	953	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	935	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	930	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	903	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	909	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	918	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	846	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	789	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	802	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	914	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	953	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	932	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	959	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	995	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	1043	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	961	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	872	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	914	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	905	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	916	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	959	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	914	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	878	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	889	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	926	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	923	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	838	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	905	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	902	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	873	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	806	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	757	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	690	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	705	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	663	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:20:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	630	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	568	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	586	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	544	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	634	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	616	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	694	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	711	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	685	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	706	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	754	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	749	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	731	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	718	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	720	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	673	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	685	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	611	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	621	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	674	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	698	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	739	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	712	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	709	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	852	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	793	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	723	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	711	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	700	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	737	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	699	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	690	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	652	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	709	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	632	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	705	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	686	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	689	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	750	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	735	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	774	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	822	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	755	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	795	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	784	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	838	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	801	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	898	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	818	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	925	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	897	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	843	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	762	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	707	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	721	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	768	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	769	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	796	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	771	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	718	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:21:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	683	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	706	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	728	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	728	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	693	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	710	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	794	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	802	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	775	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	743	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	729	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	703	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	673	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	716	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	705	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	729	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	762	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	730	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	720	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	699	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	760	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	788	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	812	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	760	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	810	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	782	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	748	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	695	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	767	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	816	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	787	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	707	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	799	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	814	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	713	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	712	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	734	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	778	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	765	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	809	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	791	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	731	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	697	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	755	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	723	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	795	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	804	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	755	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	779	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	815	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	857	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	975	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	1014	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	1084	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	1082	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	990	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	917	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	948	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1051	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	989	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:22:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	996	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	933	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	938	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	978	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	950	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	898	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	857	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	932	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	924	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	977	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	951	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	984	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	957	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	943	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	912	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	932	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	882	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	875	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	834	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	858	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	888	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	892	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	928	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1003	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	1016	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	1018	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	983	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1032	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	1058	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	1015	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	947	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	977	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	978	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	916	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	938	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	979	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1032	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1109	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1028	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	950	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	918	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	977	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	1019	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	975	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	1049	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	997	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	889	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	891	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	918	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	881	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	975	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	881	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	899	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	948	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1020	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1027	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1027	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1085	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	1048	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	972	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:23:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	899	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	900	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	856	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	898	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	969	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	887	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	868	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	898	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	956	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	999	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	948	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	917	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	832	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	857	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	898	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	944	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	934	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	892	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	889	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	869	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	874	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	840	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	852	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	873	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	900	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	864	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	907	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	927	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	979	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1069	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	1048	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	1058	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1049	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	1037	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	1039	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1026	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	957	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	936	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	907	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	976	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	950	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	955	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	944	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	833	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	879	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	870	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	852	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	784	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	795	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	768	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	838	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	836	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	880	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	917	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	916	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	844	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	834	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	757	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	693	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	698	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:24:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	667	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	643	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	712	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	768	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	748	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	717	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	760	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	697	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	770	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	795	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	758	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	808	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	847	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	900	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	818	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	822	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	827	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	804	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	811	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	813	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	862	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	53	883	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	860	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	916	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	909	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	782	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	819	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	825	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	840	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	883	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	865	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	839	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	816	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	863	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	836	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	846	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	894	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	825	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	828	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	784	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	777	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	859	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	935	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1005	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	962	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	931	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	923	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	908	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	919	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	915	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	903	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	907	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	875	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1018	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	1096	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1060	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1021	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	961	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	904	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	895	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:25:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	915	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	933	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	972	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	916	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	935	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	949	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	975	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	946	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	1027	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	1029	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1009	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	942	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	928	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	879	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	930	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	938	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	974	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	887	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	886	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	888	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	843	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	830	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	928	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	957	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	869	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	932	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	959	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	912	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	975	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	983	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1012	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	983	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	954	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	957	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	900	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	845	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	833	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	825	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	832	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	875	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	859	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	946	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	958	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	961	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	970	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	961	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	916	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	899	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	875	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	898	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	934	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	904	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	913	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	934	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	904	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	952	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	992	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	998	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	977	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	951	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:26:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	885	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	853	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	795	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	771	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	785	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	829	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	795	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	759	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	716	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	691	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	754	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	738	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	721	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	683	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	680	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	689	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	696	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	700	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	736	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	809	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	841	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	817	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	802	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	789	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	812	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	819	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	859	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	855	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	910	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	952	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	962	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	984	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	926	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	927	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	934	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	860	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	780	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	781	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	749	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	753	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	782	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	782	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	860	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	836	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	845	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	828	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	875	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	884	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	956	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	1048	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	1086	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1021	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	954	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	988	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	913	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	915	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	927	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	955	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	975	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	1068	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:27:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1069	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	1080	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	1098	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	1016	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	948	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	907	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1010	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	964	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	902	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	902	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	901	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	891	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	925	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	876	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	834	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	963	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	997	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	987	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1058	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1062	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1042	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1085	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1038	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1033	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1019	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1017	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1042	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1070	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1018	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1030	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1005	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	981	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	967	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	911	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	884	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1001	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	959	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	948	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	860	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	870	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	927	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	892	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	871	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	864	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	882	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	891	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	986	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1019	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1008	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	953	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	954	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	934	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	880	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	907	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	967	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	973	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	971	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1065	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	1095	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1080	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:28:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1022	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:29:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1033	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:29:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1006	Drywall
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:31:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	1087	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:31:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	1143	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:31:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	1170	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:31:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1185	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:31:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1155	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:31:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	1180	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:31:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	1221	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:31:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	1292	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:31:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1231	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:31:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1258	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:31:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1261	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:31:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1223	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:31:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1227	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:31:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1281	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:31:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1262	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:31:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1278	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:31:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1229	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:31:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1270	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	1174	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	1158	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1247	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1167	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1183	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1202	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1186	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	1155	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	1140	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1233	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1237	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	1217	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	1272	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1145	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1217	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1248	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1220	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1227	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	1236	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	1173	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1185	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1256	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1220	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1181	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1175	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	1161	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1257	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	1245	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1158	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1173	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	1196	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	1150	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	1174	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1212	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	1210	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	1318	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	1215	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1154	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1230	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	1261	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	1239	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	1255	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	1259	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1317	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	1261	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	1235	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1216	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1181	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1213	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1163	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	1054	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	1110	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	1208	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	1232	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	1179	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1126	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	1139	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	1237	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	1250	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:32:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	1171	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	1073	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	1047	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1200	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	1206	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1156	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	1131	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1098	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	1117	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1223	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	1260	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1272	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	1284	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	1303	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	1342	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	1293	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	1379	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	1389	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1457	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	1389	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	1351	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1363	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	1375	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1386	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1394	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1386	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1328	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1294	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1367	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1302	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1329	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1361	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1402	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1316	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1303	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1228	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1238	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	1267	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	1297	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	1332	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	1303	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	1347	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	1401	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1410	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1420	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	1475	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	1361	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	1273	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1179	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1237	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1195	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1174	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1178	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1117	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	1110	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1037	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1034	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1083	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1034	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1050	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:33:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1031	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:34:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1127	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:34:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1243	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:34:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1166	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:34:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1198	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:34:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1161	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:34:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1179	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:34:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	1083	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:34:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	1048	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:34:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	952	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:34:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	956	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:34:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1000	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:34:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	1014	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:34:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	989	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:34:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	998	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:34:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	980	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:34:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	989	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:34:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	982	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:34:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	989	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:34:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	959	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:34:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	1085	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:34:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	1167	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:34:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	1128	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:34:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1150	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:34:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1236	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:34:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1209	Poured Concrete
Building 2540	5	Scan	Survey Unit 05	"	6/15/2012	11:34:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	1231	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	614	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	656	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	667	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	643	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	630	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	616	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	683	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	731	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	754	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	727	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	668	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	691	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	47	643	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	38	645	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	625	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	561	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	626	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	711	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	733	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	674	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	707	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	673	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	675	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	753	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	735	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	780	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	712	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	701	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	731	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	717	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	731	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	660	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	602	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	634	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	659	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	704	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	698	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	807	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	778	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:41:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	700	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	752	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	813	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	818	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	809	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	781	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	735	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	675	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	703	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	675	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	683	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	670	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	703	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	715	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	705	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	708	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	778	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	755	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	783	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	766	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	779	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	741	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	746	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	709	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	755	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	746	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	705	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	773	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	659	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	638	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	641	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	646	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	650	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	650	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	620	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	617	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	657	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	667	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	631	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	649	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	672	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	648	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	661	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	614	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	611	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	588	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	601	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	609	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	664	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	698	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	705	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	775	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	778	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	785	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	951	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	829	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	823	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	757	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	693	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	758	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:42:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	704	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	684	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	705	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	740	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	734	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	744	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	716	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	684	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	656	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	649	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	617	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	635	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	592	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	595	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	588	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	622	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	697	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	669	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	621	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	616	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	632	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	683	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	714	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	636	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	675	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	730	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	636	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	594	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	605	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	651	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	697	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	681	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	669	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	702	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	751	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	652	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	648	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	660	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	655	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	694	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	698	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	656	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	645	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	658	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	694	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	641	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	724	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	678	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	627	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	679	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	724	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	750	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	721	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	744	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	727	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	712	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	678	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	674	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	626	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	588	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:43:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	602	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	599	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	652	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	719	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	811	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	829	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	796	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	793	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	758	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	790	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	762	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	720	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	721	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	747	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	715	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	637	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	680	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	698	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	678	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	689	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	693	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	665	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	722	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	770	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	770	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	738	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	735	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	732	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	694	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	653	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	712	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	701	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	672	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	747	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	721	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	761	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	754	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	725	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	745	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	680	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	752	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	746	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	786	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	765	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	676	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	671	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	667	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	666	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	654	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	621	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	650	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	641	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	658	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	658	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	704	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	682	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	734	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	740	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	726	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	728	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:44:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	728	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	808	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	813	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	738	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	780	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	781	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	762	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	687	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	831	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	901	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	924	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	857	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	840	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	839	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	837	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	852	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	837	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	838	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	882	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	888	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	814	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	807	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	732	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	686	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	638	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	601	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	670	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	648	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	639	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	676	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	639	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	710	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	701	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	706	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	764	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	724	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	749	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	732	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	765	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	778	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	758	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	757	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	775	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	727	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	737	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	721	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	730	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	740	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	748	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	710	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	656	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	632	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	693	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	638	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	643	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	646	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	699	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	667	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	700	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	658	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:45:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	709	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	746	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	687	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	667	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	610	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	627	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	565	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	537	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	515	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	511	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	564	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	549	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	573	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	679	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	756	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	716	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	751	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	768	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	762	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	731	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	682	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	674	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	762	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	802	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	754	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	691	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	718	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	810	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	791	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	895	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	882	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	806	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	768	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	701	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	716	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	693	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	677	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	661	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	649	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	696	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	690	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	718	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	723	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	721	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	781	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	761	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	741	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	761	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	795	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	783	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	801	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	741	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	783	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	735	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	689	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	696	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	703	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	727	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	670	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	687	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:46:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	682	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	653	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	656	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	712	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	712	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	705	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	700	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	724	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	678	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	717	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	731	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	680	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	714	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	661	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	626	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	667	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	645	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	615	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	617	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	684	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	691	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	639	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	645	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	601	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	601	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	625	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	609	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	574	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	581	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	595	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	667	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	664	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	665	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	630	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	590	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	593	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	560	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	555	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	542	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	44	633	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	640	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	610	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	596	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	707	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	716	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	716	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	682	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	688	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	671	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	613	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	599	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	635	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	650	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	673	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	657	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	774	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	730	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	750	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	707	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	785	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:47:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	763	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	708	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	655	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	727	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	690	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	663	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	693	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	712	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	702	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	693	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	696	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	692	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	720	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	783	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	762	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	745	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	719	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	708	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	688	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	649	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	687	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	684	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	644	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	635	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	687	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	682	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	669	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	645	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	714	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	670	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	739	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	702	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	708	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	710	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	720	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	709	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	721	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	721	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	770	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	771	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	774	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	800	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	817	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	841	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	806	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	856	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	895	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	894	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	861	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	868	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	813	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	739	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	692	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	750	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	734	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	797	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	758	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	811	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	782	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	782	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:48:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	864	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	887	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	851	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	768	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	745	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	757	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	809	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	782	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	875	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	836	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	836	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	734	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	663	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	605	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	695	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	675	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	686	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	693	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	665	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	722	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	699	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	656	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	638	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	619	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	604	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	603	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	612	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	642	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	682	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	687	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	681	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	690	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	728	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	670	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	701	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	612	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	656	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	636	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	628	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	602	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	650	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	640	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	654	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	656	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	623	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	572	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	581	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	550	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	503	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	498	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	585	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	589	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	602	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	635	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	651	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	742	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	761	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	762	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	720	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	741	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:49:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	760	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	831	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	763	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	802	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	786	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	806	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	834	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	845	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	788	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	760	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	797	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	768	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	722	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	691	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	754	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	749	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	751	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	742	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	714	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	738	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	811	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	770	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	807	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	780	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	709	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	642	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	587	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	596	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	607	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	615	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	603	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	603	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	673	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	633	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	673	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	662	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	741	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	765	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	767	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	771	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	766	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	791	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	752	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	723	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	655	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	611	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	608	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	628	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	658	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	614	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	564	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	547	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	510	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	459	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	451	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	537	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	522	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	517	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	488	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	546	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:50:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	532	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	532	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	568	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	541	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	575	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	558	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	591	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	641	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	566	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	606	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	667	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	655	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	665	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	674	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	695	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	745	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	752	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	738	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	755	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	748	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	719	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	730	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	729	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	737	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	721	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	677	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	43	686	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	739	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	701	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	743	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	863	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	866	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	814	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	777	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	707	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	758	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	750	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	723	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	675	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	636	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	660	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	649	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	660	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	648	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	640	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	706	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	698	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	657	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	648	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	628	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	612	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	643	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	602	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	567	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	550	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	569	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	629	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	637	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	618	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	582	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:51:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	621	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	592	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	617	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	650	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	674	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	649	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	686	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	624	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	663	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	635	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	641	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	610	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	628	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	40	666	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	43	661	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	45	673	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	611	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	621	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	675	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	653	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	589	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	566	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	539	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	539	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	607	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	626	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	622	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	619	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	615	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	717	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	680	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	724	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	716	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	683	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	654	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	622	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	606	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	622	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	583	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	618	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	557	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	555	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	589	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	533	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	605	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	581	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	585	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	554	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	537	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	514	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	556	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	566	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	609	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	701	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	660	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	614	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	660	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	748	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	754	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	747	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:52:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	738	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	752	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	857	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	819	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	776	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	685	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	746	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	742	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	782	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	712	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	680	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	687	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	646	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	686	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	741	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	723	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	759	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	775	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	732	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	739	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	714	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	738	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	768	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	763	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	733	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	729	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	716	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	706	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	666	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	676	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	594	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	571	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	550	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	594	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	713	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	780	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	760	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	706	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	758	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	707	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	642	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	670	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	633	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	706	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	718	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	708	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	698	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	761	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	809	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	825	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	830	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	832	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	787	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	728	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	738	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	738	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	711	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	654	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	679	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	698	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:53:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	693	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	730	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	693	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	643	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	680	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	735	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	696	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	727	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	691	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	708	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	713	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	763	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	720	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	765	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	768	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	727	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	746	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	739	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	689	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	660	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	661	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	659	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	673	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	671	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	704	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	742	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	703	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	706	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	686	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	743	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	729	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	763	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	744	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	798	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	729	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	774	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	753	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	724	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	690	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	695	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	674	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	663	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	718	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	706	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	729	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	769	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	761	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	752	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	836	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	769	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	738	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	780	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	766	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	692	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	715	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	635	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	626	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	641	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	658	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	660	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:54:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	636	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:55:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	683	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:55:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	611	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:55:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	655	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:55:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	621	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:55:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	641	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:55:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	666	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:55:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	656	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:55:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	677	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:55:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	672	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:55:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	673	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:55:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	660	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:55:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	656	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:55:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	657	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:55:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	653	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:55:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	679	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:55:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	743	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:55:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	691	Poured Concrete
Building 2540	10	Scan	Survey Unit 10	"	6/15/2012	2:55:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	708	Poured Concrete
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	585	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	600	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	590	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	534	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	568	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	561	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	650	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	626	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	621	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	641	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	622	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	663	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	630	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	623	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	596	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	563	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	549	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	592	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	583	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	555	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	531	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	563	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	561	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	592	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	592	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	631	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	634	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	640	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	667	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	713	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	713	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	717	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	638	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	664	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	641	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	635	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	616	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	694	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	734	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	712	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	652	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	610	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:08:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	585	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	564	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	592	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	606	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	674	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	679	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	744	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	754	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	710	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	690	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	705	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	641	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	678	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	648	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	675	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	717	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	693	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	700	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	729	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	684	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	676	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	634	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	673	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	724	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	699	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	679	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	714	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	718	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	722	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	686	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	669	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	789	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	752	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	768	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	710	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	670	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	622	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	548	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	587	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	591	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	591	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	606	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	604	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	704	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	694	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	628	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	635	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	614	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	637	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	629	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	625	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	686	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	637	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	630	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	591	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	604	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	566	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	563	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	545	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	580	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:09:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	609	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	563	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	522	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	501	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	507	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	553	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	539	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	583	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	629	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	635	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	605	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	617	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	682	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	677	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	695	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	655	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	671	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	726	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	750	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	688	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	726	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	676	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	671	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	637	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	689	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	637	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	641	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	700	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	682	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	665	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	660	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	650	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	609	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	620	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	742	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	715	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	625	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	611	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	655	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	709	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	677	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	718	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	707	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	688	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	762	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	800	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	43	751	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	46	783	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	847	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	814	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	877	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	733	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	752	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	820	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	769	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	780	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	884	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	866	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	887	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	879	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:10:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	802	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	834	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	904	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	885	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	809	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	768	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	847	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	821	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	846	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	846	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	835	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	856	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	805	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	837	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	769	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	821	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	859	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	785	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	796	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	746	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	762	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	787	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	783	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	770	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	780	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	828	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	831	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	854	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	874	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	912	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	854	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	886	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	923	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	916	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	961	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	912	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	980	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	928	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	878	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	884	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	878	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	858	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	935	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	882	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	898	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	886	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	809	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	758	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	693	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	673	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	593	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	642	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	741	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	817	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	847	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	823	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	919	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	998	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1001	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	983	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:11:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1001	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	936	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	904	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	894	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	957	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	944	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	887	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	819	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	823	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	894	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	863	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	870	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	886	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	877	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	825	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	759	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	772	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	740	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	786	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	753	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	745	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	750	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	731	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	730	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	672	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	682	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	759	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	810	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	817	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	851	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	790	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	796	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	772	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	764	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	710	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	707	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	672	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	621	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	586	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	657	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	703	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	695	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	698	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	646	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	662	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	649	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	616	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	555	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	585	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	589	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	567	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	537	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	628	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	553	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	598	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	530	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	498	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	495	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	572	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	625	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:12:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	668	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	774	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	718	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	660	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	640	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	666	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	687	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	688	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	647	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	600	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	609	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	651	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	697	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	678	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	732	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	711	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	702	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	761	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	719	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	684	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	622	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	548	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	511	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	529	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	574	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	628	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	644	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	668	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	745	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	728	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	738	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	768	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	736	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	698	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	694	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	642	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	680	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	642	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	623	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	627	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	608	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	606	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	643	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	668	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	679	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	710	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	722	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	722	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	786	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	817	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	776	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	697	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	779	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	791	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	803	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	743	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	763	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	811	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	771	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	750	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:13:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	689	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	725	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	714	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	670	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	646	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	603	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	601	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	569	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	574	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	558	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	635	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	698	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	678	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	620	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	663	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	640	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	646	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	626	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	585	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	597	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	654	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	694	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	652	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	629	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	649	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	662	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	673	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	681	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	705	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	663	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	648	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	683	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	746	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	728	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	760	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	763	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	664	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	652	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	666	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	598	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	607	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	605	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	592	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	595	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	585	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	529	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	643	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	659	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	613	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	624	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	584	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	632	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	628	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	663	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	662	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	642	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	634	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	684	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	682	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	747	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:14:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	706	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	720	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	723	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	691	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	678	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	662	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	696	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	655	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	565	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	580	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	575	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	582	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	566	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	574	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	625	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	629	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	704	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	649	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	597	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	597	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	528	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	555	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	519	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	560	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	590	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	604	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	682	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	693	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	744	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	707	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	697	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	665	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	619	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	592	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	594	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	641	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	648	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	662	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	603	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	634	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	690	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	673	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	634	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	641	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	687	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	660	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	737	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	720	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	747	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	695	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	690	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	730	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	669	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	719	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	696	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	772	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	800	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	791	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	722	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	698	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:15:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	716	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	670	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	690	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	661	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	673	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	647	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	637	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	650	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	686	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	715	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	695	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	621	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	629	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	622	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	678	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	652	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	622	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	582	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	561	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	544	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	552	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	506	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	445	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	441	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	448	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	480	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	514	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	487	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	486	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	461	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	441	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	470	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	462	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	453	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	469	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	506	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	572	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	599	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	586	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	622	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	561	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	617	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	600	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	565	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	562	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	584	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	520	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	511	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	553	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	491	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	533	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	521	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	537	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	547	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	573	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	509	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	503	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	464	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	467	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	412	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:16:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	368	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	377	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	421	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	432	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	477	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	480	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	434	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	479	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	467	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	492	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	516	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	520	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	493	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	457	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	449	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	455	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	474	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	498	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	493	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	512	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	495	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	547	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	589	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	626	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	564	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	594	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	636	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	641	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	656	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	653	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	689	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	696	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	691	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	695	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	712	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	712	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	735	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	769	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	840	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	802	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	799	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	890	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	858	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	810	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	747	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	754	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	720	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	842	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	774	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	709	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	723	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	733	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	741	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	770	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	772	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	719	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	712	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	713	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	761	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	739	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:17:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	689	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	694	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	687	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	649	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	570	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	624	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	642	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	633	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	600	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	596	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	657	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	622	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	641	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	645	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	579	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	605	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	674	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	625	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	595	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	616	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	644	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	679	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	697	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	703	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	704	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	650	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	630	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	600	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	600	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	630	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	684	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	714	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	703	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	670	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	645	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	655	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	619	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	625	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	631	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	659	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	636	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	650	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	666	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	617	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	567	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	631	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	637	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	652	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	620	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	660	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	671	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	691	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	695	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	725	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	734	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	673	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	741	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	667	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	720	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	754	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:18:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	737	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	723	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	718	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	661	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	673	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	683	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	690	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	714	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	717	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	696	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	654	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	681	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	643	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	646	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	639	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	623	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	722	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	696	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	771	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	774	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	778	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	740	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	692	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	640	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	624	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	611	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	610	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	662	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	708	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	777	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	742	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	696	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	680	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	618	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	590	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	572	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	540	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	514	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	617	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	604	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	614	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	632	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	557	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	573	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	591	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	556	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	528	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	531	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	532	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	545	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	511	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	528	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	592	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	590	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	626	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	609	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	618	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	591	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	581	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	541	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:19:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	517	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	624	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	622	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	664	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	663	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	699	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	664	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	664	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	661	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	717	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	652	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	724	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	680	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	631	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	591	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	511	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	541	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	552	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	598	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	585	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	588	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	613	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	655	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	644	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	682	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	716	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	647	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	708	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	699	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	682	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	667	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	633	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	714	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	797	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	747	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	697	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	702	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	669	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	679	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	675	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	682	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	693	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	685	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	714	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	714	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	645	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	657	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	611	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	596	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	564	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	619	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	648	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	569	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	608	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	562	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	604	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	626	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	613	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	621	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	682	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:20:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	733	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	684	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	588	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	610	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	663	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	649	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	618	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	624	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	574	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	579	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	493	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	583	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	597	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	609	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	593	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	597	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	680	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	687	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	670	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	624	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	667	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	669	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	701	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	658	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	612	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	649	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	706	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	706	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	616	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	555	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	530	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	615	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	627	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	619	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	653	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	641	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	703	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	703	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	671	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	758	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	715	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	693	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	662	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	652	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	618	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	639	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	622	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	570	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	598	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	622	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	595	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	576	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	557	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	561	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	61	606	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	50	549	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	40	603	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	637	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	664	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	607	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:21:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	698	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	656	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	645	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	702	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	743	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	645	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	601	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	566	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	561	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	582	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	562	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	626	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	589	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	580	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	596	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	553	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	573	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	667	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	664	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	652	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	629	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	579	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	608	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	617	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	655	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	675	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	615	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	630	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	645	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	657	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	609	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	572	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	648	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	733	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	705	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	754	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	757	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	753	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	788	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	707	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	661	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	706	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	647	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	661	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	634	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	618	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	640	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	657	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	645	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	602	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	593	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	586	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	586	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	557	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	553	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	585	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	554	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	527	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	525	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	596	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:22:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	595	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	628	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	46	656	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	634	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	661	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	673	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	674	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	624	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	654	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	675	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	638	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	574	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	579	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	585	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	610	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	582	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	538	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	592	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	581	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	699	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	665	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	631	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	646	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	703	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	727	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	690	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	684	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	646	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	682	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	667	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	730	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	719	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	709	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	731	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	657	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	694	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	644	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	693	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	689	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	682	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	703	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	662	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	644	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	591	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	557	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	530	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	511	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	551	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	615	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	658	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	614	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	633	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	636	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	767	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	733	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	774	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	847	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	798	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	824	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	780	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:23:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	770	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	681	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	697	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	702	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	762	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	696	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	701	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	622	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	618	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	592	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	604	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	602	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	603	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	665	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	698	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	749	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	722	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	664	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	663	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	631	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	617	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	637	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	619	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	638	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	647	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	652	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	586	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	573	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	609	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	617	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	614	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	749	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	860	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	858	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	786	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	865	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	861	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	858	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	821	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	792	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	860	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	837	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	769	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	779	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	722	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	755	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	741	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	681	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	641	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	621	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	651	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	702	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	682	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	671	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	646	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	651	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	675	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	705	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	671	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	691	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:24:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	754	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	736	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	735	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	662	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	672	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	638	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	550	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	550	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	573	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	521	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	567	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	529	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	518	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	559	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	557	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	613	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	636	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	654	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	725	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	646	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	660	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	696	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	653	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	619	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	660	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	641	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	686	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	667	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	642	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	646	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	627	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	587	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	586	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	557	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	587	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	565	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	584	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	594	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	594	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	579	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	559	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	566	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	561	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	567	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	652	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	720	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	738	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	745	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	719	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	659	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	671	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	624	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	665	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	585	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	588	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	578	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	594	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	583	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	574	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	589	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:25:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	603	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	593	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	607	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	607	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	661	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	582	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	565	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	547	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	536	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	572	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	576	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	604	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	635	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	655	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	644	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	657	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	679	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	642	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	714	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	671	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	701	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	638	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	597	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	40	621	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	619	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	592	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	596	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	609	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	632	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	614	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	634	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	641	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	623	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	698	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	633	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	636	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	660	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	696	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	701	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	705	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	706	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	675	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	662	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	641	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	617	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	628	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	600	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	542	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	553	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	754	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	761	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	750	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	722	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	700	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	772	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	715	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	704	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	652	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	644	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	597	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:26:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	539	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	597	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	565	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	618	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	588	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	611	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	621	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	628	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	623	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	643	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	623	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	782	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	699	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	647	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	614	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	600	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	576	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	596	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	630	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	669	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	645	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	624	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	586	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	598	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	641	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	632	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	615	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	614	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	611	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	612	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	596	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	606	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	624	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	668	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	673	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	740	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	744	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	761	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	801	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	784	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	716	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	649	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	677	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	673	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	636	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	630	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	648	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	661	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	581	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	576	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	533	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	521	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	528	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	563	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	606	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	535	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	480	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	459	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	539	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	562	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:27:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	547	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	546	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	543	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	566	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	550	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	599	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	586	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	533	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	555	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	582	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	585	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	598	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	630	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	614	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	621	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	643	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	668	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	670	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	600	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	587	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	587	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	632	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	626	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	610	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	575	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	590	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	627	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	629	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	626	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	610	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	596	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	630	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	591	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	566	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	575	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	616	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	650	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	596	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	641	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	623	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	639	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	653	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	725	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	654	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	676	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	782	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	759	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	706	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	682	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	677	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	617	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	639	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	630	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	651	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	684	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	668	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	737	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	816	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	815	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	783	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:28:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	723	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	709	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	702	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	756	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	781	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	724	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	707	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	674	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	638	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	632	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	617	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	668	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	619	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	569	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	539	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	542	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	495	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	561	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	536	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	527	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	585	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	573	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	598	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	531	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	568	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	577	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	582	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	551	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	571	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	678	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	618	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	625	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	644	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	635	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	686	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	761	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	672	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	692	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	711	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	724	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	720	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	721	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	766	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	807	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	790	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	803	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	731	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	702	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	697	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	698	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	633	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	651	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	656	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	637	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	655	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	716	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	730	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	671	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	771	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	785	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:29:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	746	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	815	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	885	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	890	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	933	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1005	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1031	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1037	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	898	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	821	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	733	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	673	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	670	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	748	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	750	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	752	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	783	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	831	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	868	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	872	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	773	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	730	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	716	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	625	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	600	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	567	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	653	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	664	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	640	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	675	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	696	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	642	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	705	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	719	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	796	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	852	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	813	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	816	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	863	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	836	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	862	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	801	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	775	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	742	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	692	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	641	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	630	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	613	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	598	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	554	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	572	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	528	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	520	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	513	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	495	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	480	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	501	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	543	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	575	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	565	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:30:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	630	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:31:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	669	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:31:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	681	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:31:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	688	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:31:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	704	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:31:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	688	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:31:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	639	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:31:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	617	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:31:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	600	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:31:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	587	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:31:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	567	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:31:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	605	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:31:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	673	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:31:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	635	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:31:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	569	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:31:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	623	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:31:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	634	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:31:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	630	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:31:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	579	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:31:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	557	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:31:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	521	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:31:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	514	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:31:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	541	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:31:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	568	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:31:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	620	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:31:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	582	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:31:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	552	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:31:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	541	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:31:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	528	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:31:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	485	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:31:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	526	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:31:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	559	Concrete Block
Building 2540	11	Scan	Survey Unit 11	"	6/15/2012	2:31:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	588	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:58:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	742	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:58:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	763	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:58:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	790	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:58:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	744	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:58:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	774	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:58:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	858	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:58:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	845	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:58:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	765	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:58:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	792	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:58:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	791	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:58:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	825	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:58:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	938	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:58:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	976	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:58:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	825	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:58:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	841	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:58:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	862	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:58:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	851	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:58:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	778	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:58:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	755	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:58:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	770	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:58:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	759	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:58:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	764	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:58:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	850	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:58:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	816	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:58:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	877	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:58:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	896	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:58:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	852	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:58:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	860	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:58:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	847	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:58:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	792	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	822	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	768	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	814	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	918	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	906	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	928	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	876	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	857	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	912	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	993	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	964	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	939	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	898	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	849	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	800	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	763	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	765	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	825	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	784	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	807	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	851	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	867	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	859	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	855	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	915	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	858	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	852	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	860	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	826	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	895	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	873	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	873	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	888	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	798	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	760	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	769	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	701	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	695	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	776	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	778	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	762	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	709	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	631	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	635	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	672	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	669	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	666	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	697	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	745	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	775	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	753	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	757	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	714	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	745	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	716	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	707	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	742	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	798	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	783	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	11:59:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	747	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	719	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	811	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	819	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	787	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	784	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	760	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	751	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	754	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	792	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	812	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	739	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	815	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	783	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	818	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	730	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	741	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	702	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	787	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	749	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	721	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	742	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	715	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	775	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	824	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	873	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	844	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	874	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	822	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	757	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	836	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	744	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	716	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	714	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	683	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	761	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	742	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	746	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	729	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	719	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	720	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	755	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	711	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	792	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	755	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	714	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	841	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	860	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	776	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	787	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	829	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	875	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	867	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	848	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	862	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	874	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	834	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	860	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	763	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	733	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:00:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	774	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	798	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	817	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	777	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	732	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	719	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	834	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	929	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	889	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	856	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	886	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	819	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	928	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	970	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	921	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	885	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	830	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	786	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	806	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	804	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	753	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	784	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	748	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	778	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	747	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	756	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	820	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	851	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	826	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	884	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	878	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	848	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	813	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	794	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	768	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	876	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	894	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	874	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	823	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	783	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	764	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	720	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	676	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	604	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	36	696	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	678	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	660	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	682	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	676	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	718	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	669	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	782	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	806	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	766	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	757	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	782	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	818	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	867	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	815	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	802	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:01:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	743	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	669	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	646	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	626	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	715	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	763	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	746	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	798	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	773	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	754	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	783	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	793	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	807	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	847	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	798	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	826	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	806	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	837	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	895	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	887	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	915	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	969	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	922	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	931	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	933	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	870	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	760	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	762	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	786	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	826	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	783	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	783	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	760	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	754	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	759	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	830	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	880	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	861	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	904	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	870	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	843	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	864	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	860	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	924	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	917	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	889	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	904	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	893	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	850	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	767	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	733	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	741	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	793	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	824	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	893	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	884	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	821	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	766	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	778	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	765	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:02:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	781	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	836	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	853	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	857	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	794	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	863	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	880	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	923	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	884	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	901	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	922	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	836	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	943	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	876	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	881	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	908	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	875	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	822	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	861	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	890	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	883	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	888	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	876	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	926	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	942	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	876	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	893	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	920	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	882	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	845	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	706	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	690	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	705	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	684	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	634	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	595	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	595	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	610	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	644	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	648	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	592	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	597	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	618	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	614	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	556	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	517	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	553	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	559	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	612	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	644	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	681	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	722	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	733	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	720	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	685	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	746	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	705	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	730	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	739	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	735	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:03:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	686	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	727	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	680	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	719	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	751	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	710	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	687	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	706	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	711	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	772	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	752	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	823	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	827	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	851	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	853	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	899	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	920	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	916	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	972	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1003	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1007	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1036	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1023	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1091	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1051	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	990	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	992	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1062	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1055	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1026	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1102	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1075	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1038	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1013	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	914	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	881	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	838	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	935	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	945	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	903	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	961	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1004	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1033	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1008	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	964	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	883	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	804	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	855	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	875	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	828	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	862	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	754	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	795	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	735	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	834	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	823	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	817	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	788	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:04:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	786	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	796	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	843	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	783	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	781	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	829	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	856	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	920	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	903	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	966	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	931	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	916	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	38	951	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	895	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	919	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	950	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	973	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	993	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1029	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1039	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	989	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	927	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	895	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	919	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	912	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	971	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	878	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	827	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	782	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	746	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	801	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	797	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	853	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	950	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	906	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	908	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	920	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	972	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	928	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1026	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	969	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	955	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	933	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	907	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1009	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	965	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1021	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	942	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	902	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	901	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	892	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	963	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	942	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	899	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	932	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	917	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1005	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	931	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	918	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	927	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:05:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	974	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	968	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	933	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	992	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1040	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1034	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	962	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	895	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	849	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	870	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	821	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	855	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	926	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	887	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	922	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	862	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	893	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	860	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	813	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	816	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	923	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	863	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	845	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	801	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	795	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	824	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	839	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	746	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	787	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	805	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	800	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	822	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	839	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	894	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	841	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	828	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	864	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	904	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	925	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	983	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	980	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	978	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	953	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	967	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	933	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	836	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	874	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	834	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	817	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	880	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	872	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	876	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	880	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	898	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	892	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	848	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	816	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	818	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	889	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	882	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:06:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	866	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	862	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	813	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	863	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	834	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	880	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	944	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	889	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	937	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	907	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	894	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	872	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	970	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	944	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	960	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	954	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1003	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1002	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	916	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	937	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	839	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	803	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	846	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	821	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	875	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	881	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	897	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	874	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	900	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	854	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	875	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	928	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	915	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	900	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	979	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1000	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	991	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1008	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	977	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1006	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	988	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	996	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	922	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	893	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	903	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	910	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	926	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	908	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	982	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1024	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1012	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	979	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	980	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	940	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	908	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	884	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	888	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	926	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	909	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	975	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:07:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	980	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	931	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	877	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	880	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	884	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	907	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	863	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	856	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	832	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	905	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	918	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	929	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	943	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	956	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	900	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	865	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	793	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	755	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	693	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	704	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	661	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	746	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	720	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	766	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	776	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	791	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	721	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	43	655	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	643	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	40	635	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	67	653	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	54	665	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	44	620	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	635	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	39	579	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	573	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	556	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	517	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	491	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	580	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	596	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	40	571	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	660	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	659	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	657	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	648	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	664	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	607	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	606	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	619	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	637	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	618	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	603	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	732	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	716	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	740	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	736	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	765	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	813	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	739	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:08:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	746	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	697	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	713	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	740	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	750	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	767	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	793	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	790	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	834	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	868	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	873	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	928	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	960	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	923	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	882	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	795	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	772	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	784	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	828	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	819	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	883	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	916	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	887	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	820	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	801	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	836	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	828	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	889	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	924	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	962	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	971	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	939	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	899	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	992	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	985	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	964	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1006	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	972	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	916	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	911	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	905	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	902	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	950	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	906	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	934	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	960	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	933	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	933	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1008	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1013	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	996	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	943	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	938	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	961	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	942	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	945	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	982	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	965	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	991	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1070	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:09:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1025	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	924	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	896	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	883	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	883	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	922	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	906	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	940	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	925	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	985	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	959	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	911	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	906	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	858	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	890	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	923	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	933	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	870	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	861	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	916	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	995	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	939	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	948	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	914	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	889	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	899	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	869	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	942	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	912	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	922	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	895	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	906	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	982	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	932	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	928	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	913	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	900	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	971	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	989	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	946	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	914	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1015	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	981	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1010	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	997	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	923	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	968	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	967	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	987	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1006	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1003	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1028	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1074	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1063	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	953	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	963	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	974	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	915	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	911	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	874	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:10:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	812	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	851	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	838	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	747	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	686	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	702	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	727	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	747	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	746	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	764	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	801	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	751	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	720	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	792	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	710	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	753	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	726	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	841	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	867	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	855	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	875	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	916	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	924	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	866	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	881	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	869	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	861	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	845	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	876	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	928	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	863	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1010	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	967	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	861	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	868	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	883	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	860	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	903	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	808	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	824	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	825	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	815	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	787	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	747	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	787	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	851	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	884	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	851	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	871	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	853	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	805	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	856	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	833	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	868	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	882	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	843	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	807	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	813	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	810	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	781	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:11:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	775	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	708	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	753	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	819	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	869	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	900	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	867	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	850	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	916	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	847	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	915	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	890	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	953	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	933	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	998	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	988	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	951	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	961	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1027	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	961	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	935	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	908	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	805	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	766	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	882	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	945	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	879	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	826	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	779	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	825	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	848	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	870	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	842	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	911	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	884	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	840	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	921	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	919	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	893	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	816	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	823	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	780	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	847	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	833	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	891	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	856	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	839	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	873	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	880	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	808	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	807	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	820	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	801	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	812	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	782	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	795	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	771	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	759	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	742	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	749	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:12:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	805	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	829	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	854	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	886	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	910	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	873	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	841	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	838	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	816	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	794	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	825	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	814	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	891	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	880	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	836	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	782	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	793	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	883	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	871	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	832	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	810	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	809	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	759	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	750	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	742	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	749	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	770	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	797	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	759	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	799	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	830	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	799	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	803	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	786	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	750	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	708	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	746	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	741	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	744	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	726	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	738	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	642	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	682	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	642	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	696	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	722	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	755	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	764	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	790	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	848	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	788	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	777	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	711	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	711	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	733	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	742	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	705	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	698	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	818	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	825	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:13:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	852	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	825	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	977	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1029	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1037	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	978	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	917	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	949	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1004	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1029	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1015	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	923	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	884	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	885	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	875	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	867	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	805	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	832	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	822	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	888	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	885	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	854	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	795	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	882	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	898	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	903	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	869	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	858	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	865	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	885	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	866	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	863	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	903	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	956	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1014	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	981	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	921	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	792	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	823	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	845	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	904	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	953	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	915	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	907	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	881	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	862	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	809	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	793	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	719	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	744	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	806	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	770	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	786	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	867	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	795	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	829	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	808	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	791	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	731	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	685	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:14:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	665	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	687	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	726	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	815	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	864	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	839	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	870	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	840	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	819	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	849	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	778	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	800	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	797	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	779	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	805	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	830	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	845	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	775	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	751	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	744	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	821	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	871	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	961	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	922	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	906	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	851	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	723	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	764	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	721	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	710	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	677	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	734	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	708	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	653	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	690	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	672	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	686	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	703	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	729	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	752	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	757	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	867	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	881	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	882	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	929	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	829	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	834	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	883	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	895	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	860	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	858	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	866	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	881	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	922	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	906	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	915	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	879	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	847	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	913	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	867	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:15:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	840	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	847	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	767	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	768	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	804	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	810	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	737	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	699	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	741	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	737	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	758	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	727	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	766	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	678	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	649	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	735	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	688	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	657	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	702	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	707	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	696	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	676	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	798	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	816	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	786	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	761	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	733	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	831	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	790	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	779	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	765	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	732	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	740	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	714	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	725	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	815	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	731	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	725	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	821	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	801	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	748	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	722	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	724	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	734	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	769	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	795	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	769	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	748	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	757	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	694	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	652	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	654	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	642	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	769	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	802	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	773	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	806	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	811	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	739	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	745	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:16:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	748	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	779	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	721	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	688	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	626	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	644	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	681	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	782	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	817	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	767	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	736	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	733	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	753	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	748	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	826	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	773	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	842	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	808	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	767	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	836	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	839	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	787	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	759	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	764	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	700	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	726	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	768	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	783	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	804	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	813	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	829	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	784	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	843	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	854	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	877	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	868	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	816	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	830	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	785	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	799	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	760	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	785	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	763	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	731	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	706	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	730	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	774	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	765	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	766	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	746	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	796	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	784	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	785	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	775	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	811	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	888	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	845	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	819	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	752	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	826	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:17:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	814	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	817	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	846	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	837	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	826	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	794	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	776	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	764	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	712	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	796	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	761	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	765	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	675	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	737	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	711	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	708	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	720	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	731	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	716	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	766	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	817	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	854	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	794	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	794	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	744	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	748	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	731	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	775	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	769	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	780	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	790	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	723	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	782	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	757	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	776	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	813	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	817	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	752	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	725	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	760	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	785	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	738	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	749	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	779	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	779	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	763	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	770	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	808	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	849	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	834	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	856	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	909	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	849	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	799	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	761	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	763	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	786	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	788	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	812	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	826	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:18:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	801	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	753	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	747	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	759	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	764	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	745	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	761	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	755	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	825	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	892	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	916	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	855	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	843	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	798	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	761	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	812	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	757	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	806	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	779	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	879	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	851	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	837	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	798	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	820	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	804	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	867	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	793	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	758	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	716	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	742	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	740	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	759	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	735	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	651	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	639	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	561	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	579	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	594	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	646	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	662	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	647	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	716	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	765	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	746	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	785	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	827	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	786	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	727	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	747	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	720	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	698	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	742	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	772	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	740	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	689	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	728	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	704	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	741	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	817	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	753	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:19:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	724	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	710	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	724	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	712	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	715	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	772	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	761	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	717	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	719	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	750	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	748	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	708	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	663	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	618	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	646	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	672	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	671	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	646	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	606	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	654	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	688	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	673	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	682	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	678	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	655	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	711	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	713	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	703	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	717	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	715	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	692	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	746	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	757	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	786	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	706	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	720	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	673	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	672	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	727	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	712	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	705	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	650	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	674	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	628	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	669	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	693	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	732	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	717	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	696	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	643	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	684	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	702	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	728	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	781	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	742	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	714	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	703	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	753	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	723	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	721	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:20:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	651	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	688	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	728	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	694	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	709	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	697	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	665	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	619	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	593	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	690	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	708	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	652	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	681	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	664	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	649	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	650	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	640	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	720	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	719	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	719	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	729	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	772	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	729	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	704	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	707	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	825	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	748	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	766	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	806	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	839	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	824	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	817	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	797	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	862	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	878	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	881	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	882	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	840	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	937	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	928	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1003	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	892	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	873	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	845	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	922	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	919	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	883	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	875	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	855	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	836	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	780	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	819	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	803	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	810	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	861	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	868	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	910	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	884	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	806	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	894	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:21:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	894	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	849	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	813	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	795	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	817	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	778	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	836	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	766	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	788	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	779	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	788	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	800	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	817	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	811	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	735	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	753	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	733	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	683	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	690	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	684	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	669	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	621	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	663	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	640	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	687	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	760	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	778	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	814	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	820	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	733	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	753	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	737	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	734	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	754	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	819	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	812	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	819	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	856	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	799	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	798	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	797	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	837	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	823	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	723	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	712	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	728	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	672	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	646	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	670	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	668	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	697	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	761	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	845	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	832	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	787	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	828	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	875	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	808	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	803	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	806	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:22:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	814	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	752	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	720	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	676	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	676	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	654	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	699	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	656	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	691	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	738	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	808	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	767	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	781	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	863	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	834	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	765	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	801	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	741	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	730	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	778	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	803	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	742	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	735	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	740	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	805	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	845	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	819	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	742	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	695	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	722	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	790	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	755	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	739	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	781	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	727	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	714	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	703	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	720	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	791	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	858	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	786	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	751	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	771	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	851	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	859	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	819	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	788	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	793	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	812	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	827	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	769	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	726	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	698	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	724	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	726	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	712	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	677	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	790	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	824	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	804	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:23:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	808	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	856	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	809	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	794	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	754	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	745	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	849	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	845	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	821	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	811	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	818	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	814	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	765	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	755	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	771	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	724	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	698	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	725	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	747	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	775	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	765	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	781	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	689	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	708	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	794	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	793	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	758	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	740	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	746	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	741	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	714	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	740	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	781	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	765	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	861	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	798	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	738	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	757	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	682	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	679	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	753	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	751	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	756	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	783	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	771	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	760	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	753	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	713	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	692	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	650	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	631	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	650	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	709	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	678	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	652	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	653	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	781	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	768	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	748	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	753	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:24:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	720	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	732	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	776	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	740	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	792	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	813	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	738	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	758	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	753	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	734	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	652	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	688	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	638	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	666	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	722	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	817	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	890	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	859	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	876	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	813	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	727	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	723	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	707	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	768	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	769	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	800	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	840	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	867	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	873	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	827	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	786	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	816	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	875	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	845	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	823	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	793	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	816	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	822	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	789	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	814	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	846	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	790	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	835	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	803	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	787	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	831	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	764	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	742	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	736	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	766	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	839	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	780	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	770	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	751	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	792	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	803	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	809	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	822	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	835	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	817	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:25:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	876	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	860	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	874	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	831	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	832	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	820	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	813	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	860	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	843	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	829	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	830	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	868	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	854	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	850	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	792	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	813	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	753	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	772	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	740	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	872	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	817	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	814	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	840	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	831	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	865	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	861	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	866	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	815	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	805	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	832	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	778	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	766	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	732	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	750	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	778	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	805	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	820	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	811	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	805	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	733	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	765	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	767	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	793	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	748	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	751	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	753	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	785	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	827	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	808	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	785	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	816	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	775	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	787	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	793	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	746	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	796	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	764	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	822	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	836	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	758	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:26:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	795	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	759	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	710	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	697	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	757	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	773	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	858	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	853	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	818	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	762	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	825	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	793	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	864	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	825	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	825	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	813	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	797	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	816	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	830	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	789	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	786	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	738	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	802	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	773	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	802	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	844	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	799	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	829	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	818	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	896	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	930	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	924	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	908	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	860	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	845	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	778	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	735	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	734	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	752	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	824	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	800	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	741	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	783	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	871	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	818	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	850	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	856	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	866	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	927	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	909	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	957	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	923	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	1008	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	917	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	855	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	840	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	878	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	886	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	808	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	755	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:27:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	669	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	759	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	660	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	696	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	721	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	779	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	837	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	834	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	798	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	816	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	830	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	887	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	832	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	859	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	933	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	926	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	900	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	820	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	733	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	686	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	657	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	668	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	643	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	620	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	594	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	637	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	573	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	555	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	599	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	589	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	603	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	593	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	546	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	544	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	551	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	594	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	630	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	658	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	692	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	744	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	807	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	766	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	792	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	765	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	791	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	735	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	776	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	742	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	738	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	711	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	708	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	711	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	774	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	749	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	765	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	746	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	867	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	880	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	909	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/14/2012	12:28:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	826	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:06:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	690	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:06:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	653	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:06:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	690	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:06:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	676	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:06:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	663	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:06:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	706	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:06:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	767	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:06:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	702	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:06:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	672	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:06:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	645	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:06:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	671	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:06:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	620	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:06:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	605	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:06:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	627	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:06:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	713	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:06:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	774	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:06:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	686	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:06:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	648	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:06:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	636	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:06:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	629	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:06:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	600	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:06:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	668	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:06:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	665	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:06:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	710	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:06:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	736	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:06:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	709	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:06:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	697	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	769	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	760	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	860	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	833	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	858	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	831	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	847	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	825	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	802	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	806	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	836	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	846	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	834	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	836	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	759	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	807	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	837	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	872	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	841	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	850	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	848	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	869	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	830	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	813	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	781	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	723	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	726	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	756	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	830	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	869	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	862	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	824	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	806	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	823	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	748	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	788	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	788	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	754	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	802	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	763	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	780	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	736	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	678	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	766	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	770	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	705	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	707	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	791	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	767	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	858	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	787	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	822	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	861	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	809	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	817	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	774	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	811	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	826	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	856	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:07:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	840	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	882	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	876	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	847	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	874	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	822	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	855	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	810	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	872	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	855	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	843	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	844	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	869	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	920	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	880	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	921	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	861	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	812	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	817	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	869	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	820	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	720	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	754	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	792	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	766	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	802	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	830	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	775	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	823	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	791	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	846	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	832	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	866	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	769	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	784	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	816	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	810	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	784	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	722	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	778	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	781	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	733	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	743	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	738	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	780	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	759	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	737	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	698	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	738	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	793	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	848	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	870	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	887	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	842	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	783	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	776	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	768	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	774	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	783	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	713	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:08:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	773	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	816	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	741	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	776	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	789	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	707	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	737	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	620	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	650	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	717	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	725	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	715	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	726	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	739	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	825	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	736	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	740	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	759	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	814	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	834	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	838	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	874	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	853	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	885	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	831	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	835	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	802	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	775	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	741	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	766	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	723	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	713	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	657	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	673	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	692	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	697	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	691	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	727	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	761	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	809	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	773	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	799	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	702	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	714	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	684	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	725	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	840	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	776	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	766	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	790	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	790	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	730	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	773	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	778	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	774	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	721	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	719	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	685	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	645	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	648	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:09:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	652	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	675	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	692	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	685	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	658	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	656	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	634	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	718	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	708	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	722	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	791	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	768	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	795	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	734	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	699	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	786	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	751	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	796	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	808	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	829	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	821	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	810	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	819	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	860	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	835	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	801	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	866	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	862	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	812	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	780	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	745	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	778	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	800	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	704	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	763	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	755	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	748	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	765	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	744	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	795	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	859	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	868	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	813	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	795	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	780	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	736	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	687	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	783	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	771	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	763	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	720	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	720	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	694	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	666	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	735	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	746	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	753	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	757	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	760	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	765	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:10:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	747	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	776	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	762	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	757	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	781	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	755	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	768	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	814	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	895	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	852	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	784	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	804	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	789	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	812	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	818	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	809	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	804	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	707	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	687	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	727	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	727	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	746	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	750	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	742	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	715	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	758	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	727	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	677	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	721	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	699	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	821	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	742	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	810	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	849	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	798	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	891	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	860	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	810	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	769	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	818	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	858	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	788	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	849	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	813	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	828	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	823	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	768	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	793	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	757	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	740	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	680	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	652	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	667	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	707	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	663	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	664	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	664	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	661	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	717	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	685	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:11:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	727	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	748	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	746	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	754	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	714	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	740	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	764	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	744	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	768	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	783	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	807	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	791	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	792	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	790	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	746	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	787	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	855	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	865	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	870	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	773	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	742	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	695	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	750	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	810	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	792	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	812	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	783	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	716	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	717	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	650	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	716	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	670	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	691	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	750	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	824	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	837	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	872	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	810	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	734	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	731	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	730	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	727	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	712	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	692	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	684	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	690	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	650	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	644	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	671	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	726	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	711	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	712	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	805	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	825	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	873	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	914	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	937	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	885	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	915	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	843	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:12:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	817	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	791	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	790	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	763	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	732	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	716	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	682	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	743	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	739	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	714	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	645	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	616	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	650	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	663	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	684	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	748	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	732	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	683	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	666	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	620	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	45	616	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	668	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	668	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	758	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	836	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	790	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	789	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	776	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	789	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	785	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	751	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	732	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	753	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	776	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	765	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	744	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	775	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	731	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	761	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	855	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	876	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	838	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	795	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	787	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	785	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	705	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	685	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	782	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	745	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	764	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	745	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	765	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	837	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	812	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	738	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	723	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	788	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	738	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	757	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	775	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:13:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	719	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	719	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	722	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	735	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	698	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	725	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	712	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	667	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	678	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	628	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	642	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	689	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	672	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	660	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	617	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	684	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	704	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	723	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	711	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	705	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	671	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	636	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	584	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	655	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	635	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	663	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	640	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	622	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	674	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	725	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	690	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	694	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	701	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	701	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	645	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	626	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	668	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	738	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	678	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	663	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	607	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	600	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	613	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	679	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	617	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	610	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	620	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	671	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	734	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	733	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	747	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	740	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	738	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	723	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	699	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	765	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	813	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	817	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	855	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	795	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:14:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	766	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	755	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	759	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	682	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	687	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	700	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	761	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	819	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	862	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	919	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	971	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	889	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	802	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	806	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	846	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	814	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	772	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	833	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	832	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	784	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	783	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	774	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	741	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	716	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	684	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	634	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	653	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	722	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	754	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	750	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	754	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	711	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	715	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	770	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	800	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	797	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	770	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	693	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	756	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	726	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	727	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	820	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	790	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	822	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	789	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	728	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	761	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	707	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	687	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	707	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	710	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	735	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	739	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	712	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	715	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	702	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	671	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	702	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	750	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	797	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:15:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	761	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	797	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	804	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	745	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	716	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	683	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	691	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	685	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	721	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	720	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	686	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	647	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	661	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	683	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	666	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	724	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	722	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	790	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	775	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	798	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	793	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	756	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	749	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	706	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	705	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	661	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	660	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	650	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	676	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	748	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	752	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	701	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	727	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	703	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	764	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	734	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	686	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	749	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	720	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	694	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	611	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	674	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	672	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	765	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	759	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	831	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	786	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	832	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	810	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	780	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	710	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	710	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	746	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	684	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	712	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	633	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	638	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	617	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	605	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	647	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:16:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	592	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	614	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	646	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	694	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	684	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	636	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	759	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	731	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	777	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	769	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	701	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	649	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	640	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	779	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	780	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	861	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	835	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	836	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	814	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	845	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	856	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	828	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	783	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	795	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	769	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	737	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	690	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	672	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	808	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	771	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	753	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	768	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	747	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	716	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	764	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	754	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	737	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	760	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	728	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	789	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	821	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	779	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	723	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	700	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	703	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	684	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	691	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	674	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	627	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	612	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	612	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	551	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	641	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	690	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	673	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	611	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	658	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	669	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	667	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	687	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:17:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	696	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	747	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	731	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	757	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	795	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	806	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	768	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	736	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	676	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	641	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	698	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	771	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	768	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	922	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	909	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	874	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	893	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	908	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	837	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	805	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	878	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	850	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	793	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	733	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	740	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	736	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	744	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	785	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	739	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	737	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	746	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	775	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	754	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	727	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	773	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	788	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	727	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	666	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	741	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	743	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	693	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	729	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	705	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	674	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	753	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	731	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	764	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	755	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	785	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	764	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	800	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	761	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	809	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	814	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	760	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	684	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	691	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	697	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	633	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	606	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:18:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	572	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	517	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	547	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	544	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	530	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	532	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	543	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	554	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	575	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	649	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	616	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	658	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	615	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	645	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	646	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	592	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	569	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	567	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	699	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	703	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	671	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	588	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	557	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	531	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	614	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	544	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	588	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	581	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	600	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	655	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	635	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	549	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	559	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	690	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	685	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	716	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	715	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	682	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	680	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	665	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	651	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	676	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	711	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	691	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	696	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	682	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	611	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	678	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	643	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	609	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	690	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	697	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	667	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	720	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	708	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	723	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	645	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	660	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	687	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	681	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:19:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	710	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	693	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	687	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	638	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	584	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	586	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	587	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	604	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	685	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	655	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	688	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	719	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	686	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	657	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	712	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	714	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	749	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	815	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	806	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	790	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	777	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	767	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	744	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	704	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	718	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	698	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	643	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	625	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	633	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	660	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	647	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	649	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	665	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	675	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	728	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	797	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	781	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	762	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	755	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	679	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	627	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	670	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	750	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	707	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	781	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	756	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	735	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	779	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	825	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	847	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	845	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	818	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	755	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	821	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	767	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	840	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	796	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	768	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	758	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	757	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:20:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	668	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	715	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	694	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	842	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	819	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	753	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	772	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	799	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	848	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	757	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	792	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	858	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	842	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	785	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	769	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	763	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	833	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	845	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	869	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	842	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	797	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	780	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	770	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	793	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	744	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	738	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	767	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	770	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	860	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	926	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	842	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	800	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	750	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	800	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	796	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	746	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	775	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	697	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	690	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	742	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	705	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	718	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	699	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	750	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	793	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	754	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	712	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	670	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	699	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	808	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	769	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	816	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	740	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	723	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	750	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	754	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	846	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	878	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	914	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	863	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:21:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	782	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	789	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	776	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	733	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	727	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	681	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	643	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	591	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	580	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	607	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	618	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	604	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	648	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	676	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	733	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	698	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	668	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	610	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	632	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	624	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	622	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	607	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	560	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	577	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	650	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	651	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	663	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	641	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	633	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	693	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	712	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	693	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	709	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	643	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	614	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	568	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	602	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	599	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	648	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	764	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	746	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	753	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	861	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	809	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	781	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	816	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	843	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	845	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	899	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	944	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	945	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	836	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	827	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	861	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	802	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	797	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	874	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	914	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	914	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	933	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:22:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	935	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	895	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	875	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	824	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	767	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	818	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	832	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	836	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	860	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	764	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	802	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	820	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	803	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	731	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	775	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	728	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	754	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	798	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	787	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	707	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	743	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	749	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	711	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	736	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	701	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	658	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	663	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	754	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	744	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	738	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	778	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	912	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	820	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	782	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	703	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	731	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	784	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	750	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	732	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	694	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	651	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	617	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	682	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	690	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	737	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	724	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	710	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	783	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	760	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	731	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	714	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	694	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	707	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	742	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	692	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	664	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	812	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	781	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	818	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	788	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:23:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	766	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	779	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	745	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	763	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	795	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	768	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	759	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	703	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	693	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	618	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	728	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	725	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	770	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	758	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	816	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	867	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	816	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	845	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	840	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	896	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	875	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	842	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	853	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	851	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	825	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	795	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	748	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	746	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	683	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	782	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	824	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	852	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	836	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	867	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	831	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	797	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	723	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	739	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	793	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	851	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	813	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	811	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	806	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	848	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	57	906	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	57	930	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	1012	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	989	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	938	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	952	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	884	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	939	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	951	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	1010	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	1060	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	1076	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	987	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	947	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	893	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	906	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:24:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	882	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	840	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	831	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	902	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	917	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	881	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	845	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	934	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	884	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	862	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	824	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	870	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	850	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	837	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	827	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	874	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	847	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	886	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	879	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	866	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	862	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	852	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	893	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	895	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	884	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	899	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	854	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	850	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	847	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	833	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	859	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	878	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	904	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	834	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	856	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	785	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	855	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	829	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	850	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	845	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	910	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	872	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	896	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	883	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	910	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	920	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	965	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	966	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	906	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	909	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	865	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	802	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	931	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	883	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	910	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	888	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	869	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	961	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	980	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	971	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:25:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	947	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	893	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	871	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	932	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	882	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	886	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	911	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	896	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	885	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	851	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	851	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	918	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	955	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	911	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	899	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	933	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	929	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	962	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1005	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	996	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	916	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	900	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	855	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	898	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	902	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	856	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	817	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	809	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	870	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	874	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	890	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	843	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	869	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	862	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	848	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	881	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	770	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	804	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	788	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	783	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	805	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	852	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	863	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	854	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	840	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	781	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	784	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	855	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	852	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	848	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	833	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	847	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	907	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	817	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	778	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	814	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	813	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	793	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	777	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	811	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:26:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	790	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	801	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	844	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	841	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	875	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	950	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	1005	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	972	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	901	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	939	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	981	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	910	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	952	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	976	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	1005	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	1066	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1047	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	998	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	913	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	935	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	938	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	963	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	942	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	920	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	890	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	893	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	903	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	903	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	926	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1056	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	969	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	1032	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1096	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1001	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1073	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1019	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1075	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	1031	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	1019	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	952	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	959	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	890	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	824	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	786	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	772	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	870	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	854	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	945	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	914	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	969	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	959	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	983	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	863	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	801	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	889	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	889	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	868	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	829	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	808	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	809	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:27:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	814	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	892	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	889	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	879	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	848	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	861	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	868	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	848	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	869	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	851	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	823	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	873	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	912	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	819	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	788	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	803	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	810	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	884	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	919	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	893	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	865	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	828	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	775	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	889	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	949	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	890	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	868	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	838	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	815	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	876	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	787	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	765	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	847	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	856	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	833	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	835	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	848	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	824	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	794	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	826	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	837	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	799	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	893	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	825	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	806	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	791	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	817	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	875	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	847	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	866	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	861	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	880	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	879	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	900	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	878	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	918	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	928	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	1002	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	971	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	913	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:28:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	808	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	767	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	726	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	758	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	793	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	769	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	703	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	797	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	838	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	887	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	874	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	775	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	739	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	724	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	713	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	796	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	782	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	735	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	719	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	720	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	688	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	705	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	798	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	804	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	764	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	771	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	759	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	717	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	797	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	805	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	790	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	816	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	762	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	698	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	680	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	692	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	843	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	763	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	768	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	827	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	761	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	708	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	698	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	702	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	708	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	711	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	758	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	752	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	781	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	761	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	727	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	735	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	695	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	731	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	766	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	747	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	778	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	713	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	689	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	684	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:29:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	678	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	717	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	661	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	647	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	709	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	718	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	761	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	776	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	744	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	670	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	712	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	738	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	724	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	723	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	688	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	753	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	769	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	770	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	820	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	792	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	821	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	801	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	786	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	772	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	875	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	776	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	811	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	906	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1041	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	937	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1006	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	965	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	905	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	895	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	827	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	877	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	847	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	788	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	806	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	757	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	770	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	701	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	727	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	749	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	755	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	727	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	761	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	755	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	814	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	810	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	820	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	756	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	770	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	703	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	702	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	704	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	773	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	727	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	747	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	741	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:30:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	769	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	737	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	736	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	684	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	668	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	664	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	655	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	659	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	725	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	716	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	697	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	740	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	770	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	728	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	702	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	752	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	792	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	732	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	788	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	671	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	660	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	718	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	755	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	755	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	747	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	767	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	732	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	719	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	791	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	777	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	756	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	797	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	801	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	731	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	802	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	810	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	829	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	849	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	812	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	854	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	818	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	745	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	799	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	798	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	768	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	788	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	738	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	779	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	780	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	827	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	762	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	836	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	793	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	777	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	730	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	788	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	752	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	734	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	722	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	791	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:31:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	732	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	683	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	723	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	756	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	749	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	745	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	800	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	704	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	706	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	632	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	657	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	659	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	684	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	645	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	681	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	667	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	707	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	728	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	681	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	757	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	738	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	735	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	664	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	615	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	690	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	646	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	694	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	664	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	712	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	723	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	746	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	795	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	816	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	731	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	784	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	820	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	845	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	958	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	941	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	960	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	949	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	896	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	909	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	932	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	869	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	865	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	895	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	825	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	772	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	852	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	848	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	801	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	817	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	836	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	892	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	873	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	935	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	930	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	889	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	892	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:32:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	907	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	803	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	776	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	764	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	735	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	734	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	699	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	622	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	585	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	665	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	630	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	590	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	668	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	715	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	738	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	712	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	668	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	733	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	718	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	716	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	782	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	763	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	685	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	747	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	808	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	844	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	830	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	739	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	785	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	782	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	840	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	829	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	870	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	853	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	783	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	725	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	701	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	680	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	712	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	715	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	681	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	724	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	769	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	797	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	795	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	795	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	772	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	775	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	787	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	796	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	827	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	796	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	835	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	813	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	829	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	794	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	792	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	767	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	791	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	831	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:33:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	878	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	921	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	926	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	864	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	907	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	873	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	845	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	821	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	813	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	794	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	793	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	768	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	812	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	824	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	839	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	862	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	854	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	794	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	824	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	772	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	785	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	783	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	828	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	809	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	780	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	781	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	780	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	885	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	850	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	903	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	880	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	825	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	826	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	736	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	734	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	795	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	770	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	736	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	769	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	768	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	782	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	758	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	821	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	810	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	768	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	839	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	838	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	861	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	881	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	890	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	835	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	802	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	797	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	793	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	826	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	805	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	50	868	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	830	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	779	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	761	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:34:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	742	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	771	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	761	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	881	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	898	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	888	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	855	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	839	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	817	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	878	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	885	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	927	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	885	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	908	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	837	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	776	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	732	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	754	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	645	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	647	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	661	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	673	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	682	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	711	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	726	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	644	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	774	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	810	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	872	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	922	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	885	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	819	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	822	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	757	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	714	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	821	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	758	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	719	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	753	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	711	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	712	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	809	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	770	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	714	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	718	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	712	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	713	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	681	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	663	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	688	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	662	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	683	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	670	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	621	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	662	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	640	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	644	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	669	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	671	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	671	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:35:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	655	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	727	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	691	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	673	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	614	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	645	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	690	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	718	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	638	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	618	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	637	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	653	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	599	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	636	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	675	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	738	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	738	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	721	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	676	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	661	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	650	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	651	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	629	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	578	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	595	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	616	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	694	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	733	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	674	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	663	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	686	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	693	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	687	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	799	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	795	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	807	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	744	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	720	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	755	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	736	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	777	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	814	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	717	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	762	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	757	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	739	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	669	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	696	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	680	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	696	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	687	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	719	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	683	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	673	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	659	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	682	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	667	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	644	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	713	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	688	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:36:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	671	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	714	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	680	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	720	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	650	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	709	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	780	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	803	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	772	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	794	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	770	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	776	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	894	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	830	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	865	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	824	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	792	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	812	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	783	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	792	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	756	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	714	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	623	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	561	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	581	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	606	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	616	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	632	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	638	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	622	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	671	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	709	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	765	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	699	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	693	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	769	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	758	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	753	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	676	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	672	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	681	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	697	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	759	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	771	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	701	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	775	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	785	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	832	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	787	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	824	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	839	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	756	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	747	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	752	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	734	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	699	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	687	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	683	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	689	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	706	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:37:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	721	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	686	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	672	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	717	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	785	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	739	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	741	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	737	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	761	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	707	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	732	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	719	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	756	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	748	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	776	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	776	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	733	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	776	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	754	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	773	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	793	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	806	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	812	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	841	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	751	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	758	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	669	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	711	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	716	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	730	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	777	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	757	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	817	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	806	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	844	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	785	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	793	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	753	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	769	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	736	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	753	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	735	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	815	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	740	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	733	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	670	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	645	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	623	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	664	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	617	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	673	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	689	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	695	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	663	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	625	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	642	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	654	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	621	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	595	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	591	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:38:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	628	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	653	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	667	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	653	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	653	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	667	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	635	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	628	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	678	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	678	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	618	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	636	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	594	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	610	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	620	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	660	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	702	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	705	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	745	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	721	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	706	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	741	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	761	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	733	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	693	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	755	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	717	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	733	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	772	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	749	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	733	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	777	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	698	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	738	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	710	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	656	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	648	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	667	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	664	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	797	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	818	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	776	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	718	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	681	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	654	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	737	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	770	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	716	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	703	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	714	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	739	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	747	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	753	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	713	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	771	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	762	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	821	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	778	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	739	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	788	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:39:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	718	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	755	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	786	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	753	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	723	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	720	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	708	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	782	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	820	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	816	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	835	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	832	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	799	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	814	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	749	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	770	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	796	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	805	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	813	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	820	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	801	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	750	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	848	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	866	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	908	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	874	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	868	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	865	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	930	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	888	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	831	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	786	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	831	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	858	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	843	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	825	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	781	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	758	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	776	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	834	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	811	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	759	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	786	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	833	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	730	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	672	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	659	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	670	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	678	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	697	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	689	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	710	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	772	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	727	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	802	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	753	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	778	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	825	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	868	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	841	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:40:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	842	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	842	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	843	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	889	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	865	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	811	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	885	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	845	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	892	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	871	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	776	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	791	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	824	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	897	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	930	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	973	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	1063	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	1065	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	1079	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1097	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1153	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	1094	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	1080	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	1048	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	1043	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	958	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	946	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	847	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	867	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	838	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	815	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	808	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	813	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	780	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	710	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	758	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	809	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	871	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	795	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	764	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	767	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	749	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	767	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	751	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	721	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	695	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	710	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	675	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	682	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	756	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	727	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	715	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	693	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	675	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	690	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	682	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	715	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	670	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	701	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	624	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:41:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	607	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	636	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	628	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	600	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	647	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	591	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	535	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	525	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	606	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	650	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	652	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	664	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	652	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	550	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	562	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	626	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	655	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	723	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	699	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	722	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	683	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	678	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	687	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	669	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	692	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	661	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	639	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	652	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	640	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	630	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	626	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	601	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	667	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	716	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	729	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	737	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	689	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	694	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	673	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	613	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	677	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	595	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	562	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	555	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	577	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	594	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	630	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	678	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	720	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	673	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	724	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	690	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	707	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	762	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	742	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	714	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	714	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	727	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	666	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	619	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:42:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	694	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	675	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	705	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	698	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	712	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	700	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	683	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	748	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	826	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	798	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	748	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	809	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	745	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	789	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	797	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	862	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	733	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	731	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	730	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	693	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	813	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	888	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	867	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	894	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	863	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	949	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	1062	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1051	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	979	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	909	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	919	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	869	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	862	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	800	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	851	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	896	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	886	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	898	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	875	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	852	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	905	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	824	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	813	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	784	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	785	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	761	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	731	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	720	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	731	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	726	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	724	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	688	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	735	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	733	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	777	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	800	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	758	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	751	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	745	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	738	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:43:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	759	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:44:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	718	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:44:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	789	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:44:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	776	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:44:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	774	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:44:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	787	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:44:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	835	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:44:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	839	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:44:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	864	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:44:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	860	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:44:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	826	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:44:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	844	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:44:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	763	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:44:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	779	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:44:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	701	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:44:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	690	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:44:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	736	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:44:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	793	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:44:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	791	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:44:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	788	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:44:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	785	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:44:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	825	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:44:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	829	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:44:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	819	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:44:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	791	Drywall
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:47:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	750	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:47:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	723	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:47:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	812	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:47:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	752	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:47:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	745	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:47:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	788	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:47:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	810	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:47:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	778	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:47:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	802	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:47:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	877	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:47:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	956	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:47:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	1034	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:47:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	1129	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:47:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	1119	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:47:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	1100	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:47:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	1059	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:47:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	1157	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:47:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1197	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:47:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1098	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:47:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1193	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:47:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1138	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:47:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1057	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:47:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	1132	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:47:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1251	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:47:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1251	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1273	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1258	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	1191	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1156	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	1200	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	1252	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1266	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1281	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1267	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1254	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	1317	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1202	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	1202	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	1109	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	1033	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	1107	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1066	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	1070	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	1104	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1100	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1069	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1027	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	1027	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	1024	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	1009	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	1020	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	1065	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	1003	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	1044	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	1024	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	991	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	1120	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	1181	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	1162	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	1226	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	1196	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	1162	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1104	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	1091	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	1124	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	1128	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	1176	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1208	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	1196	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1203	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	1156	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	1162	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	1158	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	1132	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	1044	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	1079	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	1055	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	1015	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1051	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	1065	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	1058	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	1083	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	1160	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	1147	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:48:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	1257	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:49:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	1219	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:49:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1192	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:49:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	1210	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:49:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	1184	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:49:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	1221	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:49:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	1239	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:49:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	1211	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:49:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	1162	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:49:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	1148	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:49:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	1135	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:49:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	1183	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:49:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	1176	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:49:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	1125	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:49:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	1094	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:49:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1092	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:49:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	1020	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:49:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	1021	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:49:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	987	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:49:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	1048	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:49:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	1124	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:49:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	1136	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:49:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	1133	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:49:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	1088	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:49:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	1033	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:49:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	48	1021	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:49:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	983	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:49:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	1004	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:49:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	940	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:49:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	998	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:49:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	944	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:49:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	925	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:49:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	866	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:49:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	840	Concrete Block
Building 2540	7	Scan	Survey Unit 07	"	6/18/2012	9:49:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	863	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	614	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	622	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	595	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	560	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	522	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	547	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	580	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	644	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	600	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	587	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	566	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	573	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	602	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	690	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	627	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	599	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	592	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	648	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	710	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	676	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	672	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	717	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	742	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	734	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	732	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	741	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	678	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	674	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	649	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	652	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	619	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	612	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	589	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	604	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	579	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	550	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	561	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	588	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	566	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	581	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	562	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	581	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	586	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	567	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	598	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	645	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	626	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	663	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	663	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	605	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	633	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:14:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	648	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	662	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	673	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	661	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	669	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	725	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	725	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	712	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	704	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	727	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	701	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	702	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	659	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	681	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	711	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	710	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	712	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	772	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	949	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	881	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	882	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	914	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	842	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	861	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	855	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	896	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	899	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	898	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	831	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	903	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	911	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	933	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	925	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	992	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	1067	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	1026	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	969	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	910	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	896	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	965	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	859	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	828	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	851	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	847	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	870	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	892	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	949	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	974	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	936	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	942	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	930	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	889	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	800	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	797	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	769	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	737	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	847	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	859	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	854	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	831	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:15:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	787	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	809	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	817	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	830	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	796	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	780	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	813	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	810	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	772	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	681	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	686	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	636	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	619	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	617	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	623	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	620	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	640	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	735	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	676	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	616	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	624	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	585	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	600	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	555	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	587	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	568	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	576	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	594	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	689	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	740	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	793	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	698	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	789	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	888	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	891	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	989	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	1053	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	979	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	932	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	948	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	976	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	985	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	887	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	878	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	909	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	851	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	800	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	776	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	788	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	790	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	743	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	728	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	810	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	838	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	824	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	902	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	913	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	911	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	873	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	889	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:16:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	867	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	855	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	805	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	866	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	896	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	849	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	860	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	888	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	809	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	893	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	838	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	837	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	825	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	886	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	893	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	927	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	932	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	911	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	876	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	813	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	828	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	850	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	837	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	875	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	898	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	953	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	936	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	929	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	922	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	871	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	915	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	924	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	851	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	918	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	948	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	941	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	887	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	842	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	787	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	773	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	821	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	790	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	785	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	760	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	719	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	695	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	685	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	688	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	698	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	714	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	729	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	683	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	611	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	623	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	643	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	615	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	568	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	654	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	632	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	652	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	598	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:17:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	621	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	573	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	565	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	661	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	612	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	696	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	630	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	591	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	662	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	648	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	663	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	638	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	599	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	665	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	696	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	769	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	726	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	745	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	752	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	747	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	808	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	759	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	855	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	831	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	798	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	792	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	836	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	768	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	713	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	795	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	760	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	707	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	700	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	754	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	805	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	845	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	899	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	899	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	898	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	874	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	888	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	904	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	981	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	1010	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	985	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	922	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	870	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	899	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	911	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	897	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	840	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	828	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	785	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	826	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	963	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	862	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	765	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	838	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	896	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	996	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:18:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	966	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	915	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	832	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	900	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	868	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	859	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	853	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	883	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	828	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	799	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	854	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	817	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	824	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	816	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	777	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	766	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	724	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	768	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	803	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	741	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	794	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	744	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	777	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	758	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	706	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	691	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	676	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	664	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	629	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	612	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	622	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	716	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	682	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	688	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	657	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	646	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	661	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	670	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	622	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	604	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	594	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	584	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	600	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	668	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	607	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	595	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	620	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	605	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	556	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	550	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	547	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	512	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	609	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	643	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	624	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	667	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	665	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	732	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	763	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	815	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:19:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	811	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	770	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	817	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	820	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	825	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	874	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	847	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	788	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	808	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	781	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	783	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	774	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	738	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	780	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	737	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	699	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	770	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	762	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	831	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	820	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	868	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	840	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	815	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	820	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	745	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	661	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	605	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	694	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	689	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	751	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	711	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	726	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	714	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	706	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	724	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	690	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	639	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	623	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	711	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	725	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	646	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	671	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	680	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	687	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	702	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	657	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	648	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	641	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	670	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	728	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	669	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	679	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	667	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	737	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	825	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	790	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	763	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	733	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	782	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	794	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:20:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	827	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	782	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	667	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	701	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	706	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	722	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	701	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	648	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	688	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	659	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	671	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	704	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	742	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	738	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	769	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	757	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	840	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	929	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	858	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	892	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	992	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	941	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	907	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	903	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	951	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	975	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	961	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	836	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	905	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	892	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	845	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	856	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	851	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	851	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	792	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	735	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	767	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	723	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	677	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	708	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	686	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	671	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	739	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	798	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	770	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	728	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	749	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	687	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	715	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	740	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	751	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	737	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	790	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	764	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	784	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	785	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	749	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	734	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	698	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	682	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:21:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	658	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:22:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	702	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:22:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	682	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:22:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	722	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:22:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	780	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:22:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	788	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:22:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	790	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:22:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	765	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:22:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	765	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:22:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	793	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:22:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	758	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:22:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	750	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:22:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	701	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:22:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	668	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:22:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	688	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:22:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	717	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:22:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	741	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:22:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	726	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:22:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	702	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:22:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	685	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:22:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	621	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:22:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	631	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:22:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	589	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:22:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	546	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:22:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	511	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:22:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	539	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:22:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	584	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	536	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	562	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	537	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	537	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	538	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	518	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	534	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	502	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	521	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	567	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	528	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	521	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	533	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	533	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	579	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	559	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	648	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	635	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	663	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	629	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	576	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	637	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	582	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	586	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	543	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	508	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	526	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	541	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	553	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	549	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	533	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	580	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	576	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	591	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	525	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	518	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	477	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	522	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	538	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	561	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:23:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	567	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	584	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	577	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	571	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	562	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	536	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	525	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	516	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	507	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	513	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	518	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	546	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	588	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	579	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	573	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	544	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	547	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	553	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	610	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	631	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	624	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	548	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	595	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	608	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	607	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	618	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	662	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	661	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	662	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	650	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	649	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	643	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	568	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	563	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	548	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	559	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	603	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	602	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	591	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	557	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	531	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	558	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	533	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	532	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	501	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	527	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	529	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	518	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	521	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	558	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	567	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	539	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	495	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	522	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	536	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	549	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	557	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	485	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	519	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	499	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:24:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	518	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	500	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	542	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	597	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	641	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	575	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	604	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	615	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	614	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	665	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	630	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	650	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	629	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	630	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	591	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	578	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	547	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	544	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	579	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	613	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	609	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	610	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	622	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	666	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	629	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	639	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	584	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	553	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	563	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	604	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	569	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	543	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	519	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	544	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	542	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	541	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	517	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	466	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	423	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	480	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	479	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	525	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	492	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	490	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	476	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	487	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	463	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	523	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	505	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	464	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	467	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	502	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	544	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	555	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	572	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	543	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	605	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	558	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	508	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	457	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:25:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	460	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	420	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	412	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	435	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	457	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	506	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	455	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	459	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	461	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	466	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	458	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	476	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	469	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	469	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	524	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	482	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	494	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	456	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	404	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	431	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	465	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	573	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	511	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	511	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	529	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	508	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	480	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	573	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	589	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	571	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	553	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	548	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	548	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	523	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	586	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	601	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	602	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	614	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	612	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	589	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	606	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	607	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	595	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	596	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	622	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	591	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	558	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	554	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	597	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	551	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	539	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	495	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	456	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	497	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	515	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	472	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	476	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	545	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	519	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	521	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:26:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	504	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	533	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	616	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	592	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	561	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	614	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	587	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	533	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	522	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	492	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	468	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	497	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	473	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	520	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	567	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	619	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	648	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	592	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	593	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	671	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	660	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	625	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	622	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	594	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	575	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	534	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	603	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	567	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	563	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	582	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	588	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	602	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	580	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	547	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	523	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	537	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	568	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	528	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	517	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	513	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	551	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	585	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	553	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	562	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	557	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	624	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	631	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	577	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	544	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	509	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	549	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	558	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	498	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	497	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	506	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	500	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	520	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	467	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	480	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	563	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:27:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	603	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	616	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	574	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	536	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	583	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	577	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	570	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	551	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	616	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	647	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	738	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	743	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	704	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	699	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	723	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	689	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	638	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	631	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	659	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	611	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	606	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	594	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	616	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	683	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	665	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	641	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	623	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	609	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	685	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	749	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	720	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	670	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	676	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	660	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	568	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	577	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	580	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	581	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	630	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	626	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	656	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	653	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	620	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	672	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	656	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	670	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	567	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	536	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	549	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	546	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	581	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	600	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	610	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	607	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	638	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	630	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	580	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	541	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	620	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	614	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:28:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	575	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	591	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	558	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	551	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	548	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	624	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	583	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	680	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	653	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	561	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	559	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	568	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	471	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	496	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	505	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	467	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	481	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	470	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	457	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	499	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	486	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	500	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	565	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	660	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	670	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	621	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	630	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	636	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	605	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	581	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	539	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	552	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	608	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	536	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	502	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	548	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	568	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	518	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	512	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	552	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	550	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	619	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	607	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:29:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	617	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:01:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	413	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:01:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	412	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:01:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	392	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:01:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	399	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:01:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	379	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:01:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	366	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:01:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	353	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:01:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	355	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:01:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	366	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:01:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	407	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:01:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	444	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:01:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	567	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:01:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	600	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:01:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	663	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:01:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	663	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:01:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	741	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:01:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	795	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:01:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	802	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:01:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	834	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:01:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	864	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:01:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	834	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:01:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	769	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:01:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	716	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:01:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	742	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:01:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	690	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:01:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	615	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:01:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	661	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:01:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	706	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:01:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	747	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:01:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	787	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	879	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	870	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	817	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	766	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	803	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	825	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	824	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	905	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	849	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	791	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	756	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	706	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	731	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	652	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	652	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	654	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	682	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	711	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	847	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	913	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	920	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	883	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	862	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	846	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	787	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	786	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	763	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	812	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	805	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	788	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	774	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	705	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	720	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	709	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	690	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	656	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	647	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	639	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	606	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	558	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	619	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	661	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	696	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	659	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	669	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	646	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	650	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	752	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	690	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	639	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	665	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	677	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	661	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	652	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	642	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	658	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	682	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	663	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	699	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:02:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	713	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	690	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	742	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	713	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	754	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	805	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	755	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	724	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	725	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	714	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	773	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	783	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	801	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	818	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	832	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	877	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	869	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	866	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	897	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	924	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	918	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	892	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	916	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	919	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	879	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	849	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	836	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	828	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	829	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	784	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	827	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	900	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	977	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	949	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	951	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	898	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	817	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	808	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	800	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	807	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	758	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	799	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	785	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	804	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	753	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	724	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	700	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	668	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	680	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	664	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	666	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	609	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	692	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	55	672	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	659	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	47	628	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	565	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	605	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	548	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	586	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:03:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	599	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	656	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	633	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	673	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	656	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	668	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	755	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	715	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	693	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	653	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	631	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	706	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	841	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	840	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	828	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	816	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	796	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	782	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	816	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	843	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	866	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	950	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	928	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	901	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	880	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	858	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	798	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	830	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	808	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	834	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	765	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	744	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	796	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	792	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	914	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	919	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	893	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	824	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	769	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	784	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	864	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	885	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	976	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	971	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	961	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	937	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	951	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	897	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	898	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	841	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	770	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	786	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	870	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	797	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	839	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	819	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	753	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	768	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	751	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	721	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:04:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	821	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	791	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	765	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	812	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	855	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	902	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	869	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	877	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	800	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	751	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	792	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	782	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	796	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	724	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	680	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	674	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	660	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	698	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	737	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	791	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	722	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	652	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	563	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	665	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	694	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	679	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	665	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	666	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	675	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	673	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	614	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	614	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	587	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	556	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	507	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	546	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	554	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	621	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	618	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	629	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	634	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	673	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	730	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	692	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	777	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	776	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	744	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	707	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	676	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	661	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	662	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	673	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	682	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	701	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	786	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	716	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	757	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	702	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	763	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	758	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:05:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	764	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	789	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	819	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	803	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	776	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	733	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	718	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	683	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	702	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	682	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	688	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	725	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	644	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	613	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	667	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	735	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	746	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	697	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	632	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	752	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	800	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	761	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	816	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	765	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	751	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	790	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	841	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	786	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	716	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	762	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	707	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	653	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	652	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	711	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	678	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	640	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	658	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	611	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	598	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	645	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	696	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	795	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	746	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	650	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	649	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	663	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	697	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	728	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	760	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	752	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	756	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	761	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	662	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	663	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	683	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	623	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	700	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	678	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	695	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	654	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:06:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	620	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	648	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	687	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	761	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	738	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	720	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	696	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	680	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	711	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	738	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	701	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	657	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	681	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	709	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	677	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	732	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	772	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	728	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	657	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	628	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	611	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	539	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	516	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	475	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	530	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	597	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	563	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	592	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	605	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	628	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	635	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	640	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	588	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	532	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	567	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	559	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	556	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	543	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	600	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	623	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	575	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	582	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	596	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	701	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	680	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	757	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	771	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	795	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	794	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	791	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	776	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	799	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	785	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	691	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	684	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	714	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	747	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	893	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	995	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	1053	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:07:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	1050	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:08:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	1126	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:08:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	1134	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:08:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	1032	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:08:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	927	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:08:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	852	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:08:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	768	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:08:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	688	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:08:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	658	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	11:08:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	624	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	450	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	513	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	516	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	476	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	474	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	512	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	472	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	463	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	465	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	492	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	511	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	528	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	473	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	476	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	464	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	467	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	561	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	509	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	492	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	488	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	511	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	553	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	540	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	563	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	606	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	570	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	507	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	490	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	468	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	525	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	527	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	493	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	468	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	491	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	465	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	448	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	454	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	468	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	517	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	465	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	488	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	485	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	449	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	397	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	427	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	480	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	517	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	537	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	468	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	495	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	458	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	406	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	442	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	416	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	464	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	433	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:52:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	477	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	537	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	528	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	552	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	560	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	509	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	524	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	470	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	460	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	495	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	488	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	452	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	525	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	566	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	492	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	500	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	529	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	565	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	513	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	509	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	573	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	555	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	484	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	415	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	416	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	506	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	491	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	524	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	573	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	508	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	481	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	459	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	509	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	527	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	541	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	565	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	580	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	538	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	494	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	458	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	440	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	457	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	551	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	503	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	452	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	435	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	519	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	508	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	503	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	498	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	530	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	565	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	526	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	505	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	566	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	608	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	595	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	595	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	585	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	544	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:53:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	616	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	625	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	597	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	555	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	572	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	566	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	558	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	555	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	637	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	584	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	610	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	621	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	538	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	538	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	504	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	463	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	547	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	499	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	563	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	637	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	641	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	587	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	556	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	506	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	583	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	518	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	476	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	499	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	483	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	471	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	577	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	585	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	588	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	671	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	646	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	661	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	640	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	620	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	583	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	567	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	630	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	543	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	585	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	552	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	570	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	597	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	678	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	617	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	610	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	563	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	524	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	549	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	559	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	556	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	573	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	578	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	562	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	570	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	641	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	668	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:54:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	622	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	593	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	526	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	519	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	490	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	510	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	550	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	492	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	524	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	516	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	521	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	446	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	462	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	480	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	527	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	495	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	536	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	600	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	601	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	577	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	630	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	603	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	602	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	580	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	605	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	525	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	550	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	536	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	618	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	653	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	655	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	622	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	606	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	570	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	584	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	539	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	558	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	529	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	509	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	507	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	447	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	465	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	480	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	437	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	481	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	435	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	422	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	547	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	592	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	536	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	514	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	498	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	538	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	493	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	525	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	525	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	506	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	537	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	479	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	491	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:55:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	465	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	479	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	467	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	461	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	486	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	554	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	528	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	484	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	543	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	520	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	558	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	589	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	555	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	611	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	598	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	566	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	604	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	591	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	630	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	589	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	535	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	502	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	464	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	433	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	466	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	495	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	538	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	516	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	576	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	617	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	636	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	585	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	644	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	666	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	654	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	678	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	627	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	622	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	569	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	554	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	541	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	507	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	525	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	538	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	525	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	576	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	566	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	730	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	729	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	648	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	616	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	569	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	597	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	585	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	609	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	599	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	577	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	591	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	595	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	576	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:56:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	603	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	614	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	543	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	544	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	556	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	587	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	603	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	569	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	594	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	573	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	565	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	491	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	489	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	530	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	518	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	551	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	529	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	521	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	501	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	498	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	492	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	526	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	528	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	527	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	586	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	509	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	537	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	561	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	531	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	533	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	526	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	563	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	568	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	540	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	542	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	507	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	532	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	622	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	604	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	603	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	544	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	555	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	540	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	597	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	598	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	598	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	597	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	552	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	596	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	575	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	592	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	582	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	539	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	538	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	538	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	586	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	580	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	572	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	554	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	517	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:57:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	608	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	573	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	623	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	628	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	592	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	579	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	617	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	580	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	604	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	560	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	546	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	586	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	553	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	552	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	549	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	583	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	596	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	564	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	536	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	595	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	585	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	569	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	560	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	535	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	501	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	554	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	543	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	552	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	516	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	555	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	587	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	543	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	583	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	608	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	607	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	594	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	563	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	606	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	581	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	592	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	551	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	480	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	546	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	477	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	501	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	499	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	460	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	419	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	511	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	537	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	548	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	524	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	483	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	502	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	522	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	528	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	522	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	525	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	514	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	573	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:58:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	578	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	605	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	547	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	522	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	511	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	561	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	545	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	522	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	549	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	525	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	527	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	495	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	502	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	474	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	534	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	513	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	596	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	610	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	619	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	581	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	552	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	527	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	36	612	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	609	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	633	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	570	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	622	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	551	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	591	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	538	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	595	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	595	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	597	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	564	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	515	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	553	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	537	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	492	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	502	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	499	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	520	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	555	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	574	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	569	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	577	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	568	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	601	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	622	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	642	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	603	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:59:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	614	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	419	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	473	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	523	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	480	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	478	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	522	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	556	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	587	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	601	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	638	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	644	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	668	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	635	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	652	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	655	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	647	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	648	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	656	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	601	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	614	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	613	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	620	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	653	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	678	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	698	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	51	712	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	52	701	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	672	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	601	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	40	520	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	548	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	604	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	590	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	557	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	596	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	608	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	618	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	581	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	550	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	595	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	633	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	593	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	550	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	538	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	551	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	558	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	533	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	547	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	585	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	519	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:37:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	556	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	576	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	640	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	621	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	687	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	683	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	622	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	627	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	622	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	617	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	679	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	621	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	593	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	561	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	590	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	613	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	657	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	615	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	579	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	561	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	523	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	528	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	567	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	609	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	717	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	670	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	726	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	768	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	722	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	803	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	911	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	922	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	860	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	812	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	759	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	752	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	757	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	658	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	615	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	589	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	545	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	523	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	503	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	453	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	482	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	459	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	428	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	416	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	479	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	516	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	574	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	612	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	700	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	670	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	694	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	742	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	737	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	744	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	738	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	789	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:38:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	708	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	676	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	570	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	517	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	534	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	534	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	478	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	464	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	489	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	530	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	532	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	544	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	566	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	585	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	553	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	551	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	641	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	634	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	593	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	560	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	601	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	601	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	658	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	600	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	554	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	561	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	568	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	538	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	503	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	499	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	516	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	517	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	495	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	472	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	461	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	433	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	515	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	518	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	474	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	487	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	451	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	445	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	460	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	460	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	473	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	441	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	461	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	419	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	421	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	454	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	503	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	477	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	499	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	497	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	598	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	656	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	655	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	608	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	617	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	571	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:39:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	614	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	542	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	556	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	520	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	489	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	498	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	480	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	459	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	450	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	454	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	414	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	416	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	506	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	596	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	595	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	572	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	532	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	500	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	519	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	513	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	515	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	521	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	513	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	541	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	551	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	595	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	607	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	664	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	641	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	669	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	658	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	646	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	568	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	562	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	510	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	515	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	511	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	505	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	511	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	471	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	486	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	532	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	521	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	488	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	483	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	494	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	490	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	530	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	518	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	555	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	530	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	500	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	530	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	544	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	567	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	586	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	597	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	576	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	591	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	580	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:40:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	585	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	600	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	591	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	512	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	504	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	548	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	556	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	586	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	588	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	578	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	612	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	588	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	603	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	531	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	510	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	492	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	477	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	545	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	552	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	538	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	563	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	536	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	560	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	531	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	534	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	544	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	551	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	562	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	571	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	541	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	518	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	557	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	508	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	515	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	542	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	640	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	588	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	546	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	510	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	494	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	525	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	502	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	475	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	487	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	462	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	476	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	466	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	502	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	497	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	573	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	541	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	585	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	609	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	667	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	607	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	560	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	521	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	468	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	479	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	410	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:41:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	434	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	456	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	508	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	468	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	460	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	543	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	541	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	555	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	517	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	477	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	503	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	524	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	527	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	564	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	536	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	591	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	606	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	614	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	542	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	576	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	648	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	624	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	573	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	509	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	481	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	482	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	469	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	437	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	446	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	498	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	460	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	498	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	483	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	549	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	524	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	526	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	554	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	518	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	533	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	589	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	567	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	541	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	506	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	514	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	522	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	545	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	510	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	482	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	515	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	485	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	496	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	468	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	502	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	521	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	646	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	581	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	595	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	562	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	604	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	641	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:42:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	640	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	630	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	581	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	561	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	592	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	572	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	521	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	566	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	614	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	600	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	564	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	583	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	542	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	507	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	457	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	472	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	437	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	434	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	417	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	450	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	421	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	421	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	475	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	500	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	554	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	528	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	540	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	532	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	545	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	546	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	556	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	544	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	532	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	533	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	533	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	592	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	558	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	553	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	496	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	448	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	476	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	510	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	518	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	502	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	486	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	483	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	506	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	489	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	488	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	464	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	491	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	513	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	550	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	513	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	485	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	495	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	495	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	482	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	495	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	554	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:43:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	612	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	585	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	585	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	596	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	604	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	590	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	568	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	559	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	499	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	494	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	548	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	558	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	509	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	503	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	452	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	446	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	499	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	514	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	523	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	538	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	526	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	540	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	561	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	533	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	533	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	567	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	550	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	537	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	588	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	582	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	505	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	511	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	505	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	547	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	563	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	594	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	642	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	579	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	514	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	485	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	439	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	503	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	584	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	630	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	568	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	494	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	522	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	550	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	573	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	578	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	535	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	539	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	506	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	560	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	590	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	513	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	460	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	450	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	469	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	526	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	10:44:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	539	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:10:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	646	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:10:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	604	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:10:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	588	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:10:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	605	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:10:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	557	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:10:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	539	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	548	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	545	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	519	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	487	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	505	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	584	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	598	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	597	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	560	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	521	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	525	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	506	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	478	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	535	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	558	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	554	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	483	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	565	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	512	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	528	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	565	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	621	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	619	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	571	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	592	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	649	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	659	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	611	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	596	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	629	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	565	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	525	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	584	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	551	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	604	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	603	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	588	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	637	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	644	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	648	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	615	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	633	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	635	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	639	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	620	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	605	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	615	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	555	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	574	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	556	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	552	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	583	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	562	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	558	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	542	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	516	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	532	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	520	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	584	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:11:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	562	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	556	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	576	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	648	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	624	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	630	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	580	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	617	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	646	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	637	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	686	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	740	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	693	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	664	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	674	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	684	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	689	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	686	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	36	716	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	681	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	629	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	656	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	633	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	593	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	549	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	548	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	568	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	589	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	557	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	600	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	718	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	705	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	686	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	706	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	653	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	652	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	677	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	723	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	678	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	603	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	567	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	588	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	594	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	44	630	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	36	580	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	526	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	493	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	466	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	458	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	439	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	436	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	480	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	506	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	537	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	586	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	610	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	598	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	578	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	545	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	534	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:12:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	502	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	535	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	568	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	564	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	525	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	550	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	604	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	590	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	599	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	622	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	571	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	576	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	534	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	548	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	548	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	590	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	627	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	653	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	633	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	650	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	638	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	621	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	625	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	622	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	629	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	624	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	587	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	612	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	633	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	603	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	615	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	648	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	628	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	576	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	601	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	614	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	677	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	653	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	675	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	664	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	674	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	660	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	635	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	583	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	554	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	595	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	592	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	536	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	558	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	564	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	582	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	529	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	507	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	529	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	495	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	494	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	478	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	513	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	460	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	474	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:13:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	475	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	431	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	475	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	513	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	496	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	518	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	501	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	473	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	485	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	494	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	536	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	526	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	524	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	536	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	536	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	467	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	517	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	556	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	572	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	544	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	546	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	578	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	605	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	593	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	586	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	578	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	548	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	570	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	609	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	642	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	671	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	665	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	652	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	605	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	568	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	574	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	591	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	596	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	594	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	539	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	514	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	486	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	450	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	469	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	484	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	426	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	470	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	461	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	524	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	458	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	474	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	454	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	468	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	474	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	534	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	544	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	599	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	628	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	589	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	613	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:14:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	598	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	553	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	596	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	541	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	562	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	500	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	475	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	465	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	491	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	492	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	478	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	501	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	496	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	490	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	498	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	528	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	543	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	531	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	502	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	552	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	581	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	550	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	571	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	640	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	625	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	596	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	605	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	628	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	646	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	673	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	670	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	634	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	571	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	587	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	554	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	585	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	632	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	556	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	570	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	587	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	579	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	590	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	571	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	601	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	557	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	579	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	640	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	575	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	592	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	593	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	633	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	617	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	602	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	668	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	645	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	601	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	589	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	588	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	567	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	584	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:15:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	588	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	614	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	588	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	579	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	593	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	573	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	600	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	633	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	626	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	610	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	573	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	523	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	581	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	538	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	650	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	604	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	661	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	679	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	675	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	650	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	594	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	537	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	621	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	639	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	606	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	623	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	594	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	594	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	562	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	593	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	605	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	584	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	655	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	600	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	633	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	580	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	580	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	538	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	542	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	586	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	577	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	652	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	617	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	612	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	544	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	529	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	520	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	476	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	521	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	560	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	523	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	585	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	598	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	577	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	612	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	598	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	619	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	630	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	622	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	596	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:16:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	540	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	575	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	546	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	568	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	518	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	535	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	549	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	489	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	499	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	532	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	535	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	566	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	563	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	522	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	512	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	496	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	549	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	579	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	652	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	652	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	586	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	658	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	691	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	708	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	745	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	681	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	621	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	594	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	559	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	520	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	480	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	490	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	533	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	512	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	471	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	473	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	519	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	624	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	594	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	571	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	568	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	621	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	582	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	552	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	549	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	575	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	543	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	576	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	581	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	550	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	571	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	519	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	534	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	542	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	507	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	537	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	551	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	581	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	551	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	574	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:17:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	595	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	592	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	571	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	541	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	507	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	503	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	510	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	481	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	548	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	626	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	608	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	585	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	575	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	524	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	539	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	541	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	506	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	467	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	514	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	510	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	536	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	570	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	598	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	576	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	570	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	605	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	512	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	527	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	600	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	530	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	509	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	515	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	500	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	483	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	483	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	495	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	502	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	531	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	465	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	488	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	484	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	520	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	457	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	461	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	452	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	443	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	438	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	480	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	467	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	423	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	423	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	422	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	457	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	467	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	448	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	498	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	497	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	482	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	483	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	526	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:18:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	484	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	495	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	491	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	537	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	502	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	531	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	502	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	498	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	541	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	543	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	593	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	629	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	645	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	614	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	589	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	627	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	567	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	596	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	598	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	603	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	580	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	570	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	621	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	605	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	639	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	594	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	559	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	543	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	614	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	647	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	594	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	584	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	541	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	582	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	645	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	680	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	802	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	793	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	722	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	664	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	689	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	661	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	616	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	645	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	616	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	566	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	595	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	574	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	546	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	532	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	511	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	563	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	572	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	615	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	613	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	621	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	616	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	622	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	650	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	662	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:19:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	628	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	600	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	638	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	608	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	585	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	519	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	533	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	602	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	554	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	615	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	600	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	627	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	611	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	552	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	583	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	551	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	618	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	648	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	604	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	615	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	636	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	592	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	648	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	592	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	572	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	581	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	585	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	578	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	626	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	609	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	617	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	624	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	645	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	604	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	567	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	550	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	538	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	551	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	642	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	647	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	649	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	618	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	613	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	623	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	583	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	596	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	572	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	574	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	582	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	623	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	572	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	579	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	663	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	637	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	607	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	685	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	45	634	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	616	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	702	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	705	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:20:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	708	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	631	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	603	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	590	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	592	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	592	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	558	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	542	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	553	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	551	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	538	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	525	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	562	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	625	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	609	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	653	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	622	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	630	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	646	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	626	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	622	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	611	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	39	623	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	596	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	575	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	564	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	566	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	562	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	593	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	561	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	544	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	533	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	542	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	519	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	556	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	530	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	563	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	549	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	524	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	539	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	564	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	573	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	589	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	639	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	640	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	665	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	607	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	597	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	542	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	599	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	563	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	582	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	553	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	504	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	512	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	540	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	601	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	542	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	558	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	497	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:21:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	505	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	558	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	599	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	543	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	531	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	581	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	564	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	549	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	513	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	518	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	522	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	525	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	530	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	580	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	584	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	611	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	623	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	609	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	550	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	500	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	521	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	466	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	518	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	474	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	453	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	488	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	556	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	538	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	552	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	549	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	524	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	537	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	563	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	581	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	598	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	517	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	531	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	512	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	517	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	544	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	521	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	535	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	477	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	454	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	447	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	419	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	467	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	491	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	524	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	479	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	503	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	556	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	562	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	557	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	565	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	626	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	671	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	731	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	686	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	661	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:22:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	718	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	699	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	682	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	622	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	562	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	556	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	530	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	543	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	541	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	610	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	631	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	590	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	566	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	618	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	658	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	636	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	584	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	597	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	609	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	669	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	679	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	639	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	656	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	608	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	663	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	640	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	598	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	586	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	600	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	520	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	523	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	563	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	628	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	644	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	579	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	536	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	517	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	545	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	567	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	596	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	609	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	595	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	639	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	606	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	674	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	639	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	663	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	629	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	622	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	605	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	664	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	724	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	724	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	723	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	676	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	625	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	594	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	615	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	590	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	612	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:23:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	596	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	574	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	554	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	609	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	634	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	602	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	555	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	538	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	506	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	487	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	451	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	467	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	437	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	431	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	428	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	415	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	510	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	514	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	505	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	479	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	455	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	503	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	517	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	490	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	531	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	543	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	531	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	500	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	477	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	512	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	482	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	549	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	606	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	616	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	578	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	570	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	540	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	459	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	510	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	525	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	496	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	564	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	611	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	688	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	627	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	634	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	614	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	598	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	589	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	533	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	629	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	611	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	656	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	622	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	645	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	614	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	714	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	670	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	656	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	657	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:24:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	644	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	622	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	593	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	602	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	613	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	620	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	637	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	708	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	689	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	662	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	732	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	736	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	700	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	728	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	727	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	719	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	738	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	689	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	737	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	676	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	721	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	689	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	698	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	729	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	705	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	626	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	596	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	666	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	655	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	589	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	615	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	622	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	571	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	532	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	582	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	620	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	640	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	623	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	620	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	630	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	647	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	637	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	665	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	638	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	640	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	694	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	733	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	695	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	679	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	696	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	643	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	637	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	665	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	652	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	618	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	712	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	699	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	737	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	689	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	671	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:25:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	668	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	667	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	689	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	697	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	715	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	712	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	717	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	808	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	804	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	729	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	690	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	697	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	692	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	709	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	655	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	656	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	597	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	551	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	563	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	548	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	523	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	529	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	552	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	620	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	602	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	581	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	574	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	591	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	614	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	634	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	653	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	691	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	683	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	712	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	677	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	615	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	611	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	613	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	675	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	661	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	625	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	597	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	576	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	582	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	528	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	555	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	582	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	572	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	555	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	586	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	625	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	650	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	643	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	633	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	592	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	618	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	579	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	640	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	586	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	632	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:26:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	611	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	564	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	549	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	586	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	578	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	582	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	663	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	642	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	660	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	635	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	654	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	630	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	566	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	551	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	536	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	501	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	538	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	528	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	551	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	516	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	532	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	581	Drywall

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	572	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	588	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	605	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	649	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	610	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	574	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	615	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	577	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	572	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	553	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	527	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	492	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	580	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	699	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	665	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	653	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	663	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	671	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	623	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	665	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	608	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	608	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	684	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	625	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	576	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	600	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	613	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	654	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	642	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	602	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	601	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	681	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	599	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	553	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	561	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	578	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	650	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	572	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:27:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	566	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:28:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	641	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:28:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	683	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:28:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	668	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:28:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	630	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:28:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	671	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:28:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	656	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:28:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	588	Drywall

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:28:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	625	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:28:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	630	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:28:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	620	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:28:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	628	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:28:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	588	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:28:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	625	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:28:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	631	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:28:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	637	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:28:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	643	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:28:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	587	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:28:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	557	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:28:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	543	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:28:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	678	Drywall
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	562	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	537	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	503	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	534	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	533	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	511	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	540	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	618	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	584	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	595	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	618	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	669	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	714	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	669	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	666	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	712	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	760	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	684	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	624	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	596	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	630	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	639	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	621	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	615	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	542	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	566	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	630	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	532	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	477	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	478	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	477	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	453	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	468	Laboratory Bench

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	536	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	503	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	454	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	425	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	493	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	434	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	445	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	429	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	428	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	435	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	409	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	398	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	415	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	426	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:41:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	506	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	467	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	484	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	506	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	457	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	438	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	447	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	480	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	480	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	535	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	550	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	558	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	565	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	631	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	622	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	560	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	559	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	554	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	542	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	540	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	481	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	505	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	557	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	556	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	543	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	532	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	523	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	527	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	597	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	551	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	525	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	515	Laboratory Bench

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	534	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	579	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	549	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	571	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	519	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	568	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	539	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	539	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	495	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	469	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	424	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	434	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	397	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	423	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	434	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	432	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	417	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	462	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	536	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	558	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	558	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	600	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	589	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	615	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	634	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	636	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	659	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	625	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:42:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	551	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	875	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	802	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	716	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	705	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	733	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	718	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	647	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	648	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	615	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	660	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	579	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	563	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	592	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	595	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	562	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	560	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	577	Laboratory Bench

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	544	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	544	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	555	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	529	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	498	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	554	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	537	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	523	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	536	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	523	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	529	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	555	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	532	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	555	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	553	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	542	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	484	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	513	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	507	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	515	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	484	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	493	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	513	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	526	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	565	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	595	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	537	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	597	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	553	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	550	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	526	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	484	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	472	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	521	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	547	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	500	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	532	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	510	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	518	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	501	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	497	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	496	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:43:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	516	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	520	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	465	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	456	Laboratory Bench

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	541	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	517	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	453	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	460	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	429	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	835	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	787	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	728	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	671	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	611	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	597	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	541	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	517	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	518	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	498	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	496	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	480	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	503	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	486	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	475	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	476	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	490	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	533	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	523	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	539	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	584	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	597	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	553	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	563	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	582	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	592	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	573	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	556	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	553	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	538	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	547	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	569	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	587	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	545	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	545	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	573	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	588	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	568	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	577	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	582	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	529	Laboratory Bench

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	509	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	478	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	523	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	504	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	474	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	486	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	482	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	485	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	452	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	422	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:44:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	420	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	385	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	346	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	382	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	457	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	483	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	493	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	467	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	437	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	435	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	421	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	407	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	409	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	412	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	415	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	369	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	412	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	428	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	418	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	488	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	501	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	529	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	486	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	484	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	473	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	472	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	439	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	467	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	400	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	381	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	400	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	469	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	505	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	534	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	556	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	529	Laboratory Bench

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	451	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	504	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	510	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	551	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	512	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	474	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	463	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	528	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	510	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	536	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	503	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	558	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	554	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	517	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	575	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	592	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	628	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	635	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	637	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	664	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	698	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	677	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	619	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	623	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:45:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	585	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	507	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	492	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	456	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	528	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	544	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	508	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	513	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	568	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	584	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	577	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	603	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	581	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	581	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	653	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	667	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	631	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	613	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	578	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	561	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	635	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	608	Laboratory Bench

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	596	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	539	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	529	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	473	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	464	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	490	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	510	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	492	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	510	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	471	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	451	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	455	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	425	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	481	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	478	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	512	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	506	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	556	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	530	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	531	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	512	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	473	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	508	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	504	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	499	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	463	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	418	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	491	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	455	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	471	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	496	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	495	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	505	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	550	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	548	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	546	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	615	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	589	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:46:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	544	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	594	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	585	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	555	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	551	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	504	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	474	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	508	Laboratory Bench

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	491	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	478	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	512	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	516	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	508	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	448	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	490	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	489	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	464	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	466	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	388	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	461	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	442	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	403	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	439	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	470	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	575	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	556	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	494	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	504	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	476	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	524	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	572	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	613	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	656	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	647	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	658	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	589	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	537	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	568	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	563	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	581	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	618	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	556	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	549	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	596	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	638	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	620	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	617	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	614	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	554	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	516	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	509	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	551	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	585	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	562	Laboratory Bench

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	533	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	468	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	504	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	478	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	446	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	464	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:47:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	479	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	534	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	478	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	531	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	499	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	483	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	517	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	558	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	522	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	512	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	521	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	479	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	480	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	491	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	521	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	537	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	582	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	538	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	549	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	599	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	568	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	581	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	540	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	538	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	491	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	477	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	515	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	530	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	497	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	436	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	495	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	456	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	505	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	492	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	492	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	457	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	450	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	492	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	556	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	565	Laboratory Bench

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	565	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	604	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	568	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	550	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	526	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	570	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	576	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	556	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	543	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	520	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	513	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	508	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	492	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	533	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	546	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	555	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	539	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	542	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	554	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	564	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:48:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	514	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	507	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1348	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1181	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1062	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	966	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	896	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	843	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	805	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	799	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	680	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	631	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	601	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	626	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	622	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	607	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	570	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	584	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	696	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	668	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	631	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	660	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	648	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	615	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	587	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	544	Laboratory Bench

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	530	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	554	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	598	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	622	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	594	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	663	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	607	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	536	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	580	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	548	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	558	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	555	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	485	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	463	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	500	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	566	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	581	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	597	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	600	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	562	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	544	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	543	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	532	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	566	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	515	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	496	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	493	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	536	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	541	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	531	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	545	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	500	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	531	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	530	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:49:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	509	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	494	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	467	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	458	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	518	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	499	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	506	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	538	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	592	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	595	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	586	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	600	Laboratory Bench

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	611	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	639	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	644	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	657	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	666	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	699	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	702	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	694	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	678	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	650	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	638	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	586	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	611	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	561	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	582	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	618	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	600	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	587	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	542	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	545	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	542	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	551	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	514	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	540	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	549	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	596	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	575	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	610	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	633	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	606	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	619	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	594	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	584	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	622	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:50:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	641	Laboratory Bench
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:29:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	560	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:29:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	519	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	537	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	503	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	499	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	576	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	587	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	622	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	594	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	549	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	573	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	555	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	602	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	628	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	612	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	529	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	601	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	590	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	615	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	603	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	569	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	586	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	587	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	554	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	565	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	592	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	615	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	587	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	611	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	688	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	706	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	760	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	800	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	946	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	831	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	917	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	830	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	762	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	878	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	827	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	878	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	916	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	870	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	899	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	845	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	817	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	812	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	779	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	769	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	853	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	802	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	741	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	829	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	795	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	712	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	758	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	739	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	679	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	699	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	633	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	717	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:30:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	685	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	681	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	620	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	720	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	838	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	780	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	789	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	775	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	817	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	766	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	779	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	758	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	838	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	828	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	843	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	880	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	972	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	971	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	990	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	964	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	950	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	906	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	896	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	851	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	966	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	954	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	947	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	858	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	818	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	730	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	750	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	746	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	793	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	855	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	864	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	778	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	733	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	651	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	677	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	697	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	712	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	757	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	786	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	785	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	751	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	733	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	788	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	848	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	848	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	862	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	829	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	795	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	825	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	816	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	821	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	743	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	739	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	698	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	646	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	696	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:31:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	690	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	660	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	637	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	720	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	672	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	635	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	660	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	649	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	614	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	654	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	608	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	654	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	645	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	604	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	684	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	623	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	673	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	636	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	41	616	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	45	638	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	47	649	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	38	745	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	43	727	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	724	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	40	848	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	870	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	38	852	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	859	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	869	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	784	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	682	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	668	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	636	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	618	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	637	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	616	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	603	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	570	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	633	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	593	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	619	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	652	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	701	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	742	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	783	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	818	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	809	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	747	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	753	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	756	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	716	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	670	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	659	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	678	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	687	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	725	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	725	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	722	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	696	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	690	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:32:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	615	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	626	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	667	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	664	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	665	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	631	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	696	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	691	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	709	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	679	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	690	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	650	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	687	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	649	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	640	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	607	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	606	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	594	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	570	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	552	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	536	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	492	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	486	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	541	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	528	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	532	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	547	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	533	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	546	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	614	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	557	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	588	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	578	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	633	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	615	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	591	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	650	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	595	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	585	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	577	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	592	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	607	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	663	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	682	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	680	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	709	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	688	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	660	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	681	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	687	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	763	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	756	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	756	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	715	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	706	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	775	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	786	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	771	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	808	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	779	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:33:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	746	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	693	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	741	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	749	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	745	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	752	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	757	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	748	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	684	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	692	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	700	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	667	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	691	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	707	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	677	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	686	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	706	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	686	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	701	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	705	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	720	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	684	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	704	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	709	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	702	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	706	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	688	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	684	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	645	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	695	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	703	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	699	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	726	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	713	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	716	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	692	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	710	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	697	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	744	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	730	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	741	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	772	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	793	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	801	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	750	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	699	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	759	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	776	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	696	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	754	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	726	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	678	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	676	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	676	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	624	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	655	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	668	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	700	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	637	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	665	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:34:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	704	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	730	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	763	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	732	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	762	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	731	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	730	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	675	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	624	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	588	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	615	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	543	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	692	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	662	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	669	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	654	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	689	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	684	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	684	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	707	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	712	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	711	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	656	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	635	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	640	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	645	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	594	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	583	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	599	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	599	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	565	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	558	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	577	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	559	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	536	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	501	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	510	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	517	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	520	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	570	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	608	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	574	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	629	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	690	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	652	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	635	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	663	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	640	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	643	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	689	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	663	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	682	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	667	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	681	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	707	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	732	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	651	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	617	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	611	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	655	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:35:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	620	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	603	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	605	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	603	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	650	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	641	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	622	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	626	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	610	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	552	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	605	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	592	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	636	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	571	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	586	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	611	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	542	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	517	Concrete Block

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	521	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	537	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	582	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	640	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	644	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	673	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	668	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	676	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	635	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	614	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	622	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	699	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	643	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	634	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	639	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	641	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	726	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	654	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	653	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	621	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	594	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	583	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	552	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	551	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	581	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	628	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	622	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	583	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	551	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	547	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	532	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	502	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	508	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	504	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	489	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	531	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	604	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	673	Concrete Block
Building 2540	9	Scan	Survey Unit 09	"	6/18/2012	2:36:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	672	Concrete Block
Building 2540	15	Scan	Survey Unit 15	Miller	6/20/2012	3:52:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1089	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	1168	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1141	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	1037	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1040	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1023	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1011	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1050	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1089	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1124	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1025	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	989	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1076	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1088	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1099	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1153	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1093	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1058	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1023	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1032	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	996	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	963	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	975	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	936	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	894	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	977	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1040	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1061	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1075	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	982	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1014	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	981	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	986	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	987	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1067	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	942	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	937	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	988	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	946	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	960	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1032	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	975	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	996	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1046	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1074	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1190	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1221	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1182	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1151	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	1155	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1015	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	1026	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	989	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:52:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1021	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1008	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	975	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1040	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	1060	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1054	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1073	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1193	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1148	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	1146	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1098	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	1084	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1091	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1113	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	1065	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1022	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	977	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1012	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1001	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	959	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	914	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	948	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	968	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1002	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1028	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1042	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1026	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	970	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	932	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	956	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	977	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	990	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	948	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	907	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	913	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1031	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1026	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1024	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	989	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1026	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1020	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1021	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1009	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	998	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1013	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	961	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	916	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	971	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	994	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	984	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	967	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	910	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1017	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1054	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1058	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1029	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	995	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1078	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1012	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1061	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:53:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1156	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1085	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1084	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1134	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1170	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1083	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1014	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	1030	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	1023	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	966	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	942	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	877	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	938	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	941	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	953	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	993	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	971	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1041	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1019	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1078	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1085	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1151	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1286	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1277	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1208	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1300	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1323	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1174	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1089	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1081	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1024	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	999	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1043	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1057	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1096	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1116	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1158	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1128	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1185	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1130	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	1178	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1150	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	1115	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1125	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1159	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1144	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1211	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1195	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1176	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1172	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1175	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1204	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1077	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1044	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1050	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	998	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1106	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1155	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1160	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1075	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:54:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1161	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1155	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1218	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1194	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1211	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1284	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	1255	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	45	1267	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	36	1198	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	1231	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1261	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1270	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1271	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1297	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1197	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1271	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1252	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1252	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1243	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1100	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1089	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1071	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1087	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1142	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1060	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1190	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1136	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1137	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	1128	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1105	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1164	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	1156	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	1140	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	1196	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1197	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	1264	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	1241	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	1218	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	1223	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	1140	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1308	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1373	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1366	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1323	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1300	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1372	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1398	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1243	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1248	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1289	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1282	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1252	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1229	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1164	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1212	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1196	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1139	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1183	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1150	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1117	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:55:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1157	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1228	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1118	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1144	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1113	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1128	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1131	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1109	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1186	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1110	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	1140	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1173	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	1140	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1061	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	986	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	972	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1062	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1022	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1021	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1069	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1036	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	40	1048	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	1004	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	940	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	898	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	984	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	957	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	945	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	988	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1001	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	948	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1019	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1021	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1058	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1134	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1112	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1117	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1047	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1052	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1058	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1075	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	1002	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1050	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	1055	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1127	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	1107	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1101	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1214	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1280	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1151	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1174	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1206	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1182	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1184	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1223	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1246	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1237	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1194	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1173	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1122	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:56:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1178	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1245	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1215	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1286	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1191	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1144	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1129	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1212	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1117	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1193	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1215	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1225	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	1173	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1132	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1276	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1169	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1186	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1222	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1217	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1168	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1237	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1285	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1266	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1342	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1326	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1322	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1206	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1127	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1169	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1161	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1194	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	1168	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1150	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1193	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1172	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1230	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1199	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1201	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1249	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1226	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1164	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1275	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1331	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1262	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1237	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1171	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1172	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1151	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1194	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	40	1138	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	1107	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1126	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1047	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	1019	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	988	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1052	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1082	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1189	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1147	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	1154	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:57:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	1109	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1147	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1109	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1169	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1138	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1115	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1128	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1089	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1180	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1191	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1135	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1136	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1123	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1080	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1085	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1073	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1062	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1019	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1017	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1090	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1102	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1201	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1222	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1239	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1188	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1190	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1204	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1101	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1110	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1144	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1197	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	1220	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	1195	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	1184	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1131	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1076	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	1078	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1133	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1078	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1113	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1200	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1196	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1149	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1180	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1172	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1145	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1117	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1075	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1072	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1091	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1077	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1115	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1088	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1014	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	3:58:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1025	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	697	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	738	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	657	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	613	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	566	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	536	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	512	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	472	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	463	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	487	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	496	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	501	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	476	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	475	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	487	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	508	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	472	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	506	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	569	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	600	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	576	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	554	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	563	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	582	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	564	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	592	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	673	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	660	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	686	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	648	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	626	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	596	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	573	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	578	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	617	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	576	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	559	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	543	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	594	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	573	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	557	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	556	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	541	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:02:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	520	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	559	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	544	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	611	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	618	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	672	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	656	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	636	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	596	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	623	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	593	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	618	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	580	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	628	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	625	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	622	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	627	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	610	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	597	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	539	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	548	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	577	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	593	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	638	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	700	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	637	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	654	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	641	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	621	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	604	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	635	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	585	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	623	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	582	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	594	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	575	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	590	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	591	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	547	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	570	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	613	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	613	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	610	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	575	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	602	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	588	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	545	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	613	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	578	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	605	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	636	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	643	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	624	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	632	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	578	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	535	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	639	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	655	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	611	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	632	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:03:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	603	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	639	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	575	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	533	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	548	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	545	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	532	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	512	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	653	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	585	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	612	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	634	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	636	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	618	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	625	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	624	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	621	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	607	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	562	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	536	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	561	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	671	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	668	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	704	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	673	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	647	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	659	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	711	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	635	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	568	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	586	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	614	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	591	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	558	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	532	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	580	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	561	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	512	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	506	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	524	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	515	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	531	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	578	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	649	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	668	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	640	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	608	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	640	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	611	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	610	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	620	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	595	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	597	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	609	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	596	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	641	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	657	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	614	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	577	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	549	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:04:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	523	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	549	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	629	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	633	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	590	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	555	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	566	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	562	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	559	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	592	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	614	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	588	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	555	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	540	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	518	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	568	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	541	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	576	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	570	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	598	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	551	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	615	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	653	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	708	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	700	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	737	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	729	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	691	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	695	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	710	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	703	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	669	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	655	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	630	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	591	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	536	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	630	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	578	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	616	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	603	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	592	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	536	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	515	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	519	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	514	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	510	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	549	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	547	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	558	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	543	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	573	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	590	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	593	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	562	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	606	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	643	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	577	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	616	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	615	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	585	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:05:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	552	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	540	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	528	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	462	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	499	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	551	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	637	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	619	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	606	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	615	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	659	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	657	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	600	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	577	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	639	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	608	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	562	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	515	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	498	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	529	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	641	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	563	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	569	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	540	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	496	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	537	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	547	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	589	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	592	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	571	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	530	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	488	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	510	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	561	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	532	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	579	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	591	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	595	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	643	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	637	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	551	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	573	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	589	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	525	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	516	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	648	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	607	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	604	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	555	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	576	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	606	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	643	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	645	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	674	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	626	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	646	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	558	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	498	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	461	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	522	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:06:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	533	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:07:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	555	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:07:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	588	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:07:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	610	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:07:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	619	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:07:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	536	Laminate Tile

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:07:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	515	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:07:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	524	Laminate Tile
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:11:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	1402	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:11:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1327	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:11:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1421	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:11:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1472	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:11:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1296	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:11:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1316	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:11:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1343	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:11:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1318	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:11:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1273	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:11:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1309	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:11:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1309	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1420	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1461	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1415	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1387	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1335	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1330	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1327	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1334	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1370	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1260	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	1230	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1281	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1231	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1309	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1336	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1297	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1414	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1391	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1368	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1348	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1355	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1316	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1305	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1413	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1360	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1383	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1334	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1368	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1359	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1348	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1362	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1356	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1407	Carpet

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1484	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1462	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1330	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1306	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1307	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1315	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1279	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1297	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1248	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1216	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1289	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1427	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1428	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1423	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1337	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1267	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	1246	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1276	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1240	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1290	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1321	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1418	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1382	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1375	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1252	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1279	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:12:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1216	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1237	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1230	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1166	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1217	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	1260	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1320	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1273	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1274	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1256	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1201	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1213	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1306	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1340	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1247	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1158	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1119	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1166	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	1207	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1183	Carpet

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1139	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1173	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1170	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1198	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1237	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1240	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1357	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1292	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1240	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1164	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1144	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1236	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1244	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1163	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1308	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1320	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1322	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1280	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1334	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1322	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1346	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1334	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1285	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1279	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1347	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1423	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	1419	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	1398	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1301	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1304	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	1318	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	43	1237	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	35	1179	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	1196	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1241	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1282	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1315	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1340	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1387	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1347	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:13:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1328	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1308	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1234	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1218	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	1204	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1163	Carpet

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1290	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1285	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1225	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1217	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1287	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1350	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1344	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1317	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1363	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1339	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1310	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1372	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1399	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1368	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1304	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1332	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1342	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1350	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1218	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1292	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1294	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1344	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1270	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1281	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1381	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1370	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1343	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1306	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1329	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1316	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1229	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1332	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1284	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1463	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1451	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1427	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1397	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1338	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1349	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1308	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1294	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1260	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1249	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1222	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1279	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1343	Carpet

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1278	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1421	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1445	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1493	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1388	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1411	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1473	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1566	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:14:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1501	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1341	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	1455	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	40	1451	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	1378	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1410	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1312	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1379	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1352	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1486	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1327	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1281	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	1162	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	32	1200	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1164	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1173	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1155	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1269	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1278	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1286	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1248	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1205	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1215	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1265	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1268	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1369	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1314	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1272	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1168	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1187	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1238	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1173	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1207	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1225	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1202	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1171	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1160	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1175	Carpet

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1260	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1215	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1153	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1166	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1178	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1263	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1297	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1266	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1265	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1172	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1167	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1239	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1246	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1283	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1315	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1295	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1234	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1261	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	1272	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	38	1281	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	42	1263	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	1183	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:15:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	1224	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1175	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1265	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1197	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1240	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1325	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1403	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1389	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1214	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1225	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1246	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1171	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1121	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1226	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1183	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1230	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1168	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1209	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1277	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1242	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1279	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	26	1263	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1259	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1278	Carpet

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1365	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1379	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1314	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1225	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1280	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1286	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1280	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1255	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1303	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1237	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1336	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1438	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1449	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1495	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1521	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1470	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1480	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1561	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1477	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1382	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1310	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1299	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1339	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1314	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1268	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1208	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1198	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1279	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1185	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1121	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1145	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1121	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1116	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1247	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1182	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1239	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:16:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1264	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1353	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1265	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1287	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1319	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1405	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1422	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	1439	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	1383	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	43	1394	Carpet

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	34	1351	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	1309	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1245	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	1260	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1228	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1188	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	28	1240	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	1251	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	39	1299	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	1326	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	1259	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	1214	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1281	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	1257	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	1164	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1143	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1071	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1212	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1306	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1380	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1287	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1249	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1182	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1244	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1259	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1270	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1257	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1346	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1270	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1240	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1226	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	53	1175	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	43	1216	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	45	1216	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	37	1246	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	30	1184	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1221	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1230	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1246	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1225	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1200	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1119	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1217	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1312	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	1338	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	31	1300	Carpet

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	36	1294	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	1326	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1327	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1352	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:17:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1482	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1446	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1410	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1483	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1381	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1365	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1271	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1189	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1168	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1149	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1150	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1112	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1159	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1180	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	36	1275	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	29	1322	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1244	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1155	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1137	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1142	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1183	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1152	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1160	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1238	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1254	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1106	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	24	1198	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1239	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1233	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1284	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	19	1278	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1277	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1285	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1202	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1228	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:34 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1287	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:35 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1285	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:36 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1398	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:37 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1416	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:38 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1375	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:39 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1320	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:40 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1261	Carpet

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:41 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1213	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:42 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1241	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:43 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1263	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:44 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1235	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:45 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1242	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:46 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1171	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:47 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1129	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:48 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1107	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:49 PM	"	Ludlum 43-37-1 (SN 136361)	821	0	1084	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:50 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1059	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:51 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1007	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:52 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1113	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:53 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1166	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:54 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1146	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:55 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1095	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:56 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1125	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:57 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1207	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:58 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1197	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:18:59 PM	"	Ludlum 43-37-1 (SN 136361)	821	4	1247	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:19:00 PM	"	Ludlum 43-37-1 (SN 136361)	821	3	1274	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:19:01 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1296	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:19:02 PM	"	Ludlum 43-37-1 (SN 136361)	821	2	1241	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:19:03 PM	"	Ludlum 43-37-1 (SN 136361)	821	1	1233	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:19:04 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1192	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:19:05 PM	"	Ludlum 43-37-1 (SN 136361)	821	21	1209	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:19:06 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1180	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:19:07 PM	"	Ludlum 43-37-1 (SN 136361)	821	25	1150	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:19:08 PM	"	Ludlum 43-37-1 (SN 136361)	821	20	1114	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:19:09 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1211	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:19:10 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1150	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:19:11 PM	"	Ludlum 43-37-1 (SN 136361)	821	33	1145	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:19:12 PM	"	Ludlum 43-37-1 (SN 136361)	821	27	1086	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:19:13 PM	"	Ludlum 43-37-1 (SN 136361)	821	22	1153	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:19:14 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1068	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:19:15 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1115	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:19:16 PM	"	Ludlum 43-37-1 (SN 136361)	821	11	1187	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:19:17 PM	"	Ludlum 43-37-1 (SN 136361)	821	9	1152	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:19:18 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1266	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:19:19 PM	"	Ludlum 43-37-1 (SN 136361)	821	17	1212	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:19:20 PM	"	Ludlum 43-37-1 (SN 136361)	821	14	1175	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:19:21 PM	"	Ludlum 43-37-1 (SN 136361)	821	23	1276	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:19:22 PM	"	Ludlum 43-37-1 (SN 136361)	821	18	1353	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:19:23 PM	"	Ludlum 43-37-1 (SN 136361)	821	15	1275	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:19:24 PM	"	Ludlum 43-37-1 (SN 136361)	821	12	1307	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:19:25 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1259	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:19:26 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1249	Carpet

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:19:27 PM	"	Ludlum 43-37-1 (SN 136361)	821	6	1252	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:19:28 PM	"	Ludlum 43-37-1 (SN 136361)	821	5	1280	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:19:29 PM	"	Ludlum 43-37-1 (SN 136361)	821	16	1322	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:19:30 PM	"	Ludlum 43-37-1 (SN 136361)	821	13	1229	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:19:31 PM	"	Ludlum 43-37-1 (SN 136361)	821	10	1226	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:19:32 PM	"	Ludlum 43-37-1 (SN 136361)	821	8	1278	Carpet
Building 2540	15	Scan	Survey Unit 15	"	6/20/2012	4:19:33 PM	"	Ludlum 43-37-1 (SN 136361)	821	7	1284	Carpet
Building 2541	2	Scan	Survey Unit 02	Miller	6/15/2012	9:37:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	522	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:37:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	515	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:37:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	553	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:37:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	572	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:37:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	507	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:37:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	469	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:37:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	516	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:37:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	497	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:37:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	483	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:37:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	566	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:37:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	562	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:37:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	555	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:37:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	585	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:37:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	622	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:37:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	575	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:37:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	511	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:37:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	528	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:37:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	543	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:37:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	556	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:37:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	528	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:37:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	543	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:37:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	532	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:37:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	475	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:37:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	477	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:37:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	551	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:37:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	515	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:37:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	542	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:37:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	551	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:37:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	556	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:37:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	564	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:37:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	526	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:37:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	530	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:37:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	496	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:37:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	507	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	503	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	488	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	486	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	509	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	494	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	558	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	576	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	614	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	588	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	523	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	506	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	501	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	428	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	392	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	373	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	357	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	358	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	406	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	388	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	439	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	436	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	423	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	456	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	487	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	496	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	446	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	441	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	447	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	465	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	446	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	462	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	469	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	472	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	476	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	503	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	465	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	490	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	510	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	503	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	498	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	495	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	550	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	525	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	493	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	503	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	536	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	568	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	596	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	552	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	620	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	652	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	676	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	688	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	593	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	550	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	570	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	578	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	536	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	517	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:38:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	473	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	450	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	459	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	498	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	450	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	446	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	430	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	406	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	432	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	416	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	416	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	440	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	449	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	501	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	578	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	594	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	604	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	568	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	535	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	524	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	491	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	466	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	483	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	505	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	512	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	504	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	509	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	468	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	534	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	490	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	464	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	471	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	519	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	537	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	558	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	532	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	625	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	592	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	551	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	537	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	571	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	528	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	520	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	586	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	577	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	601	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	568	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	554	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	530	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	546	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	532	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	530	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	546	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	639	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	607	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	620	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	584	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	563	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	490	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	501	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:39:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	550	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	511	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	485	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	506	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	580	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	571	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	544	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	530	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	509	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	513	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	519	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	570	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	607	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	619	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	580	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	574	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	534	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	511	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	492	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	501	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	576	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	499	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	506	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	489	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	440	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	425	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	471	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	441	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	425	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	506	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	493	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	489	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	541	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	584	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	566	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	629	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	602	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	615	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	602	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	544	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	519	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	509	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	517	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	523	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	480	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	491	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	499	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	473	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	498	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	531	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	566	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	564	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	583	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	611	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	551	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	552	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	495	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	580	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	607	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	596	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:40:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	584	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	600	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	544	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	521	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	533	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	514	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	532	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	498	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	507	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	523	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	553	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	620	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	596	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	563	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	582	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	655	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	609	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	585	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	577	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	536	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	513	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	495	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	504	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	511	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	449	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	515	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	520	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	502	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	524	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	584	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	573	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	544	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	521	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	591	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	595	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	574	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	511	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	469	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	473	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	474	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	430	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	453	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	446	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	409	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	475	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	489	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	557	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	510	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	468	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	437	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	554	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	563	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	570	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	530	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	496	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	493	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	481	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	469	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	434	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	421	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:41:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	445	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	428	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	472	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	451	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	458	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	488	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	476	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	431	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	450	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	466	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	478	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	558	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	528	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	495	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	479	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	502	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	567	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	594	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	560	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	511	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	527	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	565	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	558	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	540	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	550	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	492	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	457	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	415	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	451	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	457	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	438	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	458	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	488	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	548	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	555	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	519	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	502	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	487	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	510	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	503	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	521	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	551	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	581	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	596	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	599	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	576	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	559	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	534	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	502	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	534	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	549	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	572	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	600	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	611	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	583	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	609	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	606	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	629	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	588	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	568	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:42:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	562	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	538	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	504	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	546	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	570	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	526	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	482	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	494	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	526	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	575	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	589	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	533	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	556	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	565	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	573	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	598	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	565	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	562	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	538	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	517	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	495	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	458	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	460	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	384	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	378	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	364	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	399	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	401	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	405	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	445	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	475	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	501	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	587	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	566	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	595	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	561	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	524	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	519	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	641	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	624	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	583	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	553	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	573	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	615	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	576	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	538	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	528	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	473	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	440	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	423	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	445	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	451	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	524	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	506	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	488	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	532	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	555	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	541	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	598	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	565	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:43:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	525	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	505	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	513	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	506	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	530	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	574	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	581	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	560	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	578	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	535	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	609	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	631	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	605	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	593	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	629	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	568	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	562	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	536	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	551	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	550	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	647	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	571	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	545	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	567	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	528	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	461	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	477	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	433	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	418	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	408	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	472	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	509	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	492	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	512	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	470	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	457	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	448	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	466	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	457	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	438	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	423	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	464	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	490	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	489	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	535	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	515	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	463	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	441	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	484	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	472	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	486	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	462	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	453	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	480	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	547	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	523	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	550	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	547	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	611	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	588	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:44:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	611	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	613	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	573	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	578	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	593	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	550	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	523	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	544	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	485	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	450	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	492	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	500	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	483	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	520	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	479	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	491	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	478	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	455	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	449	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	466	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	456	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	415	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	382	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	414	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	347	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	402	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	395	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	449	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	408	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	424	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	446	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	468	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	506	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	549	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	549	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	559	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	555	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	564	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	527	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	530	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	554	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	560	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	532	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	510	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	551	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	525	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	562	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	548	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	534	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	513	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	520	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	532	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	568	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	573	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	607	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	646	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	592	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	548	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	537	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	581	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:45:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	539	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	494	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	517	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	507	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	548	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	603	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	556	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	578	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	585	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	624	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	599	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	613	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	638	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	611	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	562	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	558	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	475	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	464	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	490	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	462	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	444	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	500	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	463	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	544	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	498	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	493	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	500	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	508	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	515	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	554	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	619	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	582	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	593	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	548	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	581	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	621	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	585	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	565	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	569	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	620	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	585	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	589	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	602	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	602	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	622	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	653	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	599	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	643	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	621	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	560	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	556	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	508	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	481	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	481	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	468	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	438	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	424	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	413	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	438	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	458	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:46:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	486	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	565	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	551	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	591	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	578	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	596	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	561	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	568	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	607	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	647	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	592	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	617	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	642	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	600	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	577	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	558	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	577	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	558	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	576	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	579	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	548	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	502	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	473	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	521	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	503	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	474	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	532	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	476	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	474	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	408	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	399	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	416	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	520	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	527	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	517	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	508	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	516	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	545	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	520	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	511	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	491	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	512	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	519	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	467	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	493	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	517	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	487	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	510	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	550	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	530	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	496	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	491	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	513	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	518	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	501	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	498	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	536	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	467	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	494	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	481	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:47:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	480	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	505	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	501	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	566	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	547	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	577	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	607	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	590	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	604	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	579	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	559	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	522	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	491	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	466	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	469	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	551	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	551	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	581	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	565	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	538	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	515	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	498	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	484	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	505	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	454	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	480	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	492	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	500	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	484	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	458	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	496	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	529	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	623	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	617	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	579	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	584	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	583	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	622	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	608	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	576	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	560	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	579	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	559	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	528	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	510	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	494	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	516	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	578	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	573	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	602	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	532	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	558	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	545	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	499	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	495	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	514	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	528	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	472	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	463	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	430	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:48:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	418	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	456	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	414	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	414	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	357	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	398	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	439	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	447	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	461	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	462	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	409	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	402	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	405	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	410	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	444	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	509	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	513	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	495	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	456	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	461	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	453	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	504	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	531	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	522	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	559	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	567	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	559	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	533	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	524	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	516	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	475	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	452	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	467	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	470	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	459	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	507	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	514	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	530	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	488	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	512	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	503	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	567	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	505	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	477	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	467	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	493	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	479	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	504	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	510	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	539	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	528	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	498	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	540	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	576	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	557	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	575	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	546	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	543	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	509	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	501	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:49:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	521	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	535	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	503	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	522	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	603	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	602	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	611	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	561	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	557	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	576	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	641	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	682	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	669	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	714	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	718	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	652	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	630	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	556	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	577	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	547	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	569	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	506	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	522	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	526	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	482	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	447	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	441	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	404	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	363	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	352	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	374	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	371	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	459	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	499	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	530	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	508	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	504	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	525	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	549	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	537	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	526	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	518	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	499	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	438	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	443	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	462	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	525	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	506	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	503	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	511	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	541	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	587	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	530	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	578	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	527	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	518	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	523	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	469	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	459	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	495	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:50:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	459	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	428	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	472	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	498	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	518	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	525	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	519	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	514	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	476	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	501	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	518	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	498	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	563	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	603	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	568	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	527	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	481	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	493	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	480	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	490	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	465	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	469	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	439	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	402	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	382	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	391	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	398	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	461	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	427	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	425	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	422	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	432	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	455	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	472	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	450	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	420	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	444	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	473	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	498	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	460	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	484	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	483	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	513	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	506	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	512	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	529	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	542	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	507	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	605	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	547	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	592	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	649	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	608	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	582	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	587	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	554	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	577	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	615	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	635	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	620	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:51:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	547	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	614	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	567	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	550	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	525	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	529	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	498	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	518	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	599	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	567	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	541	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	528	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	508	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	545	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	543	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	508	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	523	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	483	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	572	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	553	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	585	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	621	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	558	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	531	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	508	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	483	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	469	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	562	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	537	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	494	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	536	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	481	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	534	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	581	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	561	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	544	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	556	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	516	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	509	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	470	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	480	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	513	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	541	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	496	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	494	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	446	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	475	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	463	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	509	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	489	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	478	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	485	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	518	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	465	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	493	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	480	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	526	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	461	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	510	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	514	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:52:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	529	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	461	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	454	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	424	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	432	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	440	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	435	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	492	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	511	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	503	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	509	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	549	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	528	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	487	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	476	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	442	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	566	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	534	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	535	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	569	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	565	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	538	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	503	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	532	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	476	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	453	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	436	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	446	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	454	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	470	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	438	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	513	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	573	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	605	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	591	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	558	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	563	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	478	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	455	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	483	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	457	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	482	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	495	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	514	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	575	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	555	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	495	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	470	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	486	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	430	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	462	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	453	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	436	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	386	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	392	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	446	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	488	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	441	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	474	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	428	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:53:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	452	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	479	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	432	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	441	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	494	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	523	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	549	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	522	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	601	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	589	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	625	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	574	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	544	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	576	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	570	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	542	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	519	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	548	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	521	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	526	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	541	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	599	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	541	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	600	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	566	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	559	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	544	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	565	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	560	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	557	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	554	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	575	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	600	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	566	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	504	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	490	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	475	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	490	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	476	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	479	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	468	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	471	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	413	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	470	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	515	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	510	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	506	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	535	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	550	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	500	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	531	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	520	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	513	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	553	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	529	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	600	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	624	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	607	Poured Concrete

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	640	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	657	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:54:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	634	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:55:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	628	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:55:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	565	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:55:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	640	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:55:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	663	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:55:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	664	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:55:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	641	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:55:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	645	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:55:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	601	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:55:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	556	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:55:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	539	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:55:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	527	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:55:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	496	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:55:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	483	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:55:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	531	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:55:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	511	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:55:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	552	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:55:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	529	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:55:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	540	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:55:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	551	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:55:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	552	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:55:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	551	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:55:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	515	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:55:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	475	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:55:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	476	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:55:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	476	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:55:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	555	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:55:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	540	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:55:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	550	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:55:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	540	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:55:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	607	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:55:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	615	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:55:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	593	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:55:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	604	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:55:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	533	Poured Concrete
Building 2541	2	Scan	Survey Unit 02	"	6/15/2012	9:55:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	606	Poured Concrete
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:00:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	759	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:00:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	717	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:00:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	680	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:00:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	755	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:00:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	767	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:00:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	791	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:00:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	831	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:00:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	797	Metal

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:00:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	728	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:00:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	725	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:00:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	748	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:00:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	722	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:00:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	671	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:00:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	761	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:00:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	718	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:00:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	686	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:00:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	749	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:00:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	778	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:00:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	746	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:00:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	772	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:00:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	749	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:00:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	696	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:00:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	643	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:00:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	726	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:00:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	692	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:00:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	722	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:00:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	720	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:00:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	730	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:00:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	646	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	557	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	541	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	553	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	596	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	667	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	675	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	717	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	710	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	653	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	667	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	683	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	622	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	652	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	725	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	713	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	704	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	753	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	745	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	748	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	787	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	786	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	812	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	749	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	742	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	797	Metal

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	747	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	705	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	724	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	700	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	705	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	649	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	38	689	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	686	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	739	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	785	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	782	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	727	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	691	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	672	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	626	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	680	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	696	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	763	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	798	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	759	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	705	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	711	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	723	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	720	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	730	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	806	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	802	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	739	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	816	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	891	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	813	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	840	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	805	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	755	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:01:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	716	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	774	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	800	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	777	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	801	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	794	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	778	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	798	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	808	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	795	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	801	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	796	Metal

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	760	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	695	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	661	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	673	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	681	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	675	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	673	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	613	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	633	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	604	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	645	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	671	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	723	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	654	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	774	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	828	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	797	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	834	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	778	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	769	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	727	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	677	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	705	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	662	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	663	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	686	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	772	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	750	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	765	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	803	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	809	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	757	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	737	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	786	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	729	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	797	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	756	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	773	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	819	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	835	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	861	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	787	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	819	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	814	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	854	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	832	Metal

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	843	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	805	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:02:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	781	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	770	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	795	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	806	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	792	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	874	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	832	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	860	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	904	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	846	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	740	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	715	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	719	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	706	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	722	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	762	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	710	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	712	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	778	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	813	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	771	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	815	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	833	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	719	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	650	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	596	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	560	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	614	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	648	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	626	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	645	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	649	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	689	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	718	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	797	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	723	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	688	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	738	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	710	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	777	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	686	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	648	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	663	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	711	Metal

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	679	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	686	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	695	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	733	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	704	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	789	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	835	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	790	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	835	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	804	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	755	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	728	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	738	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	677	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	663	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	674	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:03:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	698	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	721	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	720	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	708	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	721	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	705	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	663	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	686	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	637	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	607	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	651	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	764	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	765	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	746	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	705	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	763	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	750	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	740	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	779	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	787	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	798	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	761	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	732	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	773	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	760	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	753	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	840	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	887	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	833	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	867	Metal

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	875	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	821	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	779	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	813	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	795	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	845	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	819	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	802	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	881	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	858	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	856	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	818	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	802	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	790	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	834	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	896	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	929	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	877	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	848	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	870	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	819	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	802	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	859	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	823	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	813	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	795	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	757	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	774	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	731	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	742	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:04:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	692	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	721	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	674	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	672	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	727	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	712	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	747	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	798	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	772	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	765	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	699	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	676	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	721	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	707	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	700	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	867	Metal

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	875	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	871	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	841	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	886	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	877	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	803	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	809	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	799	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	804	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	836	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	790	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	824	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	767	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	778	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	815	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	866	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	861	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	882	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	913	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	853	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	884	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	853	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	805	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	845	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	820	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	790	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	787	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	739	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	796	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	837	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	759	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	728	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	750	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	687	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	660	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	755	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	722	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	744	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	727	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	738	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	711	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	700	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	726	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	723	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:05:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	737	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	790	Metal

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	695	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	686	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	660	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	637	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	714	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	637	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	606	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	602	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	720	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	706	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	671	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	667	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	689	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	697	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	688	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	682	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	622	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	596	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	620	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	606	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	570	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	600	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	625	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	644	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	650	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	708	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	696	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	745	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	765	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	744	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	728	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	671	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	734	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	754	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	757	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	693	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	742	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	751	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	686	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	706	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	686	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	672	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	681	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	687	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	646	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	702	Metal

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	684	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	668	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	631	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	681	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	697	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	635	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	606	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	699	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	703	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	745	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	736	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	722	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:06:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	731	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	763	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	741	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	701	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	657	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	792	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	770	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	763	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	43	731	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	806	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	795	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	778	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	754	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	763	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	686	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	774	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	773	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	694	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	697	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	644	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	614	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	611	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	574	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	616	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	656	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	747	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	720	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	707	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	825	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	862	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	825	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	850	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	812	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	741	Metal

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	770	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	703	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	752	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	735	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	719	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	709	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	711	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	771	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	853	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	829	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	921	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	870	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	855	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	832	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	810	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	760	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	673	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	695	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	755	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	750	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	746	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	756	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	738	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	735	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	752	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	733	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:07:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	729	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	797	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	828	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	784	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	775	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	753	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	798	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	761	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	738	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	732	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	698	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	732	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	775	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	791	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	811	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	771	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	808	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	734	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	742	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	774	Metal

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	788	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	729	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	684	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	657	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	658	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	681	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	697	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	686	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	767	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	747	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	767	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	761	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	752	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	819	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	810	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	802	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	810	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	797	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	805	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	711	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	791	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	742	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	877	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	843	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	821	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	779	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	777	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	790	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	764	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	811	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	792	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	791	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	789	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	765	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	733	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	782	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	745	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	753	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	782	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	839	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:08:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	885	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	878	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	824	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	838	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	745	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	788	Metal

Fort Monmouth Radiological Survey - Scanning Database

Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	822	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	873	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	776	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	787	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	0	786	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	850	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	836	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	813	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	808	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	849	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	836	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	814	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	787	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	770	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	848	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	780	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	757	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	56	691	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	69	764	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	67	784	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	54	797	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	44	848	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	35	836	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	29	814	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	842	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	19	808	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	757	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	795	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	815	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	819	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	831	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	923	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	847	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	25	768	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	20	791	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	766	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	755	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	751	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	746	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	757	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	831	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	865	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	828	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	806	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	844	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	828	Metal

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	764	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	723	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	777	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	742	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	718	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	728	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	671	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	771	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:09:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	746	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	704	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	661	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	664	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	648	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	650	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	669	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	675	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	21	705	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	17	719	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	14	649	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	732	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	886	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	830	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	808	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	699	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	693	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	720	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	711	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	721	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	689	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	660	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	636	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	708	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	688	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	705	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	729	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	746	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	722	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	663	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	698	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	726	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	757	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	753	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	736	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	23	804	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	41	788	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	33	809	Metal

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	27	769	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	780	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	39	714	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	785	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	26	764	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	733	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	46	693	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:44 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	745	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:45 AM	"	Ludlum 43-37-1 (SN 136361)	821	30	707	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:46 AM	"	Ludlum 43-37-1 (SN 136361)	821	24	743	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:47 AM	"	Ludlum 43-37-1 (SN 136361)	821	32	714	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:48 AM	"	Ludlum 43-37-1 (SN 136361)	821	37	773	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:49 AM	"	Ludlum 43-37-1 (SN 136361)	821	42	774	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:50 AM	"	Ludlum 43-37-1 (SN 136361)	821	34	762	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:51 AM	"	Ludlum 43-37-1 (SN 136361)	821	28	712	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:52 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	781	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:53 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	795	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:54 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	893	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:55 AM	"	Ludlum 43-37-1 (SN 136361)	821	22	891	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:56 AM	"	Ludlum 43-37-1 (SN 136361)	821	18	813	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:57 AM	"	Ludlum 43-37-1 (SN 136361)	821	15	853	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:58 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	806	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:10:59 AM	"	Ludlum 43-37-1 (SN 136361)	821	9	890	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:00 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	870	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:01 AM	"	Ludlum 43-37-1 (SN 136361)	821	6	808	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:02 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	816	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:03 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	812	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:04 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	784	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:05 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	791	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:06 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	720	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:07 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	728	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:08 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	719	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:09 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	722	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:10 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	767	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:11 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	731	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:12 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	763	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:13 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	792	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:14 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	731	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:15 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	741	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:16 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	741	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:17 AM	"	Ludlum 43-37-1 (SN 136361)	821	12	682	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:18 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	703	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:19 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	695	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:20 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	723	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:21 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	699	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:22 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	671	Metal

Fort Monmouth Radiological Survey - Scanning Database												
Building	Survey Unit	Type	Surface	Surveyor	Date	Time	Count Length (Sec)	Probe ID	Probe Area (cm^2)	α (cpm)	Beta (cpm)	Material
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:23 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	715	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:24 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	660	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:25 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	696	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:26 AM	"	Ludlum 43-37-1 (SN 136361)	821	2	699	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:27 AM	"	Ludlum 43-37-1 (SN 136361)	821	1	658	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:28 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	609	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:29 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	609	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:30 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	572	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:31 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	585	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:32 AM	"	Ludlum 43-37-1 (SN 136361)	821	5	711	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:33 AM	"	Ludlum 43-37-1 (SN 136361)	821	4	666	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:34 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	695	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:35 AM	"	Ludlum 43-37-1 (SN 136361)	821	3	803	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:36 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	811	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:37 AM	"	Ludlum 43-37-1 (SN 136361)	821	10	807	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:38 AM	"	Ludlum 43-37-1 (SN 136361)	821	8	861	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:39 AM	"	Ludlum 43-37-1 (SN 136361)	821	7	874	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:40 AM	"	Ludlum 43-37-1 (SN 136361)	821	16	913	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:41 AM	"	Ludlum 43-37-1 (SN 136361)	821	13	909	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:42 AM	"	Ludlum 43-37-1 (SN 136361)	821	11	827	Metal
Building 2541	1	Scan	Survey Unit 01	"	6/15/2012	9:11:43 AM	"	Ludlum 43-37-1 (SN 136361)	821	31	807	Metal

APPENDIX I

Duplicate Measurement Results

Results of Duplicate Static Gross Alpha Beta Measurements

Building Number	Survey Unit ID	Location ID	Meter ID	Count time (min)	Initial Measurement Result (counts)		Duplicate Measurement Result (counts)		NAD	
					Alpha	Beta	Alpha	Beta	Alpha	Beta
Building 2540	1	3	Ludlum 43-37 (SN 093966)	1	17	945	17	978	0.00	0.75
Building 2540	1	16	Ludlum 43-37 (SN 093966)	1	19	912	20	988	0.16	1.74
Building 2540	1	19	Ludlum 43-37 (SN 092501)	1	24	900	19	936	0.76	0.84
Building 2540	2	6	Ludlum 43-37 (SN 093966)	1	38	1081	19	1083	2.52	0.04
Building 2540	2	8	Ludlum 43-37 (SN 093966)	1	32	1072	29	1090	0.38	0.39
Building 2540	2	12	Ludlum 43-37 (SN 093966)	1	35	1120	29	1038	0.75	1.77
Building 2540	3	2	Ludlum 43-37 (SN 093966)	1	34	1093	40	1140	0.70	0.99
Building 2540	3	8	Ludlum 43-37 (SN 093966)	1	24	985	38	984	1.78	0.02
Building 2540	3	13	Ludlum 43-37 (SN 093966)	1	33	810	31	838	0.25	0.69
Building 2540	3	33	Ludlum 43-37 (SN 092501)	1	37	993	58	1034	2.15	0.91
Building 2540	3	41	Ludlum 43-37 (SN 092501)	1	51	867	42	843	0.93	0.58
Building 2540	3	44	Ludlum 43-37 (SN 092501)	1	43	932	58	976	1.49	1.01
Building 2540	4	8	Ludlum 43-37 (SN 092501)	1	8	853	10	860	0.47	0.17
Building 2540	4	16	Ludlum 43-37 (SN 092501)	1	10	816	7	833	0.73	0.42
Building 2540	4	24	Ludlum 43-37 (SN 092501)	1	9	852	6	871	0.77	0.46
Building 2540	4	29	Ludlum 43-37 (SN 092501)	1	8	853	4	832	1.15	0.51
Building 2540	5	7	Ludlum 43-37 (SN 093966)	1	6	692	5	643	0.30	1.34
Building 2540	5	11	Ludlum 43-37 (SN 093966)	1	4	688	5	670	0.33	0.49
Building 2540	5	16	Ludlum 43-37 (SN 093966)	1	3	689	1	629	1.00	1.65
Building 2540	5	29	Ludlum 43-37 (SN 093966)	1	3	694	3	693	0.00	0.03
Building 2540	6	8	Ludlum 43-37 (SN 092501)	5	49	3412	66	3364	1.59	0.58
Building 2540	6	15	Ludlum 43-37 (SN 092501)	5	44	3929	47	3918	0.31	0.12
Building 2540	6	21	Ludlum 43-37 (SN 093966)	5	28	3720	33	3761	0.64	0.47
Building 2540	6	32	Ludlum 43-37 (SN 093966)	5	38	3657	37	3674	0.12	0.20
Building 2540	7	10	Ludlum 43-37 (SN 092501)	5	38	3408	33	3599	0.59	2.28
Building 2540	7	15	Ludlum 43-37 (SN 093966)	5	29	3282	27	3310	0.27	0.34
Building 2540	7	23	Ludlum 43-37 (SN 092501)	5	52	2645	35	2639	1.82	0.08
Building 2540	7	32	Ludlum 43-37 (SN 093966)	5	17	3257	12	3312	0.93	0.68
Building 2540	8	5	Ludlum 43-37 (SN 092501)	5	34	2320	32	2269	0.25	0.75
Building 2540	8	6	Ludlum 43-37 (SN 092501)	5	30	2153	38	1942	0.97	3.30
Building 2540	8	25	Ludlum 43-37 (SN 093966)	5	9	2072	14	2017	1.04	0.86
Building 2540	8	30	Ludlum 43-37 (SN 093966)	5	18	2160	14	1942	0.71	3.40
Building 2540	9	19	Ludlum 43-37 (SN 093966)	5	38	3456	37	3333	0.12	1.49
Building 2540	9	28	Ludlum 43-37 (SN 093966)	5	28	2355	33	2290	0.64	0.95
Building 2540	9	31	Ludlum 43-37 (SN 093966)	5	26	2420	22	2419	0.58	0.01
Building 2540	9	42	Ludlum 43-37 (SN 093966)	5	39	2295	34	2282	0.59	0.19
Building 2540	9	46	Ludlum 43-37 (SN 093966)	5	26	2233	26	2255	0.00	0.33
Building 2540	9	58	Ludlum 43-37 (SN 092501)	5	43	2224	61	2295	1.77	1.06
Building 2540	9	61	Ludlum 43-37 (SN 092501)	5	39	2413	45	2565	0.65	2.15
Building 2540	9	70	Ludlum 43-37 (SN 092501)	5	78	2373	56	2292	1.90	1.19

Results of Duplicate Static Gross Alpha Beta Measurements

Building Number	Survey Unit ID	Location ID	Meter ID	Count time (min)	Initial Measurement Result (counts)		Duplicate Measurement Result (counts)		NAD	
					Alpha	Beta	Alpha	Beta	Alpha	Beta
Building 2540	9	80	Ludlum 43-37 (SN 092501)	5	43	2222	49	2250	0.63	0.42
Building 2540	10	2	Ludlum 43-37-1 (SN 136361)	1	7	563	5	629	0.58	1.91
Building 2540	10	9	Ludlum 43-37-1 (SN 136361)	1	8	772	7	704	0.26	1.77
Building 2540	10	21	Ludlum 43-37-1 (SN 136361)	1	8	560	8	594	0.00	1.00
Building 2540	10	24	Ludlum 43-37-1 (SN 136361)	1	9	729	6	679	0.77	1.33
Building 2540	11	2	Ludlum 43-37 (SN 092501)	1	5	484	10	522	1.29	1.20
Building 2540	11	6	Ludlum 43-37 (SN 092501)	1	8	699	10	661	0.47	1.03
Building 2540	11	12	Ludlum 43-37 (SN 092501)	1	6	530	8	535	0.53	0.15
Building 2540	11	20	Ludlum 43-37 (SN 092501)	1	6	502	5	530	0.30	0.87
Building 2540	11	23	Ludlum 43-37 (SN 092501)	1	9	663	13	646	0.85	0.47
Building 2540	12	5	Ludlum 43-37 (SN 093966)	1	5	596	7	549	0.58	1.39
Building 2540	12	9	Ludlum 43-37 (SN 093966)	1	3	600	6	575	1.00	0.73
Building 2540	12	24	Ludlum 43-37 (SN 092501)	1	13	620	13	582	0.00	1.10
Building 2540	13	22	Ludlum 43-37 (SN 092501)	1	14	555	10	503	0.82	1.60
Building 2540	13	27	Ludlum 43-37 (SN 092501)	1	8	537	7	525	0.26	0.37
Building 2540	13	35	Ludlum 43-37 (SN 092501)	1	13	522	11	573	0.41	1.54
Building 2540	13	40	Ludlum 43-37 (SN 092501)	1	8	614	7	568	0.26	1.34
Building 2540	14	5	Ludlum 43-37 (SN 093966)	1	45	693	52	627	0.71	1.82
Building 2540	14	13	Ludlum 43-37 (SN 092501)	1	11	510	12	584	0.21	2.24
Building 2540	14	21	Ludlum 43-37 (SN 092501)	1	7	492	9	496	0.50	0.13
Building 2540	15	4	Ludlum 43-37 (SN 093966)	1	12	1014	16	1025	0.76	0.24
Building 2540	15	8	Ludlum 43-37 (SN 093966)	1	9	1076	12	1102	0.65	0.56
Building 2540	15	11	Ludlum 43-37 (SN 093966)	1	16	968	15	1001	0.18	0.74
Building 2541	1	3	Ludlum 43-37 (SN 093966)	1	14	682	17	760	0.54	2.05
Building 2541	1	7	Ludlum 43-37 (SN 093966)	1	33	767	52	782	2.06	0.38
Building 2541	1	19	Ludlum 43-37 (SN 093966)	1	41	827	36	742	0.57	2.15
Building 2541	2	10	Ludlum 43-37 (SN 092501)	1	14	434	11	434	0.60	0.00
Building 2541	2	25	Ludlum 43-37 (SN 092501)	1	12	434	5	408	1.70	0.90
Building 2541	2	29	Ludlum 43-37 (SN 092501)	1	10	384	7	409	0.73	0.89
Building 275	1	14	Ludlum 43-37 (SN 093966)	1	1	541	2	492	0.58	1.52
Building 275	1	19	Ludlum 43-37 (SN 093966)	1	4	462	2	468	0.82	0.20
Building 275	1	24	Ludlum 43-37 (SN 093966)	1	1	584	5	541	1.63	1.28
Building 283	1	1	Ludlum 43-37 (SN 093966)	1	4	584	1	589	1.34	0.15
Building 283	1	1A	Ludlum 43-37 (SN 092501)	1	11	853	25	799	2.33	1.33
Building 283	1	10	Ludlum 43-37 (SN 093966)	1	7	576	3	552	1.26	0.71
Building 283	1	15A	Ludlum 43-37 (SN 092501)	1	29	965	23	870	0.83	2.22
Building 283	1	18A	Ludlum 43-37 (SN 092501)	1	30	584	22	593	1.11	0.26
Building 283	1	19A	Ludlum 43-37 (SN 092501)	1	17	894	20	828	0.49	1.59
Building 283	1	20	Ludlum 43-37 (SN 092501)	1	16	655	14	699	0.37	1.20
Building 283	1	26A	Ludlum 43-37 (SN 092501)	1	17	836	16	792	0.17	1.09

Results of Duplicate Static Gross Alpha Beta Measurements

Building Number	Survey Unit ID	Location ID	Meter ID	Count time (min)	Initial Measurement Result (counts)		Duplicate Measurement Result (counts)		NAD	
					Alpha	Beta	Alpha	Beta	Alpha	Beta
Building 292	1	6	Ludlum 43-37 (SN 093966)	1	13	648	9	595	0.85	1.50
Building 292	1	12	Ludlum 43-37 (SN 093966)	1	5	520	9	584	1.07	1.93
Building 292	1	29	Ludlum 43-37 (SN 093966)	1	6	643	10	614	1.00	0.82

Results of Gross Alpha/Beta Smear Duplicate Analyses

Building Number	Survey Unit ID	Location ID	Initial Measurement (dpm)				Duplicate Measurement (dpm)				NAD	
			Alpha		Beta		Alpha		Beta		Alpha	Beta
			Result	Uncertainty	Result	Uncertainty	Result	Uncertainty	Result	Uncertainty		
Building 283	1	20	0.41	0.43	-0.02	0.29	0.02	0.23	0.51	0.34	1.62	NC
Building 292	1	26	-0.67	0.40	0.48	0.37	-0.05	0.35	0.30	0.36	NC	0.70
Building 2540	1	5	0.50	0.50	0.41	0.36	0.07	0.40	0.13	0.28	1.35	1.24
Building 2540	1	12	0.27	0.43	0.20	0.28	0.62	0.53	0.28	0.30	1.03	0.38
Building 2540	1	24	-0.19	0.42	1.19	0.44	0.03	0.36	-0.38	0.33	NC	NC
Building 2540	2	7	0.34	0.43	0.48	0.34	-0.01	0.32	-0.18	0.25	NC	NC
Building 2540	2	17	0.28	0.42	0.28	0.34	0.25	0.38	0.12	0.29	0.08	0.69
Building 2540	3	2	0.02	0.33	0.00	0.27	0.19	0.27	0.36	0.31	0.77	NC
Building 2540	3	16	0.44	0.30	0.18	0.32	0.21	0.31	-0.62	0.39	1.07	NC
Building 2540	3	26	0.04	0.33	0.00	0.26	0.52	0.46	0.16	0.29	1.68	0.82
Building 2540	3	38	-0.19	0.33	-0.18	0.32	-0.07	0.30	0.44	0.38	NC	NC
Building 2540	3	43	0.46	0.45	0.68	0.37	1.56	0.72	0.27	0.35	2.59	1.60
Building 2540	4	2	0.01	0.33	0.40	0.29	0.66	0.52	0.28	0.30	2.12	0.54
Building 2540	4	16	-0.72	0.39	0.26	0.35	-0.17	0.33	-0.12	0.34	NC	NC
Building 2540	6	19	0.26	0.42	-0.05	0.28	-0.16	0.28	-0.07	0.28	NC	NC
Building 2540	6	23	0.15	0.39	0.34	0.31	-0.15	0.28	0.38	0.29	NC	0.19
Building 2540	7	11	0.04	0.36	0.17	0.28	0.66	0.49	0.25	0.33	2.06	0.36
Building 2540	9	24	0.08	0.30	-1.11	0.41	-1.08	0.39	0.07	0.34	NC	NC
Building 2540	9	52	0.38	0.46	-0.07	0.24	-0.31	0.36	0.03	0.23	NC	NC
Building 2540	9	73	0.24	0.39	-0.16	0.25	0.22	0.41	-0.13	0.29	0.07	NC
Building 2540	15	19	0.31	0.45	0.33	0.35	0.13	0.39	0.40	0.35	0.59	0.29
Building 2541	1	20	0.66	0.54	0.83	0.39	1.46	0.74	0.41	0.38	1.74	1.56
Building 2541	1	28	0.67	0.51	0.03	0.28	0.94	0.56	0.34	0.32	0.70	1.43

Note: NC = not calculated; one or more results is negative

Results of Duplicate Low Energy Beta Analyses

Building Number	Survey Unit ID	Location ID	Initial Measurement (dpm)		Duplicate Measurement (dpm)		NAD
			Result	Uncertainty	Result	Uncertainty	
Building 275	1	14	1.14	4.13	3.61	4.45	0.81
Building 275	1	19	-4.25	3.53	-2.45	3.65	NC
Building 275	1	24	1.72	4.3	3.07	4.38	0.44
Building 283	1	4	1.09	3.98	1.62	4.03	0.19
Building 283	1	16	3.01	4.21	1.08	3.96	0.67
Building 292	1	6	2.79	4.36	0.886	4.27	0.62
Building 292	1	12	-1.41	3.6	1.63	4.04	NC
Building 292	1	29	5.21	4.51	1.36	4	1.28
Building 2540	1	5	0.255	4.08	-1.95	3.72	NC
Building 2540	1	12	0.814	4.21	2.22	4.35	0.46
Building 2540	1	24	6.77	4.99	-0.0194	4	NC
Building 2540	2	7	-6.71	3.73	1.44	4.26	NC
Building 2540	2	17	-2.76	3.66	-1.08	3.84	NC
Building 2540	3	2	1.41	4.18	2.56	4.39	0.38
Building 2540	3	16	-0.522	3.91	0.863	4.16	NC
Building 2540	3	26	5.87	4.77	0.0387	3.99	1.88
Building 2540	3	38	0.856	4.12	-0.254	3.98	NC
Building 2540	3	43	-0.525	3.94	2.02	4.35	NC
Building 2540	4	2	2.51	3.35	7.38	4.8	1.66
Building 2540	4	16	3.74	4.28	4.84	4.43	0.36
Building 2540	5	7	-0.0588	4.27	-3.95	3.74	NC
Building 2540	5	11	3.59	4.73	0.214	4.28	1.06
Building 2540	6	2	6.36	3.24	3.78	2.98	1.17
Building 2540	6	9	3.12	3.51	2	3.27	0.47
Building 2540	6	20	6.46	3.82	5.45	3.68	0.38
Building 2540	7	23	5.52	3.72	4.49	3.7	0.39
Building 2540	7	31	4.1	3.51	5.02	3.72	0.36
Building 2540	7	35	-7.18	4.08	-10.5	3.98	NC
Building 2540	9	11	-1.84	3.38	-1.25	3.27	NC
Building 2540	9	37	0	3.96	-2.36	3.8	NC
Building 2540	9	49	-0.561	4.21	-1.95	3.83	NC
Building 2540	9	77	0.807	4.17	1.11	4.23	0.10
Building 2540	10	12	2.26	3.53	2.84	3.6	0.23
Building 2540	11	5	1.68	3.46	0.72	3.39	0.40
Building 2540	11	22	-0.251	3.04	2.79	3.35	NC
Building 2540	11	33	0.872	3.17	2.64	3.52	0.75
Building 2540	12	5	-6.73	4.1	-11.7	4.08	NC
Building 2540	12	15	-9.73	4.03	-9.79	4.02	NC
Building 2540	12	24	-6.64	4.02	-7.73	3.77	NC
Building 2540	13	4	-12.2	3.71	-7.26	3.81	NC
Building 2540	13	11	-10.2	3.77	-8.81	3.78	NC
Building 2540	13	27	-6.11	3.82	-8.01	3.85	NC
Building 2540	13	35	-9.19	3.74	-8.19	3.83	NC
Building 2540	14	9	5.68	3.65	3.76	3.45	0.76
Building 2540	14	23	1.84	3.26	-0.733	2.99	NC
Building 2540	15	3	6.24	3.24	3.39	2.93	1.30
Building 2540	15	30	3.14	2.91	1.73	2.78	0.70
Building 2541	1	13	-3.79	3.53	-1.77	3.67	NC
Building 2541	2	6	1.61	4.42	-1.43	4.03	NC
Building 2541	2	20	3.35	4.43	-1.09	3.86	NC

Note: NC = not calculated; one or more results is negative

APPENDIX J

Laboratory Data Packages

Included Electronically as Separate Files