### **United States Army**

Fort Monmouth, New Jersey

# Underground Storage Tank Closure and Site Investigation Report

Building 2000B Charles Wood-East

NJDEP UST Registration No. 192486-38

**NOVEMBER 2000** 

## UNDERGROUND STORAGE TANK CLOSURE AND SITE INVESTIGATION REPORT

#### **BUILDING 2000B**

CHARLES WOOD-EAST
NJDEP UST REGISTRATION NO. 192486-38

#### **NOVEMBER 2000**

#### PREPARED FOR:

UNITED STATES ARMY, FORT MONMOUTH, NEW JERSEY
DIRECTORATE OF PUBLIC WORKS
BUILDING 167
FORT MONMOUTH, NJ 07703

PREPARED BY:

VERSAR 1900 FROST ROAD SUITE 110 BRISTOL, PA 19007

PROJECT NO. 4435-043

#### **TABLE OF CONTENTS**

EXECUTIVE SUMMARY	iv
1.0 UNDERGROUND STORAGE TANK DECOMMISSIONING ACTIVITIES	1
1.1 OVERVIEW 1.2 SITE DESCRIPTION	1 2
1.2.1 Geological/Hydrogeological Setting	2
1.3 HEALTH AND SAFETY 1.4 REMOVAL OF UNDERGROUND STORAGE TANK	4 4
1.4.1 General Procedures 1.4.2 Underground Storage Tank Excavation and Cleaning	4 4
1.5 UNDERGROUND STORAGE TANK TRANSPORTATION AND DISPOSAL 1.6 MANAGEMENT OF EXCAVATED SOILS	5 5
2.0 SITE INVESTIGATION ACTIVITIES	6
2.1 OVERVIEW 2.2 FIELD SCREENING/MONITORING 2.3 SOIL SAMPLING	6 6 7
3.0 CONCLUSIONS AND RECOMMENDATIONS	8
3.1 SOIL SAMPLING RESULTS 3.2 CONCLUSIONS AND RECOMMENDATIONS	8

#### **TABLE OF CONTENTS (CONTINUED)**

#### **TABLES**

Table 1 Summary of Post-Excavation Sampling Activities

 Table 2
 Post-Excavation Soil Sampling Results

#### **FIGURES**

Figure 1 Site Location Map

Figure 2 Site Map

Figure 3 Cross Sectional View

Figure 4 Soil Sampling Location Map

#### **APPENDICES**

Appendix A NJDEP Standard Reporting Form

Appendix B Site Assessment Summary
Appendix C UST Disposal Certificate

Appendix D Soil Analytical Data Package

#### **EXECUTIVE SUMMARY**

#### **UST Closure**

On November 19, 1997, a steel underground storage tank (UST) was closed by removal in accordance with the New Jersey Department of Environmental Protection (NJDEP) underground storage tank procedures at the Charles Wood-East area of the U.S. Army Fort Monmouth, Fort Monmouth, New Jersey. The UST, NJDEP Registration No. 192486-38 (Fort Monmouth ID No. 2000B), was located northeast of Building 2000B. UST No. 192486-38 was a 2,500-gallon No. 2 fuel oil UST.

#### Site Assessment

The site assessment was performed by U.S. Army personnel in accordance with the NJDEP *Technical Requirements for Site Remediation* (N.J.A.C. 7:26E) and the NJDEP *Field Sampling Procedures Manual*. The sampling and laboratory analysis conducted during the site assessment were performed in accordance with Section 7:26E-2.1 of the *Technical Requirements for Site Remediation*. Soils surrounding the tank were screened visually and with air monitoring equipment for evidence of contamination. No holes or punctures were noted in the UST and no evidence of potentially contaminated soils was observed surrounding the tank. Groundwater was encountered at 10.0 feet below ground surface and no sheen was observed. Soil samples contained TPHC concentrations ranging from non-detect to 237.92 mg/kg.

#### Site Restoration

Following receipt of all post-excavation soil sampling results, the excavation was backfilled to grade with crushed stone, sand, and native backfill and restored to its original condition.

#### Conclusions and Recommendations

Based on the post-excavation soil sampling results, soils with TPHC concentrations exceeding the NJDEP soil cleanup criteria for total organic contaminants of 10,000 mg/kg, do not exist in the former location of the UST.

No further action is proposed in regard to the closure and site assessment of UST No. 192486-38 at Building 2000B.

## 1.0 UNDERGROUND STORAGE TANK DECOMMISSIONING ACTIVITIES

#### 1.1 OVERVIEW

One underground storage tank (UST), New Jersey Department of Environmental Protection (NJDEP) Registration No. 192486-38, was closed at Building 2000B at the Charles Wood-East area of U.S. Army Fort Monmouth, Fort Monmouth, New Jersey on November 19, 1997. Refer to site location map on Figure 1. This report presents the results of the Department of Public Works (DPW) implementation of the UST Decommissioning/Closure Plan approved by the NJDEP. The UST was a steel 2,500-gallon tank containing No. 2 fuel oil.

Decommissioning activities for UST No. 192486-38 complied with all applicable Federal, State and Local laws and ordinances in effect at the date of decommissioning. These laws included but were not limited to N.J.A.C. 7:14B-1 et seq., N.J.A.C. 5:23-1 et seq., and Occupational Safety and Health Administration (OSHA) 1910.146 & 1910.120. All permits including but not limited to the NJDEP-approved Decommissioning/Closure Plan were posted onsite for inspection. The decommissioning activities were conducted by DPW personnel who are registered and certified by the NJDEP for performing UST closure activities. Closure of UST No. 192486-38 proceeded under the approval of the NJDEP Bureau of Federal Case Management (NJDEP-BFCM). The Standard Reporting Form and signed Site Assessment Summary form for UST No. 192486-38 are included in Appendices A and B, respectively.

Based on inspecting the UST, field screening of subsurface soils and groundwater, and reviewing analytical results of soil samples, the DPW has concluded that no significant historical discharges are associated with the UST.

This UST Closure and Site Investigation Report has been prepared by Versar, to assist the United States Army Directorate of Public Works (DPW) in complying with the NJDEP regulations. The applicable NJDEP regulations at the date of closure were the *Interim Closure Requirements for Underground Storage Tank Systems* (N.J.A.C. 7:14B-1 et seq. October 1990 and revisions dated November 1, 1991).

This report was prepared using information collected at the time of closure. Section 1 of this UST Closure and Site Investigation Report provides a summary of the UST decommissioning activities. Section 2 of this report describes the site investigation activities. Conclusions and recommendations, including the results of the soil sampling investigation, are presented in the final section of this report.

#### 1.2 SITE DESCRIPTION

Building 2000B is located in the Charles Wood-East area of the Fort Monmouth Army Base. UST No. 192486-38 was located northeast of Building 2000B. No product lines were found during the excavation of the UST. A site map is provided on Figure 2.

#### 1.2.1 Geological/Hydrogeological Setting

The following is a description of the geological/hydrogeological setting of the area surrounding Building 2000B. Included is a description of the regional geology of the area surrounding Fort Monmouth as well as descriptions of the local geology and hydrogeology of the Charles Wood area.

#### Regional Geology

Monmouth County lies within the New Jersey Section of the Atlantic Coastal Plain physiographic province. The Main Post, Charles Wood, and the Evans areas are located in what may be referred to as the Outer Coastal Plain subprovince, or the Outer Lowlands.

In general, New Jersey Coastal Plain formations consist of a seaward-dipping wedge of unconsolidated deposits of clay, silt, and gravel. These formations typically strike northeast-southwest with a dip ranging from 10 to 60 feet per mile and were deposited on Precambrian and lower Paleozoic rocks (Zapecza, 1989). These sediments, predominantly derived from deltaic, shallow marine, and continental shelf environments, date from Cretaceous through the Quaternary Periods. The mineralogy ranges from quartz to glauconite.

The formations record several major transgressive/regressive cycles and contain units which are generally thicker to the southeast and reflect a deeper water environment. Over 20 regional geologic units are present within the sediments of the Coastal Plain. Regressive, upward coarsening deposits are usually aquifers (e.g., Englishtown and Kirkwood Formations, and the Cohansey Sand) while the transgressive deposits act as confining units (e.g., the Merchantville, Marshalltown, and Navesink Formations). The individual thicknesses for these units vary greatly (i.e., from several feet to several hundred feet). The Coastal Plain deposits thicken to the southeast from the Fall Line to greater than 6,500 feet in Cape May County (Brown and Zapecza, 1990).

#### Local Geology

Based on the regional geologic map (Jablonski, 1968), the Cretaceous age Red Bank and Tinton Sands outcrop at the Charles Wood area. The Red Bank sand conformably overlies the Navesink Formation and dips to the southeast at 35 feet per mile. The upper member (Shrewsbury) of the Red Bank sand is a yellowish-gray to reddish brown clayey, medium-to-coarse-grained sand that contains abundant rock fragments, minor mica and glauconite (Jablonski). The lower member (Sandy Hook) is a dark gray to black, medium-to-fine grained sand with abundant clay, mica, and glauconite.

The Tinton sand conformably overlies the Red Bank Sand and ranges from a clayey medium to very coarse grained feldspathic quartz and glauconite sand to a glauconitic coarse sand. The color varies from dark yellowish orange or light brown to moderate brown and from light olive to grayish olive. Glauconite may constitute 60 to 80 percent of the sand fraction in the upper part of the unit (Minard, 1969). The upper part of the Tinton is often highly oxidized and ironoxide encrusted (Minard).

Over the last 80 years, the natural topography of Fort Monmouth has been altered by excavation and filling activities by the military. Topographic elevations for the Charles Wood area range from 20 feet above mean seal level (MSL) to 71 feet above MSL.

#### **Hydrogeology**

The water table aquifer in the Charles Wood area is identified as part of the "composite confining units", or minor aquifers. The minor aquifers include the Navesink formation, Red Bank Sand, Tinton Sand, Hornerstown Sand, Vincentown Formation, Manasquan Formation, Shark River Formation, Piney Point Formation, and the basal clay of the Kirkwood Formation.

Six well records for monitor wells installed at locations within the Charles Wood area in February 1981 were used for reference. The wells were completed to total depths ranging from 20 to 25 feet below ground surface (bgs). Water was encountered at depths ranging from 5 to 12 feet bgs.

The lithologic descriptions for these borings described deposits that were primarily fine to coarse, glauconitic sands, with traces of gravel, silt, and clay. These sediments are part of the Hornerstown Marl, from the Tertiary Period (Paleocene Series, approximately 58 to 66 Ma). According to Jablonski, wells drilled in the Red Bank and Tinton Sands may produce from 2 to 25 gallons per minute (gpm). Some well owners have reported acidic water that requires treatment to remove iron.

Shallow groundwater is locally influenced within the Charles Wood area by the following factors:

- tidal influence (based on proximity to the Atlantic Ocean, rivers, and tributaries)
- topography
- nature of the fill material within the Charles Wood area
- presence of clay and silt lenses in the natural overburden deposits
- local groundwater recharge areas (i.e., streams, lakes)

Due to the fluvial nature of the overburden deposits (i.e., sand and clay lenses), shallow groundwater flow direction is best determined on a case-by-case basis. Building 2000B is located approximately 400 feet south of an unnamed stream that runs from east to west through the Charles Wood area. Based on the Charles Wood area topography, the groundwater flow in the area of Building 2000B is anticipated to be to the north.

#### 1.3 HEALTH AND SAFETY

Before, during, and after all decommissioning activities, hazards at the work site which may have posed a threat to the Health and Safety of all personnel who were involved with, or were affected by, the decommissioning of the UST system were minimized. All areas, which posed, or may have been suspected to pose a vapor hazard were monitored by a qualified individual utilizing an organic vapor analyzer (OVA). The individual ascertained if the area was properly vented to render the area safe, as defined by OSHA.

#### 1.4 REMOVAL OF UNDERGROUND STORAGE TANK

#### 1.4.1 General Procedures

- All underground obstructions (utilities, etc.) were identified by the contractor performing the closure prior to excavation activities.
- All activities were carried out with the greatest regard to safety and health and the safeguarding of the environment.
- All excavated soils were visually examined and screened with an OVA for evidence of contamination. Potentially contaminated soils were identified and logged during closure activities.
- Surface materials (i.e., asphalt, concrete, etc.) were excavated and staged separately from all soil and recycled in accordance with all applicable regulations and laws.
- A Sub-Surface Evaluator from the DPW was present during all site assessment activities.

#### 1.4.2 Underground Storage Tank Excavation and Cleaning

Prior to UST decommissioning activities, surficial soil was removed to expose the UST and associated piping. No product lines were found during the excavation. The UST was completely emptied of all liquids prior to removal from the ground. Approximately 385 gallons of liquid from the UST were transported to the hazardous waste storage area in Charles Wood.

The UST was cleaned prior to removal from the excavation in accordance with the NJDEP regulations. After the UST was removed from the excavation, it was staged on polyethylene sheeting and examined for holes. No holes or punctures were observed during the inspection by the Sub-Surface Evaluator. Soils surrounding the UST were screened visually and with an OVA for evidence of contamination. No evidence of contamination was observed. Groundwater was encountered at 10.0 feet below ground surface and no sheen was observed. See Figure 3 for a cross-sectional view of the excavated area.

#### 1.5 UNDERGROUND STORAGE TANK TRANSPORTATION AND DISPOSAL

The tank was transported to Mazza and Sons, Inc., Metal Recyclers. See Appendix C for a copy of the UST disposal certificate. The transportation of the UST was in compliance with all applicable regulations and laws.

The UST was labeled prior to transport with the following information:

- Site of origin
- Contact person
- NJDEP UST Facility ID number
- Former contents

#### 1.6 MANAGEMENT OF EXCAVATED SOILS

Based on OVA air monitoring and TPHC analysis results from the post-excavation soil samples, no soils exhibited signs of contamination. Therefore, the excavated soils were used as backfill following removal of the UST.

#### 2.0 SITE INVESTIGATION ACTIVITIES

#### 2.1 OVERVIEW

The Site Investigation was managed and carried out by U.S. Army DPW personnel. All analyses were performed and reported by U.S. Army Fort Monmouth Environmental Laboratory, a NJDEP-certified testing laboratory. All sampling was performed under the direct supervision of a NJDEP Certified Sub-Surface Evaluator according to the methods described in the NJDEP *Field Sampling Procedures Manual* (1992). Sampling frequency and parameters analyzed complied with the NJDEP-BUST document *Interim Closure Requirements for Underground Storage Tank Systems* (October 1990 and revisions dated November 1, 1991) which was the applicable regulation at the date of the closure. All records of the Site Investigation activities are maintained by the Fort Monmouth DPW Environmental Office.

The following Parties participated in Closure and Site Investigation Activities:

Project Manager: Dinker Desai

Employer: U.S. Army, Fort Monmouth

Phone Number: (730) 532-6224 NJDEP Certification No.: 10173

Analytical Laboratory: U.S. Army Fort Monmouth Environmental Laboratory

Contact Person: Daniel K. Wright Phone Number: (908) 532-4359

NJDEP Company Certification No.: 13461

#### 2.2 FIELD SCREENING/MONITORING

Field screening was performed by a NJDEP Certified Sub-Surface Evaluator using an OVA and visual observations to identify potentially contaminated material. Soil excavated from around the tank, as well as the UST excavation sidewalls and bottom, did not exhibit any evidence of potential contamination. Groundwater was encountered at 10.0 feet below ground surface and no sheen was observed.

#### 2.3 SOIL SAMPLING

On November 19, 1997, following the removal of the UST, post-excavation soil samples A2, B2, C2, D, E, and F were collected from a total of six (6) locations of the UST excavation. Sidewall samples A2, B2, C2, D, E, and F were collected at a depth of 8.0 feet bgs. No product lines were found during the excavation of the UST. All samples were analyzed for total petroleum hydrocarbons (TPHC) and total solids.

DPW personnel in accordance with the NJDEP Technical Requirements and the NJDEP Field Sampling Procedures Manual performed the site assessment. A summary of sampling activities including parameters analyzed is provided in Table 1. The post-excavation soil samples were collected using NJDEP *Field Sampling Procedures Manual* (1992) standard sampling procedures. Following soil sampling activities, the samples were chilled and delivered to U.S. Army Fort Monmouth Environmental Laboratory located in Fort Monmouth, New Jersey, for analysis.

#### 3.0 CONCLUSIONS AND RECOMMENDATIONS

#### 3.1 SOIL SAMPLING RESULTS

To evaluate soil conditions following removal of the UST, post-excavation soil samples were collected on November 19, 1997, from a total of six (6) locations. All samples were analyzed for TPHC and total solids. The post-excavation sampling results were compared to the NJDEP residential direct contact total organic contaminants soil cleanup criteria of 10,000 mg/kg (N.J.A.C. 7:26D and revisions dated February 3, 1994). A summary of the analytical results and comparison to the NJDEP soil cleanup criteria is provided in Table 2 and the soil sampling locations are shown on Figure 4. The analytical data package is provided in Appendix D.

All post-excavation soil samples collected on November 19, 1997, from the UST excavation contained concentrations of TPHC below the NJDEP soil cleanup criteria. Soil samples contained TPHC concentrations ranging from non-detect to 237.92 mg/kg.

#### 3.2 CONCLUSIONS AND RECOMMENDATIONS

The analytical results for all post-excavation soil samples collected from the UST closure excavation at Building 2000B were below the NJDEP soil cleanup criteria for total organic contaminants.

Based on the post-excavation sampling results, soils with TPHC concentrations exceeding the NJDEP soil cleanup criteria for total organic contaminants of 10,000 mg/kg, do not exist in the former location of the UST.

No further action is proposed in regard to the closure and site assessment of UST No. 192486-38 at Building 2000B.

**TABLES** 

TABLE 1

#### SUMMARY OF POST-EXCAVATION SAMPLING ACTIVITIES BUILDING 2000B, CHARLES WOOD-EAST AREA FORT MONMOUTH, NEW JERSEY

Page 1 of 1

Sample ID	Date of Collection	Date Analysis Started	Matrix	Sample Type	Analytical Parameters*	Analysis Method
A2	11/19/97	11/19/97	Soil	Post-Excavation	ТРНС	OQA-QAM-025
<b>B2</b>	11/19/97	11/19/97	Soil	Post-Excavation	TPHC	OQA-QAM-025
C2	11/19/97	11/19/97	Soil	Post-Excavation	TPHC	OQA-QAM-025
D	11/19/97	11/19/97	Soil	Post-Excavation	TPHC	OQA-QAM-025
E	11/19/97	11/19/97	Soil	Post-Excavation	ТРНС	OQA-QAM-025
F	11/19/97	11/19/97	Soil	Post-Excavation	TPHC	OQA-QAM-025

Note:

TPHC Total Petroleum Hydrocarbons

TABLE 2 POST-EXCAVATION SOIL SAMPLING RESULTS BUILDING 2000B, CHARLES WOOD-EAST AREA FORT MONMOUTH, NEW JERSEY

Page 1 of 1

Sample ID/ Depth	Sample Laboratory ID	Sample Date	Analysis Date	Analytical Method Used	Method Detection Limit (mg/kg)	Compound of Concern	Result (mg/kg) *	NJDEP Soil Cleanup Criteria ** (mg/kg)	Exceeds Cleanup Criteria
A2/8.0'=	3166.01	11/19/97	11/19/97	Total Solid			84.79	<u></u>	<del></del>
				TPHC	184	yes	ND	10,000	No
B2/8.0'=	3166.02	11/19/9 <b>7</b>	11/19/97	Total Solid			83.62		
				TPHC	186	yes	ND	10,000	No
C2/8.0'=	3166.03	11/19/97	11/19/97	Total Solid			81.61		
				TPHC	192	yes	ND	10,000	No
D/8.0'=	3166.04	11/19/97	11/19/97	Total Solid			79.55		
				TPHC	197	yes	ND	10,000	No
E/8.0'=	3166,05	11/19/97	11/19/97	Total Solid		<b></b>	71.39		
_, -, -, -				TPHC	212	yes	ND	10,000	No
F/8.0'=	3166,06	11/19/97	11/19/97	Total Solid			86.35	,	
170.0	3100.00	11/1///	11/1///	TPHC	173	yes	237.92	10,000	No

#### Note:


Total Solid results are expressed as a percentage.


NJDEP Residential Direct Contact soil cleanup criteria for total organics


Not detected above stated sample quantitation limit


TPHC Total Petroleum Hydrocarbons

FIGURES









# APPENDIX A NJDEP-STANDARD REPORTING FORM

# 314, 30eu. 105 196

#### **NEW JERSEY DEPARTMENT OF ENVIRONMENTAL PROTECTION**

DIVISION OF RESPONSIBLE PARTY SITE REMEDIATION BUREAU OF APPLICABILITY AND COMPLIANCE

Registration and Billing Unit CN 028, Trenton, N.J. 08625-0028 1-609-984-3156



FOR STATE	USE ONLY	
Check In	Yes 🗌	No
STATUS	COMCODE	

## UNDERGROUND STORAGE TANK FACILITY QUESTIONNAIRE

FACILITY UST #_	0192486	Charles Wood	East	
Completion of thi Hazardous Subs	s Registration Questionn tances Act, N.J.S.A. 58:1	naire will satisfy the regis 10A-21, and the Registra	tration require tion and Billin	ments of the Underground Storage of g Regulations N.J.A.C. 7:14B-2.
B. Is this a regist Is this a correct Is this a correct There have to signatures)	* **	ground storage tank not pro existing facility registration? lity registration since last su	esently registere P UST # ubmittal. UST #	<del></del>
□ Owner Name ar	nd/or Address Change nd/or Address Change r and/or Address Change Person Change	Type of Product(s) Stor Spills, Leaks, Releases Tank(s) and/or Piping C Closure (Complete Que	Changes	Financial Responsibility Change Substantial Modification(s) Sale or Transfer (Complete Questions 4,5,6 & 13D) Other (please specify)
SECTION A - G	ENERAL FACILITY INFO	ORMATION		
1. Facility Name	LIIIIII			
2. Facility Location	<u> </u>	1 1 1 1 1 1 1 NI IM	BER AND STREET	
u	Charles h		LILL	
1	سسسس	CITY	OR MUNICIPALITY	
u	COUNTY	N.J. STATE	I I I I	BLOCK LOT
3. Facility Operator		PERSON OR TITLE		Tele, No (Area Code) (Extension)
Operator Address (if different than #2)	<u> </u>	NUM	BER AND STREET	
<b></b>				
a.	STATE ZIPO	CITY  DE DECEMBER	OR MUNICIPALITY	
4. Tank Owner				
-5. Tank Owner Address	Limm		BER AND STREET	
		<del></del>	<del>1                                    </del>	
		CITY	OR MUNICIPALITY	
6. Contact Person (Tank Owner)	STATE ZIF	P CODE THP1P1/K1b19111		Contact 7325326234 (Extension)
7. EPA ID#				
8. Total number of	regulated underground stor	rage tanks at facility	(Complet	te Section B for each tank)

0. Facility Type: A State Commercial/ Industrial			100			sidence	Public Scho	H	54:4-23	s define .1 et sec	d in N.J.S., 1.)
11. Is a copy of the facility site plan submitted SECTION B - SPECIFIC TANK INFO			<del>-</del>	tion pursi	uant to N.	J.A.C, 7:1	48-2? L_	] YES	□ио		
ALL underground tanks, including those take 9/3/86) must be registered. Report all tank/	en out piping	of o	peration us change	(UNLESS es unless	S THE TAI previous	NK WAS f	REMOVED ed.	FROM T	HE GROU	ND PRI	OR TO
I. Tank Identification Number	TAI	<u>K</u>		TANK			K NO.	TANK	( NO.	TAP	NK NO.
2. CAS Number (hazardous substances only)		1							1111		
B. Date Tank Installed (Month/Day/Year)	Mo. Di	٠,	Year piph.	Mo. Day	Year	Mo. Day	Year	Mo. Day	Year	Mo. Dey	Year
. Tank Size (gallons)		וב	000		TTT						TTT
. Tank Contents (Mark one "X" for each tank)	<u> </u>					1					
A. Leaded gasoline		$\Box$									
B. Unleaded gasoline											
C. Alcohol endriched gasoline					<u> </u>						
D. Light diesel fuel (No. 1-D)		$\perp$	ļ	<b> </b>	<del> </del>		4			<b></b>	
E. Medium diesel fuel (No. 2-D)	<u> </u>	+	ļ	<del>  -</del>		1 1	+	-	<del></del>	<del>                                     </del>	<del></del>
F. Waste Oil		+-	<b></b>	<b> </b>	<del>-                                    </del>	1			-	<b> </b>	+
G. Kerosene (No. 1)		$\frac{1}{x}$	<del> </del>	<del>                                     </del>	-	1		<del>  -</del>			<del></del>
H. Home heating oil (No. 2)	<del>                                     </del>	<b>⊹</b> ^	<b> </b>	<del>  </del>	+			<del>                                     </del>	<del></del>		
J. Heating oil (No. 4)  K. Heavy heating oil (No. 6)	<b></b>	+	<del> </del>	<del>  </del>	+	1		<del>                                     </del>		<del>  </del>	+
L. Aviation fuel		+		<del>                                     </del>	<del>                                     </del>	<del>                                     </del>		<del>  -</del>			+
M. Motor oil		$\top$	<u> </u>		1	1	1				
N. Lubricating oil	<u> </u>	$\top$		<del>                                     </del>		<del>                                     </del>				1	
P. Sewage		1	1								
Q. Sewage sludge											
R. Other hazardous substances (specify)											
S. Hazardous waste (specify ID number)											
T. Mixtures (please specify)	<u></u>			ļ						<u></u>	
U. Emergency spill tank (specify substance)	L			<b>.</b>				ļ			
V. Other petroleum products (please specify)	ļ			↓		<u> </u>		<u> </u>			
W. Other (please specify)	<u> </u>			<u> </u>			•	<b> </b>		<b></b>	
i. Tank & Piping Construction (Mark one each for both tank & piping)	Tani	k	Piping	Tank	Piping	Tank	Piping	Tank	Piping	Tank	Piping
A. Bare Steel			_ <b> </b>   <b> </b>	111						$\sqcup \bot \bot$	
B. Cathodically protected steel	1-1-	<u> </u>		1-1-		1-1-	-++			+++	
C. Fiberglass-coated steel	1	ļ	++-	<del>                                      </del>	-++	<del>- - -</del>		+++		╂╌╂╌╁╴	<del></del>
D. Fiberglass-reinforced plastic		$\vdash$		╂╌╂┈┼┈		1-1-1-		<del>                                     </del>	<del>-    </del> -	╂╌┼╌	
E. Internally lined	+	L		1				<del>                                     </del>		1-1-	LL
F. Other (please specify)	┼—			+		<del>-  </del>		<del> </del>			<del></del>
7. Tank & Piping Structure	Tan	k	Piping	Tank	Piping	Tank	Piping	Tank	Piping	Tank	Piping
(Mark one each for both tank & piping)  A. Single wall	X		X								
B. Double wall		-						LLT	·		
C. Other (please specify)											
8. Type of Monitoring/Detection System	Tan	k	Piping	Tank	Piping	Tank	Piping	Tank	Piping	Tank	Piping
(Mark all that apply for both tank & piping)		1	. <b>.</b>								L
A. Statistical Inventory Reconciliation	+	├		<del></del>		1-1-1		+++	<del></del>	+++	
B. Manual Tank Gauging	╂-┼-	-		1 1 1		+++		╂╌┼╌├		$\frac{1}{1}$	
C. Inventory Control	╂-┼-	$\vdash$	-+-	+-+-				╂╌┼╌┼		<del>                                     </del>	<del></del>
D. Interstitial	++	+	++	+++			<del>-    -</del>	<del>                                     </del>		$\vdash$	
C Descision Took		1	i 1	1 1 L	1 1	1 1 1	L 1	1 1	11		
E. Precision Test	<del>                                     </del>	<del>                                     </del>									1 1
F. Ground water observation wells		-									
		-									

A.L.	1				1				T				Τ				г			
Tank Identification Number		TAN	K NO  3		TANK NO.				TANK NO.			<u>ן</u>	TANK NO.			T	TANK NO.			
8. Type of Monitoring/Detection System K. None	1	ink	Pi	ping	To	ank	Pi	ping	Та	nk	Pip	ing	Tan	k ]	Pip	ing	Tar	ık 7	Pipin	9
'L. Other (please specify)	1	· · ·							Τ'				<del>                                     </del>			<u> </u>		+		
Overfill Protection (tank only)     (Mark one X for each tank)															_				<del></del>	<del></del>
A. Yes			┷-		↓		┷		<u> </u>		Щ.		ļ	$\perp$			L		.l	
B. No		\	<u> </u>		ļ				1				<u> </u>				L			
10. Spill Containment Around Fill Pipe (Mark one X for each tank)		Γ-	_			۲	7			[-	7			_	-,				ר	
A. Yes	+		<del>,                                     </del>		<del>  -</del>	-+	+-		-		+		<del> </del>	-+	┰		├	-+-	╂──	
B. No 11. Tank Status (Mark one X for each tank)	Tį	<u> </u>	<u> </u>	ping	T	<u>n</u> k	Pj	oing	Ta	<u> </u>	Pij	oing	Tai	nk	Pij	ping	Tai	nk	Pipin	g
A. In-use	44		$\dashv$		+			-	14	_ _			<b> </b>	╄-	-	<u> </u>		<del> </del>	44	
B. Empty less than 12 months	1.1				1-1		}-	1_	$\bot \bot$	_	_			1_			<b>_</b>	1		
C. Empty 12 months or more	$\bot \bot$	ᆜ_	$\dashv$		$\bot$				$\bot \bot$			<u> </u>							$\rightarrow$	
D. Emergency spill tank (sump)	$\perp$			┷	$\perp$				Ш											
E. Emergency backup generator tank	$\perp$						丄		$\perp \perp$											
F. Abandoned in Place							_ i_			_	$_{\perp}$									
G. Removed		$\mathbf{X}$		7			$\bot \Gamma$		Ш		$oldsymbol{\perp}$			$\prod$						_
H. Other (please specify)									L											
12. If box 11B, C, or D above has been marked, indicate the estimated date	Mo	. Day	, <b>Y</b>	ear	Мо	. Day	, <b>Y</b>	eer	Mo	. Day	Y	eer L 1	Mo.	Day	Y	MAT	Mo.	Day	Year	
last used (month/day/year)	<del>    '</del>	<u></u>	1	<u> </u>	1 -	<u> </u>	11	<u> </u>	1-	1 1	11	1 1	111		Ш	<u> </u>	$\sqcup$	_ _	1_1_	<u></u>
13. Closure Information - Tank ID No.		TAN			1.	TAN	<u>Ķ Ņ</u>	<u>).</u>	1.	TAN	KNO	<u>).</u>	1 :	<u>TAN</u>	KN	<u>O.</u>	<u> 7</u> 4	ANK	NO.	
13. Closure information - Tank 10 No.			3	8	1						Ш		1 [		لــــــــــــــــــــــــــــــــــــــ		1 L	$\perp \perp$		
	Mo	., Day	' 1 Y	ear .	Mo	. Day	/ <sub>1</sub> ¥	<b>08</b> F	Mo	. Day	ή Υ	<b>62</b> 1	Mo.	Day	7	Year	Mo	Day	Yea	r
A. Date abandoned in place	11		1	11	1	1	1	11	1	11	1	11	1	1	1	11	1		11	1
B. Date taken temporarily out of service	$\perp$		11	11		11	$\perp$	<u> </u>			11	11		$\perp \perp$	$\perp$	<u> </u>			111	$\perp$
C. Date removed	11.7	119	119	795	7 ;		1	1.1	1		1	1 1	1 ,		$   _{1}$	1.1	1 ,		$I_{1}$	1
D. Date of Sale or Transfer	+ "	<del>                                     </del>	111		1	1	1.	<del></del> -	† †	†	† †	<del>''-</del>	†	<del>                                     </del>	†:		<del>  '</del>	<del>† '</del>	† <u>'                                     </u>	<u>.</u>
	-	بلسله			+	LL.		1 1	11	1	$\perp \perp$	<u> </u>	1 -	<u> </u>	11	<u> </u>	1	1 1	<u> </u>	
E. TMS # (if applicable)	Fi	4.6	181	ma	4												L			
F. ISRA # (if applicable)	Į.			,					1				1				ļ			
SECTION C - FINANCIAL RESPON  Does this facility have a Financial Respons				ce Me	echar	ıism a	as re	auirec	in 4	o CFI	R 28	0? [	Y	ES	[X]	NO	Fe	dec	L	
Please list the appropriate financial informa	ation	belov	<b>/</b> :			-		,			•				لي	,		pro	l pert	1
Туре			•						Car	τier /	lssu	ing A	gency	,						
1 1	1															\$				
Effective Date Expiration	Date			<del></del>			F	olicy	Num	ber					_	A	moun	t .		
SECTION D - MONITORING SYSTE	MS																			
Does this facility have a release detection of "No", please be aware that the facility mu	monit ust me	oring eet th	sysi e ap	em w	hich riate	is in dead	comp ine.	olianco (See	e with	h N.J. es to	A.C Kno	. 7:14 w" on	B-6? Page	4)			YES	X	NO	
SECTION E - RECORDKEEPING/C	ОМІ	PLIA	NCI																	
Please answer all the questions in this sec	tion o	n a fa	acilit	y bas	is. A	ny or	e ta	nk not	in a	omplia	ance	requ	ires a	"NC	) <b>"</b> an	swer	for the	enti	re facil	ity.
Does this facility have cathodic prot												1					YES		NO	•
If "Yes", are the systems properly of											B-5	?					YES		NO	
2. Are the performance claims and do													r or o	oerat	or			_	J	
pursuant to N.J.A.C. 7:14B-5?																	YES	· L	NO	
3. Are the proper monitoring, testing,	samp	ling,	repa	ir and	l inve	ntory	reco	ords k	ept o	n-site	pur	suant	to				t	_	3	
N.J.A.C. 7:14B-5 and 6?							•									<u> </u>	YES		NO	
4. Is the proper Release Response Pl	an ke	pt or	-site	purs	uant	to N.	J.A.C	7:14	1B-5'	?						<u> </u>	YES		NO	
5. Does the facility have spill and over	r fill p	rotec	tion	syste	ms p	ursua	int to	N.J.A	I.C. 7	7:14B	-4?					$\perp$	YES		NO	
6. Have all Fill Ports been permanent	y ma	rked	as p	er AP	'I #16	37 pi	ursua	int to	N.J.A	a.C. 7	:148	5-5?				L	YES	L	NO	

#### IMPORTANT INFORMATION

FEE:	processing. Registration and Billing Schedu		elope will expedite
	All Initial Registration fees are \$100 per fac		
PENALTY:	Act or regulations may result in the penaltie		
EMERGENCY:	<b>—</b>	tline at (609) 292-7172 must be called IMMEDIATEL)	Y - 24 hours a day.
UPGRADE EXEMPTION	: Residential heating oil underground storage	tanks are exempt from all upgrade requirements.	
		W (critical deadlines)	
		must have cathodic protection and spill/overfill protection	
•		s must have cathodic protection and spill/overfill protect	tion.
	<ul> <li>All federally regulated piping must have l</li> </ul>	•	
•	All federally regulated tank systems must	- · · · · · · · · · · · · · · · · · · ·	•
	All federally regulated tank systems must	•	
December 22, 1998	<ul> <li>All regulated tanks shall install cathodic p</li> </ul>	rotection and spill/overfill protection.	
		FICATIONS	
		E SAME AS THE PERSON SIGNING CERTIFICATI roons are required to sign No. 1 and No. 2, then they mut	
		sons are required to sign 140. I and 140. 2, then they file	St 00 S0.)
CERTIFICATION N			
Must be signed by the	highest ranking individual at the facility	vith overall responsibility	•
knowledge, information inaccurate or incompleted not believe to be truthe penalties."	on and belief. I am aware that there are sete information and that I am committing are. I am also aware that if I knowingly discussed in the set of the se	in this document is true, accurate and complete ignificant civil and criminal penalties for knowing a crime of the fourth degree if I make a written fals rect or authorize the violation of any statute, I am	ly submitting false, se statement which I
(1)	TAMES OTT Typed / Printed Name)	(Signature)	<del></del>
Director	1 Public Works (Title)	( · <b></b>	
	(Title)	(Date)	
CERTIFICATION N	10.2: Not Requiech		
<ul><li>For a partnership or</li><li>For a municipality, S</li></ul>	y a principal executive officer of at least the sole proprietorship, by a general partner of	r the proprietor, respectively ther a principal executive officer or ranking elected	d official
documents, and that b submitted information submitting false, inacc	ased on my inquiry of those individuals in is true, accurate and complete. I am awa curate or incomplete information and that not believe to be true. I am also aware the	and am familiar with the information submitted her namediately responsible for obtaining the information are that there are significant civil and criminal penals I am committing a crime of the fourth degree if I are that if I knowing to direct or authorize the violation	on. I believe that the alties for knowingly make a written false
JA	(Typed / Printed Name)	(Signature)	
DIF	(Title)	1/186/97	<del></del>
		(Date)	
<u>CERTIFICATION N</u>	NO. 3:		
If applicable, must be	signed by the individual who is certified	o perform services.	
knowledge, informati inaccurate or incompl do not believe to be to	on and belief. I am aware that there are selete information and that I am committing rue. I am also aware that if I knowingly d	I in this document is true, accurate and complete significant civil and criminal penalties for knowing a crime of the fourth degree if I make a written falsi irect or authorize the violation of any statute, I am	gly submitting false, se statement which I
Charle	s Appliby ENV. Post. Spa.	11/05	<i>A</i> 7
(Typed / Printed Nar	ne) FT. Mormosth	(Signature) 2256 (Da	ite)
U-S. 60	V. Monmosth	(N.J. Certification Number)	<del></del>
(Nam	e of Firm, if applicable)	(NJ. Cermication Number)	

UST-021 (9/94)

# APPENDIX B SITE ASSESSMENT SUMMARY

#### New Jersey Department of Environmental Protection

#### Site Remediation Program

#### UST Site/Remedial Investigation Report Certification Form

A. Facility Name: <u>U.S. Army Fort Monmouth New Jersey</u>	
Facility Street Address : <u>Directorate of Public Works</u> <u>Buil</u>	ding 173
Municipality: Oceanport (	County: Monmouth
Block:Lot(s):	Telephone Number : 732-532-6224
<b>B.</b> Owner (RP)'s Name:	
Street Address:	City :
State: Zip: Telepho	one Number :
Report (SIR) \$500 Fee  Remedial Investigation Report (RIR) \$1000 Fee  UST Registration Number: Incident Report Number	Ian Curtis, Federal Case Manager         192486-38       (7 digits)
E. Certification by the Subsurface Evaluator:  The attached report conforms to the specific reporting require  Name: Dinker Desai Signature:	UST Cert. No.: 10173
Firm Address: <u>Directorate of Public Works</u> <u>Building 173</u>	phone Number : 732-532-6224
application and all attached documents, and that based information, I believe that the submitted information significant civil penalties for knowingly submitting committing a crime of the fourth degree if I make a write	the board of directors to sign the document. A copy of the oration, shall be submitted along with the certification; or r the proprietor, respectively; or
Name (Print or Type):	Title: Directorate of Public Works
Signature:	
Company Name: U.S. Army Fort Monmouth	Date:

# APPENDIX C UST DISPOSAL CERTIFICATE

LERS FREIGHT LERS TOTAL DEDUCTIONS AMOUNT OF CHECK	MAZZA & SONS, INC.  RECYCLING DIVISION 3230 SHAFPO RD. TINTON FALLS, NJ 07753  HE OF Tecom Vinnell Servery Sqhty Seven + 50/100  Sovereign Bank  1221272332:000 1091091	Lower horge "
<b>M</b> .	AZZA & SONS, INC.  Metal Recyclers 3230 Shafto Rd.  Tinton Falls, NJ (908) 922-9292	NO DATE. 19 No. 97
Customer's Nar  Address  Weight Price  Cast Iron  Steel  7-1-1/1 87.50  Lt. Iron	B 2000 19760	Weight Price  Lt. Copper  Brass  Alum Clean
Copper #1  Copper #2	02500 F NOV 191997 CUSTU96	Stainless  Battery  87.50  TOTAL AMOUNT:
Weigher	Custom	ner MM

# APPENDIX D SOIL ANALYTICAL DATA PACKAGE

### Fort Monmouth Environmental Testing Laboratory

Bldg. 173, SELFM-PW-EV. Fort Monmouth, NJ 07703

Tel (908)532-4359 Fax (908)532-3484 EMail:appleby@doim6.monmouth.army.mil

NJDEP Certification #13461

**Chain of Custody Record** 

Customer: 500	٦ ع	Allon	Project No:						Analysis Parameters Comme					Comments:		
Phone #:			Location:						5							
(X)DERA ()OMA (	)Othe	er:	1378	Bldg - 2000			,	J	%501.35	10A+15						
/Samplers Name / Con	npany	: SICTT WPREY	14N 1 RA)	Pobwy	Samp	ole i	#	TPHC	\ \ \ \	₹.						
Lab Sample I.D.		Sample Location	Date	Time		e bot	tles	<b> </b> -	0	_\$						Remarks / Preservation Method
3166,01	20	500 - AZ (46-102°	H-14-47	1535	50;	1 6	X	χ	Y	Y						971119 -01
.0.2		- BZ(91-102)		1525												971119-02
,03		CZL96-102°)		1515			$\coprod$							<u> </u>		971119-03
104		- D(9b-102")		15.30										<u></u>		971119-04
.05		- E(96-102°)		1500		_]_										471119-05
106		- F(96-102")		1510				)								471114-06
	,															
							;									
										]						
																·
Relinquished by (signature	e):	Date/Time:	Received by (	signature):		Re	linqu	iished	by (sig	nature):		Date/	Time:	Receiv	ved by (	signature):
Jec-lost	7	1/19/97 15:40	J. Cer	du	w								<u> </u>			
Relinquished by (signature	e):	Date/Time:	Received by (	signature):		Re	linqu	ished	by (sig	nature):		Date/	Time:	Receiv	ed by (	signature):
															·	
Report Type: (_)Full, (XR	leduced.	, (_)Standard, (_)Scree	n / non-certifie	ed			F	Remar	ks:	-						:
Turnaround time: (_)Stand	ard 4 w	ks, (NRush Days,	(_)ASAP Ver	rbalHrs	<u> </u>		1									

## Report of Analysis U.S. Army, Fort Monmouth Environmental Laboratory NJDEP Certification # 13461

Client:

U.S. Army

Lab. ID #:

3166

DPW. SELFM-PW-EV

Date Rec'd:

19-Nov-97

Bldg. 173

**Analysis Start:** 

19-Nov-97

Ft. Monmouth, NJ 07703

Analysis Complete:

20-Nov-97

Analysis:

OQA-QAM-025

UST Reg. #:

Matrix:

Soil

Shake

Closure #:

Analyst: Ext. Meth: D.DEINHARDT

DICAR #:

Location #:

BLDG.

2000

		<del></del>			•	2000
Sample	Field ID	Dilution Factor	Weight (g)	% Solid	MDL (mg/kg)	TPHC Result (mg/kg)
3166.01	2000-A2(96-102")	1.00	15.08	84.79	184	ND
3166.02	2000-B2(96-102°)	1.00	15.07	83.62	186	ND
3166.03	2000-C2(96-102*)	1.00	15.02	81.61	192	ND
3166.04	2000-D(96-102")	1.00	15.00	79.55	197	ND
3166.05	2000-E(96-102")	1.00	15.56	71.39	212	ND
3166.06	2000-F(96-102")	1.00	15.77	86.35	173	237.92
			<u> </u>			
	-					
<del>,</del>	-		ļ			<u> </u>
	<u> </u>					
					<u></u>	
		<u> </u>				
				1		
METHOD BLANK	19-Nov-97	1.00	15.00	100.00	157	ND

ND = Not Detected

MDL = Method Detection Limit

Daniel K. Wright

Laboratory Director