United States Army

Fort Monmouth, New Jersey

Underground Storage Tank Closure and Site Investigation Report

Building 116A
Main Post-East Area



NJDEP UST Registration No. 90010-8

December 1997

UNDERGROUND STORAGE TANK CLOSURE AND SITE INVESTIGATION REPORT

BUILDING 116A

MAIN POST-EAST AREA NJDEP UST REGISTRATION NO. 90010-8

DECEMBER 1997

PREPARED FOR:

UNITED STATES ARMY, FORT MONMOUTH, NEW JERSEY
DIRECTORATE OF PUBLIC WORKS
BUILDING 167
FORT MONMOUTH, NJ 07703

PREPARED BY:

SMC ENVIRONMENTAL SERVICES GROUP 501 ALLENDALE ROAD KING OF PRUSSIA, PA 19406

PROJECT NO. 2429-3080

TABLE OF CONTENTS

EXECUTIVE SUMMARY	iv
1.0 UNDERGROUND STORAGE TANK DECOMMISSIONING ACTIVITIES	1
1.1 OVERVIEW 1.2 SITE DESCRIPTION	1 2
1.2.1 Geological/Hydrogeological Setting	2
1.3 HEALTH AND SAFETY	4
1.4 REMOVAL OF UNDERGROUND STORAGE TANK	4
1.4.1 General Procedures	4
1.4.2 Underground Storage Tank Excavation and Cleaning	4
1.5 UNDERGROUND STORAGE TANK	
TRANSPORTATION AND DISPOSAL	5
1.6 MANAGEMENT OF EXCAVATED SOILS	5
2.0 SITE INVESTIGATION ACTIVITIES	6
2.1 OVERVIEW	6
2.2 FIELD SCREENING/MONITORING	6
2.3 SOIL SAMPLING	6
3.0 CONCLUSIONS AND RECOMMENDATIONS	8
3.1 SOIL SAMPLING RESULTS	8
3.2 CONCLUSIONS AND RECOMMENDATIONS	8

TABLE OF CONTENTS (CONTINUED)

TABLES

Table 1 Summary of Post-Excavation Sampling Activities

Table 2 Post-Excavation Soil Sampling Results

FIGURES

Figure 1 Site Location Map

Figure 2 Site Map

Figure 3 Cross Sectional View

Figure 4 Soil Sampling Location Map

APPENDICES

Appendix A NJDEP Standard Reporting Form

Appendix B Site Assessment Summary

Appendix C Waste Manifest

Appendix D UST Disposal Certificate

Appendix E Soil Analytical Data Package

Appendix F Photographs

EXECUTIVE SUMMARY

UST Closure

On April 22, 1997, a fiberglass underground storage tank (UST) was closed by removal in accordance with New Jersey Department of Environmental Protection (NJDEP) underground storage tank closure procedures at the Main Post-East area of the U.S. Army Fort Monmouth, Fort Monmouth, New Jersey. The UST, NJDEP Registration No. 90010-8 (Fort Monmouth ID No. 116A), was located north of Building 116A. UST No. 90010-8 was an 1,000-gallon No. 2 fuel oil UST. The fill port was located directly above the tank.

Site Assessment

The site assessment was performed by U.S. Army personnel in accordance with the NJDEP *Technical Requirements for Site Remediation* (N.J.A.C. 7:26E) and the NJDEP *Field Sampling Procedures Manual*. The sampling and laboratory analysis conducted during the site assessment were performed in accordance with Section 7:26E-2.1 of the *Technical Requirements for Site Remediation*. Soils surrounding the tank were screened visually and with air monitoring equipment for evidence of contamination. Following removal, the UST was inspected for corrosion holes. No holes were noted in the UST and no evidence of potentially contaminated soils was observed surrounding the tank. Groundwater was encountered at 6.0 feet below ground surface and no sheen was observed. Soil samples contained TPHC concentrations ranging from non-detected to 333.44 mg/kg.

Site Restoration

Following receipt of all post-excavation soil sampling results, the excavation was backfilled with stone to groundwater and native backfill to grade and restored to its original condition.

Conclusions and Recommendations

Based on the post-excavation soil sampling results, soils with TPHC concentrations exceeding the NJDEP soil cleanup criteria for total organic contaminants of 10,000 mg/kg, do not exist in the former location of the UST or associated piping.

No further action is proposed in regard to the closure and site assessment of UST No. 90010-8 at Building 116A.

1.0 UNDERGROUND STORAGE TANK DECOMMISSIONING ACTIVITIES

1.1 OVERVIEW

One underground storage tank (UST), New Jersey Department of Environmental Protection (NJDEP) Registration No. 90010-8, was closed at Building 116A at the Main Post-East area of U.S. Army Fort Monmouth, Fort Monmouth, New Jersey on April 22, 1997. This report presents the results of the U.S. Army Department of Public Work (DPW)'s implementation of the UST Decommissioning/Closure Plan approved by the NJDEP. The UST was a fiberglass 1,000-gallon tank containing No. 2 fuel oil.

Decommissioning activities for UST No. 90010-8 complied with all applicable Federal, State and Local laws and ordinances in effect at the date of decommissioning. These laws included but were not limited to N.J.A.C. 7:14B-1 et seq., N.J.A.C. 5:23-1 et seq., and Occupational Safety and Health Administration (OSHA) 1910.146 & 1910.120. All permits including but not limited to the NJDEP-approved Decommissioning/Closure Plan were posted onsite for inspection. The decommissioning activities were conducted by DPW personnel who are registered and certified by the NJDEP for performing UST closure activities. Closure of UST No. 90010-8 proceeded under the approval of the NJDEP Bureau of Underground Storage Tanks (NJDEP-BUST). The Standard Reporting Form and signed Site Assessment Summary form for UST No. 90010-8 are included in Appendices A and B, respectively.

Based on inspecting the UST, field screening of subsurface soils and groundwater, and reviewing analytical results of collected soil samples, the DPW has concluded that no significant historical discharges are associated with the UST or associated piping.

This UST Closure and Site Investigation Report has been prepared by SMC Environmental Services Group, to assist the U.S. Army DPW in complying with the NJDEP-BUST regulations. The applicable NJDEP-BUST regulations at the date of closure were the *Interim Closure Requirements* for *Underground Storage Tank Systems* (N.J.A.C. 7:14B-1 et seq. October 1990 and revisions dated November 1, 1991).

This report was prepared using information collected at the time of closure. Section 1 of this UST Closure and Site Investigation Report provides a summary of the UST decommissioning activities. Section 2 of this report describes the site investigation activities. Conclusions and recommendations, including the results of the soil sampling investigation, are presented in the final section of this report.

1.2 SITE DESCRIPTION

Building 116A is located in the Main Post-East area of the Fort Monmouth Army Base, as shown on Figure 1. UST No. 90010-8 was located north of Building 116A. The fill port was located directly above the tank. Appurtenant copper piping was approximately five (5) feet in length and ran southeast to Building 116A. A site map is provided on Figure 2.

1.2.1 Geological/Hydrogeological Setting

The following is a description of the geological/hydrogeological setting of the area surrounding Building 116A. Included is a description of the regional geology of the area surrounding Fort Monmouth as well as descriptions of the local geology and hydrogeology of the Main Post area.

Regional Geology

Monmouth County lies within the New Jersey Section of the Atlantic Coastal Plain physiographic province. The Main Post, Charles Wood, and the Evans areas are located in what may be referred to as the Outer Coastal Plain subprovince, or the Outer Lowlands.

In general, New Jersey Coastal Plain formations consist of a seaward-dipping wedge of unconsolidated deposits of clay, silt, and gravel. These formations typically strike northeast-southwest with a dip ranging from 10 to 60 feet per mile and were deposited on Precambrian and lower Paleozoic rocks (Zapecza, 1989). These sediments, predominantly derived from deltaic, shallow marine, and continental shelf environments, date from Cretaceous through the Quaternary Periods. The mineralogy ranges from quartz to glauconite.

The formations record several major transgressive/regressive cycles and contain units which are generally thicker to the southeast and reflect a deeper water environment. Over 20 regional geologic units are present within the sediments of the Coastal Plain. Regressive, upward coarsening deposits are usually aquifers (e.g., Englishtown and Kirkwood Formations, and the Cohansey Sand) while the transgressive deposits act as confining units (e.g., the Merchantville, Marshalltown, and Navesink Formations). The individual thicknesses for these units vary greatly (i.e., from several feet to several hundred feet). The Coastal Plain deposits thicken to the southeast from the Fall Line to greater than 6,500 feet in Cape May County (Brown and Zapecza, 1990).

Local Geology

Based on the regional geologic map (Jablonski, 1968), the Cretaceous age Red Bank and Tinton Sands outcrop at the Main Post area. The Red Bank sand conformably overlies the Navesink Formation and dips to the southeast at 35 feet per mile. The upper member (Shrewsbury) of the Red Bank sand is a yellowish-gray to reddish brown clayey, medium-to-coarse-grained sand that contains abundant rock fragments, minor mica and glauconite (Jablonski). The lower member (Sandy Hook) is a dark gray to black, medium-to-fine grained sand with abundant clay, mica, and glauconite.

The Tinton sand conformably overlies the Red Bank Sand and ranges from a clayey medium to very coarse grained feldspathic quartz and glauconite sand to a glauconitic coarse sand. The color varies from dark yellowish orange or light brown to moderate brown and from light olive to grayish olive. Glauconite may constitute 60 to 80 percent of the sand fraction in the upper part of the unit (Minard, 1969). The upper part of the Tinton is often highly oxidized and iron oxide encrusted (Minard).

Hydrogeology

The water table aquifer in the Main Post area is identified as part of the "composite confining units", or minor aquifers. The minor aquifers include the Navesink formation, Red Bank Sand, Tinton Sand, Hornerstown Sand, Vincentown Formation, Manasquan Formation, Shark River Formation, Piney Point Formation, and the basal clay of the Kirkwood Formation.

Based on records of wells drilled in the Main Post area, water is typically encountered at depths of 2 to 9 feet below ground surface (bgs). According to Jablonski, wells drilled in the Red Bank and Tinton Sands may produce 2 to 25 gallons per minute (gpm). Some well owners have reported acidic water that requires treatment to remove iron.

Due to the proximity of the Atlantic Ocean to Fort Monmouth, shallow groundwater may be tidally influenced and may flow toward creeks and brooks as the tide goes out, and away from creeks and brooks as the tide comes in. However, an abundance of clay lenses and sand deposits were noted in borings installed throughout Fort Monmouth. Therefore, the direction of shallow groundwater should be determined on a case-by-case basis.

Shallow groundwater is locally influenced within the Main Post area by the following factors:

- tidal influence (based on proximity to the Atlantic Ocean, rivers, and tributaries)
- topography

2 1

: .1

- nature of the fill material within the Main Post area
- presence of clay and silt lenses in the natural overburden deposits
- local groundwater recharge areas (i.e., streams, lakes)

Due to the fluvial nature of the overburden deposits (i.e., sand and clay lenses), shallow groundwater flow direction is best determined on a case-by-case basis. This is consistent with lithologies observed in borings installed within the Main Post area, which primarily consisted of fine-to-medium grained sands, with occasional lenses or laminations of gravel silt and/or clay.

Building 116A located approximately 750 feet north of Oceanport Creek, the nearest water body. Based on the Main Post topography, the groundwater flow in the area of Building 116A is anticipated to be to the east.

1.3 HEALTH AND SAFETY

Before, during, and after all decommissioning activities, hazards at the work site which may have posed a threat to the Health and Safety of all personnel who were involved with, or were affected by, the decommissioning of the UST system were minimized. All areas, which posed, or may have been suspected to pose a vapor hazard were monitored by a qualified individual utilizing an organic vapor analyzer (OVA). The individual ascertained if the area was properly vented to render the area safe, as defined by OSHA.

1.4 REMOVAL OF UNDERGROUND STORAGE TANK

1.4.1 General Procedures

- All underground obstructions (utilities, etc.) were identified by the contractor performing the closure prior to excavation activities.
- All activities were carried out with the greatest regard to safety and health and the safeguarding of the environment.
- All excavated soils were visually examined and screened with an OVA for evidence of contamination. Potentially contaminated soils were identified and logged during closure activities.
- Surface materials (i.e., asphalt, concrete, etc.) were excavated and staged separately from all soil and recycled in accordance with all applicable regulations and laws.
- A Sub-Surface Evaluator from the DPW was present during all site assessment activities.

1.4.2 Underground Storage Tank Excavation and Cleaning

Prior to UST decommissioning activities, surficial soil was removed to expose the UST and associated piping. All free product present in the piping was drained into the UST, and the UST was purged to remove vapors prior to cutting and removal of the piping. After removal of the associated piping, a manway was made in the UST to allow for proper cleaning. The UST was completely emptied of all liquids prior to removal from the ground. Approximately 25 gallons of liquid from the UST and its associated piping were drummed and transported to the Fort Monmouth waste oil holding facility. Refer to Appendix C for a copy of the waste manifest.

After the UST was cleaned, it was staged on polyethylene sheeting and examined for holes. No holes were observed during the inspection by the Sub-Surface Evaluator. Soils surrounding the UST and piping were screened visually and with an OVA for evidence of contamination. No evidence of contamination was observed. Groundwater was encountered at 6.0 feet bgs and a sheen was not observed. See Figure 3 for a cross-sectional view of the excavated area.

1.5 UNDERGROUND STORAGE TANK TRANSPORTATION AND DISPOSAL

The fiberglass tank was transported in compliance with all applicable regulations and laws. Refer to Appendix D for a copy of the UST disposal certificate and Appendix F for photographs of the UST.

The UST was labeled prior to transport with the following information:

- Site of origin
- Contact person
- NJDEP UST Facility ID number
- Date
- Destination site
- Former contents

1.6 MANAGEMENT OF EXCAVATED SOILS

Based on OVA air monitoring and TPHC analysis results from the post-excavation soil samples, no soils exhibited signs of contamination. Therefore, the excavated soils were used as backfill following removal of the UST.

2.0 SITE INVESTIGATION ACTIVITIES

2.1 OVERVIEW

1 1

5.7

The Site Investigation was managed and carried out by U.S. Army DPW personnel. All analyses were performed and reported by U.S. Army Fort Monmouth Environmental Laboratory, a NJDEP-certified testing laboratory. All sampling was performed under the direct supervision of a NJDEP Certified Sub-Surface Evaluator according to the methods described in the NJDEP Field Sampling Procedures Manual (1992). Sampling frequency and parameters analyzed complied with the NJDEP-BUST document Interim Closure Requirements for Underground Storage Tank Systems (October 1990 and revisions dated November 1, 1991) which was the applicable regulation at the date of the closure. All records of the Site Investigation activities are maintained by the Fort Monmouth DPW Environmental Office.

The following Parties participated in Closure and Site Investigation Activities:

 Subsurface Evaluator: Eugene Lesinski Employer: U.S. Army, Fort Monmouth

Phone Number: (908) 532-0989 NJDEP Certification No.: 0014537

Analytical Laboratory: U.S. Army Fort Monmouth Environmental Laboratory

Contact Person: Daniel K. Wright Phone Number: (908) 532-4359

NJDEP Company Certification No.: 13461

2.2 FIELD SCREENING/MONITORING

Field screening was performed by a NJDEP Certified Sub-Surface Evaluator using an OVA and visual observations to identify potentially contaminated material. Soil excavated from around the tank and appurtenant piping did not exhibit any evidence of potential contamination. Groundwater encountered did not exhibit a sheen.

2.3 SOIL SAMPLING

On April 22, 1997, following the removal of the UST, post-excavation soil samples A, B, C, D, E, and DUP A were collected from a total of five (5) locations of the UST excavation. Sidewall samples A, B, C, D, and DUP A were collected at a depth of 5.0 feet bgs. Pipe run sample E was collected along the former piping trench, which was approximately five (5) feet in length and which ran southeast to Building 116A. Sample E was collected at a depth of 1.0 feet bgs. All samples were analyzed for total petroleum hydrocarbons (TPHC) and total solids.

U.S. Army personnel in accordance with the NJDEP Technical Requirements and the NJDEP Field Sampling Procedures Manual performed the site assessment. A summary of sampling activities including parameters analyzed is provided in Table 1. The post-excavation soil samples were collected using NJDEP *Field Sampling Procedures Manual* (1992) standard sampling procedures. Following soil sampling activities, the samples were chilled and delivered to U.S. Army Fort Monmouth Environmental Laboratory located in Fort Monmouth, New Jersey, for analysis.

3.0 CONCLUSIONS AND RECOMMENDATIONS

3.1 SOIL SAMPLING RESULTS

To evaluate soil conditions following removal of the UST and associated piping, post-excavation soil samples were collected on April 22, 1997 from a total of five (5) locations. All samples were analyzed for TPHC and total solids. The post-excavation sampling results were compared to the NJDEP residential direct contact total organic contaminants soil cleanup criteria of 10,000 mg/kg (N.J.A.C. 7:26D and revisions dated February 3, 1994). A summary of the analytical results and comparison to the NJDEP soil cleanup criteria is provided in Table 2 and the soil sampling locations are shown on Figure 4. The analytical data package is provided in Appendix E.

All post-excavation soil samples collected on April 22, 1997, from the UST excavation and from below piping associated with the UST contained concentrations of TPHC below the NJDEP soil cleanup criteria. Samples contained TPHC levels ranging from non-detected to 333.44 mg/kg.

3.2 CONCLUSIONS AND RECOMMENDATIONS

The analytical results for all post-excavation soil samples collected from the UST closure excavation at Building 116A were below the NJDEP soil cleanup criteria for total organic contaminants.

Based on the post-excavation sampling results, soils with TPHC concentrations exceeding the NJDEP soil cleanup criteria for total organic contaminants of 10,000 mg/kg, do not exist in the former location of the UST or associated piping.

No further action is proposed in regard to the closure and site assessment of UST No. 90010-8 at Building 116A.

TABLES

TABLE 1

SUMMARY OF POST-EXCAVATION SAMPLING ACTIVITIES BUILDING 116A, MAIN POST-EAST AREA FORT MONMOUTH, NEW JERSEY

Page 1 of 1

Sample ID	Date of Collection	Date Analysis Started	Matrix	Sample Type	Analytical Parameters*	NJDEP Method
Α	4/23/97	4/25/97	Soil	Post-Excavation	TPHC	OQA-QAM-025
В	4/23/97	4/25/97	Soil	Post-Excavation	TPHC	OQA-QAM-025
С	4/23/97	4/25/97	Soil	Post-Excavation	TPHC	OQA-QAM-025
D	4/23/97	4/25/97	Soil	Post-Excavation	TPHC	OQA-QAM-025
Е	4/23/97	4/25/97	Soil	Post-Excavation	TPHC	OQA-QAM-025
DUP A	4/23/97	4/25/97	Soil	Post-Excavation	TPHC	OQA-QAM-025

Note:

* TPHC Total Petroleum Hydrocarbons

TABLE 2 POST-EXCAVATION SOIL SAMPLING RESULTS BUILDING 116A, MAIN POST-EAST AREA

FORT MONMOUTH, NEW JERSEY

Page 1 of 1

Sample ID/ Depth	Sample Laboratory ID	Sample Date	Analysis Date	Analytical Parameters	Method Detection Limit (mg/kg)	Compound of Concern	Results (mg/kg) *	NJDEP Soil Cleanup Criteria ** (mg/kg)	Exceeds Cleanup Criteria
A/5.0'	2469.01	4/23/97	4/25/97	Total Solid			87.89 %		
				TPHC	172	yes	ND	10,000	No
B/5.0'	2469.02	4/23/97	4/25/97	Total Solid			78.21 %		
				TPHC	199	yes	ND	10,000	No
C/5.0'	2469.03	4/23/97	4/25/97	Total Solid	**		87.00 %		
				TPHC	178	yes	ND	10,000	No
D/5.0'	2469.04	4/23/97	4/25/97	Total Solid			83.74 %		
				TPHC	187	yes	ND	10,000	No
E/1.0'	2469.05	4/23/97	4/25/97	Total Solid			89.90 %		
				TPHC	173	yes	ND	10,000	No
DUP A/5.0'	2469.06	4/23/97	4/25/97	Total Solid			88.68%		
				ТРНС	175	yes	333.44	10,000	No

Note:

Total Solid results are expressed as a percentage.


NJDEP Residential Direct Contact soil cleanup criteria for total organics **

ND Not detected above stated method detection limit

TPHC Total Petroleum Hydrocarbons

Not Applicable

FIGURES





LONG BRANCH, NJ

40073-C8-TF-024

1954

PHOTOREVISED 1981 DMA 6164 I SE -SERIES V822



Quadrangle Location

Mapped, edited and published by the Geological Survey

FIGURE 1

SITE LOCATION MAP Building 116A

Building 116A
Main Post-East
Fort Monmouth Army Base

Monmouth County, NJ



SMC Environmental Services Group Engineers, Managers, Scientists, & Planners


Valley Forge, Pennsylvania

Scale:

1"=2,000"

Date:

DEC 1997






FIGURE 3
CROSS SECTIONAL VIEW
BUILDING 116A
FORT MONMOUTH ARMY BASE
MONMOUTH COUNTY, NJ




SMC ENVIRONMENTAL SERVICES GROUP

Engineers, Managers, Scientists & Planners VALLEY FORGE, PA.

SCALE: NTS

DATE: OCT. 1997

6A 2429 FIG3





LEGEND

SOIL SAMPLE LOCATION (APRIL 22, 1997)

LIMIT OF EXCAVATION (APRIL 22, 1997)

NOTES: 1. ALL RESULTS IN MG/KG.

- 2. SEE TABLE 2 FOR NJDEP SOIL CLEANUP CRITERIA
- 3. BGS = BELOW GROUND SURFACE

FIGURE 4 SOIL SAMPLING LOCATION MAP **BUILDING 116A** FORT MONMOUTH ARMY BASE MONMOUTH COUNTY, NJ



SMC ENVIRONMENTAL SERVICES GROUP

Engineers, Managers, Scientists & Planners VALLEY FORGE, PA.

SCALE: 1"=10'

DATE:

DEC. 1997

δ

١...ه

APPENDIX A NJDEP STANDARD REPORTING FORM



State of New Jersey Department of Environmental Protection and Energy Division of Responsible Party Site Remediation CN 028

Trenton. NJ 08625-0029

ATTN: UST Program (609) 984-3156

For State	Use Only
Date Rec'd.	
wth.	
louting .	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
IST NO.	
·	AND ADDRESS.

		NDARD REPORTING FORM orting activities at an UST facility	<i>r</i> :	
-	General Facility Informati Closure (Abandonment o Temporary Closure Change in Service	on Changes S r Removal) S	ale or Transfer ubstantial Modification inancial Responsibility Voctress Change Only	70 S
	Check ONLY One Ty	pe of Activity - Complete Form F	For That Activity	
**************************************	(More tha	n one tank can be listed per acti	vity)	
		NEW tank installations at ex Registration Questionnaire for		
Answer questions	1 through 5 and others as ap	olicable.		
	ne and address (as it gistration questionnaire):	DPW - BUILD FORT MONMO	ING 173 UTH NIT 07 EVE W. LESIN	703 USKI
2. Facility name (If different fro				
3. Contact perso	n for this activity :	GENE LESI, Telephone Number: (99	USKI 681 <u>532-09</u>	89
4. The identifica	tion number of the affected tar	nk as it appears in Question Nur	mber 12 on the Registration	Questionnaire:
BLDO	0/164		8	
	tumber (II known):	ust	1001p	
6. FOR GENERAL	FACILITY INFORMATION char	iges (address, telephone, contact	person, etc supply NEW in	formation only):
a. Facility na b. Facility lo	ration:			
	-		เม	1-8
e. Contact p				
		(OVER)		

abandonment p b. (X) Removal Attach the nece 8. For CHANGES IN I a. (1) Temporary C substances; lear b. (1) Change in s and site assessi c. (1) Changes in	ssary implementation sche er N.J.A.C. 7:14B-9.1 (d). Date: 7 / Ssary implementation sche HAZARDOUS SUBSTANCION (12 month maximum ve tank in place. ervice from a regulated subment performed per N.J.A. (service from one regulated)	Case No. dule (3 copies). ES STORED (check all in time - see N.J.A.C. 7 estance to a non-regular C. 7:148-9.1(e).	that apply): :14B-9.1(b)). Remove	eli hazardous
abandonment p b. IX Removal Attach the nece 8. For CHANGES IN I a. II Temporary C substances; lead b. II Change in s and site assessi c. II Changes in: Tank No.	er NJ.A.C. 7:148-9.1 (d). Date: 7// Ssary implementation sche HAZARDOUS SUBSTANCE Closure (12 month maximum ve tank in place. ervice from a regulated sub- ment performed per NJ.A. (service from one regulated	Case No. dule (3 copies). ES STORED (check all in time - see N.J.A.C. 7 estance to a non-regular C. 7:148-9.1(e).	that apply): :148-9.1(b)). Remove	eli hazardous
b. IX Removal Attach the nece 8. For CHANGES IN H a. Temporary C substances; lead b. Change in s and site assess c. Changes in: Tank No.	Date:	dule (3 copies). ES STORED (check all n time - see N.J.A.C. 7 estance to a non-regular C. 7:148-9.1(e).	that apply): :14B-9.1(b)). Remove	
Attach the nece 8. For CHANGES IN F a. Temporary C substances; lea b. Change in s and site assessi c. Changes in: Tank No.	SSARY implementation schellazardous SUBSTANCI HAZARDOUS SUBSTANCI Hosure (12 month maximum ve tank in place. Brivice from a regulated sub ment performed per NJA.	dule (3 copies). ES STORED (check all n time - see N.J.A.C. 7 estance to a non-regular C. 7:148-9.1(e).	that apply): :14B-9.1(b)). Remove	
8. For CHANGES IN Fa. Temporary C substances; lear b. Change in sand site assessing. Changes in: Tank No.	HAZARDOUS SUBSTANCE to the control of the control o	ES STORED (check all ni time - see NJ.A.C. 7 estance to a non-regular C. 7:148-9.1(e).	:148-9.1(b)). Remove	
a. Temporary C substances; lear b. Change in s and site assessing. Changes in: Tank No	Hosure (12 month maximum ve tank in place. ervice from a regulated subment performed per N.J.A. (service from one regulated)	n time - see N.J.A.C. 7 estance to a non-regular C. 7:148-9.1(e).	:148-9.1(b)). Remove	
substances; lead b. Change in some and site assessing Changes in: Tank No.	ve tank in place. ervice from a regulated subment performed per NJA. service from one regulated	estance to a non-regular C. 7:148-9.1(e).		
b. Change in s and site assessi c. Changes in: Tank No.	ervice from a regulated sub ment performed per N.J.A.(service from one regulated	C. 7:14B-9.1(e).	ted substance. Tank m	ust be cleaned
and site assessi c. □ Changes in: Tank No	ment performed per NJA.(service from one regulated	C. 7:14B-9.1(e).		
c. D Changes in: Tank No	service from one regulated			•
Tank No.	-	Hereignas sonsigire i	o another regulated ha	izardous substance.
	014		-	•
14-1110				
	ON		New	
	(Attach additio	nal sheets if more space	æ is needed)	
3. For TRANSFER OF	OWNERSHIP: Effe	ctive Date:	/ /	
	erator)		·	
	me			
·		**		
•	*****		w	
	****	<u> </u>		
		County		
c. Closing Attorney	/ 		Tole: (J
a. b.	ANCIAL RESPONSIBILITY Policy Type: Policy Number:	to (check appropriate d. Company/C e. Expiration D	amer: 🗆	pies of new information):
C.	Citat: []			•

	(Specify)			•
	(0,000)			

(INIT/MID-2/92)

APPENDIX B SITE ASSESSMENT SUMMARY

US	Ţ.	-0	1	4
2/9	1			

FOR STATE USE ONLY
UST#
Date Rec'd
TMS#
Staff

STATE OF NEW JERSEY DEPARTMENT OF ENVIRONMENTAL PROTECTION

Division of Responsible Party Site Remediation CN 029 TRENTON, N.J. 08625-0028 Tel. # 609-984-3156 Fax.# 609-292-5604

Scott A. Weiner Commisioner

Karl J. Delaney Director

UNDERGROUND STORAGE TANK SITE ASSESSMENT SUMMARY

Under the provisions of the Underground Storage of Hazardous Substances Act in accordance with N.J.A.C. 7:14B

This Summary form shall be used by all owners and operators of Underground Storage Tank Systems (USTS) who have either reported a release and are subject to the site assessment requirements of N.J.A.C. 7:14B-8.2 or who have closed USTS pursuant to N.J.A.C. 7:14B-9.1 et seq. and are subject to the site assessment requirements of N.J.A.C. 7:14B-9.2 and 9.3.

INSTRUCTIONS:

- ♦ Please print legibly or type.
- Fill in all applicable blanks. This form will require various <u>attachments</u> in order to complete the Summary. The technical guidance document, <u>Interim Closure Requirements for UST's</u>, explains the regulatory (and technical) requirements for closure and the <u>Scope of Work, Investigation and Corrective Action Requirements for Discharges from Underground Storage Tanks and Piping Systems</u> explains the regulatory (and technical) requirements for corrective action.
- Return one original of the form and all required attachments to the above address.
- Attach a scaled site diagram of the subject facility which shows the information specified in Item IV B of this
 form.

_0192477-1 Facility Registration #
Facility Registration #
th

II.	DISCHARGE REPORTING REQUIREMENTS
	A. Was contamination found?YesXNo If Yes, Case No(Note: All discharges must be reported to the Environmental Action Hotline (609) 292-7172)
	B. The substance(s) discharged was (were)N/A
	C. Have any vapor hazards been mitigated?Yes NoX N/A
III.	DECOMMISSIONING OF TANK SYSTEMS Closure approval No. NJDEP "Blanket Closure"
	The site assessment requirements associated with <u>tank decommissioning</u> are explained in the Technica Guidance Document, Interim Closure Requirements for UST's, Section V. AD. <u>Attach completed documentation of the methods used and the results obtained for each of the steps of tank decommissioning used. Please include a <u>site</u> map which shows the locations of all samples and borings, the location of all tanks and piping runs at the facility at the beginning of the tank closure operation and annotated to differentiate the status <u>of all tanks and piping</u> (e.g., removed, abandoned, temporarily closed, etc.). The same site map can be used to document other parts of the site assessment requirements, if it is properly and legibly annotated.</u>
IV.	SITE ASSESSMENT REQUIREMENTS
	A. Excavated Soil
	Any evidence of contamination in excavated soil will require that the soil be classified as either Hazardous Waste or Non-Hazardous Waste. Please include all required documentation of compliance with the requirements for handling contaminated excavated soil (if any was present) as explained in the technical guidance documents for closure and corrective action. Describe amount of soil removed, its classification and disposal location.
	B. Scaled Site Diagrams
	1. Scaled site diagrams must be attached which include the following information:
	 a. North arrow and scale b. The locations of the ground water monitoring wells c. Location and depth of each soil sample and boring d. All major surface and subsurface structures and utilities e. Approximate property boundaries f. All existing or closed underground storage tank systems, including appurtenant piping g. A cross-sectional view indicating depth of tank, stratigraphy and location of water table h. Locations of surface water bodies
	C. Soil samples and borings (check appropriate answer)
	1. Were soil samples taken from the excavation as prescribed? X_YesNoN/A
	2. Were soil borings taken at the tank system closure site as prescribed?Yes NoX_ N/A
	3. Attach the analytical results in tabular form and include the following information about each sample
	 a. Customer sample number (keyed to the site map) b. The depth of the soil sample c. Soil boring logs d. Method detection limit of the method used

QA/QC Information as required

۱. _a

L 3

D.	Ground Water Monitoring
1.	Number of ground water monitoring wells installed0
2.	Attach the analytical results of the ground water samples in tabular form. Include the following information for each sample from each well:
	 a. Site diagram number for each well installed b. Depth of ground water surface c. Depth of screened interval d. Method detection limit of the method used e. Well logs f. Well permit numbers g. QA/QC Information as required
V. S	COIL CONTAMINATION
	A. Was soil contamination found?YesXNo If "Yes", please answer Question B-E If "No", please answer Question B
	B. The highest soil contamination still remaining in the ground has been determined to be: 1N/Appb total BTEX,N/Appb total non-targeted VOC 2N/Appb total B/N,N/Appb total non-targeted B/N 3333.44ppm TPHC 4N/AppbN/A(for non-petroleum substance)
	C. Remediation of free product contaminated soils
	 All free product contaminated soil on the property boundaries and above the water table are believed to have been removed from the subsurface Yes No Free product contaminated soils are suspected to exist below the water table Yes No Free product contaminated soils are suspected to exist off the property boundaries Yes No
	D. Was the vertical and horizontal extent of contamination determined?YesNoN/A
	E. Does soil contamination intersect ground water?YesNoN/A
VI.	GROUND WATER CONTAMINATION
	A. Was ground water contamination found?YesXNo If "Yes", please answer Questions B-G. If "No", please answer only Question B.
	B. The highest ground water contamination at any 1 sampling location and at any 1 sampling event to date has been determined to be: N/A
	1ppb total BTEXppb total non-targeted VOC
	2. ppb total B/N. ppb total non-targeted B/N
	3ppb total MTBEppb total TBA
	4ppb(for non-petroleum substance) 5. greatest thickness of separate phase product found
	6. separate phase product has been delineatedYes No N/A

4 1 2 2124 2 200 4

C. I	Resu	ults (s) of well search
		A well search (including a review of manual well records) indicates that private, municipal or commercial vells do exist within the distances specified in the Scope of WorkYesNo N/A
	2. 7	The number of these wells identified is
D.	Pro	ximity of wells and contaminant plume
	1.	The shallowest depth of any well noted in the well search which may be in the horizontal or vertical potential path(s) of the contaminant plume(s) is feet below grade (consideration has been given for the effects of pumping, subsurface structures, etc. on the direction(s) of contaminant migration). This well is feet from the source and its screening begins at a depth of feet.
	2.	The shallowest depth to the top of the well screen for any well in the potential path of the plume(s) (as described in D1 above above) is feet below grade. This well is located feet from the source.
	3.	The closest horizontal distance of a private, commercial, or municipal well in the potential path of the plume (as determined in D1) is feet from the source. This well is feet deep and screening begins at a depth of feet.
E.	Α	plan for separate phase product recovery has been includedYes No N/A
F.		ground water contour map has been submitted which includes the ground water elevations for each wellYesNoN/A
G.	De	elineation of contamination
	1.	The ground water contaminants have been delineated to MCLs or lower values at the property boundaries. Yes No
		The plume is suspected to continue off the properly at concentrations greater than MCLs. Yes No
	3.	Off property access (circle one): is being sought has been approved has been denied
VII.		<u>SITE ASSESSMENT CERTIFICATION</u> [preparer of site assessment plan - N.J.A.C. 7:14B-8.3(b) &9.5(a)3]
		The person signing this certification as the "Qualified Ground Water Consultant" (as defined in N.J.A.C.7:14B-1.6) responsible for the design and implementation of the site assessment plan as specified in N.J.A.C. 7:14B-8.3(a) & 9.2(b)2, must supply the name of the certifying organization and certification number.
		"I certify under penalty of law that the information provided in this document is true, accurate, and complete and was obtained by procedures in compliance with N.J.A.C. 7:14B-8 and 9. I am aware that there are significant penalties for submitting false, inaccurate, or incomplete information, including fines and/or imprisonment."
		NAME (Print or Type) <u>Eugene Lesinski</u> SIGNATURE <u>SEE ATTACHED SUB-SURFACE EVALUATOR LOG</u> COMPANY NAME <u>U.S. Army Fort Monmouth</u> DATE (Preparer of Site Assessment Plan)
		CERTIFYING ORGANIZATION NJDEP NUMBER 0014537

The state of the s

VIII. TANK DECOMMISSIONING CERTIFICATION [person performing tank decommissioning portion of closure plan - N.J.A.C. 7:14B-9.5(a)4] "I certify under penalty of law that tank decommissioning activities were performed in compliance with N.J.A.C. 7:14B-9.2(b)3. I am aware that there are significant penalties for submitting false, inaccurate, or incomplete information, including fines and/or imprisonment." NAME (Print or Type) SAME AS SITE ASSESSMENT SIGNATURE _____ DATE COMPANY NAME (Peformer of Tank Decommissioning) IX. CERTIFICATIONS BY THE RESPONSIBLE PARTY(IES) OF THE FACILITIES A. The following certification shall be signed by the highest ranking individual with overall responsibility for that facility [N.J.A.C. 7:14B-2.3(c)11]. "I certify under penalty of law that the information provided in this document is true, accurate, and complete. I am aware that there are significant penalties for submitting false, inaccurate, or incomplete information, including fines and/or imprisonment." NAME (Print or Type) ______ SIGNATURE / NAME COMPANY NAME U.S. Army Fort Monmouth B. The following certification shall be signed as follows [according to the requirements of N.J.A.C. 7:14B-2.3(C)2I]: 1. For a corporation, by a principal executive officer of at least the level of vice president. 2. For a partnership or sole proprietorship, by a general partner or the proprietor, respectively; or 3. For a municipality, State, Federal or other public agency by either the principal executive officer or ranking elected official. 4. In cases where the highest ranking corporate partnership, governmental officer or official at the facility as required in A above is the same person as the official required to certify in B, only the certification in A need to be made. In all other cases, the certifications of A and B shall be made. "I certify under penalty of law that I have personally examined and am familiar with the information submitted in this application and all attached documents, and that based on my inquiry of those individuals immediately responsible for obtaining the information, I believe that the submitted information is true, accurate, and complete. I am aware that there are significant penalties for submitting false, inaccurate, or incomplete information, including fines and/or imprisonment." NAME (Print or Type) ______SIGNATURE _____ COMPANY NAME _____ DATE _____

IS ARMY, SELFM-PW- / DAILY UST SUBSURFACE REMOVAL LOG

, y'	BLDG.#: 164 REG.#: 0090010 - 8 CLOSURE#: NA	
	DATE: 4-22-97 TOA: * 0 900 TOD: 100	
, <i>)</i>	GOV. SSE: $\frac{1e_{S}NSK!}{1e_{S}NSK!}$ NJDEP CERT.#: $\frac{OQ}{453}$	
L. J	CLOSURE SUPERVISOR: Le Martin (NJDEP CERT.#:	
()	WEATHER: SUNNY - 550 F	
L		
r x :	ACTIVITY	YES/ NO
ديا	THE SUPERVISOR (CLOSURE CERT.) WAS ON-SITE DURING ALL CLOSURE RELATED ACTIVITIES	7
(7	THE SSE WAS ON-SITE DURING UST REMOVAL AND SITE SCREENING AND SAMPLING ACTIVITIES	4
No. 1.0	ALL ON-SITE PERSONNEL HAD TRAINING IAW ALL SAFETY REQUIREMENTS (E.G. 29CFR)	Y
r)	A CONFINED ENTRY PERMIT WAS COMPLETED AND POSTED ON-SITE BY THE CONTRACTOR	NR
h	THE UST WAS PLACED ONTO PLASTIC, SCRAPED OFF, INSPECTED FOR HOLES AND PHOTOGRAPHED	Y
- '	A DISCHARGE WAS REPORTED TO THE NUDEP (609-292-7172), CASE#	N
ديا	PHOTOS HAVE UST#, BLDG. #, DATE, TIME, NAME OF SSE AND DESCR. WRITTEN ON BACK	Y
1 1	GROUNDWATER WAS ENCOUNTERED AT 6 FEET BG, A SHEEN (WAS NOT) OBSERVED ON GW	Y
3i	IF OVA/Hnu WAS USED: WAS IT CAL. AND FOUND TO BE OPERATIONAL (cal. data on COC)	4
7 1 (IF SAMPLES WERE TAKEN: COC, SCALED SITE MAP (VERT. SOIL HORIZONS AND PLOT PLAN)	<u>/</u>
Notes	ALL SAMPLE COLLECTION ACTIVITIES WERE AS DESCRIBED IN THE NJDEP FSPM, 1992	Δ
1 1	ALL SAMPLING WAS BIASED TOWARD HIGHEST OVA/FID RECORDED SITES IAW 7:26E-3.6 et seq.	Y
k, w	ALL PETROL. CONT. SOILS WERE SECURED FROM THE WEATHER BY CLOSE OF BUSINESS TODAY	NA
Γ)	THE SSE AUTHORIZED BACKFILLING THE EXCAVATION (STONE TO 1" ABOVE GROUNDWATER)	7
<u></u>	ADDITIONAL NOTES WERE TAKEN AND ARE RECORDED ON THE BACK OF THIS FORM	N
F X	THE FOLLOWING DOCUMENTS WERE ADDED TO THE PROJECT FOLDER TODAY: (CIRCLE EACH)	
Normal	SCRAP TICKET, CSE PERMIT, ACCIDENT REPORT, HAZ. WASTE MANIFEST, DAILY UST CLOSURE LOG, SCALED SITE MAP (SAMPLING), SRF-CLOSURE, CHAIN OF CUSTODY SOIL ANALYTICAL RESULTS, CLEAN	1
t t	FILL TICKETS (IN YDS ³), PHOTOGRAPHS (UST, EXCAVATION, SAMPLING POINTS) CHECK ALL BOXES, LEAV	NO POLICE
I c	ertify under penalty of law that tank decommissioning activities	
perf	formed in compliance with N.J.A.C. 7:14B-9.2(b)3 and 7:26 et seq I a	m aware
that	there are significant penalties for submitting false, inaccura	ite, or
inco	omplete information, including fines and/or imprisonment.	
SIGN	NATURE: DATE: $\frac{y-72-9}{}$	
	•	

/ ca\ms\ust\removal\sitessls.doc

APPENDIX C

WASTE MANIFEST

LORCO PETROLEUM SERVICES

RD 1 BOX 5A OLD BRIDGE, NJ 08857

	OLD BRIDGE, NJ 0885/						
	NON-HAZARDOUS WASTE MANIFEST N.J.3.21.0.0.205.9.70.2058	2. Page of		NH	z 002	988	
	MAIN POST ON TOE FALLOW - BLDG 173 GOSWIESZ-6223 FILT MONMONTH NJ 07703	SAME					
	LIONETTI OIL RECOVERY CO INC N. J. D. 0.8 4 0.4 4 0.6 4 908 721-0900						
	7. Transporter 2 Company Name 8. US EPA ID Number B. Transporter's Phone						
	L Cesignated Facility, Name and Site Address L I ONE IT OIL RECOVERY CO INC DBA LORCO PETROLEUM SVCS RUNYON&CHEESEQUAKE RDS						
	OLD BRIDGE, NJ 08857 N.J.D.O.8.4.0.4.4.0.6.4	J	721-				
	11. Waste Shipping Name and Description		12. Cont No.	Type	13. Total Quantity	14. Unit Wt/Vol	
	PETROLEUM OIL(PETROLEUM OIL) COMBUSTIBLEL LIQUID UN1270 PGIII		0. 0. 1	Т. Т	13000	G	
GENERATOR	ь.		· ·				
A T O R	c. ,						
	d.						
	D. Additional Descriptions for Materials Listed Above T,L PETROLEUM OIL 60% WATER 40%	E. Handling Codes for Wastes Listed Above TO4 FILTRATION				ve	
	15. Special Handling Instructions and Additional Information 24 HR EMERGENCY RESPONSE#(908) 721-0900 DECAL#73624ERG#128 DEXSIL TEST KIT RESULTS MA-PPM MANIFEST USED FOR TRACKING PURPOSES ONLY						
~		7	1		<i></i>		
11 q	16. GENERATOR'S CERTIFICATION: I certify the materials described above on this magness are not subject to fedefall Brinted/Typed Name Significant Significant	regulations for	reportin	g prope	disposal of Hazard	ous Waste.	
ľ	17. Transporter 1 Acknowledgement of Receipt of Materials	VA	700		<u> </u>	<u> </u>	
TRANSPORTER	Printed/Typed Name DON TAGUINOT Signature Very				0.40	oy Year 3 9.7	
CR	18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name Signature		·····		Month L	ay Year	
Ē	19. Discrepancy Indication Space					<u> </u>	
ļ							
	20. Facility Owner or Operator: Certification of receipt of waste materials covered by this manifest except as n	oted in Iten	n 19.				
	Printed/Typed Name Tow Willett Signature Some	${c}$	K	\mathbb{Q}	Month 8)3 9	
20.44	ORIGINAL - RETURN TO GENERATOR						

116-A

LORCO PETROLEUM SERVICES RD 1 BOX 5A OLD BRIDGE, NJ 08857

	NON-HAZARDOUS WASTE MANIFEST	1. Generator's US	EPA ID No.	Manifest Johnson Ja.	2. Page of	1	NH	z 001	531		
A	3. Generator's Name and Mailing Address .										
	5. Transporter 1 Company Name LIONETTI OIL RECOVERY CO	INC	US EPA ID N. J. D. O. 8. 4.	Number 0, 4, 4, 0, 6, 4		porter's Pl		00			
	7. Transporter 2 Company Name		B. US EPA ID			porter's Ph	none				
	9. Designated Facility Name and Site Address 10. US EPA ID Number LIONETTI OIL RECOVERY CO INC DBA LORCO PETROLEUM SVCS RUNYON&CHEESEQUAKE RDS										
1	OLD BRIDGE, NJ 08857 [N. J. D. O. 8. 4. 0. 4. 4. 0. 6. 4] 908 721-0										
	11. Waste Shipping Name and Description					No.	Туре	Total Quantity	Unit Wt/Val		
	° PETROLEUM OIL (PETROLEUM COMBUSTIBLEL LIQUID UN12	OIL) 70 PGIII				0 0 1	T. T	X3.200	G		
GENE	ь.										
R A T O R	c.										
	d.										
	D. Additional Descriptions for Materials Listed T,L PETROLEUM OIL / %	Above			E. Hand	dling Code	es for W	astes Listed Abov	e		
	WATER 99 %				T04	FILTE	RATIO	ON			
,	15. Special Handling Instructions and Addition 24 HR EMERGENCY RESPONSE DECAL# 7363 & ERG#128 DEXS MANIFEST USED FOR TRACKI	#(908) 721-0 SIL TEST KIT	RESULTS NA	PPM							
				7	1) 					
	16. GENERATOR'S CERTIFICATION: 1 certify Printed/Typed Name	the materials described a	bove on this maniful are	not subject to federal i	egylations 1	for reporting	proper	Month Do			
	17. Transporter 1 Acknowledgement of Receip	ot of Materials	- Cur	my A	rsu	Ny st		10.412	419.7		
	17. Transporter 1 Acknowledgement of Receiper 1 Acknowledgement 1 Acknowledgement 1 Acknowledgement 1 Acknowledgement 1 Acknow	rienzu	Signovore	Kaul I	2	7		10412	<u>4</u> 9.7		
1111			Signature					Month Do	y Year		
	19. Discrepancy Indication Space										
-	20. Facility Owner or Operator: Certification	of receipt of waste ma	terials covered by this	manifest except as no	oted in Iter	m 19.					
-	Printed/Typed Name	6	Signature	les X	00	ul	e	19. E/2	14/37		
m i sa		OPIGINA	AL - RETURN TO (CENERATOR							

APPENDIX D UST DISPOSAL CERTIFICATE



MONMOUTH COUNTY RECLAMATION CENTER

TINTION FALLS, NJ

MAILING 6000 ASBURY AVE. ADDRESS: NEPTUNE, NJ 07753

OPER.

PIMIN

VEHICLE TYPE

Rollotf Open 116-A

CUSTOMER COPY

FACILITY I.D. NO. 1336F1SP01

RECEIPT DOCUMENT NUMBER

01628705

MARPSW6937 MARPAL COMPANY PO BOX 188

ENTRY TIME

1 : 00

Goale 01

1.3

LINCRUFT

DATE

Ø6/19/97

@1778369

VEHICLE NUMBER

1.7100

206SAM

QUANTITY

NJ 07738

OPER.

JJJ

PLATE NUMBER

XV19FN

DESCRIPTION/ORIGIN

EXIT TIME

Scale 04

16

Bulky Waste - (MRF)

MONMOUTH COUNTY

EATOHTOWN BORDUCH

14:19

MARPS08937
MARPAL COMPANY
E PO BOX 188

LINCROFT 07738 2400.00 **GROSS WEIGHT** TARE WEIGHT NET WEIGHT 35240 LB) 31820 LB) 3420 LB Scale Ø1 Scale 64 15.91 T) 17.62 T) 1.71 17 TRANSACTION TYPE Normal UNIT PRICE AMOUNT UNITS 103.10 184.80 Tons 00.00k

I hereby certify that the	ne informa	tion provided on this form is true to the best of my knowledge.	38140.	BV *** DOCUMENT TOTAL	
PRINT	104	SIGNATURE	***		\$184.05

APPENDIX E SOIL ANALYTICAL DATA PACKAGE

US ARMY FT. MONMOUTH ENVIRONMENTAL LABORATORY **NJDEPE # 13461**

REPORT OF ANALYSIS

Client:

U.S. Army

DPW, SELFM-PW-EV

Bldg. 173

Ft. Monmouth, NJ 07703

Project:

Total Petroleum Hydrocarbons

96-1262

Bldg. 116A

UST

Project # 2469 Date Rec. 04/23/97 Date Compl.04/25/97

Released by:

Daniel K. Wright **Laboratory Director**

Table of Contents

Section	Pages
Cover Sheet	1
Table of Contents	2
Method Summary	3
Conformance/Non-Conformance	4
Chain of Custody	5
Results Summary	6
Initial Calibration Summary	7
Continuing Calibration Summary	8-10
Surrogate Results Summary	11
MS/MSD Results Summary	12
Quality Control Spike Summary	13
Raw Sample Data	14-25
Laboratory Deliverable Checklist	26

Method Summary

NJDEP Method OOA-OAM-025-10/97

Gas Chromatographic Determination of Total Petroleum Hydrocarbons in Soil

Fifteen grams (15g)(wet weight) of a soil sample is added to a 125 mL acid cleaned, solvent rinsed, capped Erlenmeyer flask. 15g anhydrous sodium sulfate is added to dry sample. Surrogate standard spiking solution is then added to the flask.

Twenty five milliliters(25mL) Methylene Chloride is added to the flask and it is secured on a gyrotory shaker table. The agitation rate is set to 400rpm and the sample is shaken for 30 minutes. The flask is the removed from the table and the particulate matter is allowed to settle. The extract is transferred to a Teflon capped vial. A second 25mL of Methylene Chloride is added to the flask and shaken for an additional 30 minutes. The flask is again removed and allowed to settle. The extracts are combined in the vial then transferred to a 1mL autosampler vial.

The extract is then injected directly into a GC-FID for analysis. The sample is analyzed for petroleum hydrocarbons covering a range of C8-C42 including pristane and phytane. Total Petroleum Hydrocarbon concentration is determined by integrating between 5 minutes and 22 minutes. The baseline is established by starting the integration after the end of the solvent peak and stopping after the last peak.

The final concentration of Total Petroleum Hydrocarbons is calculated using percent solid, sample weight and concentration.

PHC Conformance/Non-conformance Summary Report

	<u>No</u>	<u>Yes</u>
1. Method Detection Limits provided.	_	r
2. Method Blank Contamination - If yes, list the sample and the corresponding concentrations in each blank.	<u>Ľ</u>	
3. Matrix Spike Results Summary Meet Criteria. (If not met, list the sample and corresponding recovery which falls outside the acceptable range).	_	\underline{V}
4. Duplicate Results Summary Meet Criteria. (If not met, list the sample and corresponding recovery which falls outside the acceptable range).		$ \underline{\nu}$
5. IR Spectra submitted for standards, blanks, & samples	r	TA
6. Chromatograms submitted for standards, blanks, and samples if GC fingerprinting was conducted.		$ \underline{\vee}$
7. Analysis holding time met.		$\underline{\nu}$
(If not met, list number of days exceeded for each sample)		
Additional Comments:		

Laboratory Authentication Statement

I certify under penalty of law, where applicable, that this laboratory meets the Laboratory Performance Standards and Quality Control requirements specified in N.J.A.C. 7:18 and 40 CFR Part 136 for Water and Wastewater Analyses and SW 846 for Solid Waste Analysis. I have personally examined the information contained in this report, and to the best of my knowledge, I believe that the submitted information is true, accurate, complete, and meets the above referenced standards where applicable. I am aware that there are significant penalties for purposefully submitting falsified information, including the possibility of a fine and imprisonment.

Daniel K. Wright Laboratory Manager



Fort Monmouth Environmental Testing Laboratory

Bldg. 173, SELFM-PW-EV, Fort Monmouth, NJ 07703

Tel (908)532-4359 Fax (908)532-3484 EMail:appleby@doim6.monmouth.army.mil

NJDEP Certification #13461

Chain of Custody Record

Customer: GENE	LESINSKI - DPW	Project No:					Ana	lysis l	Param	eters			Commen		
Phone #: ()DERA ()OMA (()Other:	Location: B. 116A			2,	TE SOLAS	Musel						X = 5 KEPT E	AMPLES BELOW	4°C.
	mpany: GARY DIMARTI	US - TVS	Sample	#	B	1/3	13					MH			
Lab Sample I.D.	Sample Location	Date Ti	те Туре	bottles	1	6,	11		 <u></u>			Ø	Remarks /	Preservation !	Method
2469.01	116A-A	4-22-97 14	40 SOIL	1	\geq	\geq	\geq					ND	SIDEWAL	1@5.0'	*
· 0 2	116A-B	14	50									ND			
.03	116A-C	14	54									עא			
. ૦ન	116A-D	15	05									ND	\	· · · · · · · · · · · · · · · · · · ·	
-05	116A-E	15	09									ND	Piping Ru	N@1.0'	
ما ٥.	116A-DUP	V -	$- \mid \downarrow \mid$	V	\bigvee	1	1						FIELD D	UPLICATE	
													· · · · · · · · · · · · · · · · · · ·		
					L										
NOTE: OUA (PALIBRATED W/95,	PPM CAY	ZERO(U)	PIR (2/2	(OD H	RS. 6	W	4	72-9	76	· G	DIMAR	TINIS	
11	,										1	(SERIAL T	#A52114	2
Religioushed by singland	Date/Time: 4/23/97 1/46	Received by (signatu	he):	Relino	quished	by (sig	nature):		Date/	Time:	Receive	d by (signature):		
Relipquished by (signatur	e): Date/Time:	Received by (signatu	are):	Reline	quished	by (sig	nature):		Date/	Time:	Receive	d by (s	signature):		
Report Type: ()Full, 🖂	Reduced, ()Standard, ()Screen	/ non-certified		•	Rema	rks: D	EDIC	ATEL	SA.	mpu	NG 7	TOU	LS USEI	D. SEE	
	lard 4 wks, ARush 7 Days,		Hrs.		ATTI	ACHE	0 SA	ETC	H F	OR I	AMPL	الايرار	1 LOCAT	70NS.	

Report of Analysis U.S. Army, Fort Monmouth Environmental Laboracy NJDEP Certification # 13461

Client:

U.S. Army

Lab. ID#:

2469

DPW. SELFM-PW-EV

Date Rec'd:

23-Apr-97

Bldg. 173

Analysis Start:

25-Apr-97

Ft. Monmouth, NJ 07703

Analysis Complete:

25-Apr-97

Analysis:

OQA-QAM-025

UST Reg. #:

Matrix:

Soil

Closure #:

Analyst:

P. Skelton

DICAR #:

Ext. Meth:	Shake			B116A		
Sample	Field ID	Dilution Factor	Weight (g)	% Solid	MDL (mg/kg)	TPHC Result (mg/kg)
2469.01	116A-A	1.00	15.52	87.89	172	ND
2469.02	116A-B	1.00	15.12	78.21	199	ND
2469.03	116A-C	1.00	15.16	87.00	178	ND
2469.04	116A-D	1.00	15.04	83.74	187	ND
2469.05	116A-E	1.00	15.14	89.90	173	ND
2469.06	116A-DUP	1.00	15.10	88.68	175	333.44
						,
	<u> </u>					
	<u> </u>					
	<u> </u>					
METHOD BLANK	25-Apr-97	1.00	15.00	100.00	157	ND

ND = Not Detected

MDL = Method Detection Limit

Daniel K. Wright

Laboratory Director

Response Factor Report F1 , TCD

Method : C:\HPCHEM\1\METHODS\TPH5.M (Chemstation Integrator)

Title : TPHC Calibration 01/17/97
Last Update : Wed Apr 16 08:30:41 1997

Calibration Files

.

, 1

7 8

. .

. .

1 (

1 =T01046.D 2 =T01045.D 3 =T01042.D

1 =T01046.D 2 =T01045.D 4 =T01041.D 5 =T01040.D

	Compound	1	2	3	4	5	Avg	%RSD
1) s 2) t	o-terphenyl tphc						3.770 E4 5.626 E4	

Continuing Calibration Report Evalua

Data File : C:\HPCHEM\1\DATA\970425\T01120.D

Acq On : 25 Apr 97 1:45 pm

Vial: 1 Operator:

: 50 ppm Check Sample

Inst : FID/TCD

Misc Multiplr: 1.00

IntFile : autoint1.e

1 9

i = 1

, 1

1.00

7. 9

1 1

1 1

Method : C:\HPCHEM\1\METHODS\TPH5.M (Chemstation Integrator)

: C:\HPCHEM\1\MBING_2\. : TPHC Calibration 01/17/97 Title Last Update : Wed Apr 16 08:30:41 1997 Response via : Multiple Level Calibration

Min. RRF : 0.000 Min. Rel. Area : 50% Max. R.T. Dev 0.50min

Max. RRF Dev : 25% Max. Rel. Area : 150%

	Compound	AvgRF	CCRF	%Dev	Area%	Dev(min)
1 s 2 t	o-terphenyl tphc		43.669 E3 46.193 E3		119 91	0.00

Continuing Calibration Re ort Evalua

Data File : C:\HPCHEM\1\DATA\970425\T01130.D

Operator:

Acq On : 25 Apr 97 8:45 pm

: 50 ppm std Sample Misc

Inst : FID/TCD

Vial: 1

Multiplr: 1.00

IntFile : autoint1.e

. .

7 1

. .

Method : C:\HPCHEM\1\METHODS\TPH5.M (Chemstation Integrator)
Title : TPHC Calibration 01/17/97
Last Update : Wed Apr 16 08:30:41 1997 Response via: Multiple Level Calibration

Min. RRF : 0.000 Min. Rel. Area : 50% Max. R.T. Dev 0.50min

Max. RRF Dev : 25% Max. Rel. Area : 150%

 Compound	AvgRF	CCRF	%Dev	Area%	Dev(min)
o-terphenyl tphc		42.929 E3 45.170 E3		:	

Continuing Calibration Report Evalua

Data File : C:\HPCHEM\1\DATA\970429\T01162.D

Operator:

Acq On : 29 Apr 97 11:57 pm

Vial: 1 Inst : FID/TCD

: 50 ppm check Sample

Multiplr: 1.00

Misc IntFile : autoint1.e

7 1

A 2

Method : C:\HPCHEM\1\METHODS\TPH5.M (Chemstation Integrator)
Title : TPHC Calibration 01/17/97
Last Update : Wed Apr 16 08:30:41 1997 Response via : Multiple Level Calibration

Min. RRF : 0.000 Min. Rel. Area : 50% Max. R.T. Dev 0.50min

Max. RRF Dev : 25% Max. Rel. Area : 150%

	Compound	AvgRF	CCRF	%Dev	Area%	Dev(min)
1 s 2 t	o-terphenyl tphc		28.201 E3 48.215 E3	25.2# 14.3	77 95	0.00

Report of Analysis U.S. Army, Fort Monmouth Environmental Laboratory NJDEP Certification # 13461

Surrogate Recovery Report

Lab. ID #: 2469
Location #: B116A

Sample		Surrogate Added (ppm)	Amount Recovered (ppm)	Percent Recovery
2469.01		20.00	20.08	100.39
2469.02		20.00	20.22	101.12
2469.03		20.00	20.39	101.94
2469.04		20.00	20.31	101.56
2469.05		20.00	20.14	100.71
2469.06		10.00	10.56	105.60
	-			
			 	
}				
	<u> </u>	<u> </u>		
Extraction Blank	25-Apr-97	20.00	21.31	106.57

Surrogate Added: o-Terphenyl

Report of Analysis U.S. Army, Fort Monmouth Environmental Laboratory NJDEP Certification # 13461

Matrix Spike Recovery Report

Lab. ID#:

2469

Location #: B116A

Sample	Spike Amount Added (ppm)	Sample Amount (ppm)	Matrix Spike Amount (ppm)	Percent Recovery	QC Limits
2435.01MS	630	0.00	704.25	111.78	75-125
2435.01MSD	630	0.00	761.92	120.94	75-125

١,

RPD	7.87	20.00

6/3/97

Report of Analysis U.S. Army, Fort Monmouth Environmental Laboratory NJDEP Certification # 13461

Blank Spike Recovery Report

Lab. ID #:

2469

Location #:

B116A

Sample	Date Extracted	Spike Amount Added (ppm)	Matrix Spike Amount (ppm)	Percent Recovery	QC Limits %
Blank Spike	25-Apr-97	630	705.85	112.04	75-125

Quantitation Report 'T Reviewed)

Data File : C:\HPCHEM\1\DATA\970425\T01123.D

Vial: 4

Acq On : 25 Apr 97 3:51 pm Sample : 2469.01

Operator:

Inst : FID/TCD

Misc

Multiplr: 1.00

IntFile : autoint1.e

Quant Time: Apr 29 7:40 1997 Quant Results File: TPH5.RES

Quant Method : C:\HPCHEM\1\METHODS\TPH5.M (Chemstation Integrator)

: TPHC Calibration 01/17/97 Title Last Update : Wed Apr 16 08:30:41 1997

Response via : Initial Calibration

DataAcq Meth: TPH5.M

Volume Inj. : Signal Phase: Signal Info :

Compound	R.T.	Response	Conc Units
System Monitoring Compounds 1) s o-terphenyl	13.39	784546	20.078 mg/L m
Target Compounds 2) t tphc	0.00	0	N.D. mg/L

١.,

Quantitation Report

Data File : C:\HPCHEM\1\DATA\970425\T01123.D

Vial: 4

Acq On : 25 Apr 97 3:51 pm

Operator:

Sample : 2469.01

Inst : FID/TCD
Multiplr: 1.00

Misc :

IntFile : autoint1.e


Quant Time: Apr 29 7:40 1997 Quant Results File: TPH5.RES

Quant Method : C:\HPCHEM\1\METHODS\TPH5.M (Chemstation Integrator)

Title : TPHC Calibration 01/17/97 Last Update : Wed Apr 16 08:30:41 1997 Response via : Multiple Level Calibration

DataAcq Meth : TPH5.M

Volume Inj. : Signal Phase : Signal Info :



T01123.D TPH5.M

Tue Apr 29 07:41:07 1997

Quantitation Report 'T Reviewed)

Data File : C:\HPCHEM\1\DATA\970425\T01124.D

Vial: 5

Acq On : 25 Apr 97 4:34 pm Sample : 2469.02

Operator:

Inst : FID/TCD

Multiplr: 1.00

Misc IntFile : autoint1.e

Quant Time: Apr 29 7:41 1997 Quant Results File: TPH5.RES

Quant Method : C:\HPCHEM\1\METHODS\TPH5.M (Chemstation Integrator)

Title : TPHC Calibration 01/17/97 Last Update : Wed Apr 16 08:30:41 1997

Response via : Initial Calibration

DataAcq Meth: TPH5.M

Volume Inj. : Signal Phase: Signal Info :

Compound	R.T.	Response	Conc Units	_
System Monitoring Compounds 1) s o-terphenyl	13.39	789578	20.223 mg/L m	
Target Compounds 2) t tphc	0.00	0	N.D. mg/L	

Quantitation Report

Data File : C:\HPCHEM\1\DATA\970425\T01124.D

Vial: 5

Acq On : 25 Apr 97 4:34 pm

Operator:

Sample : 2469.02

Misc

Inst : FID/TCD

Multiplr: 1.00

IntFile : autoint1.e


Quant Time: Apr 29 7:41 1997 Quant Results File: TPH5.RES

Quant Method : C:\HPCHEM\1\METHODS\TPH5.M (Chemstation Integrator)

Title : TPHC Calibration 01/17/97
Last Update : Wed Apr 16 08:30:41 1997
Response via : Multiple Level Calibration

DataAcq Meth : TPH5.M

Volume Inj. : Signal Phase : Signal Info :



T01124.D TPH5.M

Tue Apr 29 07:41:26 1997

Quantitation Report 'T Reviewed)

Data File : C:\HPCHEM\1\DATA\970425\T01127.D

Vial: 8 Acq On : 25 Apr 97 6:40 pm Operator:

Sample : 2469.05 Inst : FID/TCD Misc Multiplr: 1.00

IntFile : autoint1.e

Quant Time: Apr 29 7:42 1997 Quant Results File: TPH5.RES

Quant Method : C:\HPCHEM\1\METHODS\TPH5.M (Chemstation Integrator)

: TPHC Calibration 01/17/97 Title Last Update : Wed Apr 16 08:30:41 1997

Response via : Initial Calibration

DataAcq Meth : TPH5.M

Volume Inj. : 1 ul Signal Phase : HP-5

Signal Info : 30m x 0.32mm

Compound	R.T.	Response	Conc Units	
System Monitoring Compounds 1) s o-terphenyl	13.39	786716	20.141 mg/L m	
Target Compounds 2) t tphc	0.00	0	N.D. mg/L	

100

Quantitation Report

Data File : C:\HPCHEM\1\DATA\970425\T01127.D

Vial: 8

Acq On : 25 Apr 97 6:40 pm Operator: : FID/TCD

: 2469.05 Sample

1 21

Inst

Misc

Multiplr: 1.00

IntFile : TPHCINT.E

Quant Time: Apr 29 7:42 1997 Quant Results File: TPH5.RES


Quant Method : C:\HPCHEM\1\METHODS\TPH5.M (Chemstation Integrator)

: TPHC Calibration 01/17/97 Title Last Update : Wed Apr 16 08:30:41 1997 Response via : Multiple Level Calibration

DataAcq Meth: TPH5.M

Volume Inj. : 1 ul Signal Phase: HP-5

Signal Info : 30m x 0.32mm



Quantitation Report 'T Reviewed)

Data File : C:\HPCHEM\1\DATA\970429\T01170.D

Vial: 19

Acq On : 30 Apr 97 5:32 am Sample : 2469.06

Operator:

Inst : FID/TCD

Misc

Multiplr: 1.00

IntFile : autoint1.e

Quant Time: Apr 30 11:08 1997 Quant Results File: TPH5.RES

Quant Method : C:\HPCHEM\1\METHODS\TPH5.M (Chemstation Integrator)

Title : TPHC Calibration 01/17/97 Last Update : Wed Apr 16 08:30:41 1997 Response via : Initial Calibration

DataAcq Meth : TPH5.M

Volume Inj. Signal Phase: Signal Info :

Compound	R.T.	Response	Conc Units
System Monitoring Compounds 1) s o-terphenyl	13.38	453802	10.560 mg/L m
Target Compounds 2) t tphc	13.38	9698672	89.320 mg/L m

Quantitation Report

Data File : C:\HPCHEM\1\DATA\970429\T01170.D

Vial: 19

Acq On : 30 Apr 97 5:32 am

Operator:

Sample : 2469.06

Inst : FID/TCD

Misc : Multiplr: 1.00

IntFile : autoint1.e


Quant Time: Apr 30 11:08 1997 Quant Results File: TPH5.RES

Quant Method : C:\HPCHEM\1\METHODS\TPH5.M (Chemstation Integrator)

Title : TPHC Calibration 01/17/97 Last Update : Wed Apr 16 08:30:41 1997 Response via : Multiple Level Calibration

DataAcq Meth : TPH5.M

Volume Inj. : Signal Phase : Signal Info :



LABORATORY DELIVERABLES CHECKLIST AND NON-CONFORMANCE SUMMARY

THIS FORM MUST BE COMPLETED BY THE LABORATORY OR ENVIRONMENTAL CONSULTANT AND ACCOMPANY ALL DATA SUBMISSIONS

The following Laboratory Deliverables checklist and Non-Conformance Summary shall be included in the data submission. All deviations from the accepted methodology and procedures, of performance values outside acceptable ranges shall be summarized in the Non-Conformance Summary. The Technical Requirements for Site Remediation, effective June 7, 1993, provides further details. The document shall be bound and paginated, contain a table of contents, and all pages shall be legible. Incomplete packages will be returned or held without review until the data package is completed.


It is recommended that the analytical results summary sheets listing all targeted and non-targeted compounds with the method detection limits, practical quantitation limits, and the laboratory and/or sample numbers be included in one section of the data package <u>and</u> in the main body of the report.

1.	Cover page, Title Page listing Lab Certification #, facility name and address, & date of report submitted	
2.	Table of Contents submitted	
3.	Summary Sheets listing analytical results for all targeted and non-targeted compounds submitted	
4.	Document paginated and legible	
5.	Chain of Custody submitted	
6.	Samples submitted to lab within 48 hours of sample collection	
7.	Methodology Summary submitted	
8.	Laboratory Chronicle and Holding Time Check submitted	
9.	Results submitted on a dry weight basis	
10.	Method Detection Limits submitted	
11.	Lab certified by NJDEP for parameters of appropriate category of parameters or a member of the USEPA CLP	
	noratory Manager or Environmental Consultant's Signature	

Laboratory Certification #13461

^{*}Refer to NJAC 7:26E - Appendix A, Section IV - Reduced Data Deliverables - Non-USEPA/CLP Methods for further guidance

APPENDIX F
PHOTOGRAPHS



December 1997

PHOTOGRAPHIC LOG

UST No. 90010-8

Building 116A Main Post-East Fort Monmouth



SMC Environmental Services Group

Engineers, Managers, Scientists, & Planners Valley Forge, Pennsylvania